


AD-A080 495 HUGHES AIRCRAFT CO CANOGA PARK CALIF MISSILE SYSTEMS--ETC F/G 1/3
DESIGN-FOR-REPAIR CONCEPT DEFINITION VOLUME II. DETAILED ANALYS--ETC(U)
AUG 79 F A GERKIN, J L GREEN, J M KING F33615-78-C-1461
UNCLASSIFIED MSG-9285-VOL-2 AFAL-TR-79-1130-VOL-2 NL

1 OF 3
AD
A080495





AFAL-TR-79-1130


② LEVEL III



ADA 080495

Hughes Aircraft Company
Support Systems
Canoga Park, California 91304

AUGUST 1979



VOLUME II: DETAILED ANALYSES, AFAL-TR-79-1130
Final Report for Period 15 August 1978 - 15 May 1979

DDC FILE COPY
30430412

Approved for Public Release; Distribution Unlimited

Air Force Avionics Laboratory
Air Force Wright Aeronautical Laboratories
Air Force Systems Command
Wright-Patterson Air Force Base, Ohio 45433


80 2 7 055

NOTICE


When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely related Government procurement operation, the United States Government thereby incurs no responsibility nor any obligation whatsoever; and the fact that the government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

This report has been reviewed by the Information Office (OI) and is releasable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nations.

This technical report has been reviewed and is approved for publication.




DON L. LOWDERMILK, 2Lt, USAF
Project Engineer



EUGENE E. JONES, Lt Col, USAF
Avionic Systems Engineering Branch
System Avionics Division

FOR THE COMMANDER



RAYMOND E. SIFORD, Colonel, USAF
Chief
System Avionics Division

"If your address has changed, if you wish to be removed from our mailing list, or if the addressee is no longer employed by your organization please notify AFAL/AAA, WPAFB, OH 45433 to help us maintain a current mailing list".

Copies of this report should not be returned unless return is required by security considerations, contractual obligations, or notice on a specific document.

19 REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER ⑧ AFAL-TR-79-1130-Vol-2	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) ⑨ Design-for-Repair Concept Definition Volume II, Detailed Analyses		⑩ TYPE OF REPORT & PERIOD COVERED Final Report 15 August 78 -> 15 May 79
5. AUTHOR(s) ⑩ F. A. Gerkin J. L. Green J. M. King		⑪ PERFORMING ORG. REPORT NUMBER ⑪ MSG-9285-Vol-2
6. PERFORMING ORGANIZATION NAME AND ADDRESS Hughes Aircraft Company, Support Systems 8433 Fallbrook ⑫ Canoga Park, CA 91304		⑫ CONTRACT OR GRANT NUMBER(S) F33615-78-C-1461
7. CONTROLLING OFFICE NAME AND ADDRESS Air Force Avionics Laboratory (AFAL/AAA) Air Force Systems Command Wright-Patterson AFB, Ohio 45433		⑬ PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS ⑬ 2003-09-11
8. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office) ⑭ 12285		⑭ REPORT DATE August 1979
		⑮ NUMBER OF PAGES 278
		⑯ SECURITY CLASS. (of this report) Unclassified
		⑰ DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) D D C ⑮ 12285 FEB 8 1980 B		
18. SUPPLEMENTARY NOTES This technical report is also composed of the following: 1) Volume I, Technical Report 2) Volume III, Field Evaluation Reports		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Design-for-Repair Maintainability Repairability Cost Effectiveness Availability Design Process Supportability		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Current techniques used in the equipment design process have not improved avionics repairability to the level expected. This limitation on repairability results primarily from the maintenance concepts currently implemented and repairability techniques being "designed in" after the system design has been frozen. Subsequently, maintainability, repairability, availability, and supportability of AF equipment suffers during its inter-usable lifetime. The objective of this study was to identify and define Design-for-Repair Concepts which show the greatest potential for enhancing Air Force avionic		

DD FORM 1 JAN 73 EDITION OF 1 NOV 65 IS OBSOLETE

409 721

Block 20 Continued:

maintenance. By identifying design and support problems associated with existing systems, design features required for implementation of an appropriate Design-for-Repair Concept or Concepts were then identified. This technical report includes the approach taken and the rationale on which Design-for-Repair Concepts were selected. The work conducted under this effort and the selected Design-for-Repair Concepts will formulate the baseline for the following phase of the effort, Design-for-Repair Methodology Guideline Development. This Phase II effort will provide the design engineer with methodologies and guidelines for designing repairability and maintainability into avionic equipment during the early design phases. The Air Force Program Monitor was Lt. Don L. Lowdermilk, System Evaluation Group, Avionic Systems Engineering Branch (AFAL/AAA-3).

PREFACE

The Design-For-Repair Concept Definition technical report is prepared in three separately bound books. Supportive analyses details for the technical report are contained in the appendices.

Volume I - Technical Report

Volume II - Detailed Analyses

Volume III - Field Evaluation Reports

ACCESSION for	
NTIS	White Section <input checked="" type="checkbox"/>
DDC	Buff Section <input type="checkbox"/>
UNANNOUNCED	<input type="checkbox"/>
JUSTIFICATION _____	
BY _____	
DISTRIBUTION/AVAILABILITY CODES	
Dist.	AVAIL and/or SPECIAL
A	

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
I MAINTAINABILITY ANALYSIS	1
AN/APG-63 Radar	2
AN/AWG-20 Armament Control System	8
AN/ARC-109 Radio	13
Mark V TACAN Navigation Set	17
Target Identification System Electro-Optical	22
Direct Radar Scope Recording System	26
AN/APQ-130 Attack Radar	30
Strike Camera	40
II RELIABILITY ANALYSIS	44
AN/APG-63 Radar	45
AN/AWG-20 Armament Control System	51
AN/ARC-109 Radio	53
Mark V TACAN Navigation Set	55
Target Identification System Electro-Optical	57
Direct Radar Scope Recording System	61
AN/APQ-130 Attack Radar	64
Strike Camera	70
III EQUIPMENT ANALYSIS	72
F-4E Radar Scope Camera System	73
F-4E Target Identification Electro-Optical	76
F-111D Strike Camera	79
F-111D AN/APQ-130 Attack Radar	82
C-5A AN/ARC-109 Radio	88
C-5A Mark V TACAN	90
F-15 AN/APQ-63 Radar	93
F-15 AN/AWG-20 Armament Control System	99
F-16 AN/ARC-164 Radio	103
F-16 AN/ARN-118 TACAN	105
IV SUBSYSTEM CATEGORY/EQUIPMENT ANALYSIS	107
Communications Equipment	108
Navigation Equipment	114
Reconnaissance Equipment	121
Weapons Delivery Equipment	128
Weapons Control Equipment	132

<u>SECTION</u>		<u>PAGE</u>
V	MAINTENANCE ITEM AREA TREND ANALYSIS	143
	Accessibility	144
	Age of System and Technology	147
	Debriefing	152
	Depot Support	157
	Flight Inspections (Pre-, In-, Post-)	160
	Level of Base Repair	163
	Maintainability Characteristics of Equipment Design	168
	Maintenance Data Collection, Documentation and Feedback System	173
	Maintenance Organization	178
	Organizational Level AGE	182
	Preventive Maintenance	187
	Technical Manuals	190
	Training and Personnel Skill Levels	193
	Troubleshooting Methods	198
VI	MAINTENANCE ITEM AREA TRENDS	203
	Accessibility	204
	Age of System and Technology	206
	Debriefing	208
	Depot Support	209
	Flight Inspections (Pre-, In-, Post-)	210
	Level of Base Repair	212
	Maintainability Characteristics of Equipment Design	214
	Maintenance Data Collection, Documentation and Feedback System	218
	Maintenance Organization	220
	Organizational Level AGE	222
	Preventive Maintenance	224
	Technical Manuals	225
	Training and Personnel Skill Levels	226
	Troubleshooting Methods	227
VII	DESIGN FEATURES AND TECHNIQUES DEFINITION	229
	Communications Equipment	230
	Navigation Equipment	233
	Reconnaissance Equipment	236
	Weapons Delivery Equipment	239
	Weapons Control Equipment	241
	Support System	247
VIII	DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION	257
	Communications Equipment	258
	Navigation Equipment	260
	Reconnaissance Equipment	263
	Weapons Delivery Equipment	265
	Weapons Control Equipment	268
	Support System	274

SECTION I
MAINTAINABILITY ANALYSIS

F15 RADAR (APG-63)

LOCATION! SUMMARY
LIGHT HOURS: 72289.0

TYPE: FRAMED LAND
F-5 RADAR (APG-63)
ORGANIZATIONAL SUMMARY

卷之三

LOCATIONS SUMMARY 72289,0

115

SUCCESS RATE (% OF SORTIES)	5.3
MEAN TIME BETWEEN DEMANDS	11.4
SORTY SUCCESS RATE (%)	89.4

WNCOP = 5673.0

LOCATION SUMMARY
FLIGHT HOURS: 72289.0

F15 RADAR (APP-63)
INTERMEDIATE LEVEL
LRU MAINTAINABILITY SUMMARY

01/11/79

LRU	WUC	END OF MONTH			TIME FRAME INVENTORY	82	SORTIES:	53274
		NUMBER OF ARRIVALS	MEAN TIME BETWEEN ARRIVALS	PERCENT NO FAULTS				
1	74FJ0	269	246.7	22	8.2	107.8	107.8	92.6
1	74FC4	265	24.7	16.6	22.8	14.8	14.8	12.1
1	74FC0	575	125.7	80	1.5	50.3	146.6	146.6
1	74FJ0	590	125.5	80	1.5	50.3	146.6	146.6
1	74FJ0	617	125.5	80	1.5	50.3	146.6	146.6
1	74FJ0	464	18.5	10.0	2.6	1.0	2.6	2.6
1	74FJ0	969	172.4	21.5	1.6	9.9	172.4	172.4
1	74FJ0	442	104.0	22.0	3.5	7.5	104.0	104.0
1	74FM0	649	104.0	22.0	3.5	11.4	46.0	69
	5074				14.2	116.5	16.3	53.8
						11.9	1041	9215.2

NRTS RATE (%) ----- 20.5
 MEAN TIME BETWEEN REPAIR (MTBR) --- 19.3
 MEAN TURN AROUND TIME (MTAT) ----- 51.2
 CONFIRMED FAILURES PER FLIGHT---- 0.070

X NRTS2 = 165.0

FIS RADAR (APG-65)
SRU INTERMEDIATE LEVEL SUMMARY

LOCATION! SUMMARY
REGISTRATION NUMBER: 72289.0

F15 RADAR (APG-63)
INTERMEDIATE LEVEL
SRU MAINTAINABILITY SUMMARY
TIME PERIOD: 1600
END OF MONTH AIRCRAFT INVENTORY: 82

The figure consists of three vertically stacked dot plots sharing a common x-axis labeled "NUMBER OF FAULTS".

- Top Plot:** Y-axis is "NUMBER OF REPAIRS". The data points show a general upward trend as the number of faults increases.
- Middle Plot:** Y-axis is "MEAN TURNAROUND TIME". The data points are clustered around two values: approximately 2.4 for lower fault counts and approximately 7.2 for higher fault counts.
- Bottom Plot:** Y-axis is "MEAN TIME TO BEHIND SCHEDULE". The data points are clustered around two values: approximately 0.6 for lower fault counts and approximately 7.2 for higher fault counts.

END OF MONTH AIRCRAFT INVENTORY: 18 NOVEMBER 1982

Detailed description: This is a scatter plot with 'NUMBER OF REPAIRS' on the x-axis and 'MEAN TURN AROUND TIME (HOURS)' on the y-axis. The x-axis has major tick marks at 0, 200, 400, 600, 800, and 1000. The y-axis has major tick marks at 0, 2, 4, 6, and 8. There are 12 data points plotted as open circles. A dashed horizontal line is drawn at y ≈ 2. A solid horizontal line is drawn at y ≈ 7. Two vertical lines are drawn at x = 72 and x = 240.

Number of Repairs (X)	Mean Turn Around Time (Hours) (Y)
0	0.5
100	0.5
200	0.5
300	0.5
400	0.5
500	0.5
600	0.5
700	0.5
800	0.5
900	0.5
1000	0.5
1000	1.0

SORTIES: 53274

01/11/79

SHOP
MAINTENANCE

— 1 —

EAN
URN
OUND

NUMBER
NRTS

MEAN
TIME
TO

MEAN
TURN
AROUND

ANSWER

NUMBER
SHOP
REPAIRS

ooooooooooooooo-ooooooooooooooo-ooooooooooooooo-ooooooooooooooo

MEAN
TURN
AROUND

FAULT

NUMBER
SHOP
NO FAUL.

oooooooooooooooooooooooooooooooooooo

EAN
EN

NUMBER
OF
SHP

NUMBER

8 8-1 88 8 8888 8888

PART

LRU

— 1000000 — 000000 — 000000 — 000000 — 000000 — 000000 — 000000 —

01/11/79

NUMBER OF PARTS	LAR	MUC	PART NUMBER
0000	00	00	0000 00 00
1	1	1	1111 1111 1111
2	2	2	2222 2222 2222
3	3	3	3333 3333 3333
4	4	4	4444 4444 4444
5	5	5	5555 5555 5555
6	6	6	6666 6666 6666
7	7	7	7777 7777 7777
8	8	8	8888 8888 8888
9	9	9	9999 9999 9999
10	10	10	1010 1010 1010
11	11	11	1111 1111 1111
12	12	12	1212 1212 1212
13	13	13	1313 1313 1313
14	14	14	1414 1414 1414
15	15	15	1515 1515 1515
16	16	16	1616 1616 1616
17	17	17	1717 1717 1717
18	18	18	1818 1818 1818
19	19	19	1919 1919 1919
20	20	20	2020 2020 2020
21	21	21	2121 2121 2121
22	22	22	2222 2222 2222
23	23	23	2323 2323 2323
24	24	24	2424 2424 2424
25	25	25	2525 2525 2525
26	26	26	2626 2626 2626
27	27	27	2727 2727 2727
28	28	28	2828 2828 2828
29	29	29	2929 2929 2929
30	30	30	3030 3030 3030
31	31	31	3131 3131 3131
32	32	32	3232 3232 3232
33	33	33	3333 3333 3333
34	34	34	3434 3434 3434
35	35	35	3535 3535 3535
36	36	36	3636 3636 3636
37	37	37	3737 3737 3737
38	38	38	3838 3838 3838
39	39	39	3939 3939 3939
40	40	40	4040 4040 4040
41	41	41	4141 4141 4141
42	42	42	4242 4242 4242
43	43	43	4343 4343 4343
44	44	44	4444 4444 4444
45	45	45	4545 4545 4545
46	46	46	4646 4646 4646
47	47	47	4747 4747 4747
48	48	48	4848 4848 4848
49	49	49	4949 4949 4949
50	50	50	5050 5050 5050
51	51	51	5151 5151 5151
52	52	52	5252 5252 5252
53	53	53	5353 5353 5353
54	54	54	5454 5454 5454
55	55	55	5555 5555 5555
56	56	56	5656 5656 5656
57	57	57	5757 5757 5757
58	58	58	5858 5858 5858
59	59	59	5959 5959 5959
60	60	60	6060 6060 6060
61	61	61	6161 6161 6161
62	62	62	6262 6262 6262
63	63	63	6363 6363 6363
64	64	64	6464 6464 6464
65	65	65	6565 6565 6565
66	66	66	6666 6666 6666
67	67	67	6767 6767 6767
68	68	68	6868 6868 6868
69	69	69	6969 6969 6969
70	70	70	7070 7070 7070
71	71	71	7171 7171 7171
72	72	72	7272 7272 7272
73	73	73	7373 7373 7373
74	74	74	7474 7474 7474
75	75	75	7575 7575 7575
76	76	76	7676 7676 7676
77	77	77	7777 7777 7777
78	78	78	7878 7878 7878
79	79	79	7979 7979 7979
80	80	80	8080 8080 8080
81	81	81	8181 8181 8181
82	82	82	8282 8282 8282
83	83	83	8383 8383 8383
84	84	84	8484 8484 8484
85	85	85	8585 8585 8585
86	86	86	8686 8686 8686
87	87	87	8787 8787 8787
88	88	88	8888 8888 8888
89	89	89	8989 8989 8989
90	90	90	9090 9090 9090
91	91	91	9191 9191 9191
92	92	92	9292 9292 9292
93	93	93	9393 9393 9393
94	94	94	9494 9494 9494
95	95	95	9595 9595 9595
96	96	96	9696 9696 9696
97	97	97	9797 9797 9797
98	98	98	9898 9898 9898
99	99	99	9999 9999 9999
100	100	100	100100 100100 100100

LRU	MUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT	MEAN TURN AROUND TIME	NUMBER SHOP REPAIRS	MEAN TURN AROUND TIME	NUMBER NRTS	MEAN TURN AROUND TIME	SHOP MAINTENANCE HOURS
610	74FHG	3271950-15	104	995.1	0	0.0	1	0.5	103	(0.449)	85.3
610	74FHG	3271950-20	100	722.9	0	0.0	0	0.0	100	26.6	97.0
610	74FHG	3387026-2	44	1642.9	0	0.0	0	0.0	44	10.4	37.4
610	74FHG	3173856-100	1	7286.9	0	0.0	1	0.5	0	0.0	7.3
868			3584	20.2	5	11.4	13	386.2	6.7	3566	53.4
											3656.2

NRTS RATE (%) = 99.5
 MEAN TIME BETWEEN REPAIR (MTBR) = 20.2

X NRTS2 = 1.0

**AN/AWG-20 ARMAMENT CONTROL SYSTEM
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY**

03/08/79

LOCATION: SUMMARY
FLIGHT HOURS: 58119.0

**TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY!**

8081168143401

LRU	FLIGHT	MEAN TIME LINE BETWEEN MAINT	NUMBER CND AS MAINT ACTIONS (FM)	CND AS % OF MAINT ACTIONS	MEAN MAINT TIME CND MAINT (HRS)	NUMBER CANNIB ACTIONS	MEAN MAINT TIME CND MAINT (HRS)	CANN AS % OF LINE MAINT	MEAN REPAIR TIME (DEMAND) CND ACTIONS (HRS)	NUMBER REMOVAL TIME CND ACTIONS (HRS)	MEAN MAINT TIME (DEMAND) CND ACTIONS (HRS)	NUMBER OTHER ACTIONS REMOVAL (HRS)	MEAN MAINT TIME CND ACTIONS (HRS)	NUMBER MAINT TIME CND ACTIONS (HRS)	MEAN MAINT TIME CND ACTIONS (HRS)	NUMBER MAINT TIME CND ACTIONS (HRS)	MEAN MAINT TIME CND ACTIONS (HRS)
10	532	109.2	4	0.6	4.6	135	25.4	5.5	38	2.3	224	3.5	296	4.1	2860.9		
20	3	1932.9	0	0.0	0.0	1	33.3	1.0	0	0.0	1	6.0	2	2.2		11.5	
30	821	70.8	2	0.2	12.9	374	45.6	4.4	10	2.9	365	2.7	412	3.0	4262.4		
40	7	8302.7	1	14.3	3.5	0	0.0	0.0	0	0.0	0	0.0	5	3.8		22.3	
60	2	29059.4	0	0.0	0.0	1	50.0	1.0	0	0.0	0	0.0	1	4.5		9.5	
120	1	58118.4	0	0.0	0.0	0	0.0	0.0	0	0.0	0	0.0	0	0.0		1.0	
999	721	80.6	45	6.2	4.5	1	0.3	1.5	14	11.2	7	5.2	704	5.6	4326.0		
2067	27.6	52	2.5	4.8	513	24.6	4.7	62	4.4	597	3.1	1420	4.7	11419.6			

CND RATE (% OF GROWTH).....0.1

MEAN TIME BETWEEN DEMANDS 07.4

SUBSYNTHETIC RATE (%)
99.9

WNCOP 8 450

AN/AWG-20 ARMAMENT CONTROL SYSTEM
 INTERMEDIATE LEVEL
 LRU MAINTAINABILITY SUMMARY

03/08/79

LOCATION: SUMMARY
 FLIGHT HOURS: 58119.0

END OF MONTH AIRCRAFT INVENTORY: 74

TIME FRAME: SUM

LRU	WUC	NUMBER	MEAN TIME IF SHIP	PERCENT OF FAULTS	MEAN TURN AROUND	MEAN TURN AROUND	MEAN TURN AROUND	MEAN TURN AROUND	MEAN TURN AROUND
			ARRIVALS	NO FAULT ARRIVALS	(DAYS)	(DAYS)	(DAYS)	(DAYS)	(DAYS)
10 175MA01	261	222.7	79	30.3	33.7	153	148.8	6.4	85
30 175MC01	277	219.8	51	18.4	109.8	235	103.3	6.2	79
40 175MD01	1	58118.9	0	0.0	0.0	0	0.0	0.0	0.0
80 175ML01	1	58118.9	0	0.0	0.0	0	0.0	0.0	0.0
999 175MH01	1	58118.9	0	0.0	0.0	1	1059.0	6.0	0.0
									8.0
541		117.4	130	24.0	63.5	369	123.7	7.5	164
									154.1
									7986.1

NRTS RATE (%): 30.3

MEAN TIME BETWEEN REPAIR (MTRR): 149.4

MEAN TURN AROUND TIME (MTAT): 108.6

CONFIRMED FAILURES PER FLIGHT: 0.009

MRRTS2 = 22.0

AN/AWG-20 ARMAMENT CONTROL SYSTEM
INTERMEDIATE LEVEL
SRU MAINTAINABILITY SUMMARY

03/08/79

LOCATION: SUMMARY
FLIGHT HOURS: 58119.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 74

SORTIES: 43401

LAU	MUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT	MEAN TURN AROUND TIME	NUMBER SHOP REPAIRS	MEAN TIME TO REPAIR (HRS)	NUMBER NRHS											
									MAIN	MAINTENANCE	TURN	AROUND	TIME	MAIN	MAINTENANCE	TURN	AROUND	TIME	MAIN	MAINTENANCE
10	175MAC	11078-12	2	29059.5	0	0.0	0	2	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MANI	11078-13	0	0.0	1	0.5	1	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAA	30612-1	1	14529.7	0	0.0	1	14529.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAE	30676-1	4	14529.7	1	14529.7	1	14529.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MDI	30688-1	3	19373.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAI	30688-1	1	58118.9	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MDI	30688-1	1	58118.9	1	0.5	1	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAC	30688-1	4	14529.7	0	0.0	1	14529.7	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAF	31184-1	3	19373.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAG	31222-1	3	19373.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAG	31256-1	10	58118.9	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAG	31256-1	3	19373.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAG	31260-1	2	29059.5	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAD	31310-1	1	58118.9	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	175MAG	31376-1	3	19373.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCD	11077-15	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MMH	11077-20	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MDI	11078-10	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCR	30486-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCQ	30488-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCT	30568-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCN	30584-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCE	30790-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCT	30862-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCB	30866-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MC2	30928-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MC3	30930-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCE	30966-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MC2	30976-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MC2	30976-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCL	30978-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MXX	31058-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCJ	31062-1	0	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MMH	31068-1	61	58118.9	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCS	31070-1	15	58118.9	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCJ	31070-1	1	58118.9	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
30	175MCG	31072-1	2	29059.5	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0

03/08/70

LRU	WUC	PART NUMBER	NUMBER OF DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER OF SHOP DEMANDS	MEAN TIME IN SHOP	NUMBER OF NO FAULT	MEAN TURN AROUND TIME	NUMBER OF NRTS	MEAN TURN AROUND TIME	SHOP MAINTENANCE HOURS	MEAN TIME IN SHOP
30	175MCB	311A001	1	58118.9	0	0.0	0	0.0	1	60.0	0.5	0.0
30	175C4	31132e1	1	58118.9	0	0.0	0	0.0	1	60.0	1.6	0.0
30	175MCH	311421e1	1	58118.9	0	0.0	0	0.0	1	31.0	0.5	0.0
30	175MCW	31156e1	3	19373.0	2	42.5	0	0.0	1	43.0	7.6	0.0
30	175MCF	31172e1	1	58118.9	0	0.0	0	0.0	1	40.0	2.0	0.0
30	175MC4	31174e1	1	58118.9	0	0.0	0	0.0	1	40.0	0.6	0.0
30	175C4	31176e1	4	14529.7	1	12.0	1	0.2	1	10.0	3.5	0.0
30	175MC8	31180e1	1	58118.9	1	10.0	0	0.0	1	10.0	1.0	0.0
30	175CRI	31180e1	1	58118.9	0	0.0	0	0.0	1	10.0	0.7	0.0
30	175MC8	31180e1	7	58102.7	62.0	28.0	1	1.2	1	5.0	3.6	0.0
30	175ICE	31182e1	4	14529.7	0	0.0	3	42.5	1	1.1	0.5	0.0
30	175CKI	31184e1	16	3632.4	0	0.0	12	650.5	4	1.4	212.7	11.0
30	175C8	31216e1	1	58118.9	0	0.0	10	0	1	60.0	12.0	0.0
30	175C7	31224e1	2	29059.5	0	0.0	12	561.0	0	0	1.7	0.7
30	175MCH	31226e1	5	11623.6	0	0.0	1	97.0	1	1.3	133.7	4.8
30	175MCU	31228e1	4	14529.7	0	0.0	1	102.0	1	1.3	12.7	4.6
30	175C8	31230e1	21	2767.6	10	557.7	2	1.2	1	5.0	250.2	14.5
30	175MCU	31232e1	1	58110.9	0	0.0	10	103.5	1	1.0	45.0	0.5
30	175C8F	31264e1	2	29059.5	0	0.0	12	561.0	0	0	2.7	0.7
30	175MC3	31266e1	1	58118.9	0	0.0	1	62.0	0	0	0.7	0.0
30	175MCH	31266e1	1	58118.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175C3	31266e1	2	29059.5	0	0.0	1	62.0	0	0	0.5	0.0
30	175MCH	31268e1	1	58118.9	0	0.0	1	60.0	0	0	0.7	0.0
30	175NEA	31270e1	6	9686.5	602.5	602.5	0	0.0	1	196.2	3.2	0.0
30	175MCL	31272e1	7	8302.7	572.5	576.0	0	0.0	1	263.0	2.6	0.0
30	175MC4	31272e1	1	58118.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175MCH	31274e1	2	29059.5	0	0.0	1	62.0	0	0	0.5	0.0
30	175MC6	31276e1	2	29059.5	0	0.0	1	62.0	0	0	0.5	0.0
30	175MC8	31282e1	1	58118.9	0	0.0	1	60.0	0	0	0.7	0.0
30	175C8	31282e1	3	19373.0	600.0	600.0	1	100.0	5	10.0	196.2	2.3
30	175MCU	31288e1	1	58118.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175MCC	31296e1	11	5283.5	0	0.0	1	377.6	1	1.1	223.5	1.5
30	175MC7	31304e1	2	29059.5	0	0.0	1	79.0	0	0	1.6	0.7
30	175C8P	31306e1	10	58111.9	405.3	405.3	1	1.7	1	1.7	105.0	5.4
30	175MCX	31310e1	5	11623.6	0	0.0	1	97.0	1	1.2	140.0	4.7
30	175MCL	31316e1	3	19373.0	0	0.0	1	96.0	0	0	1.7	0.7
30	175MD	31336e1	1	58110.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175MCV	31338e1	6	9686.5	56110.9	56110.9	1	1.1	1	1.4	60.7	4.0
30	175MCX	31338e1	1	58110.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175MK	31396e1	11	5283.5	0	0.0	1	227.6	0	0	1.6	0.7
30	175MC7	31400e1	6	7264.9	914.0	914.0	0	0.0	1	1.2	106.0	5.2
30	175C8	31400e1	2	29059.5	0	0.0	1	62.0	0	0	0.5	0.0
30	175C8P	31506e1	1	58110.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175MEI	31516e1	1	58110.9	0	0.0	1	62.0	0	0	0.5	0.0
30	175MC7	31556e1	6	7264.9	63.7	63.7	0	0.0	1	1.2	6.0	0.7

03/08/79

LRU	MUC	PART NUMBER	NUMBER OF DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER SHOP DEMANDS	MEAN TIME TO NO FAULT	NUMBER SHOP REPAIRS	MEAN TIME TO REPAIR	NUMBER NRTS	MEAN TURN AROUND TIME	MEAN TURN TIME	MEAN TIME TO REPAIR (HRS)	NUMBER MAIN HOURS	MEAN TURN AROUND TIME (DAYS)	SHOP MAINTENANCE MAN HOURS	
30	175MCC	31696-1	7	4302.7	0	0.0	0	0.0	7	205.0	0.0	6.3	62.0	1.0	1.0	1.0
30	175MCH	31700-1	1	58116.9	1	0.0	0	0.0	1	56.0	0.0	1.0	62.0	1.0	1.0	1.0
30	175MCC	31734-1	1	58116.9	1	0.0	0	0.0	1	56.0	0.0	1.0	62.0	1.0	1.0	1.0
30	175MCA	31744-1	1	58116.9	1	0.0	0	0.0	1	56.0	0.0	1.0	62.0	1.0	1.0	1.0
40	175MDP	11077-13	1	58116.9	1	0.0	0	0.0	1	56.0	0.0	1.0	62.0	1.0	1.0	1.0
40	175MDP	13170-1	1	58116.9	1	0.0	0	0.0	1	56.0	0.0	1.0	62.0	1.0	1.0	1.0
40	175MDP	130962-1	2	29059.5	0	0.0	0	0.0	1	191.0	0.0	0.7	22.0	2.0	2.0	2.0
40	175MDP	130986-1	5	11623.6	0	0.0	0	0.0	3	116.7	0.0	0.7	16.7	1.0	1.0	1.0
40	175MDP	31104-1	4	14529.7	0	0.0	0	0.0	4	12.7	0.0	0.5	10.0	0.5	0.5	0.5
40	175MDP	31140-1	1	58116.9	1	0.0	0	0.0	1	56.0	0.0	1.0	62.0	1.0	1.0	1.0
40	175MDL	31190-1	4	14529.7	0	0.0	0	0.0	3	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDF	31214-1	3	19373.0	0	0.0	0	0.0	3	106.3	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDJ	31218-1	1	58116.9	1	0.0	0	0.0	1	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDC	31220-1	3	19373.0	0	0.0	0	0.0	2	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDL	31260-1C	1	58116.9	1	0.0	0	0.0	1	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDF	31280-1	4	14529.7	0	0.0	0	0.0	3	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDW	31286-1	2	29059.5	0	0.0	0	0.0	2	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDL	31288-1	17	3418.6	57.7	0.0	0	0.0	1	950.5	0.0	0.7	17.2	1.0	1.0	1.0
40	175MDC	31289-1	1	58116.9	1	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
40	175MDL	31290-1	3	19373.0	0	0.0	0	0.0	2	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDL	31296-1	2	29059.5	0	0.0	0	0.0	2	12.5	0.0	0.5	12.0	0.5	0.5	0.5
40	175MDO	31300-1	6	9666.5	0	0.0	0	0.0	6	47.2	0.0	0.5	45.1	1.0	1.0	1.0
40	175MDP	31302-1	19	3058.9	2	0.0	0	0.0	8	67.5	0.0	0.5	65.3	1.0	1.0	1.0
40	175MDJ	31328-1	1.1	5283.5	64.0	0.0	0	0.0	2	167.0	0.0	0.5	14.0	1.0	1.0	1.0
40	175MDV	31344-1	1	58116.9	1	0.0	0	0.0	1	107.0	0.0	0.7	10.0	0.5	0.5	0.5
40	175MDC	31396-1	3	19373.0	0	0.0	0	0.0	3	12.5	0.0	0.5	12.0	0.5	0.5	0.5
40	175MDL	31670-1	19	3058.9	5	0.0	0	0.0	4	64.2	0.0	0.5	62.0	0.5	0.5	0.5
40	175MDF	31694-1	1	58116.9	1	0.0	0	0.0	0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
40	175MDL	31677-1	3	19373.0	0	0.0	0	0.0	1	12.0	0.0	0.5	11.0	0.5	0.5	0.5
40	175MDK	81641-1	2	29059.5	120.0	0.0	0	0.0	2	626.5	0.0	0.5	53.7	1.0	1.0	1.0
999	17544XX	31310-1	1	58116.9	0	0.0	0	0.0	1	21.0	0.0	0.5	21.0	0.5	0.5	0.5
			463	125.5	46	288.2	114	424.1	301	301	0.9	0.0	0.0	0.0	0.0	0.0

NRTS RATE (%) 65.0
 MEAN TIME BETWEEN REPAIR (MTBR) = 140.0

XNRT92 = 0.0

AN/ARC-109 RADIO SET
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY

03/09/19

LITERATURE REVIEW

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 87
SOURCES: 9465

END RATE (% OF SITE 3) -----

MEAN TIME BETWEEN DISEASES = 6.01

ECONOMIC SURVEY OF THE USSR (1981)

1100

THIS PAGE IS BEST QUALITY PRINTING TO EDD THIS PAGE IS BEST QUALITY PRINTING TO EDD

AN/ARC-109 RADIO SET

**INTERMEDIATE LEVEL
LRI MAINTAINABILITY SUMMARY**

03/09/79

**LOCATION: SUMMARY
FLIGHT HOURS: 84866.0**

**TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 27**

SORTIES: 9465

LRI	MUC	NUMBER OF SHOP ARRIVALS	MEAN TIME BETWEEN ARRIVALS	NUMBER NO FAULTS	PERCENT NO FAULT	MEAN TURN AROUND TIME (DAYS)	MEAN REPAIR TIME (DAYS)	MEAN TURN AROUND TO REPAIR (HRS)	MEAN NUMBER NRTS	MEAN TURN AROUND NRTS (DAYS)	MEAN SHOP REPAIRS	MEAN NUMBER NRTS	MEAN TURN AROUND NRTS (DAYS)	MEAN SHOP REPAIRS
10	163AA0	442	101.5	7	1.6	1.1	390	16.0	51	169.5	4946.4			
20	163AB0	6	747.3	0	0.0	0.0	0	7.0	1	0.5	84.5			
999	163A00	2	22423.0	0	0.0	0.0	1	9.0	0	0.0	13.0			
		450	99.7	7	1.6	1.1	397	19.1	52	166.2	5043.9			

NRTS RATE (%): 11.6

MEAN TIME BETWEEN REPAIR (MTBR): 101.2

MEAN TURN AROUND TIME (MTAT): 18.6

CONFIRMED FAILURES PER FLIGHT: 0.047

XNRT92 = 0.0

AN/ARC-109 RADIO SET
INTERMEDIATE LEVEL
Semi-Maintainability Summary

LOCATIONS SUMMARY
FLIGHT HOURS: 4846.0

END OF MONTH AIRCRAFT INVENTORY: 27

TIME FRAME: Sum

03/09/79

LRU	MUC	PART NUMBER	NUMBER SHIP DEMANDS	MEAN TIME BETWEEN FAULTS	MEAN TURNAROUND TIME	NUMBER OF FAULTS	MEAN TURNAROUND TIME	MEAN TIME TO REPAIR (HRS)	NUMBER WORKS	MEAN TURNAROUND TIME	MEAN MAINTENANCE MAN HOURS
10	63AAF133592-1		1	40446-3	1	10.0	0.0	0.0	0	0.0	0.0
10	63AAE14000008-101B		1	40446-0	0	0.0	1	2.0	0	0.0	4.0
10	63AAE14000008-101A		0	40446-0	0	0.0	0	0.0	0	0.0	0.0
10	63AAB15280629-001		0	40446-0	0	0.0	0	0.0	0	0.0	0.0
10	63AAD1524966-001		1	40446-0	0	0.0	0	0.0	1	1.0	1.0
10	63AAQ152806298-001		1	40446-0	0	0.0	0	0.0	1	59.0	1.0
10	63AAE152806328-001		1	40446-0	0	0.0	0	0.0	1	10.0	2.0
10	63AAG152806304-001		1	40446-0	0	0.0	0	0.0	1	3.0	2.0
10	63AAE152880676-001		1	40446-0	0	0.0	0	0.0	1	4.0	2.0
10	63AAE152806229-001		1	40446-0	0	0.0	0	0.0	1	2.0	2.0
10	63AAH15280625-001		0	40446-0	0	0.0	1	6.0	0	0.0	7.0
10	63AAE15280625-001		0	40446-0	0	0.0	0	0.0	0	0.0	0.0
10	63AAE15280628-001		3	14948-7	0	0.0	3	254.0	0	0.0	33.0
10	63AAE15280628-001		1	40446-0	0	0.0	0	0.0	1	1.0	1.0
10	63AAE15280628-001		0	40446-0	0	0.0	0	0.0	0	0.0	0.0
10	63AAE15280629-001		6	7474-3	0	0.0	4	22.7	4	4.4	26.2
10	63AAE15280629-001		14	7203-3	0	0.0	13	25.0	5	3	120.0
10	63AAE15280629-001		1	40446-0	0	0.0	0	0.0	1	105.0	1.0
10	63AAE15280629-001		1	40446-0	0	0.0	0	0.0	1	72.0	0.0
10	63AAE15280629-001		26	9724-8	0	0.0	21	44.0	0	0.0	1.5
10	63AAC15280630-001		22	2058-5	0	0.0	22	13.0	5	7	307.9
10	63AAE15280630-001		1	40446-0	0	0.0	1	10.0	0	0.0	1.0
10	63AAD15280631-001		1	40446-0	0	0.0	1	24.0	3	5	18.0
10	63AAE15280632-001		1	40446-0	0	0.0	0	0.0	0	0.0	0.0
10	63AAE15280633-001		1	40446-0	0	0.0	1	26.0	6	7	2.0
10	63AAE15280633-001		1	40446-0	0	0.0	1	26.0	0	0.0	2.0
10	63AAE15280634-001		9	4042-9	0	0.0	1	17.0	0	0.0	22.7
10	63AAH15280635-001		6	7074-3	0	0.0	6	9.7	0	0.0	6.0
10	63AAJ15280635-001		1	40446-0	0	0.0	0	0.0	1	1.0	0.5
10	63AAA15280635-001		3	14948-7	0	0.0	3	38.3	0	0.0	55.3
10	63AAJ15280636-001		12	3737-2	1	0.0	0	0.0	1	7.0	10.3
10	63AAH15280636-001		0	40446-0	0	0.0	1	0.0	0	0.0	0.0
10	63AAJ15280636-001		41	1493-8	0	0.0	1	10.0	4	0	21.2
10	63AAK15280637-001		1	40446-0	0	0.0	1	28.0	6	0	6.0
10	63AAA15280638-001		1	40446-0	0	0.0	1	15.0	4	0	8.0
10	63AAC15280638-001		2	22423-1	0	0.0	0	0.0	2	0.5	1.0
10	63AAE15280676-001		12	1737-2	0	0.0	0	0.0	12	2.5	14.2
10	63AAH15280676-001		0	40446-0	0	0.0	0	0.0	0	0.0	0.0
10	63AAE15280676-001		1	40446-0	0	0.0	1	0.0	1	0.0	0.0
10	63AAE152806929-001		0	40446-0	0	0.0	0	0.0	1	2.0	3.5
10	63AAD152806926-001		3	14948-7	0	0.0	0	0.0	0	0.0	0.0
10	63AAE15280710-001		5	A069-2	0	0.0	0	0.0	4	0.0	61.4
											11.2

THIS PAGE IS BASED ON QUALITY PLANNING
FROM COPY PERTAINING TO DNG

03/09/19

MEAN TIME BETWEEN REPAIR (MTBR)=151.5
UNITS RATE (%)-----41.1

MARK V NAVIGATION SET
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY

03/09/79

LOCATION SUMMARY
FLIGHT HOURS: 44440.0

TIME FRAME: SUM
END OF MINTH AIRCRAFT INVENTORY: 27

LRU	FLIGHT	MEAN TIME BETWEEN MAINT	NUMBER OF MAINT (FH)	CND AS ARTNS	MEAN TIME LINE	NUMBER OF CANN	CANN AS CND	MEAN TIME LINE	NUMBER OF CANN	MEAN TIME LINE											
10	1177	36.1	22	1.9	51	4.3	2.5	311	2.0	745	2.0	593	2.0	3530.4	2.0	2.0	2.0	2.0	2.0	2.0	
20	1	44845.6	0	0.0	0	0.0	0	0.0	0	0.0	0	0	0	1	2.2	2.2	2.2	2.2	2.2	2.2	
30	360	124.6	1	0.3	1.2	6	1.7	2.1	2.1	2.6	1.6	1.6	1.6	1.17	2.1	2.1	2.1	2.1	2.1	2.1	
40	2	22422.9	0	0.0	0.0	0	0.0	0.0	0	0.0	0	0	0	0.0	2	2.0	2.0	2.0	2.0	2.0	
999	1	501	89.5	158	31.5	1.9	2	0.4	0.4	0.4	1	2.0	5	2.1	357	2.6	1254.7	2.6	1254.7	2.6	
		2041	22.0	181	A.9	1.8	59	2.9	2.9	528	2.4	916	2.3	1070	1.9	1070	2.2	5853.6	2.2	5853.6	2.2

CND RATE (% OF SURTIES)-----1.9

MEAN TIME BETWEEN DEMANDS-----47.9

SURTY SUCCESS RATE (%)-----75.8

MMCDP ■ 2266.0

THIS PAGE IS FEST QUALITY PRACTICALLY
FROM COPY PUBLISHED TO LOG

MARK V NAVIGATION SET
INTERMEDIATE LEVEL
LRU MAINTAINABILITY SUMMARY

03/09/79

LOCATIONS SUMMARY
FLIGHT HOURS: 44646.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 27

SORTIES: 9465

LRU	MUC	NUMBER OF SHOP ARRIVALS	MEAN TIME BETWEEN ARRIVALS	NUMBER OF NO FAULT ARRIVALS	PERCENT OF NO FAULT ARRIVALS	MEAN TURN AROUND TIME (DAYS)	NUMBER SHOP REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER TU REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER NRTS	MEAN TURN AROUND TIME (DAYS)	MEAN TURN AROUND TIME (DAYS)	SHOP MAINTENANCE HOURS
10 171A01	643	19.7	56	6.7	11.9	4.9	507	11.1	5.6	11.1	146	15.4	15.4	5326.3

NRTS RATE (%): 22.7

MEAN TIME BETWEEN REPAIR (MTBR): 76.4

MEAN TURN AROUND TIME (MTAT): 10.5

CONFIRMED FAILURES PER FLIGHT: 0.062

XNRTS2 = 0.0

MARK V NAVIGATION SET
INTERMEDIATE LEVEL
SRU MAINTAINABILITY SUMMARY

03/09/79

LOCATION 1 SUMMARY
FLIGHT HOURS: 44846.0

SRU	WUC	PART NUMBER	TIME FRAME: SUM			TIME FRAME: SUM			TIME FRAME: SUM		
			END 11F MONTH AIRCRAFT INVENTORY: 27			SHUTTLES: 9465			SHUTTLES: 9465		
			NUMBER OF SHOPS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT	NUMBER SHIPS	MEAN TURN AROUND TIME	MEAN TIME TO REPAIR (DAYS)	NUMBER NRTS	MEAN TURN AROUND TIME	MEAN TIME TO REPAIR (DAYS)
10	171LAM13020000358=2	1	44846.0	0	0	0	0.0	0.0	1	1.0	0.5
10	171LAE1JK11003	1	44846.0	0	0	0	1.0	2.0	0	0.0	2.0
10	171LA91K12000=1014	1	44846.0	0	0	0	3.0	7.0	0	0.0	7.0
10	171LA14K90016=1018	1	44846.0	0	0	0	1.0	0.2	0	0.0	0.3
10	171LAH4K90016=1018	1	44846.0	0	0	0	0.0	0.0	1	0.5	0.6
10	171LAC14K90031=1014	1	44846.0	0	0	0	1.0	2.5	0	0.0	5.0
10	171LA914812000=1014	1	44846.0	0	0	0	1.0	2.0	0	0.0	1.0
10	171LAE180000317=4	1	44846.0	0	0	0	0.0	0.0	1	5.0	1.0
10	171LAM180100000089=1	0	44846.0	0	0	0	0.0	0.0	0	0.0	0.0
10	171LAD180100000089=1	1	44846.0	0	0	0	1.0	1.7	0	0.0	3.3
10	171LA918010000089=1	1	44846.0	0	0	0	0.0	0.0	1	5.0	1.0
10	171LAD180100000089=1	1	44846.0	0	0	0	0.0	0.0	1	10.0	0.5
10	171LAM180100000314=2	1	44846.0	0	0	0	0.0	0.0	1	2.0	2.0
10	171LAJ180100000349=2	1	44846.0	0	0	0	0.0	0.0	1	1.0	0.8
10	171LAK180200000306=6	3	14948.7	0	0	0	0.0	0.0	3	1.0	3.5
10	171LA4180200000309=3	1	44846.0	0	0	0	0.0	0.0	1	0.5	0.5
10	171LAF180200000318=3	1	44846.0	0	0	0	0.0	0.0	1	4.0	2.7
10	171LAK180200000304=6	1	44846.0	0	0	0	0.0	0.0	1	12.0	0.5
10	171LAK180200000316=6	10	44846.0	0	0	0	0.0	0.0	1	15.7	10.4
10	171LAF180200000304=6	1	44846.0	0	0	0	0.0	0.0	1	8.0	8.0
10	171LAK180200000306=6	14	32023.3	0	0	0	0.0	0.0	14	70.0	10.9
10	171LAG180200000306=6	1	44846.0	0	0	0	0.0	0.0	1	3.0	0.5
10	171LAF180200000306=6	1	44846.0	0	0	0	0.0	0.0	1	2.0	2.0
10	171LAJ180200000306=6	1	44846.0	0	0	0	0.0	0.0	1	3.0	3.5
10	171LAK180200000316=6	6	14747.3	0	0	0	0.0	0.0	1	1.0	1.0
10	171LAF180200000306=6	1	44846.0	0	0	0	0.0	0.0	1	0.5	1.3
10	171LAK180200000316=6	16	2802.9	0	0	0	0.0	0.0	16	4.0	8.3
10	171LAG180200000308	5	8969.2	0	0	0	0.0	0.0	5	2.0	3.0
10	171LAA180200000308=2	9	4982.9	0	0	0	0.0	0.0	9	63.0	18.0
10	171LAM180200000309=2	3	14948.7	0	0	0	0.0	0.0	3	36.7	1.5
10	171LAA180200000309=2	1	44846.0	0	0	0	0.0	0.0	1	0.5	1.0
10	171LAD180200000309=2	1	44846.0	0	0	0	0.0	0.0	1	11.0	1.0
10	171LAA180200000309=3	3	14948.7	0	0	0	0.0	0.0	3	1.0	3.0
10	171LAK180200000309=3	1	44846.0	0	0	0	0.0	0.0	1	0.5	2.0
10	171LAA180200000309=5	1	44846.0	0	0	0	0.0	0.0	1	4.0	0.5
10	171LAM180200000309=1	1	44846.0	0	0	0	0.0	0.0	1	10.0	0.5
10	171LAA180200000309=3	125	358.8	0	0	0	0.0	0.0	124	10.5	125.7
10	171LAM180200000312=2	1	44846.0	0	0	0	0.0	0.0	1	4.0	1.0
10	171LAL180200000312=2	27	1661.0	0	0	0	0.0	0.0	27	101.0	39.7

03/09/79

LRU	HUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER OF NO FAULT	MEAN TURN AROUND TIME	NUMBER OF REPAIRS	MEAN TIME TO REPAIR (HRS)	NUMBER OF NRTS	MEAN TURN AROUND TIME (DAYS)	NUMBER OF MAINTENANCE MAN HOURS
10	71LAD	8020000312-2	1	44846.0	0	0.0	0	0.0	1	3.0	1.0
10	71LAL	8020000312-2	18	2491.4	0	0.0	0	0.0	18	6.4	24.0
10	71LAC	8020000312-2	1	44846.0	0	0.0	0	0.0	1	1.0	0.5
10	71LAL	8020000312-5	12	3737.2	0	0.0	1	0.0	11	4.3	20.1
10	71LAB	8020000313-3	36	1245.7	0	0.0	0	0.0	36	34.7	33.5
10	71LAJ	8020000313-3	1	44846.0	0	0.0	0	0.0	1	2.0	2.0
10	71LAB	8020000313-3	16	2491.4	0	0.0	0	0.0	16	2.3	27.0
10	71LAM	8020000314-2	8	5605.7	0	0.0	0	0.0	6	14.6	6.5
10	71LAM	8020000314-2	1	44846.0	0	0.0	0	0.0	1	10.0	1.8
10	71LAM	8020000314-2	27	1661.0	0	0.0	0	0.0	27	2.9	30.8
10	71LAB	8020000314-2	1	44846.0	0	0.0	0	0.0	1	1.0	0.5
10	71LAM	8020000314-8	54	830.5	0	0.0	0	0.0	54	4.1	55.4
10	71LAC	8020000315-3	40	1121.1	0	0.0	0	0.0	40	11.0	33.0
10	71LAD	8020000316-6	28	1601.6	0	0.0	0	0.0	28	48.6	20.8
10	71LAE	8020000317-4	17	2638.0	0	0.0	0	0.0	17	69.7	20.0
10	71LAJ	8020000317-4	1	44846.0	0	0.0	0	0.0	1	3.0	2.0
10	71LAE	8020000317-4	14	3203.3	0	0.0	0	0.0	14	1.9	12.8
10	71LAJ	8020000317-4	1	44846.0	0	0.0	0	0.0	1	0.5	2.0
10	71LAE	8020000317-4	11	4076.9	0	0.0	0	0.0	11	3.5	12.8
10	71LAF	8020000318-3	30	1494.9	0	0.0	0	0.0	30	36.0	33.6
10	71LAN	8020000347-1	4	11211.5	0	0.0	0	0.0	4	1.0	3.0
10	71LAM	8020000347-1	1	44846.0	0	0.0	0	0.0	1	3.0	1.0
10	71LAN	8020000347-1	23	1949.8	0	0.0	0	0.0	23	45.8	24.5
10	71LAJ	8020000349-2	20	2242.3	1	1.0	1	0.0	19	11.1	21.2
10	71LAG	8020000349-2	1	44846.0	0	0.0	0	0.0	1	6.0	0.5
10	71LAJ	8020000349-2	12	3737.2	0	0.0	0	0.0	12	2.9	10.5
10	71LAH	8020000356-2	14	3203.3	0	0.0	0	0.0	14	1.2	16.2
10	71LAN	8020000356-2	1	44846.0	0	0.0	0	0.0	1	0.5	2.0
10	71LAD	8020000356-2	16	2802.9	1	1.0	1	0.0	16	127.8	20.3
10	71LAL	8020000356-2	1	44846.0	0	0.0	0	0.0	1	1.0	2.0
10	71LAH	8020000356-2	27	1661.0	0	0.0	0	0.0	27	3.1	35.6
10	71LAD	802000036-13	1	44846.0	0	0.0	0	0.0	1	4.0	1.0
10	71LAJ	802000036-13	1	44846.0	0	0.0	0	0.0	1	0.5	2.0
10	71LAN	8020000368-2	1	44846.0	0	0.0	0	0.0	1	88.0	2.0
10	71LAF	802000300-6	1	44846.0	0	0.0	0	0.0	1	12.0	0.5
10	71LAK	802000306-6	2	22423.0	0	0.0	0	0.0	2	4.7	1.0
10	71LAA	802000309-3	3	14948.7	0	0.0	0	0.0	3	5.7	3.5
10	71LAB	802000313-3	2	22423.0	0	0.0	0	0.0	2	14.0	1.0
10	71LAM	802000314-2	1	44846.0	0	0.0	0	0.0	1	1.0	0.5
10	71LAC	802000315-3	1	44846.0	0	0.0	0	0.0	1	1.0	0.5
10	71LAD	802000316-3	1	44846.0	0	0.0	0	0.0	1	4.0	1.0
10	71LAF	802000316-3	1	44846.0	0	0.0	0	0.0	1	2.0	0.9
10	71LAH	802000316-3	1	44846.0	0	0.0	0	0.0	1	4.0	1.0
10	71LAJ	802000349-2	1	44846.0	0	0.0	0	0.0	1	1.0	0.5
10	71LAL	802000356-2	1	44846.0	0	0.0	0	0.0	1	3.0	0.5

LRU	WUC	PART NUMBER	NUMBER IF SHIP	MEAN TIME BETWEEN FAULTS	NUMBER SHIP FAULT	MEAN TIME TURN AROUND	NUMBER SHIP REPAIRS	MEAN TIME REPAIR	NUMBER NATS	MEAN TIME AROUND	SHOP MAINTENANCE MAN HOURS
			DEMANDS		TIME NO FAULT		TIME	(HRS)			
30	171LC11PG213U		2	22423.0	0	0.0	2	2.5	0	0.0	11.3
30	171LC914K1103=119		4	11211.5	0	0.0	4	1.7	0	0.0	20.0
30	171LCC1A010000003=1		71	631.6	8	1.2	21	12.2	42	2.4	132.5
			782	57.3	9	1.2	35	8.7	2.5	738	25.6
											942.5

NATS RATE (X).....: 94.4
 MEAN TIME BETWEEN REPAIR (MTRR)=1 56.0

XNRTR2 = 0.0

TARGET IDENTIFICATION SYSTEM ELECTRO-OPTICAL
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY

03/12/70

LOCATION: SUMMARY
FLIGHT HOURS: 100589.0

**TIME FRAME: 6M
END OF MONTH AIRCRAFT INVENTORY**

CND RATE (% OF GRIPPIES).....0.6

MEAN TIME BETWEEN DEMANDS 94

W.H.N.C.D.P. # 443960

TARGET IDENTIFICATION SYSTEM ELECTRO-OPTICAL
 INTERMEDIATE LEVEL
 IRU MAINTAINABILITY SUMMARY

03/12/79

LOCATION SUMMARY
 FLIGHT HOURS 144589.0

FIND OF MINTN AIRCRAFT INVENTORY

SHUTTERS: 111545

LNU	MUC	NUMBER OF SHIP ARRIVALS	MEAN TIME BETWEEN ARRIVALS	NUMBER OF FAULTS	PERCENT OF FAULTS	NUMBER OF ARRIVALS	MEAN TURN AROUND TIME (DAYS)	NUMBER OF SHIP REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER OF SHIP REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER OF SHIP REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER OF SHIP REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER OF SHIP REPAIRS	MEAN TURN AROUND TIME (DAYS)
10	71UAD	623	238.5	116	18.6	20.2	5.9	16.7	6.6	121	34.0	110.0	19.6	0	0.0	0	0.0
20	71UBO	5	29717.8	1	20.0	2.0	4	1.4	2.2	0	0.0	3.4	3.4	0	0.0	0	0.0
50	71UCG	1	148588.8	0	0.0	0.0	1	11.5	1.2	0	0.0	12.0	12.0	1	2.0	1	2.0
40	71UDG	1	146588.8	0	0.0	0.0	0	0.0	0.0	0	0.0	107.3	3906.0	24	107.3	24	107.3
60	71UME	277	536.4	101	36.5	43.2	237	61.3	6.9	26	6.9	660.5	660.5	4	21.0	4	21.0
70	71UKO	44	1768.9	36	42.9	68.7	61	104.4	3.6	5	3.6	106.1	106.1	5	106.1	5	106.1
80	71UL0	152	977.0	46	36.3	3.0	122	23.9	2.6	1	2.6	10.0	10.0	1	10.0	1	10.0
90	71UQ0	3	40529.0	1	35.3	0.5	1	2.0	2.5	1	0.5	10.0	10.0	1	10.0	1	10.0
90	71UN0	1	146588.8	0	0.0	0.0	1	15.0	3.0	1	0.0	0.0	0.0	1	0.0	1	0.0
1147		129.5	301	26.2	32.5	1016	33.1	6.0	166	44.4	13657.7						

NATS RATE (%): 13.0

MEAN TIME AFTER REPAIR (MTR) = 175.8

MEAN TURN AROUND TIME (MAT) = 33.0

CONFIRMED FAILURES PER FLIGHT = 0.008

XNRTS2 = 1.0

TARGET IDENTIFICATION SYSTEM ELECTRO-OPTICAL
INTERMEDIATE LEVEL
SPU MAINTAINABILITY SUMMARY

03/12/70

LICENSING SUMMARY
FLIGHT HOURS: 106580.0

END OF MONTH AIRCRAFT INVENTORY: 86

TIME FRAME: SUM

SPOTIES: 1115AS

LNU	WUC	PART NUMBER	NUMBER OF DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER SHIP FAULT	MEAN TURN AROUND TIME	NUMBER SHOP REPAIRS	MEAN TIME TO REPAIR (HRS)	MEAN TURN AROUND TIME (DAYS)		NUMBER NRTS	MEAN TURN AROUND TIME (DAYS)	MEAN MAINTENANCE MAN HOURS
									NO FAULT	NO FAULT			
10	171UAD	301115	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0.0
10	171UAF	301115	0	0.0	1	146588.8	0	0.0	0	0.0	0	0.0	0.4
10	171UAD	199922601	1	146588.8	1	146588.8	0	0.0	1	1.0	0	0.0	2.0
50	171UFA	301115	1	146588.8	1	146588.8	0	0.0	0	0.0	0	0.0	15.8
50	171UFM	301425	14	10613.5	0	0.0	0	0.0	0	0.0	0	0.0	26.9
50	171UFA	301430	19	7820.5	0	0.0	1	1.0	14	1.0	0	0.0	12.6
50	171UFG	301445	11	13508.1	0	0.0	0	0.0	0	0.0	0	0.0	20.3
50	171UFB	3014504	17	21227.0	0	0.0	4	4.0	4	4.0	0	0.0	5.7
50	171UFE	301465	4	37147.2	0	0.0	0	0.0	0	0.0	0	0.0	3.8
50	171UFC	301475	4	37147.2	0	0.0	0	0.0	3	1.3	0	0.0	1.0
50	171UFG	301475	0	146588.8	0	0.0	0	0.0	0	0.0	0	0.0	7.2
50	171UFC	301475	0	37147.2	0	0.0	0	0.0	0	0.0	0	0.0	3.5
50	171UFN	301495A	25	5943.4	1	1.0	15	1.0	24.1	24.1	0	0.0	35.0
50	171UFO	301495	6	18573.0	4	79.0	4	4.0	79.0	79.0	0	0.0	12.0
50	171UFA	301520	9	16509.9	0	0.0	0	0.0	87.5	87.5	0	0.0	25.0
50	171UFE	301615	1	146588.8	0	0.0	0	0.0	0	0.0	0	0.0	1.0
50	171UFA	302520	1	146588.8	0	0.0	0	0.0	0	0.0	0	0.0	1.0
50	171UFG	304045	0	146588.8	0	0.0	0	0.0	0	0.0	0	0.0	1.0
60	171UHF	301115	0	0.0	1	146588.8	0	0.0	0	0.0	0	0.0	0.5
60	171UHA	301115	1	146588.8	1	146588.8	0	0.0	0	0.0	0	0.0	0.5
60	171UHK	301470	1	146588.8	0	0.0	0	0.0	0	0.0	0	0.0	2.0
60	171UHA	301630	6	24764.8	0	0.0	0	0.0	0	0.0	0	0.0	10.0
60	171UHQ	301635	5	49529.6	0	0.0	0	0.0	0	0.0	0	0.0	15.0
60	171UHG	301640	2	74294.4	2	74294.4	0	0.0	46.5	46.5	0	0.0	0.5
60	171UHQ	301645	1	146588.8	1	146588.8	0	0.0	0	0.0	0	0.0	0.5
60	171UHC	301650	0	16509.9	0	0.0	0	0.0	0	0.0	0	0.0	2.0
60	171UHA	301655	1	146588.8	0	0.0	0	0.0	56.5	56.5	0	0.0	25.5
60	171UHQ	301655	5	29717.6	0	0.0	0	0.0	0	0.0	0	0.0	1.0
60	171UHA	301655	2	74294.4	2	74294.4	0	0.0	31.2	31.2	0	0.0	1.0
60	171UHG	301655	32	4643.4	32	4643.4	0	0.0	20.6	20.6	0	0.0	1.0
60	171UHL	301660	1	146588.8	1	146588.8	0	0.0	0	0.0	0	0.0	0.5
60	171UHC	301660	4	18573.0	4	18573.0	0	0.0	0	0.0	0	0.0	1.0
60	171UHL	301665	57	2606.8	57	2606.8	0	0.0	12.4	12.4	0	0.0	73.8

03/12/79

L#	A#	PART NUMBER	NUMBER OF SHIP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER OF SHIPS	MEAN TIME TO ARRIVE	NUMBER OF SHIPS	MEAN TIME TO ARRIVE	NUMBER OF SHIPS	MEAN TIME TO ARRIVE	NUMBER OF SHIPS	MEAN TIME TO ARRIVE
64	171UHJ1301465		1	144588.9	0	0.0	0	0.0	1	11.0	1	2.5
64	171UHJ1301465		10	14958.9	6	2.4	6	0.0	10	12.0	10	16.5
64	171UHJ1301670		11	13508.1	0	0.0	5	70.2	0.9	6.7	6	15.9
64	171UHJ1301670		1	144588.9	0	0.0	0	0.0	1	7.0	1	2.0
64	171UHJ1301670		6	20164.8	0	0.0	0	0.0	6	26.7	12	2.0
64	171UHJ1301680		3	40229.6	0	0.0	2	71.5	0.6	1020.0	1	2.7
64	171UHE301695		5	20717.8	0	0.0	5	98.3	0.9	2	5.5	4.3
64	171UHF1301700		1	144588.8	0	0.0	0	0.0	1	2.0	1	1.6
64	171UHU301715		12	12342.7	0	0.0	9	35.8	1.0	352.0	3	13.1
64	171UHM1301720		1	144588.4	0	0.0	1	76.0	1.4	0	0	1.4
64	171UHM1301730		5	20217.8	0	0.0	2	112.5	2.4	3	6.0	13.6
64	171UHMJ1301740		4	37407.2	0	0.0	2	113.0	1.0	2	7.0	4.9
64	171UHF1301750		17	470.5	0	0.0	1	29.3	0.7	6	14.6	16.2
64	171UHM1301765		26	5715.0	0	0.0	19	50.7	1.6	7	30.6	43.3
64	171UHM1301765		1	144588.8	0	0.0	0	0.0	1	7.0	1	2.0
64	171UHM1301765		1	144588.8	0	0.0	0	0.0	1	36.0	1	2.0
70	171UHA1301810		11	14508.1	0	0.0	2	148.0	1.1	0	119.4	14.7
106	171UHD1301815		0	n.o.	0	0.0	0	0.0	0	0.0	0	0.0
999	171UHQ171217-10		7	21227.0	0	0.6	3	2.2	2.7	4	9.6	31.4
			175	396.2	9	3.2	216	42.7	1.3	150	53.3	567.1

NRTS RATE (2) 40.0
 MEAN TIME BETWEEN REPAIRS (MTHR) = 406.0

XNRTS2 = 0.0

THIS PAGE IS FOR SUMMARY PURPOSES ONLY
 NO COPY REQUESTS WILL BE MADE

DIRECT RADAR SCOPE RECORDING SYSTEM
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY

03/09/79

LOCATIONS SUMMARY
FLIGHT HOURS: 146509.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 86

SORTIES:*****

LRU	FLIGHT LINE	MEAN TIME BETWEEN MAINT	NUMBER CND AS	MEAN CND	NUMBER CANN AS	MEAN CANN	NUMBER REPAIR	MEAN REPAIR	NUMBER MAINT	MEAN MAINT	NUMBER REMOVAL	MEAN REMOVAL	NUMBER OTHER	MEAN OTHER	NUMBER ACTIONS	MEAN ACTIONS	NUMBER TIME	MEAN TIME	NUMBER DEMAND	MEAN DEMAND	NUMBER MAN	MEAN MAN	NUMBER TIME	MEAN TIME	NUMBER OTHER	MEAN OTHER	NUMBER HOURS	MEAN HOURS					
120	138	1076.7	6	4.3	1	0.7	41	2.4	78	1.4	77	1.4	305.7																				
130	693	166.4	165	16.5	2.3	4	0.4	4.7	308	2.4	355	1.9	398	2.1	2615.0																		
999	29	5123.8	7	24.1	0.6	0	0.0	0.0	12	1.4	2	1.7	8	5.4	68.6																		
			1060	140.2	178	16.8	2.2	5	0.5	4.0	361	2.3	435	1.7	463	2.0	2989.5																

CND RATE (% OF SORTIES)-----| 0.2

MEAN TIME BETWEEN DEMANDS-----| 341.6

SORTY SUCCESS RATE (%)-----| 99.3

DIRECT RADAR SCOPE RECORDING SYSTEM
INTERMEDIATE LEVEL
SRU MAINTAINABILITY SUMMARY

LOCATION SUMMARY
FLIGHT HOURS: 148589.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 86

SORTIES: 111585

03/09/79

LRU	RUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT DEMANDS	MEAN TIME NO FAULT	NUMBER SHOP REPAIRS	MEAN TURN AROUND TIME	NUMBER NRTS	MEAN TURN AROUND TIME (DAYS)	NUMBER NO FAULT	MEAN TIME TO REPAIR (HRS)	NUMBER NRTS	MEAN TURN AROUND TIME (DAYS)	NUMBER NO FAULT	MEAN TIME TO REPAIR (HRS)	NUMBER NRTS	MEAN TURN AROUND TIME (DAYS)	NUMBER NO FAULT	MEAN TIME TO REPAIR (HRS)
120	177J1D	IA05A00342A	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	1	148588.8	0	0.0	0	0.0	1	0.5	1.2	2.5	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0105-1	1	148588.8	0	0.0	0	0.0	1	0.5	3.0	3.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	6	24764.8	1	40.0	5	9.0	1	0.5	1.2	10.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A01051	4	3747.2	0	0.0	4	2.4	1	0.5	1.6	11.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2B	IA05A003-1	1	148588.8	0	0.0	1	0.5	1	0.5	1.5	1.5	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	10	148588.9	5	203.0	5	202.6	1	1.1	1.1	25.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	2	74294.4	0	0.0	2	0.5	1	0.5	1.0	4.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	124	1198.3	45	25.1	77	42.6	2	0.0	2.0	372.5	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2D	IA05A0104-1	1	148588.8	1	0.5	0	0.0	1	0.5	1.0	1.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	13	14829.9	8	1.0	5	1.6	1	0.5	1.6	37.2	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	1	148588.8	0	0.0	1	0.5	3	7.7	7.7	7.7	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	35	42485.4	10	0.7	25	2.4	2	0.0	2.0	105.8	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	1	148588.8	0	0.0	1	0.5	1	0.5	1.2	2.3	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	7	22227.0	4	0.5	3	2.7	1	0.5	2.7	23.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	1	148588.8	0	0.0	1	0.5	1	0.5	2.0	4.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	61	2435.9	24	2.3	33	5.0	2	0.0	2.4	46.2	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	48	3095.6	7	0.6	38	3.1	2	0.0	2.3	193.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	2	72294.4	1	0.5	1	0.5	1	0.5	1.2	11.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	3	49529.6	0	0.0	3	14.5	1	0.5	2.6	16.7	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	1	148588.8	0	0.0	1	1.0	1	1.0	1.5	1.5	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	10	148588.9	1	0.5	1	0.5	1	0.5	1.5	25.3	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	1	148588.8	0	0.0	1	0.5	1	0.5	2.0	4.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0104-1	1	148588.8	0	0.0	1	0.5	1	0.5	1.5	2.2	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0104-1	16	9286.6	4	3.4	12	1.0	1	1.0	1.3	29.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0105-1	1	148588.8	0	0.0	1	1.0	1	1.0	1.5	13.3	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0105-1	66	2251.3	19	3.5	47	5.9	1	1.2	1.2	114.5	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0105-1	1	148588.8	0	0.0	1	1.0	1	1.0	1.5	3.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A0105-1	11	13508.1	1	1.0	1	1.0	1	1.0	2.2	32.3	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0105-14EAPT	11	74294.4	0	0.0	2	5.0	2	1.0	1.6	1.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A01051	2	74294.4	1	0.5	16	4.1	1	1.5	1.5	5.4	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A01051	19	7620.5	1	1.0	1	1.0	0	0.0	0.0	2.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A01051	1	148588.8	1	1.0	0	0.0	1	1.0	1.0	1.0	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0106-1	11	13508.1	0	0.0	1	1.0	1	1.0	1.2	22.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A0106-1	6	16573.6	0	0.0	1	1.0	1	1.0	1.5	2.1	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A01061	1	148588.8	0	0.0	2	5.0	2	1.0	1.6	1.6	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2K	IA05A01061	1	49529.6	3	6.7	3	6.7	1	1.0	1.7	1.7	0	0.0	0	0.0	0	0.0	0	0.0
130	177J2A	IA05A01065-1	2	76294.4	0	0.0	2	1.2	1	1.2	1.2	9.6	0	0.0	0	0.0	0	0.0	0	0.0

03/09/79

LNU	NUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT DEMANDS	MEAN TURN AROUND TIME NO FAULT	NUMBER SHIP REPAIRS	MEAN TURN TIME TU	NUMBER NRTS	MEAN TURN AROUND TIME (DAYS)	MEAN MAINTENANCE MAN HOURS
130	177J2K1A1UAN0601		0	0.0	0	0.0	0	0.0	0	0.0	0.0
130	177J2A8GE19A		1	148588.8	0	0.0	1	11.0	1	1.5	0.0
130	177J2H1J72E0001		1	148588.8	0	0.0	1	0.5	0	0.7	0.0
130	177J2A1J72F0001-1		1	148588.8	0	0.0	1	36.0	0	0.5	0.5
130	177J2K32-A70AA301		3	49529.0	1	1279.0	2	0.5	0	3.1	0.0
130	177J2H32E76013		1	148588.8	1	1.0	0	0.0	0	0.5	15.7
130	177J2K530879121		2	74294.4	1	2.0	1	4.0	0	0.0	0.0
130	177J2C69=4005		1	148588.8	0	0.0	1	0.5	0	1.1	0.0
130	177J2A77J2A		1	148588.8	0	0.0	1	0.5	0	1.0	0.0
999	177J2K1A05A0104-1		0	0.0	0	0.0	0	0.0	0	0.0	0.0
999	177J2A1405A01051		1	148588.8	1	8.0	0	0.0	0	0.0	0.0
			489	303.9	137	26.5	343	17.5	1.9	140.7	1411.7

NRTS RATE (λ) = 1.6

MEAN TIME BETWEEN REPAIR (MTRR) = 422.1

XNRT92 = 0.0

AN/APQ-130 ATTACK RADAR
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY

03/09/79

LOCATION: SUMMARY
FLIGHT HOURS: 14539.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 77

SORTIES: 6037

LRU	FLIGHT LINE MAINT	MEAN TIME MAINT	NUMBER CND AS CND % OF ACTIONS	MEAN MAINT LINE TIME	CANNIBALISATION	CANN AS % OF LINE	MEAN MAINT LINE TIME	IN PLACE TIME	(DEMAND)	REMOVAL TIME	OTHER MAINT	LINE MAINT	NUMBER CND AS CND % OF ACTIONS	MEAN MAINT LINE TIME	IN PLACE TIME	(DEMAND)	REMOVAL TIME	OTHER MAINT	LINE MAINT
10	277	52.5	4	1.4	2.5	11	4.0	2.8	20	3.3	310	3.6	41	1982.7	3.6	41	3.6	41	3.6
20	772	19.8	15	2.1	1.6	100	13.0	3.5	77	4.1	692	3.8	143	3.0	3.0	3.0	3.0	3.0	3.0
30	5	2907.8	3	0.0	0.0	0	0.0	0.0	0	0.3	2.3	1	2.0	2	1.0	1.0	1.0	1.0	1.0
40	586	24.8	3	0.5	1.8	34	5.8	5.1	31	3.3	607	4.3	103	3.3	3.3	3.3	3.3	3.3	3.3
50	165	89.1	2	0.0	0.0	6	4.8	2.9	9	1.2	162	3.5	36	2.4	2.4	2.4	2.4	2.4	2.4
60	169	85.0	1	0.6	1.8	34	20.1	2.9	9	2.3	138	3.1	48	2.9	2.9	2.9	2.9	2.9	2.9
70	260	55.9	2	0.8	1.0	5	1.9	4.3	16	4.0	303	5.6	43	4.5	4.5	4.5	4.5	4.5	4.5
90	300	48.5	1	0.3	18.2	16	5.3	6.0	13	2.4	291	3.9	57	2.3	2.3	2.3	2.3	2.3	2.3
100	109	133.4	2	1.8	6.1	8	7.3	5.5	31	5.0	85	7.9	25	4.5	4.5	4.5	4.5	4.5	4.5
110	217	67.0	0	0.0	0.0	11	5.1	6.1	157	2.6	77	5.2	40	3.3	3.3	3.3	3.3	3.3	3.3
999	1026	14.2	265	25.8	3.2	5	0.5	2.0	384	3.4	32	4.8	519	6.3	5556.4	6.3	6.3	6.3	6.3
	3886	3.7	294	7.6	3.1	232	6.0	4.3	750	3.3	2698	4.4	1057	4.7	21249.4				

CND RATE (% OF SORTIES)-----: 4.9

MEAN TIME BETWEEN DEMANDS-----: 5.4

SORTY SUCCESS RATE (%)-----: 47.8

WHNCDP = 3151.0

AN/APQ-130 ATTACK RADAR
INTERMEDIATE LEVEL
LRU MAINTAINABILITY SUMMARY

03/09/79

LOCATION: SUMMARY
FLIGHT HOURS: 14539.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 77

SOUTIES: 6037

LRU	WUC	NUMBER OF SHOP ARRIVALS	MEAN TIME BETWEEN ARRIVALS	NUMBER SHOP NO FAULTS	PERCENT NO FAULT	MEAN TURN ABOUT ARRIVALS	NUMBER SHOP REPAIRS	MEAN TURN ABOUT REPAIRS	MEAN TIME TO REPAIR	(HRS)	MEAN TURN ABOUT NRTS	(DAYS)	MEAN TURN ABOUT NRTS	(DAYS)	MEAN TURN ABOUT NRTS	(DAYS)	MEAN TURN ABOUT NRTS
10	73PAC	312	46.9	23	6.5	56.2	38.3	28.5	10.6	3	29.3	7312.6					
20	73PBO	701	20.7	250	35.7	18.3	51.7	25.8	9.6	31	92.9	9814.7					
33	73PCO	3	4846.3	3	0.0	0.0	0.0	67.5	8.8	1	22.0	9.8					
42	73PDC	595	24.4	162	27.2	16.6	54.3	16.3	7.4	135	29.8	7805.2					
50	73PFO	143	101.7	66	46.2	2.1	114	39.2	6.3	5	35.4	1222.5					
60	73PHO	133	159.3	37	27.8	7.5	99	35.1	7.0	43	8.2	1267.8					
75	73PKC	277	52.5	59	21.3	24.1	3.6	18.2	8.1	9	19.0	4060.1					
80	73PL0	1	14539.0	0	0.0	0.0	0.0	0.0	0.0	1	4.0	1.0					
90	73PM0	297	49.0	99	33.3	1.5	25.0	20.4	6.7	4	1.4	2806.7					
100	73PPC	82	177.3	9	11.0	22.4	7.1	69.6	4.9	24	65.5	611.8					
110	73PPO	23	726.9	6	30.0	11.2	2.1	63.1	2.7	4	14.5	104.1					
999	73PCO	2	7269.5	0	0.0	0.0	0.0	0.0	0.0	1	1.0	0.5					
999	73PKC	1	14539.0	3	0.0	0.0	1	3.0	2.5	3	0.0	5.0					
2565		5.7	728	27.6	15.1	253.6	24.7	8.3	261	34.6	3522.0						

NRTS RATE (%)-----: 10.2

MEAN TIME BETWEEN REPAIR (MTBR) : 7.8

MEAN TURN AROUND TIME (MTAT) : 22.5

CONFIRMED FAILURES PER FLIGHT---: 0.378

XNRTS2 = C.0

AN/APQ-130 ATTACK RADAR
INTERMEDIATE LEVEL
SRU MAINTAINABILITY SUMMARY

LOCATION: SUMMARY
FLIGHT HOURS: 14533.0

TIME FRAME: SUM
END OF MONTH AIRCRAFT INVENTORY: 77

SORTIES: 6037

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER SHOP NO FAULT	MEAN TURN AROUND TIME	NUMBER SHOP REPAIRS	MEAN TURN AROUND TIME	NUMBER MRTS	MEAN TURN AROUND TIME (DAYS)	NUMBER MRTS	MEAN TURN AROUND TIME (DAYS)	NUMBER MRTS	MEAN TURN AROUND TIME (DAYS)	
					NO FAULT	NC FAULT	NO FAULT	NC FAULT	NO FAULT	NC FAULT	NO FAULT	NC FAULT	NO FAULT	NC FAULT	
10	73PAA	342-10583-3	1	14539.0	2	0.0	0	0.0	0	0.0	0	0.0	1	16.0	
10	73PAC	342-10580-5	3	4846.3	3	0.0	0	0.0	0	0.0	0	0.0	3	1.7	
10	73PAD	342-10593-5	1	14539.0	2	0.0	0	0.0	0	0.0	0	0.0	1	2.0	
10	73PAAl	342-10583-8	1	14539.0	3	0.0	0	0.0	0	0.0	0	0.0	1	0.5	
10	73PACl	342-10580-8	4	3634.7	0	0.0	0	0.0	0	0.0	0	0.0	4	8.5	
10	73PAB	342-10539-2	3	4846.3	0	0.0	0	0.0	0	0.0	0	0.0	3	1.7	
10	73PAC	342-10560-2	1	14539.0	2	0.0	0	0.0	0	0.0	0	0.0	1	16.0	
10	73PAAl	342-10583-8	7	2077.0	2	0.0	0	0.0	0	0.0	0	0.0	5	276.2	
10	73PAH	342-10583-8	1	14539.0	2	0.0	0	0.0	1	1306.0	0	0.0	0	12.9	
10	73PAAl	342-10583-8	3	4846.3	0	0.0	0	0.0	0	0.0	0	0.0	3	0.0	
10	73PAH	342-10583-8	1	14539.0	2	0.0	0	0.0	0	0.0	0	0.0	3	3.3	
10	73PAB	342-10583-8	1	14539.0	2	0.0	0	0.0	1	1285.0	0	0.0	0	0.7	
10	73PAC	342-10583-8	2	7269.5	2	0.0	0	0.0	0	0.0	0	0.0	2	4.0	
10	73PAH	342-10583-8	2	7269.5	2	0.0	0	0.0	2	749.5	0	0.0	0	1.3	
10	73PAAl	342-10583-8	16	908.7	2	0.0	0	0.0	7	84.6	0	0.0	9	51.2	
10	73PAH	342-10583-8	1	14539.0	2	0.0	0	0.0	7	29.0	0	0.0	0	0.7	
10	73PAAl	342-10583-8	4	3634.7	2	0.0	0	0.0	4	3.6	0	0.0	0	0.7	
10	73PAH	342-10592-5	1	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	1	20.0	
10	73PAC	342-10592-8	51	285.1	1	8.0	3	48.3	2	8.7	87	35.7	1	62.3	
10	73PAAl	342-10592-8	1	14539.0	2	0.0	0	0.0	0	0.0	0	0.0	1	0.5	
10	73PAC	342-10592-6	26	559.2	2	4.0	2	9.5	1.5	22	156.0	0	0.0	0	37.6
10	73PAAl	342-10592-6	1	14539.0	3	0.0	1	37.0	4.1	0	0.0	0	0.0	0	16.0
10	73PAC	342-10592-6	29	501.3	7	4.1	7	5.9	2.4	15	12.4	0	0.0	0	62.5
10	73PAAl	342-10592-8	2	7269.5	0	0.0	0	0.0	0	0.0	0	0.0	2	0.5	
10	73PAC	342-10592-8	14	1038.5	1	2.0	0	0.0	0	0.0	0	0.0	13	5.2	
10	73PAD	342-105920-1	21	692.3	2	24.5	6	27.7	2.6	13	3.8	0	0.0	0	42.4
10	73PAE	342-105920-6	17	855.2	2	0.0	3	4.7	4.1	14	5.6	0	0.0	0	32.0
10	73PAE	342-105920-5	17	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	3	0.5	
10	73PAE	342-105920-5	29	501.3	7	4.1	7	5.9	2.4	15	12.4	0	0.0	0	62.5
10	73PAE	342-105920-8	2	7269.5	0	0.0	0	0.0	0	0.0	0	0.0	2	0.5	
10	73PAE	342-105920-8	14	1038.5	1	2.0	0	0.0	0	0.0	0	0.0	13	5.2	
10	73PAE	342-105920-1	21	692.3	2	24.5	6	27.7	2.6	13	3.8	0	0.0	0	42.4
10	73PAE	342-105920-6	17	855.2	2	0.0	3	4.7	4.1	14	5.6	0	0.0	0	32.0
10	73PAE	342-105920-5	17	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	3	0.5	
10	73PAC	342-10592-5	20	726.9	6	8.0	2	7.5	1.1	12	6.8	0	0.0	0	27.0
10	73PAC	342-10592-5	1	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	1	0.5	
10	73PAE	342-10592-5	14	1038.5	0	0.0	3	6.7	1.5	11	5.4	0	0.0	0	18.3
10	73PAE	342-105920-1	21	692.3	2	24.5	6	27.7	2.6	13	3.8	0	0.0	0	42.4
10	73PAE	342-105920-6	17	855.2	2	0.0	3	4.7	4.1	14	5.6	0	0.0	0	32.0
10	73PAE	342-105920-5	17	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	3	0.5	
10	73PAF	342-10592-1	10	1453.9	1	3.0	1	3.0	0	0.0	0	0.0	1	0.5	
10	73PAC	342-105920-8	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	
10	73PAE	342-105920-1	1	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	1	0.5	
10	73PAE	342-105920-1	1	14539.0	0	0.0	0	0.0	0	0.0	0	0.0	1	0.5	
10	73PAE	342-105920-6	2	7269.5	2	0.0	0	0.0	0	0.0	0	0.0	2	6.0	
10	73PAE	342-105435	5	7269.5	2	0.0	0	0.0	0	0.0	0	0.0	2	6.0	

THIS PAGE IS EAST QUALITY PRINTED BY DELL

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT	MEAN TURN AROUND TIME	NUMBER REPAIRS	MEAN TURN TIME	TIME TO REPAIR (HRS)	NUMBER WRTS	MEAN TURN AROUND TIME	NUMBER MAINTENANCE MAN HOURS	SHOP MAINTENANCE MAN HOURS
					NO FAULT	NO FAULT	NO FAULT	NO FAULT	NO FAULT	NO FAULT	NO FAULT	NO FAULT	NO FAULT
20	73PBL	66530-505-21	10	1453.9	1	7.0	2	3.7	0.6	7	32.3	7.7	
20	73PBC	66530-506-21	1	14539.0	0	0.0	0	0.0	0.0	1	81.9	0.5	
20	73PBL	66530-505-21	10	1453.9	3	7.3	0	0.0	0.0	7	8.3	17.0	
20	73PBH	66530-505-21	1	14539.0	0	0.0	0	0.0	0.0	1	0.5	0.3	
20	73PBL	66530-506-21	2	7269.5	0	0.0	0	0.0	0.0	2	0.5	2.5	
20	73PBC	66535-505-21	1	14539.0	1	2.0	0	0.0	0.0	0	0.0	0.7	
20	73PBE	66535-505-21	1	14539.0	2	C.0	0	0.5	0.7	0	0.0	0.7	
20	73PBF	66535-505-21	1	14539.0	1	23.0	0	0.0	0.0	0	0.0	0.7	
20	73PBE	66535-505-21	2	7269.5	1	3.0	0	0.0	0.0	0	0.0	1.3	
20	73PBF	66535-505-21	1	14539.0	1	2.0	0	0.0	0.0	0	0.0	0.7	
20	73PBE	66535-505-21	15	969.3	5	5.2	0	0.0	0.0	9	12.8	12.8	
20	73PBL	66535-506-21	36	403.9	7	12.3	8	33.6	1.2	21	61.2	35.9	
20	73PBC	66660-506-21	1	14539.0	0	0.0	0	0.0	0.0	21	1067.0	1.0	
20	73PBG	66660-505-21	2	7269.5	1	6.0	0	0.0	0.0	1	7.0	1.7	
20	73PBC	66660-505-21	2	7269.5	1	17.0	0	0.0	0.0	1	1067.0	4.0	
20	73PBL	67340-506-51	1	14539.0	0	0.0	0	0.0	0.0	0	0.0	1.0	
20	73PBD	68850-505-15	5	2907.8	0	0.0	1	1.0	1.2	1	1.0	10.4	
20	73PBP	68850-505-15	1	14539.0	0	0.0	0	0.0	0.0	1	1.0	0.5	
20	73PBE	68850-505-15	1	14539.0	0	0.0	0	0.0	0.0	1	1.0	0.5	
20	73PBD	68850-505-15	0	0.0	0	0.0	0	0.0	0.0	0	0.0	0.0	
20	73PBP	68850-506-71	1	14539.0	0	0.0	0	0.0	0.0	0	0.0	1.0	
20	73PBB	68972050621	12	1211.6	2	11.7	0	0.0	0.0	7	16.4	14.4	
20	73PBG	68972050621	1	14539.0	1	13.0	0	0.0	0.0	0	0.0	1.0	
20	73PBL	68975-505-41	1	14539.0	0	0.0	0	0.0	0.0	1	5.0	0.5	
20	73PBH	68975-505-41	6	2423.2	1	7.0	2	47.0	1.4	3	21.3	7.8	
20	73PBN	68960050621	13	1116.4	3	12.0	0	0.0	0.0	10	6.2	9.6	
20	73PBP	68975-506-71	9	1615.4	1	2.0	4	8.0	0.7	11	5.2	6.7	
20	73PBB	68972050621	12	1211.6	2	11.7	0	0.0	0.0	7	16.4	14.4	
20	73PBG	68972050621	1	14539.0	1	13.0	0	0.0	0.0	0	0.0	1.0	
20	73PBL	68975-505-41	1	14539.0	0	0.0	0	0.0	0.0	1	5.0	0.5	
20	73PBN	6897350621	6	2423.2	1	7.0	2	47.0	1.4	3	21.3	7.8	
20	73PBN	68960050621	13	1116.4	3	12.0	0	0.0	0.0	10	6.2	9.6	
20	73PBP	68975-506-71	9	1615.4	1	2.0	4	8.0	0.7	11	5.2	6.7	
20	73PBM	68865-505-71	1	14539.0	0	0.0	1	16.0	0.7	0	0.0	0.7	
20	73PBP	68865-505-71	49	296.7	5	13.4	16	14.1-2	0.7	28	35.1	41.3	
20	73PBR	68865-505-71	1	14539.0	0	0.0	0	0.0	0.0	1	80.0	1.0	
20	73PBP	6886550631	41	354.6	2	14.5	8	19.6	0.7	31	10.9	35.5	
20	73PBM	688670-505-51	20	726.9	7	10.0	2	4.0	0.7	11	5.2	18.9	
20	73PBN	688670-505-51	1	14539.0	0	0.0	1	16.0	0.7	0	0.0	0.7	
20	73PBP	688670-505-51	38	382.6	9	16.1	8	15.4	0.7	21	128.7	32.6	
20	73PBP	688670-505-51	2	726.9	0	0.0	1	20.0	0.7	1	7.0	1.7	
20	73PBP	688670-505-51	6	2423.2	2	7.5	0	0.0	0.0	4	10.5	6.7	
20	73PBP	68970-505-31	2	726.9	0	0.0	0	0.0	0.0	2	34.0	2.4	
30	73PCC		1	14539.0	0	0.0	0	0.0	0.0	0	0.0	2.4	
30	73PCD	38560-505-41	1	14539.0	0	0.0	0	0.0	0.0	1	4.0	0.3	
30	73PCG	584188900-506-2	1	14539.0	0	0.0	0	0.0	0.0	1	0.5	0.5	
30	73PCA	6510050631	26	559.2	2	0.5	0	0.0	0.0	2	151.5	1.8	
30	73PCC	6510050631	1	14539.0	3	0.0	0	0.0	0.0	1	9.0	0.3	
30	73PCK	66200-506-21	1	14539.0	0	0.0	1	15.0	0.7	0	0.0	0.7	
30	73PCF	66510-505-31	15	969.3	2	4.0	5	58.1	0.9	8	158.5	14.6	
30	73PCG	65540-505-31	3	4846.3	3	0.0	0	0.0	0.0	3	19.7	3.5	

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER OF FAULTS	MEAN TURN AROUND TIME	NUMBER OF REPAIRS	MEAN TURN AROUND TIME	NUMBER OF WRTS	MEAN TURN AROUND TIME (DAYS)	SHOP MAINTENANCE MAN HOURS	
											NO FAULT	NC FAULT
30	73PCL166545-505-1		3	4846.3	1	15.0	0	0.0	2	6.0	2.0	
30	73PCT166545-505-1		1	14539.0	0	0.0	1	84.0	0	0.3	1.1	
30	73PCJ1665455261		5	2957.8	0	0.0	1	16.0	2.0	4	7.2	6.0
30	73PCB16655-526-21		1	14539.0	0	0.0	0	2.0	0.0	1	2.0	0.3
30	73PCK16655050621		12	1211.6	2	4.5	8	4.7	2	5.7	7.7	
30	73PCH166555-505-21		5	2957.8	0	0.0	2	4.2	0.7	3	3.9	4.3
30	73PCL166505-505-1		9	1615.4	1	1.0	1	6.0	14.0	7	11.3	13.0
30	73PCD188500-505-151		5	2907.8	0	0.0	2	2.7	0.7	3	4.7	2.1
30	73PCC188500-505-21		2	7269.5	0	0.0	0	0.0	0.0	2	42.3	4.0
30	73PCD188500-505-41		1	14539.0	0	0.0	0	0.0	0.0	1	60.0	2.0
30	73PCC18855050651		80	181.7	8	2.0	264.1	20	51.8	14	52	28.6
30	73PCD188560-505-41		42	346.2	3	6.0	24	60.7	1.6	15	20.5	57.4
30	73PCC188560-505-41		41	14539.0	0	0.0	0	0.0	0.0	1	55.0	4.0
30	73PCD18856050641		15	969.3	3	22.7	0	0.0	1	11	15.5	22.3
30	73PCC188700-505-21		1	14539.0	0	0.0	0	0.0	0	1	28.0	2.0
30	73PCC188850-505-51		1	14539.0	1	14.0	0	0.0	0	0	0.0	4.0
30	73PCE16655-505-71		4	3634.7	0	0.0	2	7.7	0.7	2	12.0	2.3
30	73PCC188653-505-81		1	14539.0	0	0.0	0	0.0	0.0	1	19.0	1.0
30	73PCE188865-505-121		2	7269.5	0	0.0	1	25.2	0.7	1	0.5	2.7
30	73PCG16685-505-121		1	14539.0	0	0.0	0	0.0	0	0	0.0	0.7
30	73PCE188865506131		29	501.3	3	10.8	3	59.2	0.7	0	17	46.4
30	73PCG188900-505-41		44	330.4	8	8.0	11.5	14	162.7	0.7	24	83.5
30	73PCE188900-505-41		1	14539.0	0	0.0	0	0.0	0.0	1	6.0	32.2
30	73PCC188900C050641		11	1321.7	2	10.5	2	49.5	0.6	7	171.3	9.7
30	73PCH188925-505-41		3	4646.3	2	13.0	2	2.0	0.0	1	5.0	3.0
30	73PCJ1893050651		2	7269.5	0	0.0	0	0.0	0	2	7.0	1.0
30	73PCK1893550651		11	1321.7	1	125.0	7	10.9	0.6	3	43.7	7.3
30	73PCH189400-505-21		1	14539.0	0	0.0	0	0.0	0.0	1	28.0	1.0
30	73FCF189400-505-71		4	3634.7	3	5.7	0	0.0	0	1	6.0	7.3
30	73PCJ189355066-61		1	14539.0	0	0.0	0	0.0	0	1	116.0	2.0
40	73RDQ11693-505-1		1	14539.0	1	1041.0	0	0.0	0	0	0.0	0.7
40	73PDC1169350661		1	14539.0	0	0.0	0	0.0	0.0	0	0.0	0.5
40	73PDB165100-505-21		2	7269.5	0	0.0	0	0.0	0.0	2	3.5	1.4
40	73PDB165395-505-21		88	165.2	4	273.7	19	65.7	1.1	65	48.0	141.4
40	73PDR165395-505-21		1	14539.0	0	0.0	0	0.0	0	1	1.0	2.5
40	73PDA16539550621		88	165.2	2	2.0	0	0.0	0	1	87	83.6
40	73PDB15400-505-21		7	2077.0	2	2.0	0	0.0	0.0	0	0.0	4.0
40	73PDA165400-505-21		0	0.0	0	0.0	0	0.0	0.0	0	0.0	0.0
40	73PDB16540050621		46	302.9	2	6.0	46.0	2.5	45	31.9	47.3	
40	73PDD166209-505-1		1	14539.0	0	0.0	0	0.0	0	1	0.0	0.5
40	73PDR16620-505-1		2	7269.5	2	15.5	0	0.0	0	0	0.0	3.0
40	73PDA166700-505-31		2	7269.5	2	0.0	0.0	0.0	0.0	2	4.0	4.0
40	73PDB166700-505-31		1	14539.0	0	0.0	0	0.0	0	1	27.0	0.5
40	73PDC166700-505-31		1	14539.0	0	0.0	0	0.0	0	1	1.0	0.3
40	73PDA156700-505-31		1	14539.0	0	0.0	0	0.0	0	0.0	0.0	0.5

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER SHOP NO FAULT	MEAN TURN AROUND TIME	NUMBER NRTS	MEAN TURN AROUND TIME						
40	73PDC	66760-505-31	2	7269.5	2	0.0	1	1.8	1	1042.0	8	1	1042.0	8
40	73PDA	66765-505-31	4	3634.7	2	0.0	0	0.0	4	2.1	34	4	2.1	34
40	73PDL	66753-505-1	3	4846.3	2	0.0	0	0.0	3	19.3	11	1	19.3	11
40	73PDE	66723-505-1	1	14539.0	2	0.0	0	0.0	1	7.0	5	1	7.0	5
40	73PDD	66719-505-1	6	2423.2	2	0.0	0	0.0	6	5.8	3	5.8	3	
40	73PDC	66711-506-11	73	199.2	2	0.0	31	23.5	42	46.1	66	42	46.1	66
40	73PDD	65711-505-11	2	7269.5	2	0.0	1	34.0	1	34.0	67	1	34.0	67
40	73PDC	55711-505-11	13	1118.4	2	0.0	6	19.3	7	11.0	67	7	11.0	67
40	73PDD	65711-506-11	1	14539.0	2	0.0	0	0.0	1	1041.0	10	1	1041.0	10
40	73PDC	56711-506-11	36	403.9	2	0.0	1	15.0	35	40.2	29	1	15.0	29
40	73PDF	55737-505-31	4	3634.7	2	0.0	0	0.0	4	2.0	21	2	2.0	21
40	73PDJ	55737-505-31	1	14539.0	2	0.0	1	2.0	0	0.0	0	0	0.0	0
40	73PDF	55735-505-31	3	4846.3	2	0.0	0	0.0	3	1.7	13	1	1.7	13
40	73PDC	67711-505-1	1	14539.0	2	0.0	0	0.0	1	2.0	5	1	2.0	5
40	73PDD	57554-401-21	1	14539.0	1	13.0	0	0.0	0	0.0	0	0	0.0	0
40	73PDE	6894CC50611	29	501.3	2	13.5	3	44.3	24	9.3	26	7	9.3	26
40	73PDC	885-505-41	1	14539.0	1	7.0	1	0.0	0	0.0	0	0	0.0	0
50	73PEA	12555-21	2	7269.5	2	0.0	1	5.0	1	2.0	12	1	2.0	12
50	73PFP	65355-505-21	1	14539.0	2	0.0	0	0.0	1	2.0	7	1	2.0	7
50	73PEA	16514-2	1	14539.0	1	3.0	0	0.0	0	0.0	0	0	0.0	0
50	73PFB	659-505-1	1	14539.0	2	0.0	0	0.0	0	0.0	0	0	0.0	0
50	73PEA	16590-506-21	14	1038.5	1	57.0	8	8.1	5	11.8	76	7	11.8	76
50	73PFB	659-505-21	1	14539.0	2	0.0	0	0.0	0	0.0	0	0	0.0	0
50	73PEA	16510-505-21	1	14539.0	2	0.0	0	0.0	1	1.0	5	1	1.0	5
50	73PFP	65355-505-21	1	14539.0	2	0.0	0	0.0	1	1.0	5	1	1.0	5
50	73PFW	659-505-21	1	14539.0	2	0.0	1	16.0	0	0.0	0	0	0.0	0
50	73PEA	16590-506-21	63	230.8	3	13.0	16	17.9	44	38.0	39	0	38.0	39
50	73PFB	659-505-21	19	765.2	1	51.0	8	11.8	10	14.2	96	8	11.8	96
50	73PFE	659-506-21	3	4846.3	2	0.0	1	289.0	2	4.0	16	2	4.0	16
50	73PEL	65925-506-21	2	7269.5	2	0.0	0	0.0	2	41.5	6	2	41.5	6
50	73PEN	659-50-506-21	1	14539.0	2	0.0	0	0.0	1	1.0	5	1	1.0	5
50	73PFP	65555-50621	1	14539.0	2	0.0	0	0.0	0	0.0	0	0	0.0	0
50	73PFG	659-505-1	3	4846.3	2	0.0	0	0.0	3	15.3	6	1	15.3	6
50	73PEH	65972-505-31	1	14539.0	2	0.0	0	0.0	1	25.0	20	1	25.0	20
50	73PFS	65980-505-21	3	4846.3	2	0.0	0	0.0	3	3.3	7	3	3.3	7
50	73PFT	65990-505-41	4	3634.7	2	0.0	0	0.0	4	18.0	25	1	18.0	25
50	73PFP	66015-505-24	1	14539.0	2	0.0	0	0.0	1	5.0	3	1	5.0	3
50	73PEW	66335-5062	2	7269.5	2	0.0	0	0.0	0	0.0	0	0	0.0	0
50	73PFI	66440-505-1	1	14539.0	2	0.0	0	0.0	1	5.0	5	1	5.0	5
50	73PFW	65555-5061	23	632.1	2	0.0	0	0.0	22	12.4	10	2	12.4	10
50	73PPF	65555-50621	14	1038.5	1	14539.0	1	246.0	11	117.9	91	13	117.9	91
50	73PFD	166160-505-1	1	14539.0	2	0.0	0	0.0	1	1.0	3	1	1.0	3
50	73PKI	65765-505-1	4	3634.7	2	0.0	0	0.0	4	11.0	23	1	11.0	23
50	73PER	1661705061	23	632.1	2	0.0	0	0.0	20	9.1	19	1	9.1	19
50	73PFI	65375-505-21	4	3634.7	2	0.0	0	0.0	22.2	12.2	10	3	12.2	10
50	73PEW	65380-505-0	1	14539.0	2	0.0	0	0.0	263.0	1.0	1	3	1.0	1
50	73PFEJ	166380-505-1	4	3634.7	2	0.0	0	0.0	263.0	1.0	1	3	1.0	1

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	MEAN TURN AROUND TIME	NUMBER OF FAULTS	MEAN TURN AROUND TIME	MEAN TIME TO REPAIR (HRS)	NUMBER OF WORKERS	MEAN TURN AROUND TIME (DAYS)	MEAN MAINTENANCE MAN HOURS
50	73PFC	1553855261	23	532.1	0	0	0.0	2.4	15.1	14.7	
50	73PFD	0166340-5C5-21	2	7269.5	2	0	0.0	0.0	2	3.0	1.0
50	73PFB	73FB	1	14539.0	0	0	0.0	0.0	0	0.0	0.7
50	73PFR	85370-5C5-1	2	7269.5	0	0	0.0	0.0	2	4.0	1.0
50	73PFA	89450-5C5-41	1	14539.0	0	0	0.0	0.0	0	0.0	0.7
50	73PFG	85450-5C5-41	1	14539.0	0	0	0.0	0.0	0	0.0	1.0
50	73PFL	85465-5C5-1	1	14539.0	0	0	0.0	0.0	1	25.0	1.0
50	73PEV	89460-5C5-21	1	14539.0	0	0	0.0	0.0	1	3.0	0.3
50	73PAH	125354511	56	220.3	2	5.0	11	13.0	53	6.2	45.9
50	73PAH	42400-4C1-31	3	4646.3	0	0	0.0	0.0	3	3.3	0.8
60	73PAH	42420-4C1-11	8	1617.4	0	0	0.0	0.0	8	0.9	3.3
50	73PHB	424624C111	34	427.6	1	3.0	19	18.0	14	7.1	16.5
50	73PHC	167515-5C5-41	76	227.7	1	11.0	22	33.7	47	29.8	
50	73PHH	80211-505-101	1	14539.0	0	0	0.0	0.0	0	0.0	0.7
70	73PKQ	1413202002	26	519.2	0	0	0	28.9	0.7	21	10.6
70	73FKD	452-3721-301	1	14539.0	0	0	0	0.0	1	2.0	0.3
70	73PKP	1476066-222	5	2927.6	0	0	0.0	0.0	5	3.6	3.3
70	73PKG	65205261	12	1211.6	0	0	0.0	0.0	12	9.9	9.1
70	73PKF	16520550621	8	1817.4	0	0	0.0	80.2	0.8	5.7	5.5
70	73PKJ	65210-505-21	17	855.2	0	0	0.0	0.0	17	3.4	12.0
70	73PKE	165235-505-21	5	2927.8	0	0	0.0	0.0	5	7.8	3.8
70	73PKD	6524C-505-1	11	1321.7	0	0	0.0	0.0	11	4.2	6.1
70	73PKC	165245-505-1	1	14539.0	0	0	0.0	0.0	1	3.0	0.3
70	73PKL	1674050611	1	14539.0	0	0	0.0	0.0	1	3.0	2.0
70	73PKH	124550521	1	14539.0	0	0	0.0	0.0	1	20.0	0.8
70	73PKB	18740-505-1	8	1817.4	0	0	0.0	0.0	7	4.9	6.4
70	73PKH	87445-505-21	42	346.2	0	0	0.0	0.0	32	42.4	26.3
70	73PKM	157245-505-1	2	7269.5	0	0	0.0	0.0	0	0.0	0.7
70	73PKH	8725-506-21	11	1321.7	0	0	0.0	0.0	11	5.4	4.9
70	73PKF	16747550611	30	484.6	2	3.0	0	88.0	0.9	25	4.5
70	73PKF	16727550641	1	14539.0	0	0	0.0	0.0	1	0.5	2.0
70	73PKH	167300-5C5-11	3	4846.3	0	0	0.0	0.0	1	6.0	0.5
70	73PK3	167300-5C5-51	1	14539.0	0	0	0.0	0.0	3	3.0	1.5
70	73PK1	167300-5C5-51	3	4846.3	0	0	0.0	0.0	0	0.0	2.7
70	73PKU	87300-5C5-51	1	14539.0	0	0	0.0	0.0	0	0.0	2.7
70	73PK1	167300-5C5-51	1	14539.0	0	0	0.0	0.0	1	25.0	1.0
70	73PKD	87300-5C5-51	1	14539.0	0	0	0.0	0.0	1	6.0	0.3
70	73PKK	167325-505-1	10	1453.9	0	0	0.0	0.0	10	1.9	5.8
70	73PKA	87330-5C5-11	29	521.3	0	0	0.0	0.0	29	7.0	41.8
70	73PKH	187330-505-11	1	14539.0	0	0	0.0	0.0	1	15.0	0.5
70	73PKA	8733052611	18	807.7	0	0	0.0	0.0	18	5.2	11.3
70	73PKN	18745-505-21	1	14539.0	0	0	0.0	0.0	1	1.0	0.5
70	73PKM	1874355611	23	632.1	0	0	0.0	0.0	19	59.7	12.3

AMERICAN AIRLINES
COPY FURNISHED TO DOD

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER NO FAULT	MEAN TURN AROUND TIME	NUMBER SHOP REPAIRS	MEAN TURN AROUND TIME	NUMBER OF WORKS	MEAN TURN AROUND TIME	NUMBER OF WORKS	MEAN TURN AROUND TIME
70	73PKL	87440-505-11	22	560.9	2	36.5	13	13.7	6.7	7	12.9	13.1
70	73PKC	87440-505-11	2	7269.5	2	0.0	0	0.0	2	4.0	1.0	
70	73PKL	87440-505-21	25	581.6	2	32.5	1	46.0	1.3	22	7.7	16.2
70	73PKD	874470-505-1	16	908.7	0	0.0	0	0.0	0	16	4.3	11.4
70	73PKP	874475061	1	14539.0	0	0.0	0	0.0	1	2.0	1.0	
70	73PKD	874725061	1	14539.0	0	0.0	0	0.0	1	2.0	0.3	
70	73PKC	87480-505-1	2	7269.5	2	0.0	0	0.0	2	1.5	1.0	
90	73PMJ	00-505-1	1	14539.0	0	0.0	0	0.0	1	8.0	2.0	
90	73PMC	187915051	2	7269.5	0	0.0	0	0.0	2	6.5	1.3	
90	73PMF	474-036-006	4	3634.7	0	0.0	0	0.0	4	15.5	3.1	
90	73PMG	474-036-007	2	7269.5	0	0.0	0	0.0	2	0.7	0.6	
90	73PMH	4740035025	1	14539.0	0	0.0	0	0.0	1	3.0	1.0	
90	73PMC	47910-505-41	1	14539.0	0	0.0	0	0.0	1	12.0	0.5	
90	73PME	54188025-00-5	1	14539.0	0	0.0	0	0.0	1	2.0	1.0	
90	73PMB	65890-506-11	10	14539.0	0	0.0	2	14.9	1.3	8	2.0	5.9
90	73PMA	87075-505-1	1	14539.0	0	0.0	0	0.0	1	2.0	2.0	
90	73PMC	871050641	3	4846.3	0	0.0	0	0.0	3	0.3	1.5	
90	73PMA	87150-506-1	1	14539.0	0	0.0	0	0.0	1	1.0	0.3	
90	73PMC	871850-505-41	1	14539.0	0	0.0	0	0.0	1	2.0	1.0	
90	73PME	87650-505-1	1	14539.0	0	0.0	0	0.0	1	2.0	0.0	
90	73PMD	878850-506-51	1	14539.0	0	0.0	0	0.0	0	0.0	4.8	
90	73PMA	87850-50551	1	14539.0	0	0.0	0	0.0	0	0.0	0.5	
90	73PME	8785050651	1	14539.0	0	0.0	0	0.0	1	1.0	0.3	
90	73PMA	8787550621	63	230.8	0	0.0	0	0.0	63	22.6	33.6	
90	73PMD	87880-505-21	2	7269.5	2	0.0	0	0.0	2	1.0	1.0	
90	73PMJ	87910-506-1	22	660.9	3	8.0	2	519.5	0.7	17	44.5	23.3
90	73PMC	8791050641	41	354.6	2	6.5	0	0.0	39	4.4	45.3	
90	73PME	88025-505-51	70	267.7	3	22.3	19	203.2	0.7	48	56.3	43.9
90	73PMA	88025-505-51	3	4846.3	0	0.0	0	0.0	3	21.0	1.5	
90	73PME	88025-505-51	12	1211.6	0	0.0	0	0.0	12	2.7	8.3	
90	73PMA	88025-505-51	3	4846.3	0	0.0	0	0.0	3	1.7	3.0	
90	73PME	88205-505-41	49	296.7	0	0.0	0	0.0	49	7.4	55.6	
100	73PPQ	194C0-505-41	1	14539.0	0	0.0	0	4.0	2.7	0	0.0	5.5
100	73PPB	326-105620-5	4	3634.7	0	0.0	0	0.0	2	4.4	2.0	
100	73PPD	326-105611-10	1	14539.0	0	0.0	0	0.0	71.0	6.0	6.0	
100	73PPC	362-10561-1	16	906.7	0	0.0	5	44.6	0.7	11	17.5	11.3
100	73PPE	362-105833-8	1	14539.0	0	0.0	0	0.0	0	0.0	0.0	
100	73PPA	362-105220-1	1	14539.0	0	0.0	0	0.0	1	1.0	0.5	
100	73PPD	362-105615-1	5	297.8	0	0.0	0	0.0	3	4.7	2.9	
100	73PPC	362-106216-1	1	14539.0	0	0.0	0	0.0	68.0	0.7	0.7	
100	73PPD	362-105215-1	1	14539.0	0	0.0	0	0.0	0	0.0	0.3	
100	73PPC	362-106216-1	2	7269.5	2	0.0	0	0.0	2	2.7	1.3	
100	73PPD	362-105215-10	12	1211.6	1	0.0	0	0.0	11	7.3	7.3	
100	73PPB	342-105215-10	1	14539.0	0	0.0	0	0.0	1	4.0	0.3	
100	73PPD	342-106215-10	1	14539.0	0	0.0	0	0.0	1	4.0	1.5	

03/09/79

LRU	WUC	PART NUMBER	NUMBER OF SHOP DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER OF NO FAULT DEMANDS	MEAN TURN AROUND TIME	NUMBER OF REPAIRS	MEAN TURN AROUND TIME TO REPAIR	NUMBER OF NETS	MEAN TURN AROUND TIME	NUMBER OF NETS	MEAN TURN AROUND TIME	SHOP MAINTENANCE MAN HOURS
100	73PPC	342105604-2	1	14539.0	0	0.0	0	0.0	1	1.0	0	0.5	
100	73PPD	3421062161H	4	3636.7	0	0.0	0	0.0	4	6.2	1.0		
110	73PQD	667050631	1	14539.0	0	0.0	1	2.0	3.5	0	0.3	3.5	
999	73PEF	3561-393300	1	14539.0	0	0.0	0	0.0	1	0.5	0.3		
			2747	5.3	194	52.0	558	86.9	2.3	1995	35.2	3937.7	

NETS RATE (%) :- : 72.6

MEAN TIME BETWEEN REPAIR (MIBR) :- : 5.7

XNRTS2 = 1.0

STRIKE CAMERA
ORGANIZATIONAL LEVEL
MAINTAINABILITY SUMMARY

03/09/79

LOCATION: SUMMARY
FLIGHT HOURS: 14539.0

END OF MONTH AIRCRAFT INVENTORY: 77
TIME FRAME: SUM

SORTIES: 6037

LRU	FLIGHT LINE	MEAN TIME BETWEEN MAINT	NUMBER CND AS	MEAN % OF MAINT	CANN AS	MEAN % OF MAINT	NUMBER CND AS	MEAN % OF MAINT	NUMBER CND AS	MEAN % OF MAINT
10	190	76.5	2	1.1	0	0.0	11	1.4	201	1.1
999	29	501.3	8	27.6	1.7	0	0.0	0.1	5	3.5
219	66.4	10	4.6	1.6	0	0.0	16	2.0	201	1.1

CND RATE (% OF SORTIES)-----| 0.2

MEAN TIME BETWEEN DEMANDS-----| 72.3

SORTY SUCCESS RATE (%)-----| 100.0

STRIKE CAMERA
INTERMEDIATE LEVEL
(LRU) MAINTAINABILITY SUMMARY

03/09/79

LOCATION: SUMMARY
FLIGHT HOURS: 14539.0

END OF MIRTH AIRCRAFT INVENTORY: 77

TIME FRAME: SUM

LRU	PERC	NUMBER	MEAN TIME BET EFN ARRIVALS	NUMBER OF SHIP FAULTS	PERCENT OF FAULT ARRIVALS	MEAN TURN AROUND TIME (DAYS)	NUMBER SHOP REPAIRS	MEAN TURN AROUND TIME (DAYS)	NUMBER NHTS	MEAN TURN AROUND NHTS (DAYS)	NUMBER NHTS	MEAN TURN AROUND NHTS (DAYS)
10 1774A.0	1	14539.0	0	0.0	0.0	1	5.0	0.5	0	0.0	0	0.5

NHTS RATE (%): 0.0

MEAN TIME BETWEEN REPAIR (MTRR): 14539.0

MEAN TURN AROUND TIME (MTAT): 5.0

CONFIRMED FAILURES PER FLIGHT: 0.000

41 XNHTS2 = 0.0

STRIKE CAMERA
INTERMEDIATE LEVEL
SRU MAINTAINABILITY SUMMARY

LOCATIONS SUMMARY
FLIGHT HOURS: 14539.0

TIME FRAMES: SUM
END OF MONTH AIRCRAFT INVENTORY: 77

03/09/79

LRU	MUC	PART NUMBER	NUMBER OF SHOP DEMANDS			MEAN TIME BETWEEN DEMANDS			NUMBER OF FAULTS			MEAN TURN AROUND TIME			NUMBER OF REPAIRS			MEAN TURN AROUND TIME			NUMBER OF NRYS			MEAN TURN AROUND TIME			NUMBER OF NRYS		
			NO	FAULT	NO FAULT	MEAN	TIME	BETWEEN	NO	FAULT	NO FAULT	MEAN	TIME	TURN	AROUND	TO	REPAIR	MEAN	TIME	TURN	AROUND	TO	REPAIR	MEAN	TIME	TURN	AROUND	TO	REPAIR
10	77AAE11193C500		1		1	14539.0			0	0.0	0	1	4.0	1.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11190RA6		1		1	14539.0			0	0.0	0	1	2.0	3.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193B62		8		8	1617.4			0	0.0	0	0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193B86		53		53	274.5			7	4.6	46	46	86.3	1.7			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193B8A		2		2	7269.5			0	0.0	0	2	4.5	1.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193B88		73		73	199.2			4	5.7	69	3.5	1.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0		
10	77AAD11193B88		1		1	14539.0			0	0.0	0	1	22.0	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193B88		25		25	581.6			0	0.0	0	25	3.0	1.3			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193B8A		1		1	14539.0			0	0.0	0	1	14.0	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193B88		13		13	1118.4			0	0.0	0	13	4.0	1.2			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAD11193B88		1		1	14539.0			0	0.0	0	1	1.0	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193B88		13		13	1118.4			0	0.0	0	12	2.6	1.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAD11193C50		5		5	2907.8			0	0.0	0	5	275.3	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193C50		3		3	4846.3			0	0.0	0	3	2.0	1.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAD11193C50		56		56	259.6			2	3.5	54	23.9	0.6			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0		
10	77AAE11193C50		1		1	14539.0			0	0.0	0	1	4.0	1.2			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAD11193C50		34		34	427.6			0	0.0	0	34	1.3	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193C50		1		1	14539.0			0	0.0	0	1	1.0	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193C50		41		41	3544.6			0	0.0	0	41	3.6			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0		
10	77AAE11193C50		1		1	14539.0			0	0.0	0	1	0.5	0.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAD11193C500		14		14	1038.5			0	0.0	0	14	2.5	0.6			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193C86		1		1	14539.0			0	0.0	0	1	1.0	0.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAC11193D4		12		12	1211.6			7	0.0	0	0	0.0	0.0	0.0		0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAK11193D5		3		3	4846.3			8	0.0	0	10	6.4	4.1			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193D50		11		11	1321.7			2	0.0	0	10	10.0	7.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAF11193D50		1		1	14539.0			0	0.0	0	1	0.5	0.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193D50		10		10	14539.0			1	0.0	0	9	2.3	1.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAD11193D50		1		1	14539.0			0	0.0	0	9	1.0	0.5			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193D6		2		2	7269.5			2	0.0	0	10	10.0	7.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193D8		2		2	7269.5			0	0.0	0	11	4.7	1.3			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAC11193D4		51		51	285.1			14.5			1	0.0	0.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193D50		1		1	14539.0			0	0.0	0	1	1.0	0.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193D50		3		3	4846.3			0	0.0	0	1	0.7	1.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAH11193D6		2		2	7269.5			0	0.0	0	10	10.0	7.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193D8		2		2	7269.5			0	0.0	0	11	4.7	1.3			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAC11193D4		1		1	14539.0			0	0.0	0	1	1.0	0.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAK11193D5		1		1	14539.0			0	0.0	0	1	0.7	1.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAE11193D50		2		2	7269.5			0	0.0	0	10	10.0	7.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAA11193D6		1		1	14539.0			0	0.0	0	11	4.7	1.3			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	
10	77AAC11193D4		3		3	4846.3			0	0.0	0	1	0.7	1.0			0.0	0.0	0.0	0.0	0		0.0	0.0	0.0	0.0	0.0	0.0	

03/09/79

LRU	MUC	PART NUMBER	NUMBER OF DEMANDS	MEAN TIME BETWEEN DEMANDS	NUMBER OF FAULTS	MEAN TURN AROUND TIME	NUMBER OF REPAIRS	MEAN TURN AROUND TIME	NUMBER OF FAULTS	MEAN TURN AROUND TIME	NUMBER OF FAULTS	MEAN TURN AROUND TIME	NUMBER OF FAULTS	MEAN TURN AROUND TIME	NUMBER OF FAULTS	MEAN TURN AROUND TIME	NUMBER OF FAULTS	MEAN TURN AROUND TIME
10	177AAAI119366		1	14539.0	0	0.0	1	1.0	1	1.5	0	0.0	3	0	0	0.0	0	0.0
10	177AAD11196650		1	14539.0	0	0.0	1	0.5	1	1.0	0	0.0	1	0	0	0.0	0	0.0
10	177AAAI1198888		3	4866.3	0	0.0	3	0.3	1	1.5	0	0.0	4	5	0	0.0	0	0.0
10	177AAFI12E42000A01		20	726.9	6	1.2	13	10.7	2	7	1	78.0	56	7	0	0.0	0	0.0
10	177AAD11993650		3	4866.3	0	0.0	3	2.2	1	0.0	0	0.0	5	0	0	0.0	0	0.0
10	177AAE11993020		0	0.0	0	0.0	0	0.0	0	0.0	0	0.0	0	0	0	0.0	0	0.0
10	177AAA193888		4	3634.7	0	0.0	4	8.2	1	0.0	0	0.0	7	0	0	0.0	0	0.0
			486	29.9	28	5.1	433	16.2	14	25	9.5	953.5						

NPTS RATE (%) ----- 5.1

MEAN TIME BETWEEN REPAIR (MTBR) = 31.7

XNRTS2 = 0.0

SECTION II
RELIABILITY ANALYSIS

AN/APG-63
DRC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM R OP CND TAC
EQ NO 05 QPA=1 EH/FH=2.61
EQ FUNCTION RADAR FC
EG IDENT WUC 74FA0 LRU 00 EG DESC: RADAR SYS

MONTH	WS	OP TIME	TOTAL	MTEF	MTEVA	3 MO	3 MO	X	X	Maint	Aborts	Conds	DATE PROCESSED
YR	INV	FLT HRS	FAILS	FG HRS	EG HRS	EMTEF	EMTEVA	FAILS	NRTS	INDEX			02/17/79
78SEP	271	6320	17	543	970.3	48.1	875.1	48.4	5	2	0	0	
78AUG	298	7047	21	334	875.8	55.1	920.4	54.1	6	0	0	0	371.8
78JUL	253	5159	17	301	791.9	44.7	878.2	49.0	6	3	0	0	335.6
78JUN	265	6486	15	284	1126.6	59.6	801.2	44.8	5	2	0	0	303.4
78MAY	280	5852	20	347	763.7	44.0	765.8	43.4	6	2	0	0	432.4
78APR	267	5159	22	344	612.0	39.1	861.3	42.1	6	0	0	0	292.6
78MAR	272	5569	17	305	1114.1	47.5	1370.9	44.9	4	0	0	0	234.5
78FEB	258	4262	10	279	1112.4	39.9	1860.6	44.3	4	0	0	0	426.4
78JAN	257	4371	4	241	2852.1	47.3	1721.5	49.9	2	0	0	0	426.2
77DEC	243	4262	4	239	2781.0	46.5	1262.2	49.7	2	0	0	0	1092.8
77NOV	235	5218	13	245	1047.6	55.6	1130.6	48.3	5	0	0	0	1065.5
77OCT	135	4061	11	227	963.6	46.7	1605.8	46.9	5	10	0	0	401.4
TOTAL	253	63745	167	3494	956.3	47.7			5	2	0	0	381.7

AN/APG-63
DRC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM R OP CND TAC
EQ NO 05 QPA=1 EH/FH=2.61
EQ FUNCTION RADAR FC
EG IDENT WUC 74FA0 LRU 11 EG DESC: XMTR

MONTH	WS	OP TIME	TOTAL	MTEF	MTEVA	3 MO	3 MO	X	X	Maint	Aborts	Conds	DATE PROCESSED
YR	INV	FLT HRS	FAILS	FG HRS	EG HRS	EMTEF	EMTEVA	FAILS	NRTS	INDEX			02/17/79
78SEP	271	6320	54	71	305.5	232.3	225.9	76	85	0	0	0	
78AUG	298	7047	47	64	391.3	267.4	301.1	18H.4	73	9	23	0	117.0
78JUL	253	5158	49	79	274.7	170.4	280.2	15H.6	62	1	35	0	149.9
78JUN	255	6486	66	116	256.5	145.9	273.5	161.9	57	6	33	0	105.3
78MAY	280	5852	48	92	31P.2	164.2	271.8	167.5	52	7	36	0	98.3
78APR	267	5159	53	75	254.1	184.5	247.3	136.1	73	5	33	0	121.9
78MAR	272	5549	58	92	249.7	157.4	280.4	131.3	63	5	36	1	97.3
78FEB	258	4262	47	122	216.7	91.2	282.8	126.1	39	4	48	0	95.7
78JAN	257	4371	27	68	422.5	167.8	295.8	172.1	40	60	29	0	90.7
77DEC	243	4262	45	77	147.2	144.5	231.0	159.9	58	5	42	0	161.9
77NOV	235	5219	49	65	277.9	209.5	223.2	166.3	75	11	36	1	94.7
77OCT	155	4061	59	79	179.6	134.2	234.4	171.7	75	4	65	0	106.5
TOTAL	253	63745	602	999	276.4	166.5			60	65	36	2	105.9

THIS PAGE IS BEST QUALITY PRACTICALLY FROM COPY PUBLISHED TO DDC

THIS PAGE IS BEST QUALITY PAGE
FROM COPY FURNISHED TO DDS

AN/APG-63
DRC D STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM B OP CND TAC
EG NO 05 QPA=1 EH/FH=2.61
EQ FUNCTION RADAR FC
EQ IDENT WUC 74FFC LRU 12 EQ DESC: RECRV

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	DATA WINDOW - 12 MONTHS			DATE PROCESSED	PAGE
						MA	EQ HRS	EMTBF		
78SEP	271	6320	47	6.5	351.0	253.8	493.4	308.0	.72	6
78AUG	298	7047	27	4.8	681.2	383.2	554.4	343.5	.56	4
78JUL	253	5159	24	4.4	560.9	306.0	456.6	306.5	.55	7
78JUN	265	5486	37	5.0	457.5	338.6	439.1	317.1	.74	6
78MAY	280	5852	39	5.5	391.6	277.7	372.6	270.1	.71	4
78APR	267	5159	28	3.9	480.9	345.3	325.5	236.8	.72	110
78MAR	272	5549	49	6.6	295.6	219.6	333.5	232.8	.74	77
78FEB	258	4262	43	6.0	258.7	185.6	343.4	242.1	.72	33
78JAN	257	4371	19	5.3	600.4	345.7	406.2	293.9	.79	13
77DEC	243	4262	36	4.6	309.0	241.8	320.3	265.7	.58	42
77NOV	235	5218	74	4.4	400.6	309.5	399.1	314.1	.77	55
77OCT	135	4061	37	4.3	286.5	246.5	396.5	300.1	.86	79
TOTAL	253	63745	420	593	396.1	280.6			.71	13
									.53	1
									0	151.8

AN/APG-63
DRC D STUDY FIELD DATA ANALYSIS SUMMARY

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	DATA WINDOW - 12 MONTHS			DATE PROCESSED	PAGE
						MA	EQ HRS	EMTBF		
78SEP	271	6320	42	5.6	392.7	294.6	619.9	363.5	.75	5
78AUG	298	7047	16	3.8	1149.5	484.0	774.3	413.4	.42	21
78JUL	253	5158	20	3.9	673.1	345.2	570.8	321.6	.51	54
78JUN	265	5486	27	4.1	627.0	412.9	485.8	304.4	.66	37
78MAY	280	5852	33	6.2	462.8	246.6	419.6	258.8	.53	34
78APR	267	5159	34	4.7	396.0	286.5	383.1	238.2	.72	38
78MAR	272	5549	36	5.8	402.3	249.7	393.8	210.3	.62	40
78FEB	258	4262	32	5.9	347.6	188.5	361.9	172.6	.54	56
78JAN	257	4371	26	5.9	438.8	193.4	354.4	188.3	.44	14
77DEC	243	4262	35	7.7	317.8	144.5	312.8	186.0	.45	29
77NOV	235	5218	41	5.6	332.2	243.2	314.2	229.2	.73	36
77OCT	135	4061	37	5.7	286.5	186.0	286.8	223.0	.65	39
TOTAL	253	63745	379	649	439.0				.58	36
									.14	2
									0	168.2

THIS PAGE IS BEST QUALITY PRACTICALLY
FROM COPY FURNISHED TO DDC

AN/APG-63
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM A OP CND TAC
EG NO 05 GPA=1 EFM=2.61
EQ FUNCTION RADAR FC
EQ IDENT WUC 74FHO LRU 14 EQ DESCRIPT: POW SUPPLY

MONTH	WS	OP TIME	TOTAL	WTMF	WTMA	3 MO	X SH	X SH	NRTS	% %	MAINT	ABORTS	COND'S	INDEX	DATE PROCESSED	
															MTBF	FL HRS
78SEP	271	6320	4.0	58	412.4	284.4	474.7	274.5	69	57	1.2	.15	0	0	158.0	
78AUG	298	7047	5.0	50	613.1	317.1	421.7	223.8	52	62	1.2	.15	0	0	234.9	
78JUL	263	5158	5.1	57	434.3	236.6	366.5	175.6	54	84	1.2	.19	0	0	166.4	
78AUG	265	6486	5.2	103	325.5	164.4	393.7	192.7	50	32	1.2	.17	1	0	124.7	
78AUG	290	5652	4.1	100	372.5	152.7	496.8	198.3	41	51	1.0	.17	1	0	142.7	
78AUG	267	5159	7.3	34	585.4	396.0	550.3	181.7	68	44	3	.12	0	0	224.3	
78AUG	272	5569	2.3	54	629.7	172.4	514.1	154.2	27	36	1	.18	0	0	241.3	
78FEB	264	4262	2.5	67	445.0	114.7	450.6	166.6	26	57	5	.24	0	0	170.5	
78JAN	257	4371	2.4	59	475.5	195.6	475.7	250.2	41	57	7	.17	0	0	182.1	
77DEC	243	4262	2.5	45	445.0	241.6	397.1	282.7	54	46	2	.15	1	0	170.5	
77NOV	235	5218	2.7	35	504.4	359.1	380.9	297.6	77	60	14	.11	0	0	193.3	
77OCT	135	4051	3.7	44	246.5	240.9	360.1	265.4	94	55	14	.21	0	0	109.8	
TOTAL	253	63745	378	775	460.1	214.7	49	45	9	.17	3	0	0	0	168.6	

AN/APG-63
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM B OP CND TAC
EG NO 05 GPA=1 EFM=2.61
EQ FUNCTION RADAR FC
EQ IDENT WUC 74FJO LRU 15 EQ DESCRIPT: RF OSC

MONTH	WS	OP TIME	TOTAL	WTMF	WTMA	3 MO	X SH	X SH	NRTS	% %	MAINT	ABORTS	COND'S	INDEX	DATE PROCESSED	
															MTBF	FL HRS
78SEP	271	6320	1.3	15	1268.9	1049.7	1151.2	661.0	87	93	20	.07	0	0	486.2	
78AUG	298	7047	1.8	31	1021.8	591.2	1189.8	668.3	58	35	6	.08	1	0	391.5	
78JUL	253	5158	1.1	25	1223.5	538.5	678.2	617.1	44	56	0	.12	0	0	468.9	
78AUG	265	6486	1.2	17	1410.7	995.8	845.7	671.6	71	129	6	.09	0	0	540.5	
78MAY	260	5852	2.9	32	526.7	477.3	785.8	608.8	91	50	6	.17	1	0	201.8	
78APR	267	5159	1.5	19	1015.8	708.7	904.6	630.2	60	63	5	.11	0	0	396.6	
78MAR	272	5549	1.3	20	1114.1	724.1	804.7	597.0	65	75	15	.09	0	0	426.8	
74FEB	258	4262	1.7	23	654.5	483.6	764.9	601.0	74	43	13	.09	0	0	250.7	
78JAN	257	4371	1.6	19	600.4	400.7	695.2	68	5	11	0	0	0	0	273.2	
77DEC	243	4262	1.1	16	1011.3	794.6	803.2	640.6	79	36	0	.07	0	0	387.5	
77NOV	235	5218	1.6	19	851.2	716.8	721.8	584.9	84	47	5	.10	0	0	326.1	
77OCT	135	4061	1.7	27	623.6	481.2	725.9	519.0	77	100	9	.22	0	0	238.9	
TOTAL	253	63745	186	256	894.5	649.4	73	66	9	.10	2	0	0	0	342.7	

AN/APG-63
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM B OP CMND TAC
EQ NO 05 QPA=1 EH/FH=2.61
EQ FUNCTION RADAR FC
EQ IDENT WUC 74FKD LRU 16 EQ DESCRIPT: CONTROL

MONTH YR	WS INV	OP TIME FLT HRS	TOTAL FAILS	TOTAL MA	MTBF EQ HRS	MTBMA EQ HRS	3 MO EMTRF	3 MO EMTBMA	FAILS	% SH NRTS	% SH REPS	MAIN INDEX	ABORTS	COND'S	MTBF FL HRS
78SEP	271	6320	3	7	5498.4	2356.5	4395.5	120H.8	43	29	471	.01	0	0	2106.7
78AUG	298	7047	6	18	3065.4	1021.8	4434.9	1189.8	33	0	11	.01	0	0	1174.5
78JUL	253	5158	2	15	6731.2	897.5	4566.5	1343.1	13	7	7	.01	0	0	2579.0
78JUN	265	6486	3	9	5642.8	2116.1	4566.7	1574.7	38	50	0	.01	0	0	2162.0
78MAY	290	5852	5	11	3054.7	1388.5	3929.2	1490.4	45	36	9	.00	0	0	1170.4
78APR	267	5159	2	10	6732.5	1346.5	4884.0	1447.1	20	0	0	.01	0	0	2579.5
78MAR	272	5549	4	8	3620.7	1810.4	4626.9	1850.8	50	38	0	.02	0	0	1387.3
78FEB	258	4262	2	9	5561.9	1236.0	8614.0	1771.4	22	44	11	.02	0	0	2131.0
78JAN	257	4371	2	3	5704.2	3802.8	9037.8	2410.1	67	0	0	.00	0	0	2185.5
77DEC	243	4262	0	7	1589.1	8835.5	2078.9	0	0	0	.01	0	0	0	2609.0
77NOV	235	5218	2	5	6809.5	2723.8	4846.4	1995.6	40	40	20	.01	0	0	2030.5
77OCT	135	4061	2	5	5229.6	2119.8	2294.0	1284.6	40	0	0	.01	0	0	1931.7
TOTAL	253	63745	33	106	5041.6	1563.6	31	19	37	.01	0	0	0	0	1931.7

AN/APG-63

DRCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM B OP CMND TAC
EQ NO 05 QPA=1 EH/FH=2.61
EQ FUNCTION RADAR FC
EQ IDENT WUC 74FPX LRU 07 EQ DESCRIPT: WGUIDE COMPS

MONTH YR	WS INV	OP TIME FLT HRS	TOTAL FAILS	TOTAL MA	MTBF EQ HRS	MTBMA EQ HRS	3 MO EMTRF	3 MO EMTBMA	FAILS	% SH NRTS	% SH REPS	MAIN INDEX	ABORTS	COND'S	MTBF FL HRS
78SEP	271	6520	0	3	5498.4	8058.4	4029.2	0	0	0	0	.00	0	0	0
78AUG	298	7047	0	1	18392.7	8130.6	4878.4	0	0	0	0	.00	0	0	859.7
78JUL	253	5158	6	8	2243.7	1688.8	5708.1	2536.9	75	0	0	.00	0	0	2926.0
78JUN	265	6486	0	1	16928.5	5708.4	2686.3	0	0	0	0	.00	0	0	859.8
78MAY	280	5852	2	9	7636.9	1697.1	4802.4	1879.2	22	0	0	.00	0	0	5549.0
78APR	267	5159	6	7	2244.2	1923.6	3552.0	2056.4	86	0	0	.01	0	0	1065.5
78MAR	272	5549	1	7	14482.9	2069.0	6169.2	2643.9	14	0	0	.00	0	0	4371.0
78FEB	258	4262	4	5	2781.0	2244.8	6731.2	4808.0	80	0	0	.00	0	0	2609.0
78JAN	257	4371	1	2	11408.3	5704.2	12050.4	6025.2	50	0	0	.00	0	0	4061.0
77DEC	243	4262	0	0	0	0	11780.7	7068.4	0	0	0	0	0	0	2771.5
77NOV	235	5218	2	4	6809.5	3404.7	11308.3	6785.0	50	0	0	.00	0	0	0
77OCT	135	4061	1	1	10599.2	10599.2	16058.0	16058.0	100	0	0	.00	0	0	0
TOTAL	253	63745	23	48	7233.7	3466.1	48	0	0	.00	0	0	0	0	0

AN/APG-63
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM B OP CMND TAC
EQ NO 05 QPA=1 EH/FH=2.61
EQ FUNCTION RADAR FC
EQ IDENT WUC 74FQ0 LRU 18 EC DSCR: R DATA FROC

MONTH	WS	OP TIME	TOTAL	MTRM	3 MO	X	SH	NRTS	MAINT	ABORTS	CONDNS	MTBF
YR	INV	FLT HRS	FAILS	EQ HRS	EMTRM	FAILS	REPS	INDEX	FL HRS			FL HRS
78SEP	271	6320	46	71	356.6	232.3	393.1	204.0	65	75	*24	0
78AUG	298	7047	43	77	427.7	258.9	366.8	151.5	56	51	*20	0
78JUL	253	5158	34	89	396.0	151.3	338.3	129.7	38	47	*32	0
78JUN	265	6486	56	156	302.3	108.5	343.4	134.3	36	31	*26	0
78MAY	280	5852	45	107	339.4	142.7	357.2	141.2	42	53	*27	1
78APR	267	5159	32	77	420.8	174.9	325.6	116.3	42	44	*25	0
78MAR	272	5549	44	122	329.4	118.7	300.9	106.4	36	34	*31	1
78FEB	258	4262	44	137	252.8	81.2	297.8	116.1	32	31	*49	0
78JAN	257	4371	35	69	326.0	128.2	331.7	158.6	39	36	*30	1
77DEC	243	4262	34	64	327.2	173.8	276.1	164.4	44	44	*26	1
77NOV	235	5218	40	75	340.5	181.6	269.4	155.6	53	55	*27	1
77OCT	135	4061	54	76	156.5	139.5	204.9	135.5	71	58	*34	0
TOTAL	253	63745	507	1140	3288.2	145.9	44	44	13	*28	5	0

AN/APG-63
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

TGT FROC AN

MONTH	WS	OP TIME	TOTAL	MTRM	3 MO	X	SH	NRTS	MAINT	ABORTS	CONDNS	MTBF
YR	INV	FLT HRS	FAILS	EQ HRS	EMTRM	FAILS	REPS	INDEX	FL HRS			FL HRS
78SEP	271	6320	50	65	329.9	253.8	335.8	229.1	77	58	*32	0
78AUG	298	7047	52	82	353.7	224.3	399.9	254.1	63	48	*32	0
78JUL	253	5158	42	64	320.5	210.3	443.3	294.6	66	55	*52	0
78JUN	265	6486	28	46	604.6	604.6	466.0	340.8	61	54	*21	0
78MAY	280	5652	33	45	462.8	339.4	432.2	315.5	73	69	*26	0
78APR	267	5159	37	43	363.9	313.1	407.0	302.9	86	77	*38	0
78MAR	272	5549	30	49	482.8	295.6	435.5	313.7	61	51	*31	0
78FEB	258	4262	29	37	303.6	300.6	388.8	297.8	78	62	*29	0
78JAN	257	4371	26	32	438.8	356.5	368.9	280.2	81	50	*26	0
77DEC	243	4262	32	44	347.6	252.8	299.5	234.1	73	70	*30	0
77NOV	235	5218	40	53	340.5	257.0	295.0	234.0	75	47	*31	0
77OCT	135	4061	46	54	230.4	196.3	274.5	226.2	85	69	*39	0
TOTAL	253	63745	445	614	373.9	271.0	72	58	22	*32	0	143.2

**THIS PAGE IS BEST QUALITY PAPER
FROM COPY PROVIDED TO DDS**

AN/AMG-20
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM 9 OF CND TAC				DATA WINDOW - 12 MONTHS				PAGE 7				
EQ NO 49	OP#1	EM/FH#1.84		PERIOD ENDING - SEP78				DATE PROCESSED	02/17/79			
EQ FUNCTION WPNS DELY				EQ DESCRIPTOR: ARM CONT SYS								
EQ IDENT WJC 75M00 LRU 00												
MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	WTBMA	3 MO	% SH	%	Maint	Aborts	Conds
YR	INV	FLT HRS	FAILS	WA	EQ HRS	EQ HRS	EMTF	RTMSA	NRTS	FAILS	REPS	INDEX
78SEP	271	6320	0	4	242.5	242.5	310.9	0	0	0	0	0
78AUG	29H	7047	0	26	498.7	498.7	386.4	6	0	0	0.02	0
78JUL	253	5158	0	29	327.5	327.5	256.5	0	0	0	0.04	0
78JUN	265	6486	0	34	351.0	351.0	266.1	0	0	0	0.05	0
78MAY	290	5852	0	67	170.9	30470.6	27544.6	506.1	0	0	0	0
78APR	267	5159	0	24	395.5	27544.6	306.1	0	0	0	0.04	0
78MAR	272	5549	1	25	10210.2	406.4	26094.6	26.0	4	0	*02	0
78FEB	258	4262	0	41	191.3	191.3	221.7	0	0	0	0.05	0
78JAN	257	4371	0	51	254.4	254.4	280.1	0	0	0	0.05	0
77DEC	243	4262	0	25	224.1	224.1	251.7	0	0	0	0.05	0
77NOV	235	5218	C	25	384.0	384.0	236.8	0	0	0	0.03	0
77OCT	135	4061	0	36	191.6	191.6	215.6	0	3	0	*11	0
TOTAL	253	63745	1	420 11720.0	279.3	0	0	0	0	*05	0	0

51

~~THIS PAGE IS BEST QUALITY TRANSMISSION
FROM COPY FURNISHED TO DDC~~

AN/AMG-20
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM 9 OF CND TAC				DATA WINDOW - 12 MONTHS				PAGE 7					
EQ NO 49	OP#1	EM/FH#1.84		PERIOD ENDING - SEPT81				DATE PROCESSED	02/17/79				
EQ FUNCTION WPNS DELY				EQ DESCRIPTOR: CONTROL ARM									
EQ IDENT WJC 75M00 LRU 11													
MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	WTBMA	3 MO	% MO	% SH	%	Maint	Aborts	Conds
YR	INV	FLT HRS	FAILS	WA	EQ HRS	EQ HRS	EMTF	RTMSA	NRTS	FAILS	REPS	INDEX	MTBF
78SEP	271	6320	3	15	3876.3	775.3	3408.6	611.6	20	73	40	*10	0
78AUG	29H	7047	1	8	12966.5	1620.8	2149.5	731.7	13	50	25	*04	0
78JUL	253	5158	6	19	1581.8	499.5	1594.3	619.1	32	37	37	*07	0
78JUN	265	6486	9	20	1326.0	596.7	1788.6	748.7	45	20	5	*05	0
78MAY	290	5852	4	13	2691.9	928.3	1904.4	692.5	31	108	38	*05	0
78APR	267	5159	5	10	1896.5	949.3	1630.3	510.1	50	120	40	*06	0
78MAR	272	5549	7	21	1456.6	486.2	1304.7	420.9	33	57	33	*09	0
78FEB	258	4262	6	23	1307.0	341.0	1248.6	447.7	26	52	17	*12	0
78JAN	257	4371	7	18	1148.9	446.8	1415.9	653.5	39	22	33	*08	0
77DEC	243	4262	6	12	1307.0	657.5	1557.2	803.7	50	75	33	*06	0
77NOV	235	5218	5	9	1920.2	1066.8	1993.0	854.2	56	33	89	*05	0
77OCT	135	4061	5	10	1494.4	747.2	2264.1	754.7	50	60	20	*05	0
TOTAL	253	63745	64	178	1832.7	658.9	36	55	*1	*07	0	0	996.0

AN/AWG-20
DRC STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM B							OP CMND TAC							DATA WINDOW - 12 MONTHS						
EQ NO 49			QPA=1				EQ/FH=1.84			EQ FUNCTION WPN S DELY			EQ IDENT WUC 75MCO LRU 12				EQ DESCRIPT: CONV-PROGMR			DATE PROCESSED 02/17/79
MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	3 MO	% SH	% SH	REPS	NRTS	Maint	ABORTS	COND S	MTBF	FL HRS			
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EMTBMA	EMTBMA	FAILS	FAILS	REPS	NRTS	INDEX	INDEX	INDEX	FL	HRS			
78SEP	271	6320	7	36	1661.3	323.0	1262.4	415.7	19	47	33	.14	0	0	902.9	0	0			
78AUG	298	7047	9	23	1444.7	563.8	955.3	419.4	39	17	26	.06	0	0	783.0	0	0			
78JUL	253	5158	11	23	862.6	412.6	731.7	338.9	48	52	13	.09	0	0	468.9	0	0			
78JUN	265	6486	16	36	745.9	331.5	619.1	338.9	44	42	6	.07	0	0	405.4	0	0			
78MAY	280	5852	17	36	633.4	299.1	648.3	390.6	47	33	6	.11	0	0	344.2	0	0			
78APR	267	5159	19	23	499.6	412.7	744.5	500.8	83	74	13	.11	0	0	271.5	0	0			
78MAR	272	5549	11	19	928.2	537.4	1043.8	567.3	58	63	37	.08	0	0	504.5	0	0			
78FEB	258	4262	7	13	1120.3	603.2	1248.8	697.8	54	69	23	.10	0	0	608.9	0	0			
78JAN	257	4371	7	14	1148.9	574.5	1061.9	653.5	50	29	21	.11	0	0	624.4	0	0			
77DEC	243	4262	5	7	1568.4	1120.3	1132.5	673.4	71	186	71	.08	0	0	852.4	0	0			
77NOV	235	5218	12	18	800.1	533.4	1195.4	569.4	67	50	17	.06	0	0	434.8	0	0			
77OCT	135	4061	5	12	1494.4	622.7	1415.1	646.9	42	142	33	.10	0	0	812.2	0	0			
TOTAL	253	63745	126	260	930.9	451.1	48	54	20	.09	0	0	505.9							

AN/AWG-20
DRC STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM B							OP CMND TAC							DATA WINDOW - 12 MONTHS							PAGE 2
EQ NO 49			QPA=1				EQ/FH=1.84			EQ FUNCTION WPN S DELY			EQ IDENT WUC 75MXX LRU 0X				EQ DESCRIPT: ARM CONT S/S			DATE PROCESSED 02/17/79	
MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	3 MO	% SH	% SH	REPS	NRTS	Maint	ABORTS	COND S	MTBF	FL HRS				
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EMTBMA	EMTBMA	FAILS	FAILS	REPS	NRTS	INDEX	INDEX	INDEX	FL	HRS				
78SEP	271	6320	12	99	969.1	117.5	852.1	149.5	12	32	47	.31	0	0	526.7	0	0				
78AUG	298	7047	10	57	129.6	227.5	614.1	155.6	18	14	54	.12	0	0	704.7	0	0				
78JUL	253	5158	18	72	527.3	131.8	473.4	116.2	25	36	29	.21	0	0	286.6	0	0				
78JUN	265	6486	28	92	426.2	129.7	435.1	122.4	30	37	20	.20	0	1	231.6	0	0				
78MAY	280	5852	22	113	489.4	95.3	461.7	129.1	19	42	22	.23	0	0	266.0	0	0				
78APR	267	5159	24	58	395.5	163.7	474.9	137.7	41	74	59	.22	0	1	215.0	0	0				
78MAR	272	5549	20	65	510.5	157.1	543.6	127.3	31	63	43	.21	0	0	277.4	0	0				
78FEB	258	4262	14	77	560.1	101.8	593.2	121.7	18	40	27	.29	0	0	304.4	0	0				
78JAN	257	4371	14	63	574.5	127.7	592.7	149.9	22	17	.25	0	0	0	312.2	0	0				
77DEC	243	4262	12	55	653.5	142.6	622.9	148.3	22	67	31	.21	0	0	355.2	0	0				
77NOV	235	5218	17	52	564.6	184.6	724.7	139.9	33	56	.14	0	0	0	306.9	0	0				
77OCT	135	4061	11	61	679.3	182.5	808.6	131.6	18	72	33	.28	0	0	369.2	0	0				
TOTAL	253	63745	202	864	580.6	135.8	23	43	35	.22	0	2	315.6								

AN/ARC-109
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM C OP CND MAC
EQ NO 01 QPA=2 EH/FH=1.20
EQ FUNCTION COMM UHF
EQ IDENT WUC 63A00 LRU 00 EQ DESCRIPTOR: UHF COMM SYS

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	% SH	% NRTS	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EMTBMA	FAILS	REPS	INDEX			FL HRS
78SEP	74	4089	1	15	9813.6	554.6	3200.0	384.0	7	7	.03	0	8178.0
78AUG	70	4137	4	28	2468.2	354.6	3397.9	368.4	14	0	.03	0	2068.5
78JUL	68	3774	4	32	2264.4	283.0	4510.3	421.0	13	0	.04	0	1887.0
78JUN	61	4831	1	23	1159.4	504.1	1201.6	560.1	4	0	.02	0	9662.0
78MAY	62	4550	2	20	5460.0	546.0	10862.4	693.3	10	0	.03	0	4550.0
78APR	65	4621	0	17	652.4	652.4	14689.2	716.5	0	0	.03	0	
78MAR	73	4407	1	10	10576.8	1057.7	12614.4	901.0	10	0	.02	0	8614.0
78FEB	75	3213	1	14	7711.2	550.8	3955.6	818.4	7	0	.02	0	6426.0
78JAN	74	2892	0	4	1735.2	1735.2	3648.3	880.6	0	0	.01	0	
77DEC	76	3784	5	11	1816.3	825.6	3530.4	688.9	45	0	.02	0	1513.6
77NOV	78	3965	2	14	4758.0	679.7	5651.5	627.9	14	0	.02	0	3965.0
77OCT	74	4019	1	16	9645.6	602.8	7262.4	704.5	6	0	.02	0	8038.0
TOTAL	71	48282	22	204	5267.1	568.0	11	0	0	.02	0	0	4389.3

53

AN/ARC-109
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM C OP CND MAC
EQ NO 01 QPA=2 EH/FH=1.20
EQ FUNCTION COMM UHF
EQ IDENT WUC 63A00 LRU 11 EQ DESCRIPTOR: REC/YMTR

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	% SH	% NRTS	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EMTBMA	FAILS	REPS	INDEX			FL HRS
78SEP	74	4089	40	45	245.3	218.1	204.3	182.3	89	44	7	.09	0
78AUG	70	4137	60	65	165.0	152.3	201.2	173.8	92	51	5	.14	0
78JUL	68	3774	41	48	220.9	186.7	227.1	194.9	85	52	15	.11	0
78JUN	61	4831	51	63	227.3	184.0	227.1	197.7	81	37	0	.11	0
78MAY	62	4550	47	51	232.3	214.1	246.9	226.3	92	45	0	.11	0
78APR	65	4621	50	56	221.8	199.0	249.0	227.7	48	0	.10	0	193.6
78MAR	73	4407	35	37	302.2	285.9	262.8	238.0	95	51	8	.09	0
78FEB	75	3213	33	36	233.7	214.2	239.7	202.9	92	39	14	.13	0
78JAN	74	2892	33	35	247.9	210.3	232.0	183.7	85	33	24	.08	0
77DEC	76	3784	38	48	239.0	189.2	203.2	158.7	79	60	0	.16	0
77NOV	78	3965	44	58	216.3	164.1	189.6	144.2	76	34	3	.10	0
77OCT	74	4019	57	72	169.2	134.0	207.5	152.1	79	58	4	.14	0
TOTAL	71	48282	524	612	221.1	169.3	86	47	6	.11	0	0	184.3

**THIS PAGE IS BEST QUALITY AVAILABLE
FROM COPY SUBMITTED TO DSC**

THIS PAGE IS BEST QUALITY PLACED
FROM COPY PREPARED TO LOG

AN/ARC-109

DRC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM C OP CNND MAC
EQ NO 01 QPA=2 EH/FH=1.20
EQ FUNCTION COMM UHF
EQ IDENT WUC 63AFC LRU 12 EQ DSCR: CONTROL

MONTH	WS	OP TIME	TOTAL	MTHF	MTEMA	3 MO	X SH	NRTS	MAINT	ABORTS	COND S	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTBF	FAILS	REPS	INDEX			FL HRS
78SEP	74	4089	10	12	961.4	817.8	654.7	83	8	.00	0	817.8
78AUG	70	4137	16	19	620.5	522.6	566.3	84	26	.01	0	517.1
78JUL	68	3774	18	20	503.2	452.9	595.7	90	5	.01	0	419.3
78JUN	61	4831	20	21	579.7	552.1	672.1	95	5	.01	1	483.1
78MAY	62	4550	15	16	728.0	682.4	857.6	775.9	94	.19	0	606.7
78APR	65	4621	15	17	739.4	652.4	964.1	734.5	88	.02	0	616.1
78MAR	73	4407	9	13	229.1	1175.2	764.5	646.9	89	.01	0	1101.8
78FEB	75	3213	11	14	701.0	550.6	515.9	456.4	79	.03	0	584.2
78JAN	74	2892	14	16	495.8	433.8	580.4	521.2	88	.01	0	413.1
77DEC	76	3784	21	22	432.5	412.8	614.0	500.3	95	.02	0	360.4
77NOV	78	3965	9	11	1057.3	865.1	565.2	441.5	82	.01	0	881.1
77OCT	74	4019	16	23	602.8	419.4	538.0	415.0	70	.02	0	502.4
TOTAL	71	48282	173	200	669.8	579.4	87	18	1	.01	1	558.2

54

AN/ARC-109

DRC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM C OP CNND MAC
EQ NO 01 QPA=2 EH/FH=1.20
EQ FUNCTION COMM UHF
EQ IDENT WUC 63AFC LRU 0X EQ DSCR: UHF COMM S/S

MONTH	WS	OP TIME	TOTAL	MTHF	MTEMA	3 MO	X SH	NRTS	MAINT	ABORTS	COND S	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTBF	FAILS	REPS	INDEX			FL HRS
78SEP	74	4089	67	91	146.5	107.8	117.1	80.9	74	.37	18	.16
78AUG	70	4137	97	136	102.4	73.0	108.4	75.7	71	.13	0	122.1
78JUL	68	3774	92	129	110.5	70.2	118.7	83.7	64	.21	9	.27
78JUN	61	4831	103	139	112.6	83.4	122.6	89.1	74	.24	14	.19
78MAY	62	4550	81	109	134.8	100.2	141.7	102.8	74	.31	6	.19
78APR	65	4621	90	129	123.2	86.0	139.9	100.6	70	.27	5	.18
78MAR	73	4407	59	79	179.3	133.9	140.9	108.7	75	.20	0	112.3
78FEB	75	3213	61	84	126.4	91.8	116.9	89.9	73	.14	0	102.7
78JAN	74	2892	59	69	117.6	100.6	117.1	86.3	86	.20	0	149.4
77DEC	76	3784	83	111	109.4	81.8	110.3	78.5	75	.19	0	105.3
77NOV	78	3965	76	116	125.2	82.0	102.8	72.1	66	.23	0	98.0
77OCT	74	4019	97	133	99.4	72.5	107.2	75.1	73	.15	0	91.2
TOTAL	71	48282	955	1325	121.3	87.5	72	10	1	.22	0	104.3

PAGE 10

PAGE 10

PAGE 10

PAGE 10

MARK V TACAN
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM C OF CND MAC
EO NO 04 GPA2 EH/FH=1.19
EQ FUNCTION NAVIGATION
EQ IDENT WUC 71L00 LRU 00 EQ DESCRIPTOR: TACAN SYS

MONTH	WS	OP TIME	TOTAL	MTBF	MTBMA	3 MO	% SH	%	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTB	FAILS	NRTS	INDEX			FL HRS
78SEP	74	4089	0	16	608.2	560.0	0	0	*.01	0	0	0
78AUG	70	4137	0	13	757.4	689.2	0	0	*.01	0	0	0
78JUL	68	3774	0	22	408.3	3130H.9	802.8	0	0	*.02	0	0
78JUN	61	4831	0	9	1277.5	33324.8	980.1	0	0	*.03	0	0
78MAY	62	4550	1	8	10829.0	1353.6	32315.6	850.4	13	0	*.01	0
78APR	65	4621	0	17	646.9	539.5	0	0	0	*.01	0	0
78MAR	73	4407	0	13	806.8	510.6	0	0	0	*.02	0	0
78FEB	75	3213	0	24	318.6	420.3	0	0	0	*.03	0	0
78JAN	74	2892	0	12	573.6	25325.6	487.0	0	0	*.02	0	0
77DEC	76	3784	0	20	450.3	26007.8	418.0	0	0	*.02	0	0
77NOV	78	3965	1	20	9436.7	471.8	14011.1	459.4	5	0	*.02	0
77OCT	74	4019	0	27	354.3	28807.5	554.0	0	0	*.02	0	0
TOTAL	71	48282	2	201	57455.6	571.7	1	0	*.02	0	0	48282.0

MARK V TACAN
DRCO STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM C OF CND MAC
EO NO 04 GPA2 EH/FH=1.19
EQ FUNCTION NAVIGATION
EQ IDENT WUC 71L00 LRU 11 EQ DESCRIPTOR: REC/XMTR

MONTH	WS	OP TIME	TOTAL	MTBF	MTBMA	3 MO	% SH	%	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTB	FAILS	NRTS	INDEX			FL HRS
78SEP	74	4089	69	77	141.0	126.4	164.1	151.9	90	27	*.13	0
78AUG	70	4137	51	51	193.1	193.1	175.3	167.5	100	31	*.10	0
78JUL	68	3774	54	60	166.3	149.7	195.7	178.9	90	35	*.11	0
78JUN	61	4831	68	70	169.1	164.3	191.5	169.2	97	56	*.13	0
78MAY	62	4550	45	285.0	240.6	192.4	160.0	84	76	20	*.10	0
78APR	65	4621	82	161.7	134.1	163.7	136.1	83	51	7	*.17	0
78MAR	73	4407	62	75	169.2	139.8	166.8	139.0	83	49	*.16	0
78FEB	75	3213	48	57	159.3	134.2	170.5	146.2	84	4	*.15	0
78JAN	74	2892	40	48	172.1	143.4	162.3	136.9	83	46	*.12	0
77DEC	76	3784	50	56	180.1	160.8	153.0	129.1	89	11	*.12	0
77NOV	78	3965	66	81	143.0	116.5	132.2	113.9	81	37	*.14	0
77OCT	74	4019	67	80	142.8	119.6	140.5	125.3	84	29	*.11	0
TOTAL	71	48282	681	782	146.9	87	44	12	*.13	0	0	141.8

THIS PAGE IS BEST QUALITY PRACTICABLE
PRINT COPY PUBLISHED TO DAS

MARK V TACAN
DRCI STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM C OP CMDN MAC
EQ NO 04 QFAE2 EM/FTH=1.19
EQ FUNCTION NAVIGATION
EQ IDENT WUC 71LCC LRU 12 EQ DIFSCR: CONTROL

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	X SH	X NRTS	MAINT	ABORTS	CONDNS	MTBF
76SEP	74	4089	2	3	4865.9	3243.9	1503.2	1241.7	67	33	.00	0	4089.0
76AUG	70	4137	7	6	1406.6	1094.0	1378.5	1166.4	78	11	.01	0	1182.0
76JUL	68	3774	10	11	898.2	815.6	1759.4	1361.3	91	9	.36	0	754.8
76JUN	61	4831	5	6	2299.6	1915.3	2563.4	1960.3	83	0	.33	0	1932.4
76MAY	62	4550	3	6	3609.7	1804.8	2693.0	1700.8	50	17	.50	0	3033.3
76APR	65	4621	5	5	2199.6	2199.6	2648.5	1165.5	100	40	.01	0	1848.4
76MAR	73	4407	4	4	2622.2	1311.1	3574.1	1191.4	50	13	.01	0	2203.5
76FEB	75	3213	2	12	3823.5	637.2	5884.0	1384.5	17	17	.01	0	3213.0
76JAN	74	2692	1	1	683.0	683.0	4220.9	2302.3	100	0	.00	0	5784.0
77DEC	76	3784	1	4	9005.9	2251.5	2334.0	1273.1	25	25	.00	0	7566.0
77NOV	78	3965	4	6	2359.2	1572.8	1474.8	903.9	67	0	.00	0	1982.5
77OCT	74	4019	7	12	1366.5	797.1	1440.4	900.2	58	17	.00	0	1146.3
TOTAL	71	45262	51	83	2253.2	1364.5	61	12	31	.00	0	0	1693.4

MARK V TACAN
DRCI STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM C OP CMDN MAC
EQ NO 04 QFAE2 EM/FTH=1.19
EQ FUNCTION NAVIGATION
EQ IDENT WUC 71LXX LRU 0X EQ DIFSCR: TACAN S/S

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	X SH	X NRTS	MAINT	ABORTS	CONDNS	MTBF
76SEP	74	4089	76	104	128.1	93.6	135.4	95.2	73	22	.56	.16	107.6
76AUG	70	4137	62	81	158.8	121.6	141.7	109.1	77	21	.47	.13	133.5
76JUL	68	3774	73	103	123.0	87.2	158.9	120.9	71	21	.57	.17	103.4
76JUN	61	4831	79	94	145.5	122.3	160.2	121.6	84	43	.57	.18	122.3
76MAY	62	4550	45	62	240.6	174.7	152.4	109.9	73	56	1.13	.14	202.2
76APR	65	4621	4	114	130.9	93.2	131.2	86.3	71	.56	.21	0	110.0
76MAR	73	4407	63	114	126.4	92.0	131.7	88.4	73	.36	.20	0	106.2
76FEB	75	3213	55	98	139.0	78.0	135.3	83.5	56	.31	.17	0	116.8
76JAN	74	2692	52	71	132.4	96.9	122.9	79.4	73	.52	.20	0	111.2
77DEC	76	3784	67	113	134.4	79.7	114.3	72.0	59	.27	.16	0	113.0
77NOV	78	3965	87	135	69.9	97.6	67.4	64	22	.33	.19	0	91.1
77OCT	74	4019	91	141	105.1	67.8	102.5	75.2	65	.33	.15	0	88.3
TOTAL	71	45262	954	1234	134.6	93.1	69	29	.52	.17	0	0	113.1

TISEO
DRCN STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM E OP CMMND TAC
EG NO 52 GPA=1 EH/FH=1*60
EG FUNCTION RECONN
FG IDENT WUC 71U00 LRU 00 EG DESC: TISEO SYS

MONTH	WS	OP TIME	TOTAL	MTBF	MTEWA		3 MO		X SH		MAINT INDEX	ABORTS	COND'S	MTBF FL HRS
					MA	FQ HRS	EQ HRS	EMTRF	EMTHA	FAILS				
78SEP	646	12969	9	76	2305.6	266.0	5023.1	226.7	12	0	.07	0	0	1441.0
78AUG	644	14407	4	124	572.5	185.9	3438.9	226.9	3	0	.08	0	0	3601.8
78JUL	628	12302	8	78	2460.4	252.3	2544.1	241.6	10	0	.07	0	0	1537.8
78JUN	655	14128	7	86	3229.3	262.8	2583.3	254.4	8	1	.05	0	0	2018.3
78 MAY	662	13321	10	99	2111.4	215.5	2614.6	263.7	10	1	.05	0	0	1332.1
78 APR	612	14530	9	79	2533.1	294.3	3744.9	260.9	11	0	.06	0	0	1614.4
78 MAR	670	14636	7	101	3345.4	231.9	6809.6	255.4	7	0	.06	0	0	2090.9
78 FEB	676	10624	1	64	16998.4	265.6	1364.6	254.5	2	0	.06	0	0	10624.0
78 JAN	694	13044	1	75	2087.4	278.3	4708.1	270.1	1	0	.05	0	0	15044.0
77 DEC	670	12944	5	91	4142.1	227.6	3239.7	248.2	5	0	.06	0	0	2588.8
77 NOV	659	15208	8	70	3041.6	312.0	3510.8	249.8	10	0	.04	0	0	1901.0
77 OCT	564	10320	6	79	2752.0	209.0	5734.8	247.4	8	0	.05	0	0	1720.0
TOTAL	657	159433	75	1032	3379.9	245.6			7	0	.06	0	0	2112.4

TISEO

DRCN STUDY FIELD DATA ANALYSIS SUMMARY
DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM E OP CMMND TAC
EG NO 52 GPA=1 EH/FH=1*60
EG FUNCTION RECONN
FG IDENT WUC 71U00 LRU 11 EG DESC: STARGEN CONV

MONTH	WS	OP TIME	TOTAL	MTBF	MTEWA		3 MO		X SH		MAINT INDEX	ABORTS	COND'S	MTBF FL HRS
					MA	FQ HRS	EQ HRS	EMTRF	EMTHA	FAILS				
78SEP	646	12969	36	45	576.4	461.1	496.0	362.8	80	47	18	.04	0	360.3
78AUG	644	14407	54	66	426.5	339.0	514.5	359.0	79	47	12	.06	0	266.8
78JUL	628	12302	78	62	518.0	317.5	367.9	351.4	61	37	25	.07	0	323.7
78JUN	665	14128	35	52	645.9	434.7	610.6	404.6	67	96	58	.05	0	403.7
78 MAY	662	15321	59	67	546.5	318.1	647.4	417.1	58	46	16	.07	0	341.6
78 APR	682	14530	36	47	645.6	694.6	649.6	445.2	77	55	15	.08	0	403.6
78 MAR	690	14636	30	41	780.6	477.9	688.6	440.9	61	39	14	.05	0	487.7
78 FEB	676	10624	32	47	531.2	361.7	623.2	406.8	68	57	4	.06	0	332.0
78 JAN	694	13044	27	43	773.0	485.4	794.0	495.6	63	58	5	.05	0	483.1
77 DEC	670	12944	35	54	591.7	583.5	560.7	370.8	65	59	19	.07	0	369.8
77 NOV	659	15208	21	36	1158.7	675.9	531.0	349.1	58	28	14	.02	0	724.2
77 OCT	564	10320	50	76	330.2	217.3	432.1	297.6	66	53	12	.11	0	206.4
TOTAL	657	159433	433	546	585.4				67	52	.06	0	0	365.9

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY SUBMITTED TO DDC

TISEO
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM E OP CMND TAC
EQ NO 52 QPA=1 EH/FH=1.60
EQ FUNCTION RECONN

EQ IDENT MUC 71UUD LRU 12 EQ DESCRIPTOR: E-0 CONV						EQ IDENT MUC 71UFO LRU 13 EQ DESCRIPTOR: STAB GENERAT							
MONTH	WS	OP TIME	TOTAL FAILS	MTBF	MTBMA	3 MO	EMTBMA	FAILS	% SH	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	MA	EQ HRS	EQ HRS	EMTBMA	EMTBMA	REPS	NRTS	Index			FL HRS
78SEP	646	12969	0	0	0	31742.4	0	0	0	0.0	0	0	0
78AUG	644	14407	0	0	0	65359.2	16334.8	0	0	0.0	0	0	0
78JUL	628	12302	0	2	22604.8	9841.6	63601.6	15900.4	0	0	0	0	0
78JUN	665	14128	1	2	11302.4	67166.4	35583.2	50	0	0	0	0	14128.0
78MAY	662	13321	0	0	0	33989.6	0	0	0	0.0	0	0	0
78APR	692	14530	0	0	0	63664.0	15916.0	0	0	0.0	0	0	0
78MAR	690	14636	0	2	16998.4	11708.8	61286.4	15321.6	0	0	0.0	0	0
78FEB	676	10624	1	2	8499.2	8499.2	58579.2	29289.6	50	0	0.0	0	0
78JAN	694	13044	0	0	0	65913.6	0	0	0	0.0	0	0	0
77DEC	670	12944	0	0	0	20518.4	0	0	0	0.0	0	0	0
77NOV	659	15208	0	1	24332.8	15798.4	0	0	0	0.0	0	0	0
77OCT	564	10320	0	2	A256.0	31541.6	12616.6	0	0	0.0	0	0	0
TOTAL	657	156433	2	11	126746.4	23044.8	18	0	0	0.0	0	0	79216.5

TISEO

DRCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM E OP CMND TAC
EQ NO 52 QPA=1 EH/FH=1.60
EQ FUNCTION RECONN

EQ IDENT MUC 71UUD LRU 12 EQ DESCRIPTOR: E-0 CONV						EQ IDENT MUC 71UFO LRU 13 EQ DESCRIPTOR: STAB GENERAT							
MONTH	WS	OP TIME	TOTAL FAILS	MTBF	MTBMA	3 MO	EMTBMA	FAILS	% SH	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	MA	FQ HRS	EQ HRS	EMTBMA	EMTBMA	REPS	NRTS	Index			FL HRS
78SEP	646	12969	0	0	0	65339.2	65339.2	0	0	0.0	0	0	0
78AUG	644	14407	0	0	0	63601.6	63601.6	0	0	0.0	0	0	0
78JUL	628	12302	0	1	22604.8	22604.8	33583.2	100	0	0.0	0	0	14128.0
78JUN	665	14128	1	0	0	67166.4	67166.4	63664.0	100	0	0.0	0	14530.0
78MAY	662	13321	0	1	23248.0	23248.0	67979.2	67979.2	0	0.0	0	0	0
78APR	682	14530	1	1	0	63664.0	63664.0	0	0	0.0	0	0	0
78MAR	690	14636	0	0	0	0	0	0	0	0.0	0	0	0
78FEB	676	10624	0	0	0	0	0	0	0	0.0	0	0	0
78JAN	694	13044	0	0	0	0	0	0	0	0.0	0	0	0
77DEC	670	12944	0	0	0	0	0	0	0	0.0	0	0	0
77NOV	659	15208	0	0	0	0	0	0	0	0.0	0	0	0
77OCT	564	10320	0	0	0	0	0	0	0	0.0	0	0	0
TOTAL	657	156433	2	11	126746.4	23044.8	18	0	0	0.0	0	0	79216.5

TISEO
DRC STUDY FIELD DATA ANALYSIS SUMMARY
WEAPON SYSTEM E OP CMND TAC
EQ NO 52 QPA=1 EQ/FN=1.60
EQ FUNCTION RECONN
EQ IDENT WUC 71UHO LRU 14 EQ DFSCR: VIDEO PROC

MONTH	WS	OP TIME	TOTAL	MTEF	MTEMA	3 MO	% MO	% SH	REPS	NRTS	MAINT	ABORTS	COND S	MTBF	FL HRS
YR	INR	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTEF	EMTEMA	FAILS	EMTEMA	FAILS	INDEX				
76SEP	646	12969	16	21	1296.9	988.1	1113.8	857.9	76	71	10	.03	0	810.6	
78AUG	644	14407	19	24	1213.2	960.5	1126.5	806.7	79	75	0	.04	0	750.3	
78JUL	628	12302	22	29	894.7	679.7	1200.0	766.3	76	48	7	.05	1	559.2	
78JUN	665	14128	17	28	1329.7	607.3	1399.3	850.2	61	71	4	.04	0	830.1	
78MAY	642	13321	14	26	1522.4	819.8	1477.8	957.5	54	15	19	.02	0	951.5	
78APR	682	14530	17	25	1367.5	929.9	1326.3	936.2	68	72	8	.04	0	854.7	
78MAR	690	14636	15	20	1561.2	1170.9	1494.8	948.5	75	60	5	.03	0	975.7	
78FEB	676	10624	16	23	1062.4	739.1	1394.7	887.6	70	70	0	.05	0	664.0	
78JAN	694	13044	10	19	2087.0	1098.4	2059.8	1267.6	53	58	11	.03	0	1304.4	
77DEC	670	12944	16	24	1294.4	862.9	2051.8	1231.1	67	54	17	.04	0	809.0	
77NOV	659	15208	6	9	4055.5	2703.6	2747.5	1541.3	67	44	0	.01	0	2534.7	
77OCT	564	10320	8	17	2064.0	971.3	1802.4	1190.2	47	41	6	.02	0	1290.0	
TOTAL	657	158433	176	265	1440.3	956.6	66	57	8	.03	1	0	900.2		

TISEO
DRC STUDY FIELD DATA ANALYSIS SUMMARY
WEAPON SYSTEM E OP CMND TAC
EQ NO 52 QPA=1 EQ/FN=1.60
EQ FUNCTION RECONN
EQ IDENT WUC 71UKO LRU 15 EQ DFSCR: POW SUP ASSY

MONTH	WS	OP TIME	TOTAL	MTEF	MTEMA	3 MO	% MO	% SH	REPS	NRTS	MAINT	ABORTS	COND S	MTBF	FL HRS
YR	INR	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTEF	EMTEMA	FAILS	EMTEMA	FAILS	INDEX				
78SEP	646	12969	5	2	4150.1	10375.2	2760.2	9069.3	250	150	0	.01	0	2593.8	
78AUG	644	14407	12	5	1920.9	4610.2	2970.0	7259.9	240	120	0	.01	0	1200.6	
78JUL	628	12302	6	0	3260.5	3975.1	7066.8								2050.3
78MAY	665	14128	4	4	5651.2	5597.2	6716.6	100	100	25					3532.0
78APR	662	13321	6	5	3552.3	4262.7	4531.9	120	20	0					2220.2
78MAR	676	14530	2	1	11624.0	2328.0	3979.0	2768.0	200	300	0				7265.0
78FEB	690	14636	7	9	3345.4	2602.0	3225.6	1751.0	78	44	0				2020.9
78JAN	670	10624	7	13	2428.3	1307.6	3254.4	1541.6	54	31	8				1517.7
77DEC	659	15208	5	12	3451.7	1725.9	4396.8	3877.3	38	38	0				2608.8
77NOV	564	10320	6	9	4055.5	2703.6	4212.9	2367.5	50	25	17				2157.3
TOTAL	657	158433	68	7H	3727.8	3249.9	87	51	6	.01	0	0	0	5160.0	2329.9

TISEO
DRC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

PAGE 16

WEAPON SYSTEM E OP CMDN TAC

EQ NO 52 QPA=1 EH/FH=1.60

EQ FUNCTION RECONN

EQ IDENT WUC 71 ULO LRU 16 EQ DESCRIPT: CONTROL

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTEMA	3 MO	X SH	X	MAINT	ABORTS	COND'S	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTRAF	EMTMA	FAILS	NRTS	INDEX	FL HRS	FL HRS	
78SEP	646	12969	6	9	3458.4	2305.6	2760.2	1715.8	67	0	.00	0	2161.5
78AUG	644	14407	7	13	3293.0	1773.2	2613.6	1390.2	54	31	.01	0	2058.1
78JUL	628	12302	10	15	1968.3	1312.2	2355.6	1042.6	67	27	.01	0	1230.2
78JUN	665	14128	8	19	2825.6	1148.7	2798.6	1066.1	42	26	.01	0	1766.6
78AUG	662	13321	9	27	2368.2	789.4	2614.6	1114.4	33	4	.01	0	1480.1
78AUG	682	14530	7	17	3521.1	1367.5	2122.1	1248.3	41	0	.01	0	2075.7
78AUG	690	14336	10	17	2341.4	1377.5	1702.4	1201.7	59	41	.01	0	1463.6
78FEB	676	10624	13	17	1307.6	999.9	1585.2	976.3	76	59	.01	0	817.2
78JAN	694	13044	13	17	1605.4	1227.7	1883.2	1156.4	76	53	.01	0	1003.4
77DEC	670	12944	11	26	1882.8	755.6	2198.4	1139.9	42	58	.01	0	1176.7
77NOV	659	15206	11	14	2212.1	1758.1	1974.6	1285.7	79	0	.01	0	1382.5
77OCT	564	10320	6	14	2752.0	1178.4	2426.3	1433.7	43	64	.01	0	1720.0
TOTAL	657	158433	111	205	2263.7	1236.6	54	40	1	.01	0	0	1427.3

60

TISEO
DRC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

DATE PROCESSED 02/17/79

WEAPON SYSTEM E OP CMDN TAC

EQ NO 52 QPA=1 EH/FH=1.60

EQ FUNCTION RECONN

EQ IDENT WUC 71UXX LRU 0X EQ DESCRIPT: TISEO S/S

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTHMA	3 MO	X SH	X	MAINT	ABORTS	COND'S	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTRAF	EMTMA	FAILS	NRTS	INDEX	FL HRS	FL HRS	
78SEP	646	12969	77	162	269.5	12H.1	237.8	104.6	48	25	.16	0	1684
78AUG	644	14407	105	250	219.5	92.2	241.1	100.2	42	25	.20	0	137.2
78JUL	628	12302	85	231.6	100.9	252.4	98.3	44	24	12	.21	1	144.7
78JUN	665	14128	81	207	279.1	109.2	276.4	105.8	39	14	.17	0	174.4
78AUG	662	13321	A6	24.5	247.4	87.0	290.5	108.4	35	18	.17	0	154.9
78FEB	682	14530	76	18.3	305.9	127.0	286.8	116.0	42	32	.20	1	191.2
78JAN	690	14636	72	19.9	325.2	117.7	300.4	114.8	36	21	.15	0	203.3
78FEB	676	10624	74	16.7	229.7	101.8	277.6	107.9	44	34	.20	0	143.6
78JAN	694	13044	58	16.8	359.8	124.2	343.3	125.3	35	16	.17	0	224.9
77DEC	670	12944	79	20.8	266.2	99.6	293.1	111.7	58	31	.20	1	163.8
77NOV	659	15208	55	15.0	442.4	162.2	289.6	113.7	37	13	.09	0	276.5
77OCT	564	10320	76	19.3	217.3	85.6	256.4	105.6	59	30	.20	0	135.8
TOTAL	657	158433	924	2327	274.3	108.9	40	27	10	.17	1	2	171.5

DIRECT RADAR SCOPE RECORDING SYSTEM
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM E OP CMD TAC
EQ NO 51 QPA=1 EH/FH=1.54
EQ FUNCTION RECONN
E2 IDENT WUC 77J10 LRU 11 E2 DESC: DRERS E.F.C.

MONTH	WS	OP TIME	TOTAL		MTBF	MTBMA	3 MO	X SH	X RPTS	MAINT INDEX	DATE PROCESSED
			YR	IN V							
78SEP	646	12969	0	2	9986.1	10184.0	4700.3	0	150	0	*00 0
78AUG	644	14407	2	6	11097.4	1597.8	4192.6	33	133	0	*00 0
78JUL	628	12302	4	5	4736.3	3789.0	5101.4	4081.1	80	40	*00 0
78JUN	665	14126	3	4	7252.4	5439.3	5387.3	3402.5	75	75	*00 0
78MAY	652	15321	5	6	4102.9	3419.1	4673.6	2516.5	83	67	*00 0
78APR	662	14530	4	9	5594.0	2486.2	4713.6	2269.5	44	67	*00 0
78MAR	690	10626	4	11	4507.9	2049.0	4915.7	2034.1	45	45	*00 0
78FEB	576	10624	4	7	4090.2	2337.2	5630.2	1944.2	57	100	*00 0
78JAN	694	13044	3	11	660.9	1826.2	7930.2	2265.8	27	9	*00 0
77DEC	670	12944	2	11	6644.6	1A12.2	7405.9	1974.9	27	55	*00 0
77NOV	659	15208	2	6	1170.2	3903.4	8589.1	2252.7	33	67	*00 0
77OCT	564	10320	3	13	5257.6	1222.5	7569.7	1597.8	23	54	*00 0
TOTAL	657	151435	34	91	6420.7	2681.2			42	62	2 *00 0
											4169.3

DIRECT RADAR SCOPE RECORDING SYSTEM
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM E OP CMD TAC
EQ NO 51 QPA=1 EH/FH=1.54
EQ FUNCTION RECONN
E2 IDENT WUC 77J20 LRU 12 E2 DESC: RECUR ASSY

MONTH	WS	OP TIME	TOTAL		MTBF	MTBMA	3 MO	X SH	X RPTS	MAINT INDEX	DATE PROCESSED
			YR	IN V							
78SEP	646	12969	2	6	9986.1	3328.7	7630.0	1745.8	33	0	*00 0
78AUG	644	14407	5	2	4437.4	1648.9	6286.9	1572.2	42	8	*00 0
78JUL	628	12302	1	17	1H945.1	1114.4	5101.4	1423.6	6	24	*00 0
78JUN	665	14128	4	11	5439.3	1977.9	3078.5	1469.3	36	0	*00 0
78MAY	662	13321	7	15	2930.6	1367.6	2617.2	1454.0	47	7	*00 0
78APR	642	14530	10	14	2237.6	1243.1	2188.4	1134.8	56	28	*00 0
78MAR	690	14636	8	12	2617.4	1878.3	2184.7	1179.8	67	42	*00 0
78FEB	676	10624	10	24	1636.1	6A1.7	2013.7	1105.5	42	29	*00 0
78JAN	694	13044	9	14	2252.0	1434.8	2537.7	1762.3	64	43	*00 0
77DEC	670	12944	9	13	2244.9	1533.4	2962.3	1519.2	69	38	*00 0
77NOV	659	15208	7	9	3355.6	2602.3	3577.9	1600.6	7P	44	*00 0
77OCT	564	10320	4	17	3973.2	934.9	3195.7	1086.2	24	106	*00 0
TOTAL	657	151435	76	164	5210.4	1452.3			45	35	1 *00 0
											2084.6

DIRECT RADAR SCOPE RECORDING SYSTEM
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM E OP CMND TAC
EC NO 51 DPA=1 EH/FH=1.54
EQ FUNCTION RECONN
EQ IDENT WUC 77J2A LRU 13 EQ DESCRIPTOR: PERISCOPE DRS

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP 78

MONTH	WS	OP TIME	TOTAL	MTRMF	MTRMA	3 MO	% SH	% NRTS	DATE PROCESSED
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTRF	FAILS	REPS	PAGE 18
78SEP	646	12969	3	R	6657.4	2496.5	5092.0	2263.1	02/17/79
78AUG	644	14407	2	3	11053.4	7395.6	5717.2	2028.7	02/17/79
78JUL	628	12302	7	16	2706.4	1184.1	5101.4	1800.5	02/17/79
78JUN	665	14128	2	12	10878.6	1813.1	9235.4	2303.8	02/17/79
78MAY	662	13321	3	6	6838.1	3619.1	2720.0	2516.5	02/17/79
78APR	682	14530	2	10	11188.1	2237.6	6127.7	1856.9	02/17/79
78MAR	690	14636	4	10	5634.9	2253.9	5362.6	1843.4	02/17/79
78FEB	676	10624	4	13	4090.2	1258.5	8054.6	1879.4	02/17/79
78JAN	694	13044	3	9	6695.9	2232.0	15860.5	3339.0	02/17/79
77DEC	670	12944	0	A	2491.7	29623.4	4937.2	0	02/17/79
77NOV	659	15208	1	2	23420.3	11710.2	30411.9	50	02/17/79
77OCT	564	10320	1	2	15892.8	7946.4	20239.0	50	02/17/79
TOTAL	657	158433	32	99	76244.6	24644.5	32	90	02/17/79
									02/17/79

DIRECT RADAR SCOPE RECORDING SYSTEM
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM E OP CMND TAC
EC NO 51 DPA=1 EH/FH=1.54
EQ FUNCTION RECONN
EQ IDENT WUC 77J2K LRU 14 EQ DESCRIPTOR: CAMERA

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

MONTH	WS	OP TIME	TOTAL	MTRMF	MTRMA	3 MO	% SH	% NRTS	DATE PROCESSED
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EMTRF	FAILS	REPS	PAGE 19
78SEP	646	12969	15	25	1331.5	798.9	1971.1	1035.7	02/17/79
78AUG	644	14407	9	19	2465.4	1167.7	1849.7	998.2	02/17/79
78JUL	628	12302	7	15	2706.4	1263.0	1302.5	755.8	02/17/79
78JUN	665	14128	18	29	1208.7	750.2	1154.4	633.8	02/17/79
78MAY	662	13321	22	37	932.5	554.4	1109.0	564.1	02/17/79
78APR	682	14530	16	36	1398.5	621.6	1114.1	494.2	02/17/79
78MAR	690	14636	21	43	1073.3	524.2	907.5	427.5	02/17/79
78FEB	676	10624	18	45	908.9	363.6	1044.1	473.8	02/17/79
78JAN	694	13044	26	50	772.6	401.8	1244.0	634.4	02/17/79
77DEC	670	12944	10	24	1993.4	830.6	1559.1	713.8	02/17/79
77NOV	659	15208	15	26	1561.4	900.8	1351.6	620.7	02/17/79
77OCT	564	10320	13	33	1222.5	481.6	1412.0	576.3	02/17/79
TOTAL	657	158433	190	382	1284.1	638.7	50	53	02/17/79
									02/17/79

DIRECT RADAR SCOPE RECORDING SYSTEM
DRC'D STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM E OP CMD TAC
EQ NO 51 QPA=1 EH/FH=1.54

DATA WINDOW = 12 MONTHS

PERIOD ENDING - SEP73

PAGE 19

DATE PROCESSED 02/17/79

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	X	SH	X	RTS	NRTS	MAINT	ABORTS	COND'S	MTBF
78SEP	646	12969	1	1	19972.3	19972.3	10184.0	8729.2	100	0	0	0	0	0	0	12969.0
78AUG	644	14407	3	4	7395.6	5546.7	12577.8	10481.5	75	0	0	0	0	0	0	4802.3
78JUL	628	12302	2	2	9472.5	9472.5	30608.3	30608.3	100	0	0	0	0	0	0	6151.0
78JUN	665	14128	0	0	32323.8	21549.2										
78JAY	662	13321	0	0	52715.0	21810.0										
78APR	682	14530	2	3	11146.1	7456.7	10212.8	8755.8	67	0	0	0	0	0	0	7265.0
78MAR	690	14636	0	0	4090.2	14747.0	14747.0									
78FER	676	10624	4	4	9397.1	8054.5	100	0	0	0	0	0	0	0	0	2656.0
78JAN	694	13044	0	0	21147.3	15860.5										
77DEC	670	12944	2	3	9966.9	6644.6	19749.0	11849.4	67	0	0	0	0	0	0	6472.0
77NOV	659	15209	1	1	23420.3	25420.3	60823.8	15206.0	100	0	0	0	0	0	0	15208.0
77OCT	564	10320	0	1	15892.8	15892.8			0	0	0	0	0	0	0	
TOTAL	657	158433	15	19	16265.9	12941.4			79	5	0	0.00	0	0	0	10562.2

DIRECT RADAR SCOPE RECORDING SYSTEM

DRC'D STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM E OP CMD TAC
EQ NO 51 QPA=1 FH/FH=1.54

DATA WINDOW = 12 MONTHS

PERIOD ENDING - SEP78

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	X	SH	X	RTS	NRTS	MAINT	ABORTS	COND'S	MTBF
78SEP	646	12969	28	43	713.3	464.5	710.5	430.3	65	56	0	0.02	0	0	0	463.2
78AUG	644	14407	27	44	821.7	504.2	576.2	398.0	61	70	2	0.02	0	0	0	533.6
78JUL	628	12302	31	55	611.1	344.5	541.7	336.4	56	47	9	0.02	0	0	0	396.8
78JUN	665	14128	35	59	621.6	368.8	525.9	318.5	59	41	0	0.02	0	0	0	403.7
78JAY	662	13321	47	68	436.5	301.7	507.2	294.7	69	38	0	0.02	0	0	0	283.4
78FER	682	14530	40	76	559.4	294.4	475.0	247.1	53	50	1	0.02	0	0	0	363.3
78JAN	694	13044	42	78	536.7	289.0	440.2	230.4	54	53	0	0.03	0	0	0	348.5
76FEB	676	10624	47	94	348.1	174.1	447.5	235.9	50	38	0	0.04	0	0	0	226.0
77JAN	694	13044	45	84	446.4	239.1	335.7	54	51	0	0.03	0	0	0	0	289.9
77DEC	670	12944	34	61	586.3	326.9	558.3	344.5	56	61	2	0.02	0	0	0	380.7
77NOV	659	15208	28	44	836.4	532.3	691.2	245.6	64	73	0	0.02	0	0	0	543.1
77OCT	564	10320	24	67	567.6	237.2	674.6	274.5	42	72	0	0.03	0	0	0	368.6
TOTAL	657	158433	432	773	564.8	315.6			56	53	1	0.02	0	0	0	366.7

AN/APQ-130
DRC D STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM N OP CMDN TAC
EQ NO 07 QPA=1 EH/FH=2.31
EQ FUNCTION RADAR FC
EQ IDENT WUC 73PA0 LRU 00 EQ DESCRIPTOR: FC RADAR SYS

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	X SH	X REPS	X NRTS	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EMTRF	EMTMA	FAILS	NRTS	INDEX			FL HRS
78SEP	89	1637	19	61	199.0	62.0	146.2	65.9	31	0	*.27	0	0	86.2
78AUG	89	1663	26	51	137.2	75.5	135.9	64.7	55	0	*.12	0	0	59.4
78JUL	88	1639	30	61	126.2	62.1	152.9	63.1	49	0	*.23	0	0	54.6
78JUN	87	1463	23	52	146.9	58.3	145.4	53.2	40	0	*.15	0	0	63.6
78MAY	P2	1267	13	41	225.1	71.4	154.0	52.8	32	0	*.14	0	0	97.5
78APR	90	355	15	35	63.1	23.4	138.1	46.7	37	0	*.44	0	0	27.3
78MAR	PA	1512	21	61	166.3	57.3	160.0	55.2	34	0	*.16	0	0	72.0
78FEB	90	763	10	34	176.3	51.8	135.3	49.5	29	0	*.33	0	0	76.3
78JAN	67	427	8	18	123.3	54.8	162.6	68.9	44	0	*.25	0	0	53.4
77DEC	AB	1061	21	53	116.7	45.2	221.6	75.6	40	0	*.43	1	0	50.5
77NOV	88	1821	18	40	233.7	105.2	347.2	105.7	45	0	*.12	0	0	101.2
77OCT	H9	1531	7	40	505.2	69.4	451.7	110.9	18	0	*.16	0	0	216.7
TOTAL	86	15139	211	563	165.7	63.2			38	0	*.20	1	0	71.7

AN/APQ-130
DRC D STUDY FIELD DATA ANALYSIS SUMMARY

MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	X SH	X REPS	X NRTS	Maint	Aborts	Conds	MTBF
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EMTRF	EMTMA	FAILS	NRTS	INDEX			FL HRS
78SEP	89	1637	7	13	540.2	290.9	316.9	248.0	54	123	0	*.31	0	0
78AUG	89	1663	16	17	240.1	226.0	196.6	172.0	94	118	6	*.26	0	0
78JUL	88	1639	13	16	291.2	236.6	165.4	136.4	81	250	0	*.63	1	0
78JUN	A7	1463	27	31	125.2	109.0	120.8	99.0	87	46	0	*.29	0	0
78MAY	R2	1267	21	27	139.4	108.4	185.6	144.8	78	89	0	*.54	0	0
78APR	90	355	11	14	74.5	58.6	202.5	168.8	79	164	0	*.37	0	0
78MAR	RR	1512	7	9	499.0	389.1	208.1	189.1	78	89	0	*.13	0	0
78FEB	90	763	12	13	146.9	135.6	118.2	106.1	92	185	0	*.61	0	0
78JAN	67	427	11	11	89.7	89.7	131.8	117.6	100	55	0	*.59	0	0
77DEC	AB	1061	21	25	116.7	98.0	156.8	137.8	84	160	0	*.91	0	0
77NOV	H8	1821	26	29	161.8	145.1	215.2	196.0	90	59	0	*.21	0	0
77OCT	H8	1531	18	20	196.5	176.8	239.4	203.3	90	275	5	*.57	1	0
TOTAL	86	15139	190	225	184.1	155.4			84	128	1	*.45	2	0

AN/APQ-130
DRCC STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEPT 78

WEAPON SYSTEM N OP CND TAC
EQU NO 07 QPA=1 EH/FH=2.31
FG FUNCTION RADAR FC
EG IDENT WUC 73PHG LRU 12 EG DESC: FL PROCESSOR

MONTH	WS	OP TIME	TOTAL	MTEF	WTMFA	3 MO	% SH	%	MAINT	ABORTS	COND S	MTBF
YR	INV	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTBF	EMTWA	FAILS	REPS	NRTS	INDEX	FL HRS
76SEP	69	1637	14	27	270.1	140.1	202.7	114.1	52	141	4	.52
76AUG	89	1663	20	32	192.1	120.0	144.8	92.5	63	122	13	.42
76JUL	88	1639	22	41	172.1	92.5	117.4	74.2	54	102	7	.59
78JUN	87	1463	34	46	99.4	73.5	79.5	56.6	74	39	7	.41
78MAY	62	1267	30	49	97.6	59.7	83.2	64.2	62	55	2	.75
78APR	90	355	26	31	51.5	26.5	72.3	56.8	84	110	6	1.85
78MAR	96	1512	71	33	112.7	105.8	87.9	65.7	94	45	0	.51
78FEB	90	763	27	43	65.3	41.0	56.5	38.5	63	81	0	1.02
78JAN	67	427	13	13	75.6	51.9	81.3	54.6	68	74	5	.82
77DEC	68	1061	52	73	47.1	33.6	61.0	41.8	71	116	10	1.51
77NOV	88	1821	29	48	145.1	87.6	144.2	96.8	60	60	2	.30
77OCT	98	1531	51	44	114.1	80.4	141.6	95.3	70	73	2	.78
TOTAL	86	15139	324	486	106.2	72.0	68	64	5	.64	4	.46.0

AN/APQ-130

DRCC STUDY FIELD DATA ANALYSIS SUMMARY
DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEPT 78

WEAPON SYSTEM N OP CND TAC
EQU NO 07 QPA=1 EH/FH=2.31
FG FUNCTION RADAR FC
EG IDENT WUC 73PHG LRU 14 EG DESC: XMTA

MONTH	WS	OP TIME	TOTAL	MTEF	WTMFA	3 MO	% SH	%	MAINT	ABORTS	COND S	MTBF
YR	INV	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTBF	EMTWA	FAILS	REPS	NRTS	INDEX	FL HRS
76SEP	69	1637	21	33	180.1	114.6	144.4	101.9	64	103	12	.33
76AUG	89	1663	74	49	113.0	79.4	132.6	101.0	69	57	16	.31
76JUL	88	1639	24	50	157.8	126.2	146.3	118.7	80	120	20	.35
78JUN	97	1463	25	30	135.2	112.7	120.8	91.4	83	33	0	.16
78MAY	92	1267	20	25	146.3	117.1	124.8	92.8	80	120	12	.27
78APR	90	355	14	23	58.6	35.7	94.9	69.0	61	126	17	1.51
78MAR	98	1512	24	30	145.5	116.4	109.5	81.1	80	47	10	.28
78FEB	90	763	26	35	67.8	50.6	74.3	52.0	74	83	9	.86
78JAN	67	427	7	12	140.9	82.2	101.9	74.2	56	108	0	.59
77DEC	98	1061	37	53	66.2	46.2	98.0	78.4	70	158	45	1.59
77NOV	98	1821	31	38	135.7	110.7	142.9	124.0	82	150	39	.31
77OCT	98	1531	56	59	98.2	90.7	141.8	118.4	92	110	18	.76
TOTAL	86	15139	209	397	117.0	64.1	75	103	19	.49	4	.50.6

THIS PAGE IS BEST QUALITY PRACTICABLE
FROM COPY FURNISHED TO DDC

PAGE 21

DATE PROCESSED 02/17/79

AN/APQ-130
DRCD STUDY FIELD DATA ANALYSIS SUMMARY

EQ FUNCTION RADAR FC										DATE PROCESSED									
EQ IDENT WUC 73PFD LRU 14					EQ DESCRI: DOPPLER CONV					02/17/79									
MONTH	YEAR	WS	OP TIME	TOTAL FAILS	TOTAL MA	MTEF	MTEMA	EMTEF	EMTEMA	3 MO	% FAILS	% SH REPS	% NRTS	Maint Index	AFFOTS	CONDNS	MTRF FL HRS		
				EQ HRS	EQ HRS	EQ HRS	EQ HRS	EQ HRS	EQ HRS	EQ HRS									
78SEP	89	1637	3	6	1260.5	530.2	760.6	438.8	50	83	17	.04	0	0	545.7	545.7			
78AUG	89	1663	7	11	54H+8	349.2	550.4	379.6	64	36	9	.06	0	0	237.7	237.7			
78JUL	88	1639	5	9	757.2	420.7	630.8	43H+8	56	44	0	.05	0	0	327.8	327.8			
78JUN	H7	1463	8	9	422+4	375.5	593.9	323.9	89	78	0	.10	0	0	182.9	182.9			
78MAY	H2	1267	5	5	975.6	565.4	804.4	362.0	60	100	0	0	0	0	422.3	422.3			
78APR	90	355	1	8	820.0	102.5	379.5	217.0	71	63	0	.43	0	0	355.0	355.0			
78MAR	88	1512	5	7	698.5	499.0	390.1	283.7	71	0	0	.03	0	0	302.4	302.4			
78FEB	90	763	10	13	176.3	135.6	247.6	173.3	77	85	0	.21	0	0	76.3	76.3			
78JAN	H7	427	1	2	9H6.4	493.2	402.3	263.6	50	0	0	.02	0	0	427.0	427.0			
77DEC	H8	1061	16	15	245.1	163.4	407.8	283.2	67	100	0	.15	0	0	106.1	106.1			
77NOV	H8	1821	8	12	525.8	350.5	639.5	467.3	67	25	0	.05	0	0	227.6	227.6			
77OCT	H8	1531	7	9	505.2	393.0	641.9	404.6	78	C	.10	0	0	0	218.7	218.7			
TOTAL	P6	15139	68	106	514.3	523.9	64	62	2	.08	0	0	0	0	222.6	222.6			

AN/APQ-130
DRCD STUDY FIELD DATA

DATA WINDOW - 12 MONTH
PERIOD ENDING - SEPT 7A

EC FUNCTION RADAR FC										DATE PROCESSED		02/17/79			
EC IDENT WUC		73PHO		LRU 15		EC DESCRI: LV POW SUPP									
MONTH	WS	OF TIME	TOTAL	MTRF	KTRMA	3 MO	3 MO	% SH	%	Maint	AHRTS	COND	MTEF		
YR	IN V	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTRF	EMTRF	REPS	NRTS	INDEX	FL HRS	FL HRS			
77SEP	89	1637	5	6	1210.5	630.2	814.9	496.0	50	250	117	.05	1	0	545.7
77AUG	69	1663	5	7	768.2	548.8	611.5	425.4	71	0	100	.03	1	0	332.6
77JUL	88	1659	6	10	631.0	378.6	672.8	420.5	60	30	60	.12	1	0	273.2
77JUN	87	1463	7	9	482.8	375.5	647.2	285.1	78	22	0	.06	0	0	205.9
77JUN	92	1267	2	5	1463.4	585.4	804.4	514.8	40	180	0	.08	0	0	633.5
77JUN	93	1525	2	11	410.0	74.5	435.9	245.0	18	27	0	.28	0	0	177.5
77JUN	6H	1512	5	7	698.5	499.0	460.0	390.1	71	0	0	.06	0	0	302.4
77JUN	90	763	7	7	251.8	251.8	505.9	226.1	100	14	0	.04	0	0	109.0
77JAN	67	427	1	2	966.4	493.0	449.6	238.9	50	0	0	.04	0	0	427.0
77DEC	PR	1061	9	14	272.3	175.0	443.2	261.4	64	129	14	.27	0	0	117.9
77NOV	48	1421	7	14	600.9	262.9	714.7	433.9	44	13	6	.07	0	0	260.1
77CCY	88	1531	7	7	505.2	393.0	938.2	677.6	78	67	0	.15	0	0	214.7
TOTAL		15139			10*	573.2	573.2	539.5	59	62	22	.09	3	0	248.2

AN/APQ-130
DRCCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM N		OP CMDN TAC																		
EQ NO 07	GPA=1	EH/FH=2.31																		
EQ IDENT		WUC 73PK0		LRU 16		EQ DESCRI: RECEIVER														
MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	3 MO	SH	% SH	NRTS	FAILS	EMTBF	EMTMA	3 MO	3 MO	SH	% SH	MNTS	INDEX
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EQ HRS	EQ HRS	REPS	FAILS	EMTMA	EMTBF	EMTMA	EMTBF	EQ HRS	EQ HRS	REPS	FAILS	FL	HRS
78SEP	A9	1637	9	13	420.2	290.9	360.0	265.3	69	215	0	*23	1	0	161.9	0	0	0	161.9	
78AUG	A9	1663	12	17	320.1	225.0	259.7	220.1	71	76	0	*17	0	0	138.6	0	0	0	138.6	
78JUL	AA	1639	10	13	378.6	291.2	265.6	210.3	77	192	8	*30	0	0	163.9	0	0	0	163.9	
78JUN	97	1463	16	20	211.2	169.0	165.7	142.5	80	20	0	*15	0	0	91.4	0	0	0	91.4	
78MAY	82	1267	12	15	243.9	195.1	150.8	134.1	80	113	0	*21	1	0	105.6	0	0	0	105.6	
78APR	90	355	15	15	54.7	54.7	116.8	99.6	100	133	7	*79	0	0	23.7	0	0	0	23.7	
78MAR	A8	1512	21	24	166.3	145.5	138.7	113.5	87	42	0	*18	1	0	72.0	0	0	0	72.0	
78FEB	90	763	16	22	110.2	80.1	113.0	89.7	73	77	0	*49	0	0	47.7	0	0	0	47.7	
78JAN	67	427	8	9	123.5	109.6	156.0	136.5	89	89	0	*30	0	0	53.4	0	0	0	53.4	
77DEC	96	1061	22	27	111.4	90.8	192.3	159.3	81	156	4	*74	0	0	48.2	0	0	0	48.2	
77NOV	P8	1821	19	20	221.4	210.3	311.6	254.5	95	65	5	*16	0	0	95.2	0	0	0	95.2	
77OCT	PA	1531	12	17	294.7	204.0	338.8	243.9	71	118	6	*24	0	0	127.6	0	0	0	127.6	
TOTAL	A6	15139	172	212	203.3	165.0	81	102	2	.27	3	0	68.0	0	0	68.0	0	0	0	68.0

AN/APQ-130

DRCCD STUDY FIELD DATA ANALYSIS SUMMARY

DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM N		OP CMDN TAC																		
EQ NO 07	GPA=1	EH/FH=2.31																		
EQ IDENT		WUC 73PM0		LRU 17		EQ DESCRI: REF SIG GEN														
MONTH	WS	OP TIME	TOTAL	TOTAL	MTBF	MTBMA	3 MO	3 MO	SH	% SH	NRTS	FAILS	EMTBF	EMTMA	3 MO	3 MO	SH	% SH	MNTS	INDEX
YR	INV	FLT HRS	FAILS	MA	EQ HRS	EQ HRS	EQ HRS	EQ HRS	REPS	FAILS	EMTMA	EMTBF	EMTMA	EMTBF	EQ HRS	EQ HRS	REPS	FAILS	FL	HRS
78SEP	A9	1637	10	13	378.1	290.9	393.4	259.3	77	162	0	*16	0	0	163.7	0	0	0	163.7	
78AUG	A9	1663	14	23	274.6	167.0	355.1	244.6	61	113	4	*20	0	0	118.8	0	0	0	118.8	
78JUL	88	1639	5	8	475.3	215.2	325.6	265.6	63	138	0	*18	0	0	327.8	0	0	0	327.8	
78JUN	A7	1463	12	14	261.6	241.4	215.9	173.8	86	71	7	*10	1	0	121.9	0	0	0	121.9	
78MAY	A2	1267	14	16	209.1	182.9	226.2	168.4	88	81	0	*17	0	0	90.5	0	0	0	90.5	
78APR	90	355	7	11	117.1	74.5	253.1	151.9	64	118	9	*45	0	0	50.7	0	0	0	50.7	
78MAR	A8	1512	11	16	317.5	218.3	328.5	173.4	69	25	0	*06	0	0	137.5	0	0	0	137.5	
78FEB	90	763	6	13	293.6	135.6	179.3	102.0	46	85	0	*19	0	0	127.2	0	0	0	127.2	
78JAN	67	427	2	7	493.2	140.9	212.3	136.5	29	14	0	*14	0	0	213.5	0	0	0	213.5	
77DEC	98	1061	21	31	116.7	79.1	212.4	152.1	68	77	0	*39	0	0	50.5	0	0	0	50.5	
77NOV	88	1821	13	18	323.6	233.7	303.8	248.0	72	67	0	*12	0	0	140.1	0	0	0	140.1	
77OCT	HB	1531	14	18	252.6	196.5	312.7	243.9	78	78	0	*16	1	0	109.4	0	0	0	109.4	
TOTAL	96	15139	129	188	271.1	186.0	69	103	2	.17	2	0	117.4	0	0	117.4	0	0	0	117.4

THIS PAGE IS BEST QUALITY PHOTOCOPIED
FROM COPY PUBLISHED TO LDC

AN/APQ-130
DRC STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM N OP CMND TAC
EQ NO 07 GPA=1 EH/FH=2*31
EQ FUNCTION RADAR FC
EQ IDENT WUC 73PQ0 LRU 18 EC DESCRI: ANT PEDESTAL

MONTH	WS	OP TIME	TOTAL	MTBF	MTBMA	3 MO	% SH	%	Maint	Aborts	Conds	MTBF	
YR	IN V	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTEF	REPS	NRTS	INDEX	INDEX	FL HRS		
78SEP	89	1637	2	5	1690*7	760*6	475*4	40	40	*03	0	818*5	
78AUG	89	1663	6	8	640*3	480*2	667*9	458*6	25	*06	0	277*2	
78JUL	88	1639	7	11	54*9	344*2	917*5	531*2	64	91	0	234*1	
78JUN	87	1463	3	5	1126*5	675*9	1018*0	548*2	60	20	*02	487*7	
78MAY	82	1267	1	3	2922*8	724*6	482*6	33	67	33	*04	1267*0	
78APR	90	355	3	5	273*3	164*0	506*3	379*7	60	100	*13	118*3	
78MAR	88	1512	6	7	582*1	499*0	520*1	390*1	86	57	*11	252*0	
78FEB	90	763	3	4	440*6	567*5	577*8	400*0	75	150	*13	254*3	
78JAN	67	427	3	5	328*4	197*3	764*4	509*6	60	40	*13	142*3	
77DEC	88	1061	3	4	817*0	612*7	1274*3	849*5	75	175	*11	353*7	
77NOV	82	1821	4	6	1051*6	701*1	1518*8	1012*5	67	0	*03	455*3	
77OCT	98	1531	1	2	3536*6	1764*3	1210*7	813*1	50	50	*05	1531*0	
TOTAL	86	15139	42	65	832*6	538*0			65	60	.07	5	360*5

AN/APQ-130
DRC STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM N OP CMND TAC
EQ NO 07 GPA=1 EH/FH=2*31
EQ FUNCTION RADAR FC
EQ IDENT WUC 73PQ0 LRU 19 EC DESCRI: MOUNT

MONTH	WS	OP TIME	TOTAL	MTBF	MTBMA	3 MO	% SH	%	Maint	Aborts	Conds	MTBF	
YR	IN V	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTEF	REPS	NRTS	INDEX	INDEX	FL HRS		
78SEP	89	1637	2	12	1890*7	315*1	285*2	17	0	*04	0	818*5	
78AUG	99	1663	2	19	1920*8	202*2	5503*6	305*4	11	16	*05	831*5	
78JUL	88	1639	0	9	420*7	420*4	480*6	0	33	0	*04	0	
78JUN	87	1463	0	9	422*4	731*7	475*1	0	13	0	*03	0	
78MAY	82	1267	0	4	273*3	6075*3	556*9	0	25	0	*01	0	
78APR	90	355	0	3	582*1	6241*6	357*4	0	0	*04	0	0	
78MAR	58	1512	0	6	1762*5	220*3	1040*0	162*5	0	*01	0	763*0	
78FEB	90	763	1	8	164*4	420*7	1526*8	231*6	50	*05	0	0	
78JAN	67	427	0	6	1639	0	1699*0	268*3	0	*02	0	265*3	
77DEC	88	1061	4	18	612*7	467*4	3037*6	419*0	11	11	0	1621*0	
77NOV	82	1821	1	9	4206*5	321*5	2032*8	348*5	9	0	*03	1531*0	
TOTAL	86	15139	11	113	3179*7				10	12	*04	0	1376*3

PAGE 24
DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEPT 78

DATE PROCESSED 02/17/79

AN/APQ-130

DRCO STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM N OP CND TAC
 EG NO 37 GFA=1 EH/FH=2.51
 EQ FUNCTION RADAR FC
 EQ IDENT WUC 73PXX LRU 0X EQ DIFCR: FC RADAR S/S

MONTH	WS	OP TIME	TOTAL FAILS	TOTAL MA	MTHF	WTBMA	3 MO	% MO	% SH	% REPS	% NRTS	MAINT INDEX	ABORTS	CONDNS	MTBF FL HRS
YR	INV	FLT HRS	MA	EQ HRS	EQ HRS	EMTRF	EMTRF	FAILS	REPS	NRTS					
78SEP	89	1637	100	193	37.8	19.6	17.6	52	100	44	2.10	2	0	16.4	
78AUG	89	1663	151	240	25.4	16.0	24.8	63	58	47	1.85	2	0	11.0	
78JUL	88	1639	1*1	216	26.9	17.5	24.4	61	66	51	2.75	2	0	12.5	
78JUN	87	1463	162	235	20.9	14.4	18.8	12.0	69	31	1.59	1	0	9.0	
78MAY	82	1267	121	195	24.2	15.0	20.5	12.9	62	71	4.1	2.53	3	10.5	
78APR	90	355	97	163	4.5	5.0	16.6	10.7	60	65	11.9	8.80	0	3.7	
78MAR	88	1512	136	203	25.7	17.2	19.4	12.5	67	30	4.2	1.41	1	11.1	
78FEB	90	763	129	200	13.7	9.8	13.5	8.4	65	77	4.56	2	0	5.9	
78JAN	57	427	56	95	17.6	10.4	18.0	11.6	59	47	4.8	3.20	0	7.6	
77DEC	88	1061	205	323	12.0	7.6	20.1	13.2	63	111	104	6.56	2	0	5.2
77NOV	88	1821	163	240	25.8	17.5	30.3	20.2	68	57	6.4	1.46	2	2	11.2
77OCT	98	1531	139	212	25.4	16.7	31.2	19.8	66	85	73	3.12	3	2	11.0
TOTAL	86	15139	1590	2515	22.0	15.9			63	72	65	2.71	20	5	9.5

STRIKE CAMERA

DRCO STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM N OP CND TAC
 EG NO 50 3PA=1 EH/FH=1.19
 EQ FUNCTION RECON
 EQ IDENT WUC 77A00 LRU 00 EQ DIFCR: STR CAM SYS

MONTH	WS	OP TIME	TOTAL FAILS	TOTAL MA	MTHF	WTBMA	3 MO	% MO	% SH	% REPS	% NRTS	MAINT INDEX	ABORTS	CONDNS	MTBF FL HRS
YR	INV	FLT HRS	MA	EQ HRS	EQ HRS	EMTRF	EMTRF	FAILS	REPS	NRTS					
78SEP	89	1637	0	2		974.0		2938.7	0	0	0	*.00	0	0	0
78AUG	89	1663	0	0				5670.3			*.00	0	0	0	0
78JUL	88	1639	0	0				5199.1			*.00	0	0	0	0
78JUN	97	1463	0	1				1741.0			*.01	0	0	0	0
78MAY	82	1267	0	0				1835.6	0	0	*.01	0	0	0	0
78APR	90	555	0	1				422.4			*14.4	*.00	0	0	0
78MAR	58	1512	0	4				224.9			313.0	0	0	0	0
78FEB	30	763	0	1				909.0			321.5	0	0	0	0
78JAN	427	0	1	2		1262.6		2678.7	0	0	669.7	0	0	0	0
77DEC	58	1061	1	2				509.1			3937.7	1312.6	0	0	0
77NOV	98	1821	0	0				5251.5			1251.9	50	0	0	1061.0
77OCT	98	1531	0	2		910.9		1256.6	0	0	0	*.00	0	0	0
TOTAL	86	15139	1	1H 1A01E.4		1000.9			6	0	0	*.00	0	0	15139.0

THIS PAGE IS BEST QUALITY PRACTICABLE
 FROM COPY ENLARGED TO DOG

STRIKE CAMERA
DRCO STUDY FIELD DATA ANALYSIS SUMMARY
DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM N	OP CMND TAC	78SEP	89	1637	TOTAL FAILS	MTRF	MTRMA	3 MO	% SH	Maint Index	Date Processed			
FC NO 50	QPA=1 EH/FH=1.19	78AUG	H9	1663	0	EQ HRS	EQ HRS	EMTB	REPS	Abrorts	02/17/79			
EQ FUNCTION	RECONN	78JUL	R9	1639	0	16	123.7	5670.3	145.9	001				
EQ IDENT	WUC 77AAA	78JUN	H7	1463	1	24	1950.4	81.3	115.4	002				
LRU 11 EQ DESC: BODY CAMERA														
MONTH	WS	OP TIME	YR	INV	FLT HRS	TOTAL FAILS	EQ HRS	EQ HRS	EMTB	FAILS	NRTS	COND S	MTBF FL HRS	
78SEP	R9	1637	0	0	0	0	0	0	5877.4	145.9	0	0	0	
78AUG	H9	1663	0	16	123.7	123.7	5670.3	115.4	0	86	0	0	0	
78JUL	R9	1639	1	24	1950.4	81.3	5199.1	144.4	4	75	0	0	0	
78JUN	H7	1463	0	10	174.1	174.1	204.0	0	110	0	0	0	1639.0	
78MAY	H2	1267	0	2	753.9	753.9	466.2	0	400	0	0	0	0	
78APR	R9	355	0	6	70.4	70.4	521.6	0	300	0	0	0	0	
78MAR	R8	1512	0	0	0	0	0	0	0	0	0	0	0	
78FEB	R9	763	0	0	0	0	0	0	0	0	0	0	0	
78JAN	H7	427	0	1	2678.7	2678.7	892.9	0	0	0	0	0	0	
77DEC	H8	1061	1	2	1262.6	509.1	1312.6	0	400	0	0	0	0	
77NOV	H8	1821	0	0	631.3	2625.7	1725.5	50	900	0	005	0	0	
77OCT	H8	1531	1	1	1821.9	3129.7	2086.5	0	0	0	01	0	0	
TOTAL	96	15139	3	62	6005.1	290.6	3141.6	2094.4	100	0	0	0	1531.0	
									5	187	0	002	0	5046.3

STRIKE CAMERA
DRCO STUDY FIELD DATA ANALYSIS SUMMARY
DATA WINDOW - 12 MONTHS
PERIOD ENDING - SEP78

WEAPON SYSTEM N	OP CMND TAC	78SEP	R9	1637	TOTAL FAILS	MTRF	MTRMA	3 MO	% SH	Maint Index	Date Processed		
FC NO 50	QPA=1 EH/FH=1.19	78AUG	H9	1663	0	EQ HRS	EQ HRS	EMTB	REPS	Abrorts	02/17/79		
EQ FUNCTION	RECONN	78JUN	R7	1463	0	4	487.0	279.9	0	100	0	001	0
EQ IDENT	WUC 77AAA	78JUN	R7	1463	0	1	496.7	236.3	0	100	0	001	0
LRU 12 EQ DESC: STR CAM CONT													
MONTH	WS	OP TIME	YR	INV	FLT HRS	TOTAL FAILS	EQ HRS	EQ HRS	EMTB	FAILS	NRTS	COND S	MTBF FL HRS
78SEP	R9	1637	0	4	4	487.0	279.9	0	100	0	0	0	0
78AUG	H9	1663	0	4	496.7	496.7	236.3	0	92	6	005	0	0
78JUN	R7	1463	0	7	150.0	248.7	248.7	0	114	0	005	0	0
78MAY	R2	1267	0	2	753.9	753.9	621.6	0	250	0	002	0	0
78APR	R0	355	0	4	105.6	1564.8	447.1	0	350	0	013	0	0
78MAR	R8	1512	0	0	0	1071.8	643.1	0	0	0	0	0	0
78FEB	R0	763	2	3	454.0	302.7	669.7	334.8	67	33	001	0	581.5
78JAN	H7	427	1	2	508.1	254.1	1312.6	656.5	50	100	004	0	427.0
77DEC	R9	1061	1	3	1262.6	420.9	2625.7	1050.3	33	100	004	0	1061.0
77NOV	R6	1821	1	1	2167.0	2167.0	2086.5	1251.9	100	0	001	0	1821.0
77OCT	R9	1531	0	1	1421.9	3141.6	1256.6	1256.6	0	100	0	0	0
TOTAL	96	15139	5	46	3603.1	409.4	5	127	2	002	0	0	3027.6

STRIKE CAMERA
DRCC STUDY FIELD DATA ANALYSIS SUMMARY

WEAPON SYSTEM N OP CMND TAC
EQ NO 50 QPA=1 FH/FH=1.19
EQ FUNCTION RECONN
EQ IDENT WUC 77AAF LRU 13 EQ DESC: FANFL ACCY

MONTH	WS	OP TIME	TOTAL	MTBF	MTHWA	3 MO	% SH	%	MAINT	ABORTS	CONDNS	MTBF
YR	INV	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTRF	NRTS	NRTS	INDEX			FL HRS
78SEP	89	1637	2	3	974.0	669.3	979.6	67	100	0	0	818.5
78AUG	89	1663	1	1	1979.0	1890.1	945.1	100	0	*00	0	166.0
78JUL	88	1639	1	2	1950.4	2599.6	1034.8	50	0	*00	0	1639.0
78JUN	87	1463	1	3	1741.0	560.3	1671.1	1223.7	33	0	*00	0
78MAY	82	1267	0	0			932.4			*00	0	1463.0
78APR	90	355	0	0			782.4			*00	0	
78MAR	88	1512	0	4			449.8	1607.7	535.9	0	0	
78FEB	90	763	0	0			892.9	535.7		*00	0	
78JAN	67	427	2	2			254.1	1512.6	787.5	100	0	213.5
77DEC	88	1061	1	3			420.9	2625.7	1050.3	33	0	1061.0
77NOV	88	1821	0	0			0	3129.7	1564.8		*00	0
77OCT	88	1531	1	2			1821.9	2094.4	1256.6	50	100	0
TOTAL	86	15139	9	20	2001.7	900.8	45	60	0	*00	0	1682.1

71

STRIKE CAMERA
DRCC STUDY FIELD DATA ANALYSIS SUMMARY

MONTH	WS	OP TIME	TOTAL	MTBF	MTHWA	3 MO	% SH	%	MAINT	ABORTS	CONDNS	MTBF
YR	INV	FLT HRS	FAILS	EQ HRS	EQ HRS	EMTRF	NRTS	NRTS	INDEX			FL HRS
78SEP	89	1637	3	9	649.3	216.4	979.6	59.4	33	311	0	*02
78AUG	89	1663	1	39	1979.0	50.7	945.1	46.9	3	97	0	*06
78JUL	88	1639	2	51	975.2	38.2	1039.8	59.1	4	96	10	*09
78JUN	87	1463	3	31	560.3	56.2	1223.7	69.3	10	97	0	*10
78MAY	82	1267	0	6			251.3	1864.7	106.6	0	333	17
78APR	90	355	0	16			26.4	782.4	94.8	0	294	*40
78MAR	88	1512	2	13			899.6	1384.4	401.9	128.6	15	31
78FEB	90	763	2	4			454.0	227.0	243.5	121.8	50	300
78JAN	67	427	4	R			127.0	63.5	393.8	207.2	50	150
77DEC	88	1061	5	10			252.5	126.3	656.4	308.9	50	380
77NOV	88	1821	1	1			2167.0	894.2	368.2	100	900	300
77OCT	88	1531	2	6			910.9	303.6	897.6	349.1	50	149
TOTAL	86	15139	25	194	720.6	92.9	13	149	11	*07	0	1

THIS PAGE IS BASIC QUALITY PRACTICE
FROM COPY PUBLISHED TO DDC

SECTION III
EQUIPMENT ANALYSIS

F-4E RADAR SCOPE CAMERA SYSTEM

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> ● Minimal complexity (two LRUs) ● BIT features ● Simple repair by LRU replacement 	<ul style="list-style-type: none"> ● Scheduled maintenance (test, clean, lubricate) is required every 600 flying hours per -6 	<ul style="list-style-type: none"> ● Flightline maintenance environment
Accessibility	<ul style="list-style-type: none"> ● Very good (LRUs in cockpit) 	<ul style="list-style-type: none"> ● Camera cable is hidden from view (broken cable following scope maintenance is common) 	<ul style="list-style-type: none"> ● Camera is mounted on scope and must be removed each time scope maintenance is necessary
AGE of System and Technology	<ul style="list-style-type: none"> ● Solid-state components ● No flightline adjustments required 	<ul style="list-style-type: none"> ● Late '60s technology ● Electro-mechanical components 	<ul style="list-style-type: none"> ● Control panel rotary switches
Debriefing	<ul style="list-style-type: none"> ● Comprehensive sortie data logged on TAC form 93 		
Depot Support	<ul style="list-style-type: none"> ● Depot support adequate ● Depot shop has test/repair capability for LRUs 		
Pre, In, Post-flight Inspection	<ul style="list-style-type: none"> ● Accomplished by aircrews ● Limited to operational check 		<ul style="list-style-type: none"> ● Positive indication of proper operation is not provided
Level of Base Repair	<ul style="list-style-type: none"> ● LRUs are "I" level repairable for most failures (95% est.) 	<ul style="list-style-type: none"> ● Frequency control repair authorized in field 	

F-4E RADAR SCOPE CAMERA SYSTEM

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
<u>M</u> Characteristics of Equipment Design	<ul style="list-style-type: none"> BIT features Film packs loaded by Kodak Components are "I" level replaceable Modularized camera (two LRUs) 	<ul style="list-style-type: none"> No plug-in modules 	<ul style="list-style-type: none"> No external indicator is provided to indicate film is advancing when motor power light is on
Maintenance Data Collection Documentation and Feed-back System	<ul style="list-style-type: none"> Automated data processing Periodic reports Special reports as requested 	<ul style="list-style-type: none"> Accuracy of data recorded 	
Maintenance Organization	<ul style="list-style-type: none"> Two-level maintenance organization (I-level shop dispatches to flightline for system removal/installation) 		
Organizational Level AGE	<ul style="list-style-type: none"> No flightline test equipment is required 	<ul style="list-style-type: none"> "I" level boresighting equipment is not used very often. Optical maintenance should have been authorized for the depot only 	
Preventive Maintenance	<ul style="list-style-type: none"> Scheduled maintenance (primarily for cleaning/lubrication) does not appear essential to reliable operation of the system 	<ul style="list-style-type: none"> Scheduled maintenance (check, clean, lubricate per -6). Required system removal from aircraft and LRU disassembly in "I" level shop. 	
Technical Orders	<ul style="list-style-type: none"> T.O.s are adequate 		

F4-F RADAR SCOPE CAMERA SYSTEM

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Training and Personnel Skills Level	<ul style="list-style-type: none"> ● Extensive training is not essential for maintenance of this simple system 		
Troubleshooting Methods	<ul style="list-style-type: none"> ● LRUS tested in shop on test set (no substitution in aircraft) 		

F-4E TARGET IDENTIFICATION ELECTRO-OPTICAL (TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> BIT for some system functions System repair by LRU replacement 	<ul style="list-style-type: none"> No preventive maintenance inspections per -6 Complexity (4 LRUs) slows fault isolation 	<ul style="list-style-type: none"> Flightline maintenance environment
Accessibility	<ul style="list-style-type: none"> LRU-4 very accessible (in cockpit) 		<ul style="list-style-type: none"> Poor accessibility to LRU-2 for fault isolation and replacement Panels surrounding LRU-1 are attached with screws having heads requiring a special tool LRU-3 is located behind panel with 36 fasteners
AGE of System and Technology	<ul style="list-style-type: none"> Mid '70s technology Solid-state components Plug-in modules in high-failure LRUs 	<ul style="list-style-type: none"> External cooling air required Electro-mechanical components 	<ul style="list-style-type: none"> Flightline adjustments required Module connectors can be easily damaged Control panel rotary switches
Debriefing	<ul style="list-style-type: none"> Comprehensive sortie data logged on TAC form 93 		
Depot Support	<ul style="list-style-type: none"> Depot shop has test/repair capability for LRUs and SRUs 	<ul style="list-style-type: none"> LRUs from depot require realignment by "I" level before aircraft installation 	<ul style="list-style-type: none"> Inadequate spares are available at "I" level
Pre, In, Post-flight Inspections	<ul style="list-style-type: none"> All inspections performed by aircrews Continuous BIT; status indicator on control panel 	<ul style="list-style-type: none"> Boresight adjustments on control panel Extensive operational check required 	<ul style="list-style-type: none"> Boresight harmonization check/alignment required of aircrew Low-light operation might damage system

F-4E TARGET IDENTIFICATION ELECTRO-OPTICAL (TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Level of Base Repair	<ul style="list-style-type: none"> System repair by LRU replacement on the flight line LRU repair by SRU replacement 		<ul style="list-style-type: none"> • LRU-1 only 50% repairable at "I" level
M Characteristics of Equipment Design	<ul style="list-style-type: none"> Modularized system (four LRUs) Modularized LRUs (LRU-1, 2) BIT 	<ul style="list-style-type: none"> Test connector in cockpit (on control unit) for BIT failure fault isolation Interface test set for flightline use 	<ul style="list-style-type: none"> Access for test set hookup to LRU-2 is very limited in aircraft • LRU-2 replacement is difficult
Maintenance Data Collection Documentation and Feedback System	<ul style="list-style-type: none"> Automatic data processing Periodic reports Special reports as requested 	<ul style="list-style-type: none"> Accuracy of data recorded 	
Maintenance Organization	<ul style="list-style-type: none"> CRS personnel assist with aircraft periodic inspections to gain flightline experience on TISEO system 		
Organizational Level AGE		<ul style="list-style-type: none"> Interface test set is not used often (substitution is normal fault-isolation method) 	<ul style="list-style-type: none"> • Interface test set for flightline use is not used due to poor accessibility to LRU-2 connector
Preventive Maintenance			<ul style="list-style-type: none"> • Systems installed in aircraft must be realigned periodically to maintain boresight harmonization • LRUs received from depot require alignment prior to aircraft installation

F-4E TARGET IDENTIFICATION ELECTRO-OPTICAL (TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Technical Orders	<ul style="list-style-type: none"> • T.O.s are considered adequate 		
Training and Personnel Skills Level	<ul style="list-style-type: none"> • Photo technicians in the Photosensor shop are being trained to maintain the TISEO • Photosensor shop personnel assist with the 180 inspection on the aircraft to gain system experience 	<ul style="list-style-type: none"> • AGS flightline maintenance personnel have no shop experience on the TISEO 	
Troubleshooting Methods	<ul style="list-style-type: none"> • Shop personnel are able to fault isolate LRUs using test equipments and T.O.s 	<ul style="list-style-type: none"> • Substitution is used exclusively on the flightline 	<ul style="list-style-type: none"> • Mockup/spare SRUs are not available for substitution purposes

STRIKE CAMERA - KB-18A F-111D

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> Built-in-test No special maintenance aid No local modifications 		<ul style="list-style-type: none"> 125 minor inspection 500 major inspection
Accessibility	<ul style="list-style-type: none"> Access to camera including loadup, removal, replacement requires 15 minutes Access to control unit including removal/replacement requires 20 minutes Quick release fittings on access panel to camera Quick release fitting and snap-lock hinges used to secure camera 		<ul style="list-style-type: none"> Removal of camera control unit from avionics compartment hampered by pressure of wire bundles
AGE of System and Technology	<ul style="list-style-type: none"> Mature system Quick-disconnect connectors 	<ul style="list-style-type: none"> Electro-mechanical components Wiring harnesses/bundles Plug-in printed circuit cards 	<ul style="list-style-type: none"> Discrete solid-state components 10-year old technology Analog design
Debriefing	<ul style="list-style-type: none"> Debriefing performed 	<ul style="list-style-type: none"> Debriefing necessary 	<ul style="list-style-type: none"> Very little useful information from a maintenance aspect is provided during debriefing
Depot Support	<ul style="list-style-type: none"> Adequate spares provide through component level depot repair 		
(Pre, In, Post) – Flight Inspection	<ul style="list-style-type: none"> None required 		
Level of Base Repair	<p>(0) • Operate BIT</p> <p>(1) • Remove/replace LRU</p> <p> • Component level repair</p> <p> • SRU/LRU repair beyond the capability of I level</p>	<p>(I) • Component and SRU level repair</p>	<p>(0/I) • 125-hour phase inspections</p>

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design	<ul style="list-style-type: none"> • High reliability - >98% over 21 months • Easy access to LRUs • Solid-state design 	<ul style="list-style-type: none"> • Use of photo film instead of video tape or similar 	<ul style="list-style-type: none"> • Cable assembly inhibits removal of control unit • BIT/self-test requires two people: One person to activate and monitor BIT at the control unit and one person to visually monitor camera. • LRUs not co-located (included in above) • Camera is not gyro-stabilized • Component parts soldered vice plug-in (i.e., piece parts on printed circuit cards) • Camera test set (LS-83A) is reported to provide erratic readings with or without test set maintenance/calibration • Problem with alignment of IJ1 connector to camera body during re-assembly after work on drive assembly • Temperature control-heater fan inhibits access to temperature control switch. Removal of fan is necessary.
Maintenance Data Collection Documentation and Feedback System		<ul style="list-style-type: none"> • Constant review and analysis not required due to high camera system reliability 	
Maintenance Organization			

STRIKE CAMERA - KB-18A F-111D

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Organizational Level AGE	<ul style="list-style-type: none"> No maintenance AGE 	<ul style="list-style-type: none"> Electrical ground power unit required External air-conditioning unit required 	<ul style="list-style-type: none"> 125-hour phase inspections required
Preventative Maintenance			
Technical Orders	<ul style="list-style-type: none"> Hard copy TOs required To date 'adequate' to support strike camera system 		
Training and Personnel Skills Level		<ul style="list-style-type: none"> More attention is needed in manning to rank and skill level Human factor aspects of equipment/support system design requires reevaluation in light of increased integration of female technicians into the maintenance complex Technician basic system knowledge acquired through OTJ 	
Troubleshooting Methods	<p>(O) Substitution of like item (LRU) based on results of BIT/self-test or operational failure characteristics</p> <p>(I) Test equipment employed</p> <p>(T) Substitution of like item (SRU and component part)</p> <p>(D) Repair LRU/SRUs beyond the capability or scope of I level</p> <p>(D) Repair performed to and including discrete component level</p>	<p>(O) Camera related wiring problems in the aircraft are repaired by electrical vice camera shop personnel</p> <p>(O) Camera system repair (LRU) may require visual/temporal evaluation of system</p>	

RADAR SET AN/APQ-130 F-111D

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> • Solid-State circuitry • No radar system inspection requirements • System integrated BIT • BIT verifies fault presence 	<ul style="list-style-type: none"> • Removable equipment rack 	<ul style="list-style-type: none"> • BIT does not identify specific faulty LRU/fault isolation
Accessibility of Avionics	<ul style="list-style-type: none"> • Major LRUs co-located in same equipment bay • LRUs secured in equipment rack with CALFAX-type quick-release stress panel fasteners 	<ul style="list-style-type: none"> • Rear mounted LRU electrical connectors • Use of jackscrews for LRU electrical connector insertion/extraction 	
Age of System and Technology	<ul style="list-style-type: none"> • Digital system design • Quick disconnect connectors at interface 	<ul style="list-style-type: none"> • Highly integrated design • Solder connections • Plug-in LRUs in equipment rack • Wiring harness/bundles employed • Microdot wiring used • Waveguides • Software programming hard-wired into the computer 	<ul style="list-style-type: none"> • Design reflects technology of the mid-to-late 1960s. • Discrete components
Debriefing	<ul style="list-style-type: none"> • Debriefing conducted • 'Expeditor' used to initiate and monitor corrective maintenance action by AGS for problems identified during debriefing • Avionics history log maintained by AGS 	<ul style="list-style-type: none"> • Debriefing necessary 	<ul style="list-style-type: none"> • Maintenance personnel do not have access to flight crew during debriefing. • Information documented on AFTO 349/350 is not thorough enough to provide necessary visibility required to perform efficient maintenance

RADAR SET AN/APQ-130 F-111D (Continued)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Depot Support	<ul style="list-style-type: none"> Depot support present 	<ul style="list-style-type: none"> Two separate depots for AN/APQ-130. One depot for LRUs (Sacramento) and one for SRUs (Warner-Robins) 	<ul style="list-style-type: none"> Spare support a problem at component, SRU and LRU levels Less than expected reliability level for the system Incompatibility between source selection codes and maintenance concept as it relates to LRU and test equipment repair Functional problems exist during early problem implementation tying up operational unit support spares Hybrid spares support is a problem due to limited stock and items out-of-production Test spec incompatibility between field and depot test equipment SRUs exhibit matched set characteristics within LRUs Field level maintenance not informed of depot modifications which change field level test specs
(PRE, IN, POST) Flight Inspection			
Level of Base Repair	<p>(ALL) Level of Repair in agreement with maintenance concept</p> <p>(ALL) No scheduled maintenance at any repair level</p>	<p>(0) Troubleshooting necessary</p> <p>(I) Use of a hot mock-up necessary to isolate problem LRU/SRUs that cannot be repaired at the test station</p> <p>(D) Semi-automatic vice automatic test equipment employed for depot repair</p>	<p>(0) Substitution of 'suspected' LRUs necessary due to BIT limitations</p> <p>(0) Pre and post flight troubleshooting using aircraft power in an effort to approximate inflight conditions and increase OR rate</p>

RADAR SET AN/APQ-130 F-111D (Continued)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design	<ul style="list-style-type: none"> • Solid-state circuitry • Calfax stress panel fasteners for LRU retention • Easy access to LRUs in avionics bay • BIT is effective in identification of fault presence 	<ul style="list-style-type: none"> • Rear-mounted electrical pin connectors • Jackscrews employed for LRU insertion/extraction • BIT activated from cockpit • Duplexer (waveguide) present for unused (past and current) mode • Equipment rack removal • Pin replacement in connectors is a common problem due to pin malfunction • Repair of stripped female jackscrews requires drilling out old fitting in inserting and setting a new fitting • Use of wiring sensitive to stressing/vibration/aging • Microdot wiring used • Avionics maintenance personnel can not replace faulty female jackscrew fittings • Ribbon cable used • Electro-mechanical assemblies employed • Electro-hydraulic assemblies employed • Fuses used vice circuit breakers • Wire cables are used as an interface between LRUs and test equipment 	<ul style="list-style-type: none"> • BIT does not accurately identify problem source (LRU) • BIT limitations provide inadequate flightline fault isolation capability and promote 'shotgun' removals, excessive test time, and induced failures • Video cables to front of EPU are poorly protected. Repeated removal results in wire breaks • Unpredictable environmental dehumidifier saturation prior to scheduled removal resulting in moisture build-up/failures • High maintenance to flight hour ratio (2.3 MMH/FH) • Equipment rack removal difficult • Apparent poor quality pin insertion/extractor tool • Pin replacement in connectors is difficult • Female fitting for LRU jackscrews strip with age/use • Vibration and stressing (aging) of microdot wiring causes intermittent shorts and open circuit failures • Screw-type vice quick-release type fasteners used to secure LRU panels • Matched waveguides used on antenna mount

RADAR SET AN/APQ-130 F-111D (Continued)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design (continued)	<ul style="list-style-type: none"> ● Maintenance personnel estimate that 50% of maintenance time is employed with problems related to broken wires in connectors and cables at the equipment interface ● Technologically obsolescent maintenance equipment used to service the TWT oil cooling system ● About 25% of the transmitter maintenance requires violation of the environmental integrity of the TWT oil cooling system to repair oil leaks 	<ul style="list-style-type: none"> ● ARS (AN/APQ-130), especially EPU, is too sensitive to heat and cold ● Antenna ranging problems have occurred during periods of extreme cold (winter) ● Wire breaks in ribbon cable have occurred where ribbon cable is accessible to or handled by organizational and field level maintenance personnel ● Antenna feedhorn position (boresight) extremely sensitive to misalignment due to transportation/handling ● Majority of transmitter problems (60-75%) involve blown fuses ● Transmitter fuses are positioned in such a way (rear) as to make checking/replacement difficult ● Maintenance personnel can not access EPU for plug/pin checks when EPU plugged into test station ● Cable interface between LRU/test station develop wire breaks and intermittent shorts ● Cable interface between LRU/test station sensitive to bending/flexing (such as when storing or making connections) 	

RADAR SET AN/APQ-130 F-111D (Continued)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintenance Data Collection Documentation and Feed-Back System	<ul style="list-style-type: none"> ● Maintenance data collection is in accordance with the AFM 66-1 ● Constant review and analysis is performed ● Feedback information has been effective ● ARS personnel maintain an avionics history log by aircraft tail number which describes malfunctions and corrective action 	<ul style="list-style-type: none"> ● Effectiveness of feedback information dependent upon the presence of (need for) a qualified analyst ● Avionics history log required or necessary 	<ul style="list-style-type: none"> ● MDCS required to perform effective maintenance/troubleshooting
Maintenance Organization			
Organizational Level AGE		<ul style="list-style-type: none"> ● Required AGE is available 	<ul style="list-style-type: none"> ● AGE required ● AGE, while required and available, is not generally used ● AGE for transmitter (AGERD 6689 fixture) must be used in conjunction with an MJ-4 lift truck
Preventative Maintenance		<ul style="list-style-type: none"> ● No PM schedule for the AN/APQ-130 radar 	

RADAR SET AN/APQ-130 F-111D (Continued)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Technical Orders	<ul style="list-style-type: none"> Technical orders provide good functional and system interface description 	<ul style="list-style-type: none"> Hard copy technical orders required 	<ul style="list-style-type: none"> Poor technical order description regarding test points Insufficient technical data to trace signals Multiple technical orders frequently required for troubleshooting
Training and Personnel Skill Level	<ul style="list-style-type: none"> 'Authorized' skill requirements adequate to meet maintenance concept Basic training on APQ-130 is adequate 	<ul style="list-style-type: none"> APQ-130 system experience biggest asset in making effective repairs 	<ul style="list-style-type: none"> Equipment/support system design does not reflect re-evaluation of human factors in light of integration of female technicians into the maintenance complex
Troubleshooting Methods	<p>(O) BIT single and sequence mode tests</p> <p>(O) BIT used for identification of problem presence</p> <p>(D) Functional testing/verification of all returned/repaired LRUs</p>	<p>(O) High level of system integration</p> <p>(I) Hot mock-up used to screen and solve problem not resolved by the test station</p> <p>(I) Semi-automatic test equipment</p> <p>(I) Central computer processing employed with test stations (time-sharing)</p> <p>(D) Manual probing required to isolate faulty discrete components</p>	<p>(O) BIT ineffective in identification of problem source (faulty LRU). Replacement of BIT indicated faulty LRU frequently fails to resolve problem</p> <p>(O) Erroneous/spurious BIT indications require temporal analysis</p> <p>(I) Maintenance personnel have extremely low confidence level in 'I' level test station (RTM)</p> <p>(I) A significant amount of manual testing is performed at the 'I' level LRU functional layout requires 'jumping around' to different SRUs to troubleshoot a signal path</p>

C-5A AN/ARC-109 RADIO


AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> Redundant radio sets (two per aircraft) Low complexity (two LRU per set) Ease of repair (LRU replacement) Benign maintenance environment BIT features 	<ul style="list-style-type: none"> No preventive maintenance inspections per -6 	
Accessibility	<ul style="list-style-type: none"> Console mounting in cockpit of control unit Rack mounting in avionics compartment on flight deck of R/T unit 		
AGE of System and Technology	<ul style="list-style-type: none"> Solid-state components Plug-in modules (R/T unit only) Front panel thumbwheel switches 	<ul style="list-style-type: none"> Early '70s technology Electro-mechanical channel selector Non-modularized control unit 	<ul style="list-style-type: none"> Cooling air for R/T unit is required Sealed and pressurized R/T unit case Front panel rotary switches
Debriefing	<ul style="list-style-type: none"> Comprehensive sortie data logged on MAC form 278 		<ul style="list-style-type: none"> Limited/inaccurate malfunction function description is relayed to maintenance shop
Depot Support	<ul style="list-style-type: none"> Depot shop has test/repair capability for LRUs/SRUs Depot shop has same equipment as field shops 		<ul style="list-style-type: none"> SRU repair authorized at "I" level
Pre, In, Post-flight Inspections	<ul style="list-style-type: none"> Performed by aircrew Limited to operational check 		


C-5A AN/ARC-109 RADIO

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Level of Base Repair	<ul style="list-style-type: none"> System repair by LRU replacement LRU repair by SRU replacement 	<ul style="list-style-type: none"> SRU repair authorized at "I" level 	
M Characteristics of Equipment Design	<ul style="list-style-type: none"> Redundant systems in aircraft Modular R/T unit R/T unit test meter 	<ul style="list-style-type: none"> Non-modularized control unit 	<ul style="list-style-type: none"> Internally mounted fuze Preset function design SRUs (2) beyond "I" level repair capability
Maintenance Data Collection Documentation and Feedback System	<ul style="list-style-type: none"> Automated data processing Periodic reports Special reports if requested 	<ul style="list-style-type: none"> Accuracy of data logged on the 349s 	
Maintenance Organization	<ul style="list-style-type: none"> Two-level maintenance system (flightline maintenance performed by "I" shop) 		
Organizational Level AGE	<ul style="list-style-type: none"> Flightline test set authorized 	<ul style="list-style-type: none"> Flightline test set not used 	<ul style="list-style-type: none"> User-built interconnection box for AN/ARC-109 testing
Preventive Maintenance		<ul style="list-style-type: none"> None required 	
Technical Orders			
Training and Personnel Skills Level		<ul style="list-style-type: none"> Least experienced work air-craft problems on flightline 	<ul style="list-style-type: none"> High attrition rate
Troubleshooting Methods		<ul style="list-style-type: none"> Exclusive use of substitution techniques on flightline 	

AD-A080 495 HUGHES AIRCRAFT CO CANOGA PARK CALIF MISSILE SYSTEMS--ETC F/G 1/3
DESIGN-FOR-REPAIR CONCEPT DEFINITION VOLUME II. DETAILED ANALYS--ETC(U)
AUG 79 F A GERKIN, J L GREEN, J M KING F33615-78-C-1461
UNCLASSIFIED MSG-9285-VOL-2 AFAL-TR-79-1130-VOL-2 NL

2 OF 3
AD
A080495





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963

C-5A MARK V TACAN

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> ● Redundant TACAN sets (two per aircraft) ● Low complexity (two LRUs per set) ● BIT for system check ● Ease of repair (LRU replacement) ● Benign maintenance environment 	<ul style="list-style-type: none"> ● No preventive maintenance inspections per -6 	
Accessibility	<ul style="list-style-type: none"> ● Control unit console mounted in cockpit ● R/T unit rack mounted in avionics compartment on flight deck 		
AGE of System and Technology	<ul style="list-style-type: none"> ● Solid-state components ● Plug-in modules (R/T unit only) ● Plug-in circuit boards in R/T unit modules ● Non-pressureized R/T unit case ● No electro-mechanical components 	<ul style="list-style-type: none"> ● Early '70s technology ● External cooling air required for R/T unit ● Non-modularized control unit 	<ul style="list-style-type: none"> ● Front panel rotary switches
Debriefing	<ul style="list-style-type: none"> ● Comprehensive sortie data logged on MAC form 278 		<ul style="list-style-type: none"> ● Limited/inaccurate malfunction description is relayed to maintenance shop

C-5A MARK V TACAN

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Depot Support	<ul style="list-style-type: none"> Depot shop has test/repair capability for LRUs/SRUs Depot shop has same LRU test equipment as field shops Depot shop has SRU test sets to facilitate test and repair 		<ul style="list-style-type: none"> Control unit and some R/T unit repairs beyond field capability
Pre, In, Post-flight Inspection	<ul style="list-style-type: none"> Performed by aircrew Limited to operational check/BIT 		<ul style="list-style-type: none"> LRU repairs beyond field capability
Level of Base Repair	<ul style="list-style-type: none"> System repair by LRU replacement LRU repair by SRU replacement 		
<u>M</u> Characteristics of Equipment Design	<ul style="list-style-type: none"> Redundant aircraft TACAN sets Modularized R/T unit Plug-in circuit boards in R/T unit modules Test connector on R/T unit 	<ul style="list-style-type: none"> BIT (not required by aircrews or maintenance personnel to check system operation) Non-modularized control unit No BIT meter on R/T unit 	<ul style="list-style-type: none"> Control unit design which precludes field repair
Maintenance Data Collection, Documentation and Feedback System	<ul style="list-style-type: none"> Automated data processing Periodic reports Special analysis if requested 		<ul style="list-style-type: none"> Accuracy of data logged on the 349s
Maintenance Organization		<ul style="list-style-type: none"> Two-level maintenance system (flightline maintenance performed by Nav Shop) 	

C-5A MARK V TACAN

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Organizational Level AGE	<ul style="list-style-type: none"> • Common, portable, simple-to-use flightline test set 	<ul style="list-style-type: none"> • Flightline test set not utilized • "I" level test set complexity 	<ul style="list-style-type: none"> • "I" level test set design deficiencies (interconnection cable connector problems)
Preventive Maintenance		<ul style="list-style-type: none"> • None required 	
Technical Orders	<ul style="list-style-type: none"> • Flightline and overhaul manuals satisfactory 		<ul style="list-style-type: none"> • "I" level manual problems (complex checkout procedure, many changes, TOPS pages excessive)
Training and Personnel Skills Level		<ul style="list-style-type: none"> • Five-level manning is low (66% of authorized) 	
Troubleshooting Methods		<ul style="list-style-type: none"> • Exclusive use of substitution techniques on flightline 	

F-15 RADAR SET AN/APG-63

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> • High frequency, pulse doppler • 0.5 MMH/FH • No -6 inspection requirements 	<ul style="list-style-type: none"> • Weapon System Integrated BIT 	
Accessibility of Avionics	<ul style="list-style-type: none"> • Generally no accessibility problems • Majority of LRUs are co-located in the forward-left nose equipment bay. • Most units can be removed or replaced within 5 minutes. • Quick disconnects provided for electrical cables, coaxial cables, liquid cooling lines and waveguides. • LRU secured by rack mounted, swing-latch bolts. 		
Age of System and Technology	<ul style="list-style-type: none"> • Solid state design • Micro-electronic circuitry • Hybrids • Programmable signal processor 	<ul style="list-style-type: none"> • Electro-hydraulic components • Electro-mechanical components • Late 60's - early 70's technology • Waveguides • Multi-strand wire cables • Combined analog and digital processing • Ribbon cable 	<ul style="list-style-type: none"> • Maintenance personnel do not attend debriefing or have a qualified representative. • Information documented by the debriefer on the AFTO 349 is not sufficient enough to provide the necessary visibility required to perform maintenance.
Debriefing	<ul style="list-style-type: none"> • Debriefing Performed 	<ul style="list-style-type: none"> • Debriefing necessary for maintenance • Even with debriefing, maintenance personnel often have to perform functional testing to identify problem areas. 	

F-15 RADAR SET AN/APG-63

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Depot Support	<ul style="list-style-type: none"> Depot Support Established LRU and SRU repair performed at the same depot (Warner-Robins) 	<ul style="list-style-type: none"> MACAIR Interim Depot 	<ul style="list-style-type: none"> Continuing functional problems have reduced spare resources (LRU and SRU) available to operational units. Of the unsatisfactory reports received by the depot, over 50% test good, and over 45% are problems associated with test tolerances. Due to paucity of resources, some modules, classified as throwaway, are being accepted and repaired by the depot.
(Pre, In, Post) - Flight Inspection	<ul style="list-style-type: none"> None required 		
Level of Base Repair	<ul style="list-style-type: none"> No scheduled maintenance No deviation from specified maintenance concept. 		
Maintainability Characteristics of Equipment Design	<ul style="list-style-type: none"> Solid state circuitry Quick disconnect cannon-type plugs for wiring interface to and between LRUs. Quick disconnect swing-latch fasteners for simplified installation/removal of waveguides and LRUs. Each major (powered) LRU has a BIT fault indicator. BIT provides inflight continuous monitoring. Operator initiated BIT employed to determine unit and overall system status. 	<ul style="list-style-type: none"> Maintenance personnel would like a hot mockup to screen suspected LRUs and to provide for functional testing of repaired LRU's. Troubleshooting of the transmitter (011) requires draining of the liquid coolant (oil). Test points for the (011) transmitter are not located so that the majority of troubleshooting could be performed without violating the environmental integrity of the cooling system. 	<ul style="list-style-type: none"> Organizational and intermediate level maintenance personnel have noted apparent tolerance differences between depot and intermediate test equipment an AN/APG-63 BIT. LRUs sometimes exhibit a tendency to operate as matched sets. Transmitter (011) maintenance equipment: Fill-drain system for oil coolant requires 45 minutes to drain, purge, fill and recirculate oil.

F-15 RADAR SET AN/APG-63

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design (continued)	<ul style="list-style-type: none"> • BIT determines fault presence (essentially fully effective) • BIT traces fault to specific LRU (70-80% effective) • BIT fault indicators provided for each major LRU. 	<ul style="list-style-type: none"> • Troubleshooting false radar target problems ('Birds') requires detailed data on radar operational mode and observed display pattern. A more technically accurate troubleshooting method is needed. • Potentially dangerous situation exists when removing certain LYPS (610) seals due to presence of pressurized nitrogen. • Pin insertion/extractor tools are considered to be of poor quality - malfunction or breaking after 1-3 uses. • Forward equipment bay doors must be opened before radome mounting bolts can be accessed. • Maintenance delays are reported by radar technicians due to requirement for ECS (Environmental Control) personnel to service the AN/APG-63 coolant system. Radar technicians would prefer to service the coolant system themselves as it relates to the AN/APG-63. 	<ul style="list-style-type: none"> • BIT inconsistency - it is sometimes difficult to verify inflight BIT failures under ground power conditions or to obtain consistent BIT indications. • Insufficient organizational AGE (primarily electrical power and air cooling units) to support maintenance. • Use of screw-on vice plug-in coaxial connector on the receiver (022). • Pin replacement in connectors is difficult. • Moisture problems exist with the waveguide providing 'RF' to the missiles station from the radar (problem is associated with the water separator). • BIT for radar range and angle tracking functions needs improvement (such as the provision of a low power level output through a dummy load to check these functions).

F-15 RADAR SET AN/APG-63

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintenance Data Collection Documentation and Feedback System	<ul style="list-style-type: none"> Maintenance data collection is in accordance with AFM 66-1. Constant review and analysis is performed. Feedback information has been effective. Failure trend analysis are performed by on-site contractor representatives which have proven to be most useful. 	<ul style="list-style-type: none"> Effectiveness of feedback information is dependent upon the presence of (need for) a qualified analyst. 	<ul style="list-style-type: none"> MDCS required to perform effective maintenance/troubleshooting.
Maintenance Organization			
Organizational Level AGE		<ul style="list-style-type: none"> Required AGE is available 	<ul style="list-style-type: none"> In actual practice, maintenance personnel will use AGE only when absolutely necessary.
Preventative Maintenance	<ul style="list-style-type: none"> No PM scheduled for the AN/APG-63 radar. 		
Technical Orders	<ul style="list-style-type: none"> Technical orders available at all maintenance levels. 	<ul style="list-style-type: none"> Hard copy T.O.s required Depot level technicians find it to be cumbersome to trace necessary data through multiple T.O.s. 	<ul style="list-style-type: none"> Sufficient data on BIT operation is not provided to organizational maintenance personnel. Difficulty is encountered in discriminating between system and BIT failure.

F-15 RADAR SET AN/APG-63

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Technical Orders (continued)			<ul style="list-style-type: none"> BIT Matrix data (LRU BIT failure parameters) are not available to 'I' level technicians - such data would facilitate more efficient troubleshooting.
Training and Personnel Skills Level	<ul style="list-style-type: none"> 'Authorized' skill requirements adequate to meet maintenance concept 	<ul style="list-style-type: none"> AN/APG-63 experience is biggest asset in making effective repairs. Extensive AN/APG-63 OJT required for a technician to become proficient; basic training in electronics for unexperienced personnel needs to be expanded. 	<ul style="list-style-type: none"> 'Authorized' skills level requirements not available Equipment/support system design does not reflect revaluation of human factors in light of integration of female technicians into the maintenance complex.
Troubleshooting Methods	<p>(O) BIT employed to identify faulty LRUs.</p> <p>(D) Functional testing/ verification of all returned/repaired LRUs.</p>	<p>(I/D) Manual probing/testing necessary to supplement ATE.</p>	<p>(O/I) When local spares become critical, a hot mockup used to screen and re-pair faulty LRUs (aircraft with an operational radar used as a hot mockup).</p>

F-15 RADAR SET AN/APG-63

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Technical Orders (continued)			<ul style="list-style-type: none"> • Schematics and definitive diagrams are not provided to aid field level technicians in troubleshooting. • Field level technical orders are of little use in aiding technicians in finding faults not detected by automatic test equipment. • Test spec updates occasioned by depot level mods are not communicated to intermediate maintenance in a timely manner. Units are erroneously rejected at 'I' level due to testing to the wrong specs. • Insufficient program documentation provided to "I" level technicians for soft-wave/software changes. As a result, it is difficult to determine exactly what circuitry is being tested. • Absence of feedback from depot to 'I' level on NRTS items. NRTS failure data could facilitate more accurate and complete 'I' level troubleshooting of like items. • Reported inconsistencies between T.O. and test stations terminology.

F-15 ARMAMENT CONTROL AN/AWG-20

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> • AN/AWG-17 reconfigured to AN/AWG-20 by combining three LRUs into two. • Automatic Bit and initiated BIT circuit. • No spectral maintenance aids or local modifications 		
Accessibility of Avionics	<ul style="list-style-type: none"> • No accessibility problems with converter programmer (located in forward left avionics bay). • Converter programmer requires only 3-4 minutes to remove or replace. • Converter-programmer wiring interface features quick disconnect cable plugs. • Converter-programmer secured with quick release hinged latches. 	<ul style="list-style-type: none"> • ACP secured in instrument console with 'Phillips' type brass screws. 	<ul style="list-style-type: none"> • Some difficulty encountered in removal/replacement of armament control panel due to limited play of ACP wire bundle at rear of ACP (ACP mounted in left side of pilots forward instrument console within cockpit). • Brass 'Phillips' type screws securing ACP strip at the star slots.
Age of System and Technology	<ul style="list-style-type: none"> • AN/AWG-20 features integrated circuitry, hybrids, extensive microelectronics and printed circuit cards. • Wire-wrap connections • Digital design • Quick disconnect connectors for wiring and waveguides at interface. 	<ul style="list-style-type: none"> • AN/AWG-20 installed in F-15 around 1973 but reflects mid-to late 60's technology. • AN/AWG-20 installed in F-15 airframe using system integration approach. • Waveguides used • AN/AWG-20 is pre-programmed and controlled from central computer. • Wiring cables/bundles 	<ul style="list-style-type: none"> • Soldered connections

F-15 ARMAMENT CONTROL AN/AWG-20

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Debriefing	<ul style="list-style-type: none"> • Debriefing performed 	<ul style="list-style-type: none"> • Debriefing necessary 	<ul style="list-style-type: none"> • AN/AWG-20 maintenance personnel do not attend debriefing - discrepancy information is relayed via AFTO 349
Depot Support	<ul style="list-style-type: none"> • Depot support established • LRU and SRU depot maintenance located at same facility. 	<ul style="list-style-type: none"> • About a 15% AWP rate • MACAIR Interim Depot 	<ul style="list-style-type: none"> • Spare support is a continuing problem at the LRU level • Pipeline spares requirement has been significantly increased due to increased depot maintenance time caused by manual probe requirements.
(Pre, in, Post)-Flight Inspection			<ul style="list-style-type: none"> • Stay voltage check necessary (safety requirement)
Level of Base Repair	<ul style="list-style-type: none"> • No scheduled maintenance required • No deviation from specified maintenance concept 		<ul style="list-style-type: none"> • Pre and Post flight inspections performed (stray voltage check using AWM-75)
Maintainability Characteristics of Equipment Design	<ul style="list-style-type: none"> • Solid state design with BIT • Plug-in SRUs • BIT is good for confirming error presence 	<ul style="list-style-type: none"> • Poor quality pin extractor/insertion tools 	<ul style="list-style-type: none"> • BIT does not resolve faults to LRU. • BIT circuits fail more frequently than primary functions • Problem with wires pulling and breaking at quick-disconnect plugs • Trouble is experienced in replacing pins in connectors.

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design (continued)			<ul style="list-style-type: none"> Shortage of spare LRUs has resulted in extensive cannibalization
Maintenance Data Collection Documentation and Feed Back System	<ul style="list-style-type: none"> MDCS is in accordance with the procedures of AFM 66-1 Local management and special study reports are provided at the base level. 	<ul style="list-style-type: none"> Constant review and analysis required for effective maintenance 	
Maintenance Organization			
Organizational Level AGE	<ul style="list-style-type: none"> Required AGE available 	<ul style="list-style-type: none"> AGE required to perform maintenance Base level capability exists to repair AN/AWM-74 (tests launchers, racks, pylons) at PMEL - but test set designated for depot repair. 	
Preventive Maintenance	<ul style="list-style-type: none"> None required 		
Technical Orders	<ul style="list-style-type: none"> T0s are adequate to perform maintenance as authorized 	<ul style="list-style-type: none"> T.O. logic trees are difficult to understand 	
Training and Personnel Skill Levels	<ul style="list-style-type: none"> Personnel assigned are considered to be satisfactorily qualified mechanically 		<ul style="list-style-type: none"> Personnel assigned are considered to be deficient in electronic qualifications

F-1, ARMAMENT CONTROL AN/AWG-20

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Troubleshooting Methods	<ul style="list-style-type: none"> (O) BIT indicates failure presence (I) Fault isolation utilizing ATE (D) Functional checkout of all returned and repaired LRUs 	<ul style="list-style-type: none"> (O) AN/AWM-72 must be used in conjunction with BIT to resolve failures to LRU. (D) Manual probing required to isolate faulty components 	<ul style="list-style-type: none"> (O) An AN/AWM-72 checkout of the weapon system requires four hours - as a result it is frequently not used to check the AN/AWG-20. Rather, the converter-programmer, historically the prime failure cause, is replaced based on a BIT indication of AN/AWG-20 fault presence. If this does not resolve problem the ACP is replaced. (I) High NRTS rate for C-P. (I) The armament control panel is time-consuming to troubleshoot. (I) C-P is difficult to troubleshoot due to insufficient test detail in T.O. (I) AIS repair capability is limited for the C-P. The majority of C-P units are NRTS items. (D) AN/AWG-20 ATE diagnostics are not fully developed

F-16 AN/ARC-164 RADIO

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> ● Minimum complexity (one LRU) ● Ease of repair (LRU replacement) 	<ul style="list-style-type: none"> ● Lack of preventive maintenance inspections ● No BIT features 	<ul style="list-style-type: none"> ● Flightline maintenance environment
Accessibility	<ul style="list-style-type: none"> ● Console mounting in cockpit maximizes accessibility of R/T unit 		
AGE of System and Technology	<ul style="list-style-type: none"> ● Mid '70s technology ● Solid-state components ● No cooling air required ● No electro-mechanical components ● Ultra-simplified R/T unit modularity (only five modules) 	<ul style="list-style-type: none"> ● R/T unit modules interconnected by flat cable 	<ul style="list-style-type: none"> ● Front panel rotary switches
Debriefing	<ul style="list-style-type: none"> ● Comprehensive sortie data logged on AFFTC form 300 	<ul style="list-style-type: none"> ● Debriefing independent of maintenance shops 	
Depot Support	<ul style="list-style-type: none"> ● Depot shop has test/repair capability for LRUs, SRUs and circuit boards ● Depot shop LRU/SRU test equipment same as field shops ● Depot shop has circuit board test sets to facilitate repair 	<ul style="list-style-type: none"> ● SRUs tested using mock-up LRU (no SRU test equipment available) 	<ul style="list-style-type: none"> ● Circuit board test equipment complexity ● Initial support limited to circuit card repair
Pre, In, Post-flight Inspection		<ul style="list-style-type: none"> ● Performed by aircrew ● Limited to operational check 	

F-16 AN/ARC-164 RADIO

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Level of Base Repair	<ul style="list-style-type: none"> • LRU repair by replacing SRU (slice) 	<ul style="list-style-type: none"> • No SRU repair authorized in "I" level shop 	<ul style="list-style-type: none"> • Lack of LRU test capability at depot initially
M Characteristics of Equipment Design	<ul style="list-style-type: none"> • Minimum complexity (one major LRU) • Maximum LRU accessibility • Modular R/T unit (only 5 modules) • Circuit boards in modules 	<ul style="list-style-type: none"> • No BIT meter 	<ul style="list-style-type: none"> • Fragile flat flex harness interconnecting modules/circuit cards can be damaged during troubleshooting and SRU replacement
Maintenance Data Collection Documentation and Feedback System	<ul style="list-style-type: none"> • Automated data processing • Periodic reports • Special reports as requested 	<ul style="list-style-type: none"> • Accuracy of data logged on forms 	
Maintenance Organization			
Organizational Level AGE	<ul style="list-style-type: none"> • Simple "I" level test set (interconnection box plus common test instruments) 	<ul style="list-style-type: none"> • Flightline test equipment not utilized 	
Preventive Maintenance		<ul style="list-style-type: none"> • None required 	
Technical Orders	<ul style="list-style-type: none"> • Flightline manuals being validated and corrected 	<ul style="list-style-type: none"> • SRUs for the "I" level not clearly defined 	
Training and Personnel Skills Level			
Troubleshooting Methods		<ul style="list-style-type: none"> • Exclusive use of substitution on flightline 	

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> ● Low complexity (three major LRUs) ● BIT for system check ● Ease of repair (LRU replacement) 	<ul style="list-style-type: none"> ● Lack of preventive maintenance inspections 	<ul style="list-style-type: none"> ● Flightline maintenance environment
Accessibility	<ul style="list-style-type: none"> ● Control unit console mounted in cockpit ● R/T and D/A converter mounted in avionics bay at shoulder height 	<ul style="list-style-type: none"> ● Twenty fasteners on avionics bay access panel 	
AGE of System and Technology	<ul style="list-style-type: none"> ● Mid '70s technology ● Solid-state components ● No electro-mechanical components 	<ul style="list-style-type: none"> ● External cooling air required 	<ul style="list-style-type: none"> ● Front panel rotary switches
Debriefing	<ul style="list-style-type: none"> ● Comprehensive sortie data logged on AFFTC form 300 		
Depot Support	<ul style="list-style-type: none"> ● LRU repair by Collins under five year RIW contract 		
Pre, In, Post-Flight Inspections		<ul style="list-style-type: none"> ● Performed by aircrew ● Limited to operational check/BIT 	
Level of Base Repair	<ul style="list-style-type: none"> ● LRU replacement on flight-line ● LRU functional check at "I" level 	<ul style="list-style-type: none"> ● No LRU repair at "I" level 	

F-16 AN/ARN-118 TACAN

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
<u>M</u> Characteristics of Equipment Design	<ul style="list-style-type: none"> ● Accessible LRUs ● R/T unit test connector 	<ul style="list-style-type: none"> ● BIT ● No test meter on R/T 	
Maintenance Data Collection Docu- mentation and Feedback System	<ul style="list-style-type: none"> ● Automatic data processing ● Periodic reports ● Special reports as required 	<ul style="list-style-type: none"> ● Accuracy of data recorded 	
Maintenance Organization			
Organizational Level AGE	<ul style="list-style-type: none"> ● Simple flightline test set authorized ● Simple "I" level test set (interconnection box with common test instruments) 		
Preventive Maintenance		<ul style="list-style-type: none"> ● None required 	
Technical Orders	<ul style="list-style-type: none"> ● Flightline manuals being validated and corrected as required 	<ul style="list-style-type: none"> ● "I" level manual very limited in scope 	
Training and Per- sonnel Skills Level	<ul style="list-style-type: none"> ● Adequate for LRU repair at "I" level if required 		
Troubleshooting Methods		<ul style="list-style-type: none"> ● Exclusive use of substitution on flightline 	

SECTION IV
SUBSYSTEM CATEGORY/EQUIPMENT ANALYSIS

ANALYSIS: COMMUNICATIONS EQUIPMENT
(AN/ARC-109 and AN/ARC-164 Radio Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> • Low system complexity (one to two LRUs) • Simplified maintenance concept (one LRU, the R/T unit contains majority of electronics, and is replaced to correct most malfunctions) • Operational tests provide adequate confidence level • Local maintenance aids/modifications not required for AN/ARC-164 • BIT meter on AN/ARC-109 (provides some quantitative test capability for maintenance purposes) 	<ul style="list-style-type: none"> • No scheduled performance checks per -6 (alignments of R/T units on a scheduled basis would improve system performance) • No BIT features on AN/ARC-164 (majority of maintenance checks and all aircrew checks are qualitative) 	<ul style="list-style-type: none"> • Antennas vulnerable to physical damage because of protrusion from fuselage, especially lower antennas • Locally manufactured AN/ARC-109 test sets (several different configurations were found in the single depot shop) • Antenna switching relays and controls not part of the R/T unit (adds to complexity of system)
Accessibility		<ul style="list-style-type: none"> • Console mounted (in cockpit) AN/ARC-164 R/T unit can be easily removed/installed in approximately 5 minutes using only screwdriver • Rack mounted AN/ARC-109 R/T unit can be easily removed/installed in approximately 10 minutes using no tools (due to convenient location in electronics compartment on flight deck of C-5) 	<ul style="list-style-type: none"> • Antenna selector relay location in AN/ARC-109 and 164 systems (other equipment must be removed to gain access for test/replacement)

ANALYSIS: COMMUNICATIONS EQUIPMENT
(AN/ARC-109 and AN/ARC-164 Radio Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Age of System and Technology	<ul style="list-style-type: none"> Mid-70s technology of AN/ARC-164 (small package, simplified interconnection between modules, etc.) Solid-state components (both AN/ARC-109 and 164) No electronic cooling air required for AN/ARC-164 R/T unit No electro-mechanical tuning in AN/ARC-164 Simplified modularity in AN/ARC-164 R/T unit (5 modules versus 11 in AN/ARC-109) Thumbwheel switches in AN/ARC-109 control panel (no lost knobs, slipping knobs, etc.) Quick release connectors and fasteners on both radio sets 	<ul style="list-style-type: none"> Early-70s technology (AN/ARC-109) requires remote R/T unit because of size, weight, etc. Flat flex-cable interconnecting modules in AN/ARC-164 R/T unit (easily damaged during maintenance) Analogue signal processing with alignments for signal levels 	<ul style="list-style-type: none"> Electronic cooling is required for AN/ARC-109 R/T unit Electro-mechanical tuning servo in AN/ARC-109 Rotary switches on AN/ARC-109 and -164 control panels (problems: lost knobs, slipping knobs, knobs lost in cockpit, etc.) Analog signal processing with alignments for signal levels
Debriefing		<ul style="list-style-type: none"> Simple, standardized write-ups (adequately descriptive, easily entered in the aircraft forms by aircrews, and easily comprehended by debriefers) 	

ANALYSIS: COMMUNICATIONS EQUIPMENT
 (AN/ARC-109 and AN/ARC-164 Radio Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Debriefing (continued)	<ul style="list-style-type: none"> Comprehensive data recorded on debriefing forms and transmitted to maintenance shop (eliminates need for direct communication between radio maintenance personnel and debriefing) 		
Depot Support	<ul style="list-style-type: none"> Depot shop has test/repair capability for LRUs and SRUS beyond capability of field shops Same test equipment (hot mock-up concept using interconnection box) is used for LRU/SRU testing in depot and field shops AN/ARC-164 circuit boards from defective SRUS/slices are fault-isolated using depot test sets (better test access, more test capability, etc. when compared to hot mock-up concept) 	<ul style="list-style-type: none"> AN/ARC-109 modules are tested/fault-isolated to the component level using a hot mock-up (simplifies test equipment required but is probably less efficient than using special test sets) AN/ARC-164 depot shop did not initially have any LRU/SRU test/repair capability (circuit boards were originally expected to be the only depot returns) AN/ARC-164 circuit board test sets are over-designed (power supply capability is far in excess of requirements) 	
Pre-, In-, Post-Flight Inspections	<ul style="list-style-type: none"> Performed by aircrews (maintenance checks radios only in response to a write-up or pre-flight call to aircraft) prior to each sortie 	<ul style="list-style-type: none"> Qualitative check only (no BIT for constant monitoring of power out or SWR is provided and marginal performance or incipient failure might be overlooked) 	

ANALYSIS: COMMUNICATIONS EQUIPMENT
(AN/ARC-109 and AN/ARC-164 Radio Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Level of Base Repair	<ul style="list-style-type: none"> System repair requires only LRU replacement (no alignments at system level) Modules from both AN/ARC-109, -164 can be repaired in the intermediate level shop (Note: AN/ARC-164 module repair is limited to circuit board replacement by -6) 	<ul style="list-style-type: none"> AN/ARC-164 circuit board alignments are beyond intermediate shop capability (returned to depot for alignment using depot test set) 	<ul style="list-style-type: none"> AN/ARC-109 control unit and AN/ARC-164 control panel are depot repair items (due to high density wiring on rotary switches)
Characteristics of Equipment Design	<ul style="list-style-type: none"> Modular R/T units for repair by SRU replacement AN/ARC-164 SRUs are modularized (containing circuit boards) for ease of repair AN/ARC-164 has no chassis (flat flex harness inter-connects the 5 modules). Each subassembly of the AN/ARC-164 is a true SRU stocked as a spare) AN/ARC-109 has BIT meter on R/T unit Redundant AN/ARC-109 sets in the C-5A 	<ul style="list-style-type: none"> AN/ARC-109 has none modularized control unit (beyond repair capability of intermediate shops) AN/ARC-109 has no BIT meter 	<ul style="list-style-type: none"> internally mounted fuze non-tamper-proof preset frequency selector AN/ARC-164 interconnecting that flex harness is easily damaged during radio maintenance
Maintenance Data Collection Documentation and Feedback System		<ul style="list-style-type: none"> Automated data processing Periodic reports Special reports as required 	

**ANALYSIS: COMMUNICATIONS EQUIPMENT
(AN/ARC-109 and AN/ARC-164 Radio Sets)**

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintenance Organization	<ul style="list-style-type: none"> • No radio shop support of debriefing is necessary • Two-level maintenance organization can be utilized (intermediate shop dispatches to flightline for system repair) 		
Organizational Level AGE	<ul style="list-style-type: none"> • No special flightline equipment required (common radio test set authorized but normally only an SWR meter is used) • IRU checks/alignments using simple interconnection box for hot mock-up • AN/ARC-164 circuit boards tested/fault-isolated using specialized test sets at depot • AN/ARC-164 hot mock-up interconnection box factory built 	<ul style="list-style-type: none"> • AN/ARC-109 modules tested/fault-isolated using same hot mock-up equipment as supports LRUs 	<ul style="list-style-type: none"> • AN/ARC-109 hot mock-up interconnection box required local manufacturer • AN/ARC-164 circuit board test equipment is over-designed (far too many power supplies utilized)
Preventive Maintenance	<ul style="list-style-type: none"> • None per -6 (maintenance personnel, in general, seem to support this concept) 		<ul style="list-style-type: none"> • Periodic adjustment at some (undefined) interval seems necessary to maintain peak performance due to analog design with adjustments

ANALYSIS: COMMUNICATIONS EQUIPMENT
(AN/ARC-109 and AN/ARC-164 Radio Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Technical Orders	<ul style="list-style-type: none"> ● Organizational level manuals satisfactory ● AN/ARC-109 intermediate / depot manual satisfactory 	<ul style="list-style-type: none"> ● AN/ARC-164 intermediate manual does not clearly define SRUs for replacement and return to depot 	<ul style="list-style-type: none"> ● AN/ARC-164 depot manual lacks sufficient detail for repair of some repairables
Training and Personnel Skills Level	<ul style="list-style-type: none"> ● Depot personnel 7-level skilled (low turnover, high experience level, more specialized, etc.) in electronics maintenance 	<ul style="list-style-type: none"> ● Intermediate level personnel average 5-level skills (high turnover, less specialization, etc.) and can best be used for SRU replacement 	<ul style="list-style-type: none"> ● Organizational level personnel (and intermediate level personnel dispatched to flightline) have only 3-level electronics maintenance skills and are limited to LRU replacement.
Troubleshooting Methods		<ul style="list-style-type: none"> ● AN/ARC-109 system level LRU substitution following system check using BIT meter (redundant C-5A radios provide convenient spare LRUs) ● AN/ARC-164 fault-isolation by substitution (only 5 modules, functions clearly labeled) following checkout on hot mock-up 	<ul style="list-style-type: none"> ● AN/ARC-164 system level LRU substitution following system operational check (damage to substituted unit might result) ● AN/ARC-109 fault-isolation by substitution (11 modules with interrelationships between functions in some cases) following checkout on hot mock-up

ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> ● Redundant systems (C-5A aircraft only) ● Low complexity systems (2 or 3 units plus shock mount, antenna switching in receiver/transmitter) ● Built-in-test features ● Simplified repair concept (replace unit and align if necessary) ● Flush mounted lower antennas minimize physical damage ● Operational checks performed by aircrews provides adequate confidence levels 	<ul style="list-style-type: none"> ● No scheduled performance checks/alignments per -6 (alignment of analog circuitry on a scheduled basis might improve performance) 	<ul style="list-style-type: none"> ● TACAN antenna selector switch located on anti-ice panel rather than TACAN control panel (AN/ARN-118) ● Antennas vulnerable to physical damage due to protrusions from fuselage (upper antennas only)
Accessibility		<ul style="list-style-type: none"> ● Console mounted (in cockpit) control units easily removed/installed in 5 minutes using only a screwdriver ● MARK V receiver/transmitter rack-mounted in avionics compartments on C-5 flight deck can be replaced in 10 minutes without tools 	<ul style="list-style-type: none"> ● AN/ARN-118 avionics compartment door on F-16 aircraft requires considerable time to open/close (fastened with 20 fasteners)

ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Accessibility (continued)	<ul style="list-style-type: none"> AN/ARN-118 receiver/transmitter and digital/analog adapter are rack-mounted in F-16 shoulder height avionics compartment for 10 minute replacement without tools (Note: does not include opening/closing door on compartment) 		
Age of System and Technology	<ul style="list-style-type: none"> Mid-70s solid-state electronics (AN/ARN-118) Non-pressurized receiver/transmitter cases Forced cooling air not required for AN/ARN-118 receiver/transmitter No electro-mechanical servos (for receiver/transmitter tuning) Digital signal processing used extensively 	<ul style="list-style-type: none"> Forced cooling air required for MARK V receiver/transmitter Some analog signal processing techniques used Early-70s solid-state electronics (MARK V) Shock-mounted units plug into mount which interfaces with aircraft wiring 	<ul style="list-style-type: none"> Rotary switches (versus pushbutton or thumbwheel switches) on control units
Debriefing	<ul style="list-style-type: none"> Comprehensive sortie data logged on debriefing forms Simple, standardized write-ups describe most malfunctions (associated with displayed range/bearing or identification tone) 	<ul style="list-style-type: none"> Navigation shop personnel do not participate in aircrew debriefing (an infrequent problem is the loss of valuable maintenance data associated with complex problems) 	<ul style="list-style-type: none"> Write-ups caused by TACAN failure but not directly attributable to that system (such as automatic navigation system errors) are not adequately descriptive as logged by debriefing

ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Depot Support	<ul style="list-style-type: none"> • AN/ARN-118 LRU repair by Collins under 5 year reliability improvement warranty • MARK V unit and module test/repair capability provided by depot shop • Same hot mock-up test set-up for testing units in both the depot and intermediate shops (MARK V only) • Module test sets supporting hot mock-up in depot shop (MARK V only) 		
Pre-, In-, Post-Flight Inspections		<ul style="list-style-type: none"> • Performed by aircrews (maintenance checks TACAN only in response to write-up or preflight call to aircraft) prior to each sortie • Cross-checks between C-5A redundant TACANs provides aircrews additional data on system status • Quantitative checks performed (range, bearing on local stations and built-in-test) during preflight provide good tests of most-used system functions 	<ul style="list-style-type: none"> • TACAN outputs to automatic navigation systems not thoroughly checked during preflights

ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Level of Base Repair	<ul style="list-style-type: none"> • System repairable by unit replacement (alignments, if required, are normally accomplished in the intermediate shop) on the flightline • Receiver/transmitter repair by module replacement (MARK V) in an intermediate level shop • No receiver/transmitter repair at intermediate level (AN/ARN-118) during the reliability improvement warranty program (5 years) 		<ul style="list-style-type: none"> • Control unit designs which precludes intermediate level repair • Chassis complexity which precludes intermediate level repair (MARK V receiver/transmitter)
M Characteristics of Equipment Design	<ul style="list-style-type: none"> • Built-in-test circuitry for system test • Simplified system repair by unit replacement • Modular receiver/transmitter (MARK V) with plug-in modules for ease of repair • Discardable, plug-in circuit boards in receiver/transmitter modules (MARK V) for simplified module repair 		<ul style="list-style-type: none"> • Test connectors on the receiver/transmitters before test access. Results in complex test set and test procedures (MARK V) plus adding considerably to complexity of the unit • No built-in-test meter on the receiver/transmitter units for quantitative system checks at aircraft

ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintenance Data Collection Documentation and Feedback System	<ul style="list-style-type: none"> ● Automated data processing ● Periodic reports ● Special reports as required ● Receiver/transmitters are equipped with power-on elapsed time indicators ● Operating time from failed unit is supposed to be logged on repairable item tag, AFTO 350 ● Collins, by acting as the depot on the AN/ARN-118, has direct access to elapsed time indicator readings for accurate determination on utilization and reliability 	<ul style="list-style-type: none"> ● Maintenance personnel often times fail to log the elapsed time indicator reading on the AFTO 350 and that data is lost (MARK V only) 	
Maintenance Organization	<ul style="list-style-type: none"> ● Two-level maintenance organization (intermediate shop dispatches to flight-line) can be effectively utilized to support these systems due to their low failure rates, especially the AN/ARN-118 ● Three-level maintenance organizations (flightline personnel repair aircraft system) can effectively support these systems due to their low complexity and ease of repair 		

ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Organizational Level AGE	<ul style="list-style-type: none"> Common, portable, simple-to-use flightline test sets authorized Simple hot mock-up interconnection test set for intermediate level AN/ARN-118 maintenance (used only for a unit fault-verification test) 	<ul style="list-style-type: none"> Complex hot mock-up interconnection test set for intermediate level MARK V maintenance (high complexity results from the AGE connector interface/display requirements) 	<ul style="list-style-type: none"> AGE connectors and cables on the MARK V hot mock-up interconnection test set are poorly designed and unreliable
Preventive Maintenance	<ul style="list-style-type: none"> None per -6 (maintenance personnel, in general, seem to support this concept based on past experience) 	<ul style="list-style-type: none"> Periodic tests/alignments at some (undefined) interval seems necessary to maintain peak performance due to analog design with adjustments in both receiver/transmitter and interface functions 	
Technical Orders	<ul style="list-style-type: none"> Organizational level flightline manuals are adequate for these systems Depot manual for the MARK V is adequate 	<ul style="list-style-type: none"> Intermediate level manual for the AN/ARN-118 is very limited in scope (this is not a problem because no repair is accomplished at this level) 	<ul style="list-style-type: none"> Intermediate level manual for the MARK V contains a complex, often revised checkout procedure with many errors
Training and Personnel Skills Level	<ul style="list-style-type: none"> Depot personnel maintaining the MARK V have 7-level skills and can support the system effectively 	<ul style="list-style-type: none"> Intermediate level personnel average 5-level skills but have a high turnover, insufficient specialization, etc. 	<ul style="list-style-type: none"> Organizational level personnel (and intermediate level personnel dispatched to flightline) have only 3-level skills

**ANALYSIS: NAVIGATION EQUIPMENT
(AN/ARN-118 and MARK V TACAN Sets)**

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Training and Personnel Skills Level (continued)	<ul style="list-style-type: none"> ● Organizational personnel (and intermediate shop personnel dispatched to the flightline) have adequate skills to support these TACAN sets ● Intermediate level checks required in support of the AN/ARN-118 can be easily accomplished by the majority of shop personnel 	<ul style="list-style-type: none"> ● MARK V intermediate level maintenance should only be accomplished by the more experienced shop personnel due to its complexity 	
Troubleshooting Methods	<ul style="list-style-type: none"> ● System fault-isolation by substitution of units is successful in most cases following fault-verification using built-in-test ● MARK V receiver/transmitter fault-isolation by module substitution is successfully utilized ● TACAN control units and AN/ARN-118 receiver/transmitter are given a fault-verification test at intermediate level prior to return to the depot ● MARK V receiver/transmitter modules are fault-isolated at the depot by substitution of circuit boards 	<ul style="list-style-type: none"> ● MARK V receiver/transmitter fault-isolation using technical manual procedures is difficult for other than highly skilled technicians due to complexity of the procedure ● MARK V control units are fault-isolated by point-to-point continuity checks in the depot shop 	

ANALYSIS: RECONNAISSANCE EQUIPMENT
 (KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> • Low complexity systems (2 units plus film magazine) • Aircrews install/remove KS-97A film pack • Built-in-test features • No special maintenance aids or local modifications required • Simple maintenance concept (Replace defective unit) • Low utilization rates for camera systems (maintenance resources required for support are minimized due to the low maintenance demand rate) 	<ul style="list-style-type: none"> • Built-in-test features, etc. do not provide adequate confidence of proper camera functioning (KS-97A motor running is verified by feel--film pack vibrates--and film advancement cannot be verified) 	<ul style="list-style-type: none"> • Preventive maintenance inspections which require removal of the equipment from aircraft for shop maintenance, are required by the -6 technical manual
Accessibility	<ul style="list-style-type: none"> • KS-97A camera system (mounted in F-4E rear cockpit) can be easily removed or installed in 15 minutes • KA-18A camera system units (mounted in left forward avionics compartment and in lower forward fuselage of F-111D) can be readily removed or installed in 15-20 minutes • KS-97A film pack installation/removal is simple operation requiring less than one minute (performed by aircrews) 	<ul style="list-style-type: none"> • KB-18A film pack location (accessible only to maintenance personnel; maintenance workload could be greatly decreased by aircrews handling film) • KB-18A built-in-test panel not co-located with camera which discourages system checkout following film loading. 	<ul style="list-style-type: none"> • Removal/installation of KB-18A control unit is hampered by presence of wire bundles • KS-97A mounts on radar scope (removal required for scope maintenance) • KS-97A cable connects under instrument panel and is hidden from view (cables are frequently damaged when scope removal is attempted with cable connected)

ANALYSIS: RECONNAISSANCE EQUIPMENT
(KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
	<ul style="list-style-type: none"> Quick-release fasteners and connectors utilized on all access doors, mountings and connections 		<ul style="list-style-type: none"> Poor access to temperature control switch in camera compartment (KB-18A)
Age of System and Technology	<ul style="list-style-type: none"> Solid-state components No system harmonization adjustments required on the aircraft Fixed lens-systems (minimum complexity, high reliability) Commercially loaded film packs (Kodak refills KS-97A film packs) 	<ul style="list-style-type: none"> Electro-mechanical components Analog signal processing Technolog and equipment in excess of 10 years old; (however, no mention of wear-out problems was encountered) 	<ul style="list-style-type: none"> Control panel rotary switches (KS-97A) Film recording medium (processing delays, hazardous/messy chemicals, etc.)
Debriefing	<ul style="list-style-type: none"> Simple, standardized write-ups (adequately descriptive for maintenance purposes while easily entered in forms by aircrews / debriefers) Comprehensive sortie data logged on debriefing forms (made available to maintenance organization for aircraft history) 	<ul style="list-style-type: none"> Coordination between debriefing, photo shop and camera maintenance shop is required (for fault-isolation between film pack and camera) Comprehensive sortie data logged on debriefing forms (made available to maintenance organization for aircraft history) 	<ul style="list-style-type: none"> Camera system status cannot be determined during debriefing due to delays in film processing and assessment (delayed write-ups, discovered following the maintenance debriefing, are difficult to process properly)
Depot Support		<ul style="list-style-type: none"> Depot shop has test/repair capability for units and subassemblies beyond repair capability of the intermediate shops 	

ANALYSIS: RECONNAISSANCE EQUIPMENT
 (KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
	<ul style="list-style-type: none"> Depot test sets (GPATS, collimators, etc.) provide more extensive test capability (tighter tolerances, more comprehensive tests, etc.) than intermediate level test equipment 		<ul style="list-style-type: none"> Built-in-test function (KS-97A system) does not provide positive indication of camera operation. Aircrew determines motor running/film advancing by feel Visual checks of KB-18A camera (desirable for aircrew to determine if film pack is loaded/replaced) are not practical due to inaccessibility of film pack
Pre, In, Post-Flight Inspection	<ul style="list-style-type: none"> Performed by aircrews (maintenance checks camera operation only in response to reported problem) prior to and during flight 	<ul style="list-style-type: none"> Positive indication of operational status provided to aircrew for KB-18A system (reset film counter which advances when camera activated for operational test) Built-in-test features operable from cockpit are not provided for the KB-18A system Warning light (rather than film counter) for film remaining in KS-97A film pack 	
Level of Base Repair	<ul style="list-style-type: none"> System repair by unit replacement (no alignments required at system level) Electro-mechanical components replaceable in intermediate level shop (easily accomplished with resources available) allows repair of most failures 		<ul style="list-style-type: none"> Electronic component replacement in intermediate shop (resources, especially electronics fault-isolation experience, are not readily available). Control units, especially, contain electronics circuitry which is beyond the repair resources of camera shops

ANALYSIS: RECONNAISSANCE EQUIPMENT
(KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment	<ul style="list-style-type: none"> Built-in-test functions for system checks Line-replaceable units for system repair (no alignments required on the aircraft) Film packs reloadable by vendor (reduces photo/camera shop manpower requirements) Modularized KB-18A control unit (plug-in circuit boards simplify fault-isolation/repair) Lens assemblies replaceable in intermediate shop for depot repair 	<ul style="list-style-type: none"> Lack of built-in-test control/indicator in cockpit (KB-18A) prevents aircrews from checking system status Lack of modularity (no plug-in subassemblies, etc.) in KS-97A camera control unit 	<ul style="list-style-type: none"> KB-18A built-in-test control/indicators on control panel in avionics bay (co-location with camera or cockpit locations are preferable) Camera shop support in the form of film pack installation and removal, required for system operation (servicing tests should be accomplishable by organizational level personnel or aircrews rather than intermediate level personnel) KB-18A built-in-test and system operational checks require two personnel (one activates test and one observes camera) Problem with connector alignment following maintenance on camera drive assembly
Maintenance Data Collection Documentation System		<ul style="list-style-type: none"> Constant review and analysis not required (high reliability/low utilization rate) Automatic data processing of AFTO 349s and AFTO 350s provides periodic reports and special reports, if requested 	<ul style="list-style-type: none"> Camera systems not equipped with elapsed time indicators (assessment of reliability, utilization, etc. is difficult or impossible)

ANALYSIS: RECONNAISSANCE EQUIPMENT
(KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintenance Organization	<ul style="list-style-type: none"> • Two-level maintenance organizations (with intermediate level shop dispatch to flight line) can maintain camera systems due to low maintenance demand rate and simplicity of system in aircraft (Note: servicing of camera systems with film is not considered maintenance) • Three-level maintenance organization can support camera systems due to low complexity, ease of checkout, etc. • Aircrews can install, checkout, remove KS-97A film packs due to system design 	<ul style="list-style-type: none"> • Film pack installation, removal, and handling in support of KB-18A operations accomplished by intermediate level shop (problems with transportation and control of personnel on flightline during periods of high system utilization not compatible with intermediate shop dispatch concept) 	
Organizational Level Age	<ul style="list-style-type: none"> • No special flightline equipment is required • Portable, simple suitcase type test sets provide functional checkout capability at intermediate level 	<ul style="list-style-type: none"> • Optical checkout/alignment fixtures provided to intermediate level for support of KS-97A (equipment is little used since most maintenance at intermediate level is replacement of electromechanical components) 	<ul style="list-style-type: none"> • Camera test set (LS-83A) is reported to provide erratic readouts

ANALYSIS: RECONNAISSANCE EQUIPMENT
(KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Preventive Maintenance	<ul style="list-style-type: none"> Frequent preventive maintenance (for cleaning, lubrication, alignment, etc.) does not seem to be essential to maintaining reliable system operation 	<ul style="list-style-type: none"> Camera system designs requiring cleaning and lubrication which cannot be accomplished with the system installed in the aircraft 	<ul style="list-style-type: none"> KB-18A preventive maintenance every 125 hours which requires camera removal from aircraft for intermediate shop maintenance (KS-97A requirement, as a comparison, is 600 hours)
Technical Orders	<ul style="list-style-type: none"> Camera system manuals are satisfactory 		<ul style="list-style-type: none"> Fault-isolation to the electronic component level in the intermediate shop (requires training/experience beyond that possessed by the average 5-level camera technician) Lack of specialized training/experience and high turnover rates in the intermediate level shops detracts from their capability to perform repair of electronics/optics in camera systems

ANALYSIS: RECONNAISSANCE EQUIPMENT
 (KB-18A Strike Camera and KS-97A Radar Scope Camera Systems)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Troubleshooting Methods	<ul style="list-style-type: none"> ● Complete system pulled from aircraft and each unit tested in shop (used exclusively on the KS-97A and approximately 50% of the time for the KB-18A) ● Substitution of line-replaceable-units utilized 50% of time for the KB-18A (low complexity, built-in-test, and analysis of malfunction provides high degree of success on first attempt) ● Substitution of plug-in modules in the KB-18A control unit 	<ul style="list-style-type: none"> ● Intermediate level fault-isolation using technical manual procedures, circuit analysis, substitution of parts and electronic components, etc. 	

ANALYSIS: WEAPON DELIVERY EQUIPMENT
(AN/AWG-20 Armament Control)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> • AN/AWG-17 reconfigured to AN/AWG-20 by combining three LRUs into two. • Automatic Bit and Initiated BIT circuit. • No special maintenance aids or local modifications 		<ul style="list-style-type: none"> • Some difficulty encountered in removal/replacement of armament control panel due to limited play of ACP wire bundle at rear of ACP (ACP mounted in left side of pilots forward instrument console within cockpit). • Brass 'Phillips' type screws securing ACP strip at the star slots.
Accessibility of Avionics	<ul style="list-style-type: none"> • No accessibility problems with converter programmer (located in forward left avionics bay). • Converter programmer requires only 3-4 minutes to remove or replace. • Converter-programmer wiring interface features quick disconnect cable plugs. • Converter-programmer secured with quick release hinged latches. 	<ul style="list-style-type: none"> • ACP secured in instrument console with 'Phillips' type brase screws. 	
Age of System and Technology	<ul style="list-style-type: none"> • AN/AWG-20 features integrated circuitry, hybrids, extensive microelectronics and printed circuit cards. • Wire-wrap connections • Digital design • Quick disconnect connectors for wiring and waveguides at interface. 	<ul style="list-style-type: none"> • AN/AWG-20 installed in F-15 around 1973 but reflect mid-to late 60's technology. • AN/AWG-20 installed in F-15 airframe using system integration approach. • Waveguides used • AN/AWG-20 is pre-programmed and controlled from central computer. • Wiring cables/bundles 	

ANALYSIS: WEAPON DELIVERY EQUIPMENT
(AN/AWG-20 Armament Control)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Debriefing	<ul style="list-style-type: none"> • Debriefing performed 	<ul style="list-style-type: none"> • Debriefing necessary 	<ul style="list-style-type: none"> • AN/AWG-20 maintenance personnel do not attend debriefing - discrepancy information is relayed via AFTO 349
Depot Support	<ul style="list-style-type: none"> • Depot support established • LRU and SRU depot maintenance located at same facility. 	<ul style="list-style-type: none"> • About a 15% AWP rate • MACAIR Interim Depot 	<ul style="list-style-type: none"> • Spare support is a continuing problem at the LRU level • Pipeline spares requirement has been significantly increased due to increased depot maintenance time caused by manual probe requirements.
Pre. in. Post)- Flight Inspection			<ul style="list-style-type: none"> • Stay voltage check necessary (safety requirement) • Pre and Post flight inspections performed (stray voltage check using ATM-75)
Level of Base Repair	<ul style="list-style-type: none"> • No scheduled maintenance required • No deviation from specified maintenance concept 		
Maintainability Characteristics of Equipment Design	<ul style="list-style-type: none"> • Solid state design with BIT • Plug-in SRUs • BIT is good for confirming error presence 	<ul style="list-style-type: none"> • Poor quality pin extractor/insertion tools 	<ul style="list-style-type: none"> • BIT does not resolve faults to LRU. • BIT circuits fail more frequently than primary functions • Problem with wires pulling and breaking at quick-disconnect plugs • Trouble is experienced in replacing pins in connectors.

ANALYSIS: WEAPON DELIVERY EQUIPMENT
(^/ANG-27 Armament Control)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design (continued)			<ul style="list-style-type: none"> Shortage of spare LRUs has resulted in extensive cannibalization
Maintenance Data Collection Documentation and Feed Back System	<ul style="list-style-type: none"> MDCS is in accordance with the procedures of AFM 66-1 Local management and special study reports are provided at the base level. 	<ul style="list-style-type: none"> Constant review and analysis required for effective maintenance 	
Maintenance Organization			
Organizational Level AGE	<ul style="list-style-type: none"> Required AGE available 		<ul style="list-style-type: none"> AGE required to perform maintenance Base level capability exists to repair AN/AWM-74 (used to launchers, racks, pylons) at PMEL - but test set designated for depot repair.
Preventive Maintenance	<ul style="list-style-type: none"> None required 		
Technical Orders	<ul style="list-style-type: none"> TOs are adequate to perform maintenance as authorized 		<ul style="list-style-type: none"> T.O. logics trees are difficult to understand
Training and Personnel Skill Levels	<ul style="list-style-type: none"> Personnel assigned are considered to satisfactorily qualified mechanically 		<ul style="list-style-type: none"> Personnel assigned are considered to be deficient in electronic qualifications

ANALYSIS: WEAPON DELIVERY EQUIPMENT
(AN/AWG-20 Armament Control)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Troubleshooting Methods	<ul style="list-style-type: none"> (O) BIT indicates failure presence (I) Fault isolation utilizing ATE (D) Functional checkout of all returned and repaired LRUs 	<ul style="list-style-type: none"> (O) AN/AWM-72 must be used in conjunction with BIT to resolve failures to LRU. (D) Manual probing required to isolate faulty components 	<ul style="list-style-type: none"> (O) An AN/AWM-72 checkout of the weapon system requires four hours - as a result it is frequently not used to check the AN/AWG-20. Rather, the converter-programmer, historically the prime failure cause, is replaced based on a BIT indication of AN/AWG-20 fault presence. If this does not resolve problem, the ACP is replaced. (I) High NRTS rate for C-P. (I) The armament control panel is time-consuming to troubleshoot. (I) C-P is difficult to troubleshoot due to insufficient test detail in T.O. (I) AIS repair capability is limited for the C-P. The majority of C-P units are NRTS items. (D) AN/AWG-20 ATE diagnostics are not fully developed

ANALYSIS: WEAPONS CONTROL EQUIPMENT
 (AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
General	<ul style="list-style-type: none"> System modularity (functions pertained into line-replaceable units): <ol style="list-style-type: none"> 4 units (TISEO) 8 units (AN/APQ-130) 9 units (AN/APG-63) Built-in-test features (simplify system checkout, aid in fault-isolation, etc.) Simple system maintenance concepts (designed for operational test plus built-in-test and repair by unit replacement. Requirements for system level alignments have been minimized.) No local maintenance aids or modifications required. No preventive maintenance required by the -6 technical manual. 	<ul style="list-style-type: none"> Complexity of AN/APQ-130 and AN/APG-63 radar sets, with 8 or 9 units (and even the TISEO with 4 units) increases fault-isolation requirements on the flightline. 	<ul style="list-style-type: none"> Heavy line-replaceable-units, exceeding carrying capacity of two men (receiver/transmitters, both AN/APQ-130 and AN/APG-63 radars) that require support equipment for handling.
Accessibility	<ul style="list-style-type: none"> Collocation of major radar units in single equipment bay (minimizes number of doors/panels that must be opened for maintenance of both AN/APG-63 and AN/APQ-130 radars). Swing-away radome provides quick and easy access to radar antenna (both AN/APQ-130 and AN/APG-63 radars). Quick-release latches (3) on F-15 equipment bay door (AN/APG-63 radar) provides quick access to radar units. Control units mounted in cockpit are directly accessible for 	<ul style="list-style-type: none"> Fasteners (13) utilized on F-111 equipment bay door (latches would have reduced access time for AN/APQ-130 units) 	<ul style="list-style-type: none"> Fasteners (36) utilized on F-4 access panel for TISEO power supply (latches would have reduced access time). Undersized access panel and in-the-wing location of the TISEO video processor (cables cannot be disconnected without partially removing unit; unit removal requires special positioning of wing leading edge flap). Fuzes located on back of AN/APQ-130 antenna (checks and replacement are a problem).

ANALYSIS: WEAPONS CONTROL EQUIPMENT
 (AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Accessibility (continued)	replacement (normally, the canopy is open and cockpit unoccupied).		
Age of System and Technology	<ul style="list-style-type: none"> • Early-70s design (AN/APG-63 & TISEO). • Solid-state components with hybrids and ICs (both AN/APG-63 & TISEO). • Software controlled, reprogrammable signal processor (AN/APG-63). • Direct interconnection of units using cables, thereby avoiding rack wiring/connector problems. • Quick disconnect/release connectors, fasteners and fittings. • Digital signal processing techniques (extensively used in AN/APG-63). • Plug-in circuit cards/modules. 	<ul style="list-style-type: none"> • Solid-state components with limited use of hybrids and ICs (AN/APQ-130) • Analog signal processing techniques with associated alignments, tolerance checks, etc. • Miniature coaxial cables, specifically Microdot brand, as used in the AN/APQ-130 (becomes brittle with age, breaks easily, and is difficult to repair). • Temperature sensitive electronics (AN/APQ-130 target ranging problems reported in extreme low temperature situations. • Flat ribbon cables interconnecting circuit cards in the AN/APG-63 units (fragile and easily damaged during maintenance). 	<ul style="list-style-type: none"> • Late-60s design (AN/APQ-130) • Hard-wired, nonprogrammable signal processing (AN/APQ-130) • Plug-in units, with rack-mounted interface connectors and inter-rack wiring (AN/APQ-130) • Hybrids utilized in system are out-of-production items (AN/APQ-130) • Unit subassemblies exhibit marginal problems when installed in units (AN/APQ-130) • Less than predicted reliability (AN/APQ-130) • Liquid cooling of transmitters (both AN/APQ-130 and AN/APG-63)
Debriefing		<ul style="list-style-type: none"> • Comprehensive sortie data logged on debriefing forms, copies of which are available to maintenance for aircraft history. 	<ul style="list-style-type: none"> • Complex, interrelated malfunctions which are difficult to debrief properly (write-ups entered on forms can be erroneous or inadequately descriptive) • Representatives from fire control maintenance shops, in general, are not available at debriefing to provide technical advice to debriefers, and direct communications of technical information to shop)

ANALYSIS: WEAPONS CONTROL EQUIPMENT
(AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Depot Support	<ul style="list-style-type: none"> Depot shops provide test repair for units and subassemblies beyond the repair capability of the field shops. Single depot shop repairs units and subassemblies (AN/APG-63 and TISEO) 	<ul style="list-style-type: none"> TISEO units repaired at the depot must be aligned in the intermediate level field shop prior to aircraft installation (based on past maintenance experience). Two depot shops, one for units and one for subassemblies, that are remotely located from each other (AN/APQ-130 units repaired at Sacramento ALC and subassemblies repaired at Warner Robins ALC). Modules originally designated discard-at-failure are being repaired at depot (due to the lack of AN/APG-63 spares). 	<ul style="list-style-type: none"> Depot replacement of defective hybrids is becoming impossible due to limited stock and items out-of-production (AN/APQ-130) Test tolerance incompatibilities between intermediate/depot test equipment; items repaired at depot check bad when tested at intermediate level then when returned with Unsatisfactory Report (UR) item checks good at depot (AN/APQ-130 and AN/APG-63) Inadequate quantity of spares available at intermediate level.
Pre, In, Post-Flight Inspection	<ul style="list-style-type: none"> No maintenance pre-flight or post-flight inspections required. Pre-flight inspections performed by aircrews (use combination of operational checks and built-in-test failures) Continuous fault-monitoring using built-in-test features 		<ul style="list-style-type: none"> Boresight harmonization alignment required (TISEO) Low light level operation can damage system (TISEO) which prohibits aircrew checks on some sorties.
Level of Base Repair	<ul style="list-style-type: none"> Organizational level system repair by replacement of defective units in conjunction with operational and built-in-test testing (No requirements for system level alignments) Intermediate level unit repair by replacement of defective shop-replaceable-assemblies and alignment 		<ul style="list-style-type: none"> Intermediate level maintenance shop, in order to duplicate and repair malfunctions discovered on the flightline, must test units on the hot mock-up in addition to performing unit tests on test station (AN/APQ-130) Organizational level maintenance is required to perform quick-fix (system repair during aircraft preflight checks with engine running on the AN/APQ-130

ANALYSIS: WEAPONS CONTROL EQUIPMENT
(AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Level of Base Repair (continued)	<ul style="list-style-type: none"> Intermediate level maintenance using unit test sets is able to duplicate/repair TISEO unit malfunctions/built-in-test failures discovered on the flightline. 	<ul style="list-style-type: none"> Organizational level maintenance is required to check system operation on aircraft power to duplicate some mal-functions by approximating inflight conditions (AN/APQ-130) Intermediate level maintenance cannot duplicate/repair some AN/APG-63 unit built-in-test flightline (units check good on existing test stations and no hot mock-up available) 	<ul style="list-style-type: none"> Receiver/transmitter unit weight (both AN/APQ-130 and AN/APG-63 units required handling equipment) Connector pin replacement problems due to breakage of insertion/extraction tools, etc. (AN/APQ-130 and AN/APG-63) Line-replaceable-unit fasteners which cannot be repaired by intermediate level avionics maintenance shop (female jack screw fasteners on AN/APQ-130 rack are replaced by sheet metal shop; AN/APG-63 unit fasteners are replaced at depot) Pressurized units (pressurized nitrogen in AN/APG-63 low voltage power supply makes some maintenance actions hazardous)
Maintainability Characteristics of Equipment Design	<ul style="list-style-type: none"> Modular systems (electronics and electro-mechanicals grouped by function into line-replaceable-units) Quick and easy unit removal/installation by two-man maintenance team using common hand tools (exceptions noted at right) Built-in-test functions providing constant monitoring of system status (simplifies system operational checkout, minimizes eliminates support equipment requirements allows fault-isolation by substitution) Built-in-test functions in addition to go/no-go status monitoring, which provide fault-diagnostics for maintenance use (AN/APQ-130 and AN/APG-63) 	<ul style="list-style-type: none"> Built-in-test fault-isolation connector on TISEO control panel (cockpit readout of faults, now requiring test set and control unit test connector could have been accomplished with 2 additional indicator lamps) Built-in-test control/indicators located only in cockpit (AN/APQ-130 trouble-shooting during "quick-fix" requires excessive coordination between technicians and aircrews) Unused hardware/functions not modified out of system (specifically, unused AN/APQ-130 duplexer which fails, knocks out radar, and is difficult to replace) Fuses versus circuit breakers for overload protection (AN/APQ-130) 	<ul style="list-style-type: none"> Connector pin replacement problems due to breakage of insertion/extraction tools, etc. (AN/APQ-130 and AN/APG-63) Line-replaceable-unit fasteners which cannot be repaired by intermediate level avionics maintenance shop (female jack screw fasteners on AN/APQ-130 rack are replaced by sheet metal shop; AN/APG-63 unit fasteners are replaced at depot) Pressurized units (pressurized nitrogen in AN/APG-63 low voltage power supply makes some maintenance actions hazardous)

ANALYSIS: WEAPONS CONTROL EQUIPMENT
(AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design (continued)	<ul style="list-style-type: none"> Fault-indicators on each major LRU (AN/APG-63) Modular units (electronics and electro-mechanicals packaged in plug-in modules to simplify fault-isolation by substitution and repair by replacement) 	<ul style="list-style-type: none"> Radome fasteners accessible through avionics compartment (external fasteners like used on F-4E are preferred) Flat ribbon cable (utilized for interconnecting modules within AN/APQ-130 line-replaceable units) is prone to breakage and cannot be repaired. Equipment rack which includes unit interface wiring (AN/APQ-130 rack is replaced like a line-replaceable unit when wiring problems are suspected) Flightline procedures (equipment for checking "false radar target" problems as caused by spurious signals (AN/APG-63)) Transmitter liquid coolant system servicing/maintenance on aircraft (avionics maintenance delays are encountered when support is required from responsible shop) Transmitter maintenance requires violation of TWT cooling system integrity thereby necessitating time consuming servicing (AN/APQ-130 and AN/APG-63) Transmitter cooling system servicing in intermediate shop is excessively time consuming (due to equipment/procedures utilized time required is approximately 4.5 minutes for AN/APG-63 and 7-8 hours for AN/APQ-130) 	<ul style="list-style-type: none"> Equipment rack which is difficult to remove/install with many connectors for waveguides and electrical cables, some of which are relatively inaccessible and difficult to connect/disconnect (AN/APQ-130) TISEO built-in-test functions very limited in scope (analysis of faults requires flightline test equipment, no method for testing in low-level light is provided, etc.) AN/APQ-130 built-in-test functions provide inadequate/inaccurate fault-isolation capability (promotes "shotgun" removals, excessive test time and induced failures) AN/APG-63 built-in-test results are inconsistent (inflight faults cannot be duplicated on ground, intermittent faults on repeated ground checks, units replaced for failing built-in-test check good at intermediate level, etc.) Alignments sensitive to shock/vibration during handling/transportation (feedhorn alignment which affects antenna boresight is sensitive to shock necessitating special handling)

ANALYSIS: WEAPONS CONTROL EQUIPMENT
(AN/APG-63), AN/APQ-130 Radar Sets and TISEO

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintainability Characteristics of Equipment Design (continued)			<ul style="list-style-type: none"> • AN/APG-63 built-in-test of range and angle tracking functions requires improvement (existing tests provide inadequate confidence level and do not duplicate airborne problems) • Waveguide dehumidification system maintenance procedures (duplexer blows out in AN/APQ-130 due to moisture build-up, missile RF problems in AN/APG-63 due to moisture in waveguides) • Wiring problems consume considerable maintenance manhours on AN/APQ-130 (vibration/stressing causes intermittent shorts/opens)
Maintenance Data Collection Documentation and Feedback System	<ul style="list-style-type: none"> • Maintenance data, in the form of aircraft histories, are formed by compiling files of debriefing/maintenance forms by fail number • Automatic data processing of debriefing forms, 349's and 350's (periodic reports and special reports if requested) • Failure trend analysis, using both automatic and manual techniques, is accomplished. 	<ul style="list-style-type: none"> • Effectiveness of maintenance data analysis is dependent on several factors (accuracy of data recorded on debriefing/maintenance forms, qualifications of the analyst, etc.) • Failure trend analysis, as applies to improving maintenance effectiveness on these systems, is non-automated (debriefers/avionics maintenance personnel file forms or by write-ups/fixes to review for repeat write-ups, etc.) 	<ul style="list-style-type: none"> • Constant review and analysis of maintenance data is essential to effective maintenance of these systems (especially the radars, which are more complex than the TISEO) • Automated data processing systems presently do not provide real-time information to the flightline maintenance personnel.
Maintenance Organization	<ul style="list-style-type: none"> • Intermediate level shop TISEO maintenance personnel assist flightline maintenance personnel with periodic inspections 	<ul style="list-style-type: none"> • Transmitter cooling oil systems on aircraft are not maintained by avionics flightline personnel (delays are encountered 	<ul style="list-style-type: none"> • Three-level maintenance organizations is essential to effective system maintenance (due to lack of commonality between

ANALYSIS: WEAPONS CONTROL EQUIPMENT
(AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Maintenance Organization (continued)	(shop personnel gain increased skills through additional exposure)	while awaiting support and coordination of related problems/maintenance is required)	<ul style="list-style-type: none"> • Flightline and shop maintenance tasks, complexity of test equipment utilized in shop, high maintenance manhour consumption on flightline, and integrated nature of aircraft systems) • Flightline maintenance shop must provide qualified representative at debriefing (provides technical advice to aircrews and debriefs to ensure correctness of write-ups, transfers information beyond the scope of debriefing forms from debriefing to flightline maintenance personnel)
Organizational Level Age	<ul style="list-style-type: none"> • Reusable shipping container is used to protect TISEO seeker optics/gimbals during handling/transportation between flightline and shop • Antenna hoists are a definite handling aid for removal/installation of AN/APG-63 antenna (due to height above ground) 	<ul style="list-style-type: none"> • AN/APQ-130 antenna is not provided adequate protection during removal/installation/handling (Note: antenna bore sight problems related to changes in feedhorn alignment resulting from handling) • Handling equipment for receiver/transmitters: hoists, lift truck adapters, etc. (not utilized because maintenance personnel prefer to man handle these units) • Handling cradle for AN/APG-63 antenna (no antenna damage from handling was reported, however, man handling is preferred by maintenance personnel) 	<ul style="list-style-type: none"> • Control indicator (test set for connection to control unit in cockpit) is utilized for analysis of TISEO built-in-test failures) • TISEO interface test set (for fault-isolation of the aircraft system) is difficult to use due to lack of accessibility to interface connectors) • Collimator is required for flightline checks of TISEO at night (low-level light operation can damage the system) • Handling equipment required for receiver/transmitter units (excessive weight of these units should be reduced to eliminate this requirement since maintenance personnel prefer to man handle these units)

ANALYSIS: WEAPONS CONTROL EQUIPMENT
 (AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Organizational Level Age (continued)	<ul style="list-style-type: none"> • Identical line-replaceable-unit test sets at intermediate and depot level for TISEO maintenance (provides test tolerance continuity, however, some units require realignment when received at intermediate level) • Hot mock-ups at intermediate level (maintenance personnel must presently use the hot mock-up concept to resolve differences between test tolerances/test philosophy of system built-in-test and test stations for AN/APQ-130 and AN/APG-63) 	<ul style="list-style-type: none"> • Special handling equipment for antennas (maintenance personnel would prefer antennas designed for man handling) • Inconsistency of test tolerances/philosophy between system built-in-test, intermediate level test equipment and depot test equipment (AN/APQ-130 and AN/APG-63) • AN/APQ-130 test station does not provide adequate access to interface connectors on units under test (specifically, the electronic processing unit) • Interface cables between AN/APQ-130 test station and unit-under-test are unreliable (develop breaks, intermittent shorts, etc. as a result of bending/flexing) • Transmitter cooling oil servicing equipment in intermediate level shops requires excessive amounts of time to perform purge fail (both AN/APQ-130 and AN/APG-63) 	

ANALYSIS: WEAPONS CONTROL EQUIPMENT
 (AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Preventive Maintenance	<ul style="list-style-type: none"> Scheduled maintenance is not required by the -6 and is not considered necessary based on maintenance experience with these systems (AN/APQ-130 and AN/APG-63) Scheduled maintenance is not required by the -6 (TISEO) 		<ul style="list-style-type: none"> Scheduled maintenance has been found to produce positive results and is considered recommended by maintenance personnel (TISEO) Units received from depot are tested/aligned. Past experience indicates that alignments will be necessary (TISEO)
Technical Officers	<ul style="list-style-type: none"> Technical manuals, in general, are considered adequate for support of the TISEO 		<ul style="list-style-type: none"> AN/APQ-130 flightline manuals provide insufficient data on system signal flow, test points (multiple manuals are required to trace signals) AN/APG-63 intermediate level manuals do not provide adequate technical data (unit schematics are not provided, functional diagrams are not definitive enough, test station software inadequately described system built-in-test data lacking, etc.) AN/APG-63 flightline manuals provide insufficient data on built-in-test AN/APG-63 modifications and software changes are not documented in a timely fashion (modified units received from depot are checked bad on intermediate level test equipment using wrong test specifications)

ANALYSIS: WEAPONS CONTROL EQUIPMENT
 (AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Training & Personnel Skills Level	<ul style="list-style-type: none"> Intermediate level technicians assist with TISEO scheduled inspections to gain system-level experience Extensive training/experience is not required to gain sufficient skills for TISEO repairs on the flightline or in the shop (camera technicians are learning TISEO maintenance procedure; training requirements are not extensive due to 4-unit complexity, manual test sets, simple repair concept, good manuals) 	<ul style="list-style-type: none"> Intermediate level maintenance could be more effective if system-level training/experience was provided (AN/APG-63) 	<ul style="list-style-type: none"> Extensive on-the-job training is required before maintenance proficiency is gained (AN/APG-130 and AN/APG-63)
Troubleshooting Methods	<ul style="list-style-type: none"> Flightline personnel are successful using built-in-tests and operational checks with substitution of units (preferred flightline technique requiring no flightline test equipment and minimal technical data) Flightline personnel get functional tests of all suspected units by the intermediate level shop (secondary technique used when spares are not available for substitution in aircraft) Functional testing, diagnostic tests, logical analysis and substitution are used at intermediate/depot levels to isolate faulty modules/components in the units 	<ul style="list-style-type: none"> Signal tracking, continuity checks, cross-referencing between good and bad units and other logical analysis techniques (required to supplement fault-diagnostic procedures and test routines available at the intermediate level) AN/APG-63 built-in-test fault-diagnostics have a 70-80% probability of indicating defective unit 	<ul style="list-style-type: none"> Test equipment (collimator as target source) is required on flightline for TISEO checks in low-light level conditions AN/APQ-130 built-in-test fault diagnostics are ineffective in identifying defective unit (presence but not cause of fault can be determined) Hot mock-up utilization is required to resolve problems of inconsistent test results between built-in-test on the aircraft and unit functional checks on a test station in the shop (AN/APQ-130 and AN/APG-63) A significant amount of logical analysis of malfunctions is required to supplement automatic diagnostics provided on intermediate test stations (AN/APQ-130)

ANALYSIS: WEAPONS CONTROL EQUIPMENT
(AN/APG-63, AN/APQ-130 Radar Sets and TISEO)

AREA	POSITIVE	QUESTIONABLE	NEGATIVE
Troubleshooting Methods (continued)		<ul style="list-style-type: none">• Interface test set provided for fault-isolation of TISEO system in the aircraft is not utilized (poor accessibility to interface connectors in the aircraft and amount of supporting equipment required are the reasons)	

SECTION V
MAINTENANCE ITEM AREA TREND ANALYSIS

TREND EVALUATION: ACCESSIBILITY

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
KS-97A Radar Scope Camera System		<ul style="list-style-type: none"> • LRU's in cockpit • Filmpack in cockpit • LRU remove/replace ≈ 5-10 min. 	<ul style="list-style-type: none"> • Scope mounting of LRU's • Out-of-site connector 	Positive	<p>1. Accessibility to LRU's for removal or replacement is, in general, good (5-10 minute access times) but when access times become greater than 15 minutes (example: TISEO) maintenance is delayed.</p>
F-4E AN/ASX-1 TISEO		<ul style="list-style-type: none"> • Direct access to LRU in cockpit 	<ul style="list-style-type: none"> • Special fastener tools • Undersize access panel • Number of panel fasteners • In-the-wing LRU • LRU remove/replace ≈ 5-60 min. 	Negative	<p>2. Retrofitted equipment to a weapon system (such as the TISEO) is more likely to exhibit poor accessibility.</p>
AN/ARC-109 Radio Set					<p>3. Rack mounted equipment in electronics compartments sealed by doors with latches provides the best accessibility. Access panels, in general, are less satisfactory than doors. The large number of fasteners and undersize openings provided by access panels hinder maintenance.</p>
C-5A MARK V TACAN		<ul style="list-style-type: none"> • Flight deck equipment location • Stand-up maintenance in electronic's compartments • Racked equipment • LRU remove/replace ≈ 5-10 min. 	<ul style="list-style-type: none"> • Antenna switching relay location 	Positive	<p>4. Accessibility technology (fasteners, latches, door/panel designs, etc.) advancements over time from 60s to 70s not apparent. Small improvements in accessibility have been achieved through refinements of old ideas (swing-away radomes,</p>

TREND EVALUATION: ACCESSIBILITY (continued)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
C-5A (cont)	MARK V TACAN	<ul style="list-style-type: none"> Racked equipment LRU remove/replace ≈ 5-10 min. 			4. (cont) etc.). One exception is the AN/ARC-164 receiver/transmitter which, due to its cockpit location, provides almost optimum accessibility.
	KB-18A Strike Camera System	<ul style="list-style-type: none"> LRUs in lower forward compartments Direct access to control unit in cockpit 	<ul style="list-style-type: none"> Film-pack inaccessible to aircrews Test panel not co-located with camera LRU remove/replace ≈ 10-20 min. 	<ul style="list-style-type: none"> Wire bundle hinders access in avionics bay 	5. Electronic LRUs are ideally located for access when placed in shoulder-height forward electronics compartments. Accessibility deteriorates with height above ground and aft around engines, wings, gear, etc.
F-111D AN/APQ-130 Radar		<ul style="list-style-type: none"> Co-location of LRUs in electronics bay Swing-away radome Direct access to control unit in cockpit 	<ul style="list-style-type: none"> Number of fasteners on electronics bay door Fuzes on back of antenna LRU remove/replace ≈ 10-20 min. (excluding antenna) 	<ul style="list-style-type: none"> Poor accessibility to rack connectors and fittings 	6. Camera systems with recording medium (film pack, tape cassette, etc.) accessible to aircrew in cockpit offers advantages over systems with recording medium accessible only to maintenance.
AN/APG-63 Radar					7. Greater use of micro-electronics (AN/ARC-164 and AN/APN-118 are examples) is indirectly contributing to improved accessibility. LRUs are becoming smaller and lighter which is contributing to less crowded equipment bays and leads to location of more equipment in bays (with doors) rather than behind access panels.
F-15				Positive	

TREND EVALUATION: ACCESSIBILITY (continued)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
F-15 (cont)	AN/APG-63 Radar (cont)	<ul style="list-style-type: none"> • LRU remove/replace ≈ 5-10 min. (excluding antenna) 			8. Accessibility is best in the large transport aircraft. As the aircraft size is reduced, accessibility problems are more likely.
	AN/AWG-20 Armament Control	<ul style="list-style-type: none"> • Electronics bay LRU location • Cockpit LRU location • Quick release latches on door • Direct access in cockpit • LRU remove/replaces ≈ 5-10 min. 	<ul style="list-style-type: none"> • Insufficient service loop for cockpit LRU 	Positive	
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • Direct access in cockpit to LRU • LRU remove/replace ≈ 5-10 min. 		<ul style="list-style-type: none"> • Antenna switching relay location 	Positive
	AN/ARN-118 TACAN	<ul style="list-style-type: none"> • Direct access in cockpit • Electronics bay LRU location 	<ul style="list-style-type: none"> • LRU remove/replace ≈ 5-20 min. 	<ul style="list-style-type: none"> • Number of fasteners on electronics bay door 	Positive

TREND EVALUATION: AGE OF SYSTEM AND TECHNOLOGY

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> Solid-state electronics No system-level adjustments Fixed lens system Vendor supplied film pack 	<ul style="list-style-type: none"> Electro-mechanical Analog signal processing Late-60s design Hardware age ≥ 10 years 	Positive	<ol style="list-style-type: none"> Integration of components has progressed from use of discretes in late-60s to medium-scale integration in mid-70s leading to the following secondary trends: <ul style="list-style-type: none"> Improving reliability Smaller, lighter LRUs Reduced cooling requirements Higher packaging density Analog signal processing is being superceded by digital techniques with secondary trends as follows: <ul style="list-style-type: none"> Improved reliability Improved testability Increased complexity Hardwired to reprogrammable signal processing with secondary trends: <ul style="list-style-type: none"> Increasing software emphasis Simplified incorporation of system changes Higher software change rate More difficult configuration control
F-4E	AN/ASX-1 TISEO	<ul style="list-style-type: none"> Solid-state electronics (ICs and hybrids) Early-70s design Hardware age ≤ 5 years Interconnection cables Plug-in modules Quick disconnect fasteners 	<ul style="list-style-type: none"> Analog signal processing Electro-mechanical 	Questionable	
	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> Solid-state electronics Quick-release fasteners/connectors Plug-in modules 	<ul style="list-style-type: none"> Late 60s-early 70s design Hardware age ≥ 5 years 	Questionable	<ol style="list-style-type: none"> Rotary switches in control unit Electro-mechanical servo tuner Analog signal processing Electronic cooling air Pressurized case
C-5A					

TREND EVALUATION: AGE OF SYSTEM AND TECHNOLOGY (continued)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
C-5A (cont)	MARK V TACAN Set	<ul style="list-style-type: none"> Solid-state electronics Non-pressurized case No electro-mechanical tuning servo Digital signal processing 	<ul style="list-style-type: none"> Early-70s design Cooling air required Analog signal processing 	<ul style="list-style-type: none"> Rotary switches on control unit 	Questionable	<p>4. Electro-mechanical functions are being replaced with electronics leading to:</p> <ul style="list-style-type: none"> Simplified repair Higher reliability Smaller packages
						<p>5. Quick-release connectors, fasteners and fittings are now being used extensively to:</p> <ul style="list-style-type: none"> Eliminate tool requirements Eliminate safety wire Reduce remove/replace times
	KB-18A Strike Camera System	<ul style="list-style-type: none"> Solid-state electronics Lack of system-level adjustments Fixed-focus lenses Vendor loaded film-pack Plug-in modules 	<ul style="list-style-type: none"> Electro-mechanicals Analog signal processing Hardware age ≥ 5 years Late-60s design 	<ul style="list-style-type: none"> Rotary switches Film recording medium 	Questionable	<p>6. Rotary switches have been phased out in only a few applications and still present the following problems:</p> <ul style="list-style-type: none"> Loose knobs and tools in cockpit Lower reliability through use of mechanical rather than electronic switches Repair problems due to wiring density and complexity
F-111D	AN/APQ-130 Radar	<ul style="list-style-type: none"> Solid-state electronics Quick-disconnect fittings Quick-release fasteners (safety wire used) on LRU's Plug-in modules 	<ul style="list-style-type: none"> Analog signal processing Minature coaxial cables Temperature sensitive system 	<ul style="list-style-type: none"> Late-60s design Hard-wired signal processor Inter-rack wiring Out-of-production hybrids SRA marriage problems 	Negative	<p>7. Interconnection technology for SRAs has advanced from point-to-point, discrete wires through wire-wrap assemblies to flat-ribbon cables which eliminate</p> <ul style="list-style-type: none"> Less than predicted reliability Liquid cooled LRUs Hardware age ≥ 10 years

TREND EVALUATION: AGE OF SYSTEM AND TECHNOLOGY (continued)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
AN/APG-63 Radar		<ul style="list-style-type: none"> • Early-70s design • Solid-state components with hybrids and ICs • Programmable processor • No inter-rack wiring • Quick-disconnect fittings • Quick-release fasteners (without safety wire) on LRU • Digital signal processing • Plug-in modules 	<ul style="list-style-type: none"> • Flat ribbon cable interconnecting modules 	<ul style="list-style-type: none"> • Liquid cooled LRUs 	Positive	<p>7. (cont) chassis wiring entirely which leads to:</p> <ul style="list-style-type: none"> • Increased provisioning requirements • Chassis wiring checks replaced by substitution methods • Reduced repair times • Higher parts cost
F-15	AN/AWG-20	<ul style="list-style-type: none"> • Solid-state electronics (extensive use of hybrids and ICs) • Plug-in modules • Wire-wrap technique for wiring between SRAs • Digital signal processing • Quick-disconnect fittings • Quick-release fasteners on LRUs (no safety wire) 	<ul style="list-style-type: none"> • Late-60s design • Hardware age ≥ 5 years • Hard-wired processor logic 	Positive	<p>8. LRU interconnection technology exhibits no real trend. Point-to-point rack wiring and discrete-wire bundles are being used to interconnect LRUs presently.</p>	

TREND EVALUATION: AGE OF SYSTEM AND TECHNOLOGY (continued)

Weapon System	Avionics Subsystem	Positive	Analysis Summary	Overall Assessment	Trend Analysis
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • Mid-70s design • Solid-state electronics (hybrids and ICs) • No forced cooling air required • No electro-mechanical tuners • No chassis wiring • Ultra-simplified modularity • Quick-release fasteners and connectors • Hardware age < 5 years • Non-pressurized case 	<ul style="list-style-type: none"> • Flat ribbon cable interconnecting modules 	<ul style="list-style-type: none"> • Rotary switches • Analog signal processing 	<ul style="list-style-type: none"> Positive
	AN/ARN-118 TACAN	<ul style="list-style-type: none"> • Mid-70s design • Solid-state electronics (hybrids and ICs) • No forced cooling air required • No electro-mechanical tuner • Quick release fasteners (no safety wire) • Quick-release connectors 	<ul style="list-style-type: none"> • Some analog signal processing • Rack wiring 	<ul style="list-style-type: none"> Positive 	

TREND EVALUATION: AGE OF SYSTEM AND TECHNOLOGY (continued)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-16 (cont)	AN/ARN-118 TACAN (cont)	<ul style="list-style-type: none"> • No forced cooling • are required • No electro-mechanical tuner • Quick release fasteners (no safety wire) • Quick release connectors • Hardware age < 5 years • Non-pressurized case 				

TREND EVALUATION: DEBRIEFING

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-4E	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> Simple, standardized write-ups describe camera malfunctions Debriefing can be accomplished by personnel having no camera maintenance experience Camera shop personnel are not required to assist debriefing 	<ul style="list-style-type: none"> Coordination required between debriefing, film processing shop and film evaluator (debriefing fault-isolates between filmpack and camera) 	Questionable	<p>1) Increasing system functional complexity leads to:</p> <ul style="list-style-type: none"> Reduced debriefing effectiveness (errors, etc.) Increasing need for debriefer to have had maintenance experience Increasing need for technical advice from outside sources (for aircrews and debriefers) <p>2) Increasing BIT capabilities does not lead to improved debriefing, but in fact, seems to reduce debriefing effectiveness by adding system functional complexity (debriefers must consider BIT problems in addition to the operational malfunctions)</p> <p>3) Increasing delays in determining system status (due to film processing, film assessment, etc.) reduce effectiveness of debriefing. Delays greater than 30 minutes can be significant (not uncommon)</p> <p>4) Various communication systems have been tried (to improve transmission of write-ups to maintenance control and shops) but, the trend appears to be away from such equipment and back to the telephone. In some cases, write-ups are simply hand-carried to maintenance control by debriefers.</p>
AN/ASX-1 TISEO		<ul style="list-style-type: none"> Status determined/ reported by aircrew 		Questionable	

TREND EVALUATION: DEBRIEFING

Page 2 of 5

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
C-5A	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> • Simple, standardized write-ups • Status determined/ reported by aircrew • Debriefers do not require radio maintenance experience • Radio shop personnel not required to assist debriefers • Coordination not required 			Positive	<p>5) Quality of debriefing continues to be a problem which affects maintenance of complex subsystems (such as radar). Debriefing quality does not impact maintenance of the less complex subsystems such as communication or navigation.</p> <p>6) Automatic malfunction processing systems such as the Malfunction Detection Analysis and Recording (MADAR)/Ground Processing System (GPS) used for the C-5A do not improve debriefing effectiveness. The system supplements but does not replace normal debriefing procedures.</p>
	MARK V TACAN Set	<ul style="list-style-type: none"> • Simple, standardized write-ups • Status determined/ reported by aircrews • Debriefers do not require TACAN maintenance experience • Nav shop personnel not required to assist debriefing • Coordination not required 	<ul style="list-style-type: none"> • Some interrelated malfunctions 		Positive	

TREND EVALUATION: DEBRIEFING

Page 3 of 5

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-111D	KB-18A Strike Camera System	<ul style="list-style-type: none"> Simple, standardized write-ups Debriefers do not require camera maintenance experience 	<ul style="list-style-type: none"> Coordination between shops and debriefing No camera status during debriefing Delayed write-ups 	Questionable	Questionable
	AN/APQ-130 Radar	<ul style="list-style-type: none"> Camera shop representative not required in debriefing Status determined/ reported by aircrew 	<ul style="list-style-type: none"> Complex malfunctions Debriefers require radar maintenance experience Technical advise required in debriefing Coordination with shops required Insufficient data on debriefing forms 	Negative	Negative
AN/APQ-63 Radar		<ul style="list-style-type: none"> Status determined/ reported by aircrew 	<ul style="list-style-type: none"> Complex malfunctions Insufficient information logged on forms 	Negative	Negative

TREND EVALUATION: DEBRIEFING

Page 4 of 5

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-15	AN/AWG-20 Armament Control			<ul style="list-style-type: none"> • Technical advise required in debriefing • Coordination with shops required • Insufficient data on debriefing forms • Maintenance experience required 	Questionable	
		<ul style="list-style-type: none"> • Simple, standardized write-ups 	<ul style="list-style-type: none"> • Some technical advise required in debriefing 	<ul style="list-style-type: none"> • Complex interrelated malfunctions • Insufficient data in debriefing forms • Maintenance background is required 		
F-16	AN/ARC-164 Radio Set	<ul style="list-style-type: none"> • Simple, standardized write-ups 		<ul style="list-style-type: none"> • Status determined/ reported by aircrew • Maintenance experience not essential • Technical advise not required in debriefing • No coordination with shops required 	Positive	

TREND EVALUATION: DEBRIEFING

Page 5 of 5

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
	AN/ARN-118 TACAN Set	<ul style="list-style-type: none"> • Simple, standardized write-ups • Status determined/reported by aircrew • Maintenance experience not essential • Technical advise not required • No coordination with shops required 			Positive	

TREND EVALUATION: DEPOT SUPPORT

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-4E	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> • LRU repairs beyond I-level shop capability • More extensive test capability than I-level shops • Single depot shop 		Positive	<p>1) Repair of LRUs remains primarily an intermediate level function, however, depot repair of LRUs is becoming more feasible due to improving reliability (example: AN/ARN-118 TACAN RIW program).</p> <p>2) Repair of SRUs is being shifted almost entirely to the depot shops from the intermediate level shops.</p> <p>3) Quality of depot level support decreases (as perceived by I-level) as differences in the I-level and depot test concepts for SRUs become larger. Utilizing I-level LRU test sets at the depot for final SRA checkout minimizes the I-level rejection rate. Not performing a final SRU checkout at the LRU level in the depot shop results in a high I-level rejection rate.</p>
AN/ASX-1 TISEO		<ul style="list-style-type: none"> • LRU/SRUs received by I-level shops require realignment • All SRU repairs • Test capability (for SRUs) beyond I-level shop capability • Single depot shop 	<ul style="list-style-type: none"> • Inadequate spares in supply system 	Questionable	
C-5A	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> • LRU repairs beyond I-level shop capability • SRU repairs beyond I-level shop capability • Single depot shop 	<ul style="list-style-type: none"> • Same LRU and SRU test capability as I-level shops • Some SRU repair in I-level shops 	Questionable	
MARK V TACAN Set		<ul style="list-style-type: none"> • LRU repairs beyond I-level shop capability • All SRU repairs 	<ul style="list-style-type: none"> • Same LRU tests capability as I-level shop 	Positive	

TREND EVALUATION: DEPOT SUPPORT

Page 2 of 3

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
		<ul style="list-style-type: none"> ● Single depot shop ● More extensive test capability (for SRUs) than field shops 			
F-111D	KB-18A Strike Camera System	<ul style="list-style-type: none"> ● LRU repairs beyond field shop capability ● SRU repairs beyond field shop capability ● Single depot shop ● LRU and SRU test capability beyond field shops 	<ul style="list-style-type: none"> ● Some SRU repair in field shops 	Questionable	
F-15	AN/APQ-130 Radar	<ul style="list-style-type: none"> ● LRU repairs beyond field shop capability ● All SRU repairs ● LRU/SRU test capability beyond field shop capability 	<ul style="list-style-type: none"> ● Two depot shops (one for LRUs and one for SRUs) 	Negative	<ul style="list-style-type: none"> ● Inadequate spares in supply system ● High reject rate for items received from depot at field shop (test tolerance incompatibilities)
	AN/APQ-63 Radar	<ul style="list-style-type: none"> ● LRU repairs beyond field shop capability ● All SRU repairs ● LRU/SRU test capability beyond field shop capability 			

Weapon System	Avionics Subsystem	TREND EVALUATION: DEPOT SUPPORT			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
AN/AWG-20 Armament Control	<ul style="list-style-type: none"> • Single depot shop • LRU repairs beyond field shop capability • All SRU repairs • LRU/SRU test capability beyond field shop capability • Single depot shop 			<ul style="list-style-type: none"> • Inadequate spares in supply system 		
F-16	<p>AN/ARC-164 Radio Set</p> <ul style="list-style-type: none"> • LRU repairs beyond field shop capability • All SRU repairs • SRU test capability beyond field shop capability • Single depot shop <p>AN/ARN-11B TACAN Set</p> <ul style="list-style-type: none"> • All LRU repairs at depot (Collins) • Single depot 		<ul style="list-style-type: none"> • LRU test capability same as field shops 	<ul style="list-style-type: none"> • Initial depot ship planning did not provide LRU repair capability 	Positive	Positive

TREND EVALUATION: PRE-, IN-, POST-FLIGHT INSPECTIONS

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-4E	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> Aircrew performs operational checks Lack of maintenance inspection equipments BIT 	<ul style="list-style-type: none"> Film remaining warning, light rather than counter 	Questionable	<p>1) Preflight inspection of avionics equipment by maintenance personnel is not required with two exceptions, cameras and armament control. Maintenance checks camera operation following film-pack installation and weapons stations are checked as part of weapons loading. The general trend, however, is to preflight checks performed by the aircrew with little or no maintenance support acquired.</p> <p>2) Preflight and inflight system checks are normally performed by the aircrews using operational checkout procedures. These checks are normally limited to systems and modes specifically required for the mission at hand.</p> <p>3) BIT functions, unless automatically initiated by the system, might not be utilized by the aircrew. Aircrews tend to consider BIT as a maintenance aid and only the more experienced aircrew will provide debriefing with BIT failure data.</p>
	AN/ASX-1 TISEO	<ul style="list-style-type: none"> Aircrew performs operational checks Lack of maintenance inspection requirements BIT Constant fault-monitoring 	<ul style="list-style-type: none"> BIT/operational tests and feasible in low-light conditions Aircrew boresighting 		
C-5A	AN/ARC-104 Radio Set	<ul style="list-style-type: none"> Aircrew performs operational checks Lack of maintenance inspection requirements 	<ul style="list-style-type: none"> Qualitative checks only (no BIT for quantitative checks) No constant fault-monitoring 	Positive	
	MARK V TACAN Set	<ul style="list-style-type: none"> Aircrew performs operational checks No maintenance inspections BIT 	<ul style="list-style-type: none"> TACAN interface with automatic navigation system not checked No constant fault-monitoring 	Positive	(continued on next page)

TREND EVALUATION: PRE-, IN-, POST-FLIGHT INSPECTIONS (continued)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-111D	KB-18A Strike Camera System	<ul style="list-style-type: none"> Aircrew performs operational checks 	<ul style="list-style-type: none"> No BIT from cockpit Two men for operational checkout Maintenance check following film loading No BIT from camera compartment 	Negative	<p>4) Postflight inspection (of aircrew reported malfunctions) is accomplished in some cases as part of a quick-fix operation intended to clear malfunctions prior to aircrew debriefing. Such procedures, where utilized, are the result of low system reliability.</p>
	AN/APQ-130 Radar	<ul style="list-style-type: none"> Aircrew performs operational checks No maintenance inspections BIT Constant fault-monitoring 		Positive	<p>5) BIT failures represent a significant aid to performance of system inspection (by the aircrew) if operation is automatic to provide status of system. BIT which requires manual initiation and interpretation of displays increases the aircrew workload, extends the preflight inspection time, increases ground operating time and is therefore, less preferable.</p>
F-15	AN/APG-63 Radar	<ul style="list-style-type: none"> Aircrew performs operational checks No maintenance inspections BIT Constant fault-monitoring 		Positive	
	AN/AWG-20 Armament Control	<ul style="list-style-type: none"> Constant fault-monitoring No maintenance inspections 	<ul style="list-style-type: none"> Stray voltage checks required 	Positive	(continued on next page)

TREND EVALUATION: PRE-, IN-, POST-FLIGHT INSPECTIONS (continued)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
	AN/ARC-164	<ul style="list-style-type: none"> • Aircrew performs operational checks • No maintenance inspections 	<ul style="list-style-type: none"> • Qualitative check only (no BIT for quantitative checks) • No constant fault-monitoring 	Positive	
F-16	AN/ARN-118	<ul style="list-style-type: none"> • Aircrews perform operational checks • No maintenance inspections • BIT 		Positive	

TREND EVALUATION: LEVEL OF BASE REPAIR

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-4E	RS-97A Radar Scope Camera System	<ul style="list-style-type: none"> System repair by LRU replacement. No system alignments in the aircraft. Electro-mechanical components replaced in the intermediate shop. 	<ul style="list-style-type: none"> Inspect/repair-as-necessary every 600 flying hours. Depot repair similar to intermediate level repair. 	Questionable	<ul style="list-style-type: none"> System-level repairs are becoming less complex as system alignments are eliminated. Most systems presently have no requirements for alignments in the aircraft so that most malfunctions can be readily corrected by replacing a defective LRU. System level repair becomes simpler as the number of LRUs is reduced. Systems consisting of 4 or more LRUs are rated as difficult to repair. Systems with fewer than 4 LRUs are significantly less difficult to repair and the ideal system consists of one LRU. SRU replacement but no repair authorized is the repair concept presently most satisfactory at intermediate level. Limiting intermediate maintenance to LRU fault-verification results in under-utilization of test equipment and skills. SRU repair at intermediate level, however, results in excessive demands on skills available in the intermediate shop.
AN/ASX-1 TISEO		<ul style="list-style-type: none"> System repair by LRU replacement. LRU repair by SRU replacement (or alignment) in intermediate shop. SRU repair by component replacement in depot shop. 	<ul style="list-style-type: none"> Some system-level alignments in aircraft. System repair is unnecessarily difficult (poor accessibility hinders troubleshooting and LRU replacement). Inspect/repair-as-necessary is accomplished every 90 days. 	Positive	

TREND EVALUATION: LEVEL OF BASE REPAIR

Page 2 of 5

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
C-5A	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> • System repair by LRU replacement. • No system-level alignments. • LRU repair by SRU replacement. • Depot repair of LRUs/SRUs by component replacement. • No scheduled maintenance. 	<ul style="list-style-type: none"> • Some SRUs repaired by component replacement in intermediate shop. • Some SRUs beyond intermediate level repair capability. 	Questionable	<ul style="list-style-type: none"> • Scheduled maintenance of avionics equipment, except for a few time change items such as disseccant, is no longer required. In general, scheduled maintenance of avionics subsystems is undesirable because of the lack of evident, positive impact on system reliability. • LRU repairs at depots rather than in the intermediate shops is becoming more feasible. High reliability and adequate spares at the intermediate level appear as the most significant factors to the success of this repair concept.
MARK V Tacan Set		<ul style="list-style-type: none"> • System repair by LRU replacement. • System-level alignments not required. • LRU repair by SRU replacement in intermediate shop. • SRU repair at depot by circuit board replacement. • No scheduled maintenance. 	<ul style="list-style-type: none"> • Circuit boards are discarded at depot. 	Positive	<ul style="list-style-type: none"> • Control unit not intermediate level repairable. • Chassis (of receiver/transmitter) precludes intermediate level repair.

TREND EVALUATION: LEVEL OF BASE REPAIR

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
KB-18A Strike Camera System	<ul style="list-style-type: none"> System repair by LRU replacement. No system-level alignments. LRU repair by SRU replacement in intermediate shop. Electro-mechanical components replaced in intermediate shop. 	<ul style="list-style-type: none"> SRUs repaired at intermediate level by electronic component replacement. Depot repair similar to intermediate repair. 	<ul style="list-style-type: none"> Inspect/repair-as-necessary every 1.25 flying hours 	Questionable	Questionable
F-111D	<ul style="list-style-type: none"> AN/APQ-130 Radar Set 	<ul style="list-style-type: none"> System repair by LRU replacement. Very few system-level adjustments. LRU repair by SRU replacement in intermediate shop. SRU repair at depot by component replacement. No scheduled maintenance. 	<ul style="list-style-type: none"> System repair is excessively difficult. Quick-fix concept is used for system level repairs. Intermediate shop has difficulty duplicating system malfunctions. Depot repaired items have a high rejection rate at intermediate level. 	Positive	Uncertain

TREND EVALUATION: LEVEL OF BASE REPAIR

Page 4 of 5

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-15	AN/APG-63 Radar Set	<ul style="list-style-type: none"> • System repair by LRU replacement. • LRU repair by SRU replacement in intermediate shop. • SRU repair at depot by component replacement. • No scheduled maintenance 	<ul style="list-style-type: none"> • Intermediate shop has difficulty duplicating system malfunctions. • Depot repaired items have high rejection rate at intermediate level. 		Positive	
	AN/AWG-20 Armament Control	<ul style="list-style-type: none"> • System repair by LRU replacement. • LRU repair by SRU replacement in intermediate shop. • SRU repair at depot by component replacement. • No scheduled maintenance. 				

TREND EVALUATION: LEVEL OF BASE REPAIR

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • System repair by LRU replacement. • LRU repair by SRU replacement in intermediate shop. • SRU repair by component replacement at depot. • No system-level alignments. • No scheduled maintenance. 			Positive	
	AN/ARN-118	<ul style="list-style-type: none"> • System repair by LRU replacement. • LRU repair at Collins depot. • No system-level alignments. • No scheduled maintenance. 			Positive	

TREND EVALUATION: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> • 2 LRUs • No system-level alignments • BIT (manually initiateable) 	<ul style="list-style-type: none"> • No plug-in electronic subassemblies 	Positive	Positive	<p>1) System maintainability is directly related to the number of LRUs. Systems consisting of 1-3 LRUs are easily maintained. Systems with 4 or more LRUs are at least moderately difficult to maintain. Systems with 8 or more LRUs are considered difficult to maintain and are a problem for the maintenance organizations.</p>
F-4E AN/ASX-1 TISEO	<ul style="list-style-type: none"> • BIT (constant fault-monitoring) • Plug-in electronic SRUs used extensively • LRU concept • 4 LRUs • BIT fault-isolation connector in cockpit 	<ul style="list-style-type: none"> • System-level alignments • No BIT capability for low-level flight conditions 	Questionable	Questionable	<p>2) Difficulty of system fault-isolation, which increases proportionately to the number of LRUs, is the single most important factor by which flightline maintenance personnel rate system maintainability. Other factors such as BIT, accessibility, etc. seem to be secondary.</p>
AN/ARC-109 Radio Set	<ul style="list-style-type: none"> • 2 LRUs • No system-level alignments • Plug-in electronic SRUs used extensively in receiver/transmitter • BIT meter • Redundant radio sets in C-5A 	<ul style="list-style-type: none"> • Control unit difficulty of repair (due to multi-wafer rotary switch complexity) 	Positive	Positive	<p>3) BIT functions to provide go/no-go (operational) tests are an aid to maintenance because of the reduced test equipment requirements. BIT diagnostics, however, has met with very limited success and has not</p>
C-5A MARK V TACAN Set	<ul style="list-style-type: none"> • 2 LRUs • System-level alignments not required • Plug-in electronic SRUs used extensively in receiver/transmitter 	<ul style="list-style-type: none"> • System-level alignments and procedures • Test connector on receiver/transmitter 	Positive	Positive	<ul style="list-style-type: none"> • Control unit difficulty of repair (due to multi-wafer rotary switch complexity)

TREND EVALUATION: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
C-5A (Cont)	MARVEL TACAN Set (Con't)	<ul style="list-style-type: none"> BIT (manually initiateable in cockpit) Plug-in circuit boards used extensively in SRUs Redundant TACAN sets in C-JA 	<ul style="list-style-type: none"> No BIT meter on receiver/transmitter chassis BIT does not provide constant status monitoring 	<ul style="list-style-type: none"> Receiver/transmitter difficulty of repair (due to accessibility problems caused by cooling air plenum) 	<p>done much to improve system maintainability with one exception. Fault-indicators (flags) on each LRU which indicate BIT failure, as used in the AN/APG-63 radar, are a definite aid to fault-isolation of BIT failures and improve system maintainability.</p>
KB-18A Strike Camera System		<ul style="list-style-type: none"> 2 LRUs No system-level alignments BIT (manually initiateable) Plug-in electronic SRUs used extensively in control unit 	<ul style="list-style-type: none"> BIT does not provide constant status-monitoring Unused hardware/functions not modified out of system 	Questionable	<p>4) Maintenance personnel prefer BIT functions which are automatically initiated by the system, store failure data for use after flight, and provide a positive indication of LRU status (failure flag, etc.) on each LRU tested.</p>
F-111D AN/APQ-130 Radar		<ul style="list-style-type: none"> BIT (constant fault-monitoring) BIT (fault-diagnostics) LRU concept Plug-in electronic SRUs used extensively Limited system-level alignments required 	<ul style="list-style-type: none"> 8 LRUs BIT controls in cockpit only Fuses rather than breakers for over-load protection 	Negative	<p>5) Racked LRUs interconnected by cables represents a good maintainability design. None-racked LRUs exhibit poor accessibility and higher removal/installation times. Racked LRUs interconnected by rack wiring exhibit good accessibility and low removal/installation times but are plagued by LRU seating and rack wiring problems.</p>

TREND EVALUATION: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
F-111D (Cont)		<ul style="list-style-type: none"> • Transmitter liquid coolant system (requires hydraulic shop support, time consuming on aircraft and in shop, hinders transmitter maintenance in shop, etc.) • Flat-ribbon cable interconnecting SRUs (easily broken) • Poor quality connector pin extractor/insertion tools 	<ul style="list-style-type: none"> • Rack associated problems (repair of LRU fasteners, LRU seating, difficulty of rack removal/installation, etc.) • Connector repair difficulties (pins are difficult to replace due to problem with tools) • BIT fault-isolation capability (inadequate/inaccurate) • Wiring problems 	Negative	<p>6) System-level alignments have, in general, been eliminated. Where still required, they are definitely considered to detract from system maintainability. The trend is to accomplishment of LRU analog circuit alignment in the intermediate shop. Alignments are not performed at the aircraft unless absolutely necessary. LRU/SRU alignments performed at a depot are normally checked and realigned, if required, by the intermediate level.</p> <p>7) LRUs with plug-in electronic modules (SRUs) are more maintainable than units without the plug-ins. However, the most maintainable design eliminates the LRU chassis (which cannot be treated as an SRU) and consists entirely of SRUs. In such an LRU, the SRUs fasten directly to each other and are interconnected by cable assemblies which are protected by a cover.</p>

TREND EVALUATION: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
AN/APG-63 Radar	<ul style="list-style-type: none"> • LRU concept • BIT (constant fault-monitoring) • BIT (fault-diagnostics) • LRU fault-indicators • Plug-in electronic SRUs used extensively 	<ul style="list-style-type: none"> • 9 LRU • Transmitter liquid cooling system (requires hydraulic shop support, time consuming servicing on aircraft and in shop, hinders troubleshooter troubleshooting in shop) 	<ul style="list-style-type: none"> • LRU handling problem (excessive receiver/transmitter weight) • Connector repair difficulties (pins difficult to replace due to problem with tools) • LRU fasteners not repairable in intermediate shop • Pressurized power supply • BIT failure results are inconsistent • BIT range and angle checks insufficient • Waveguide dehumidification problems 	Questionable	<p>8) Wiring problems continue as a significant factor in maintenance of avionics systems. Problems arise because of the cumulative effects of vibration, pulling and bending stresses, chaffing, chemical deterioration, etc. Wiring problems are also associated with system complexity. Low complexity systems (one to three LRU's) involve very few wiring problems. Higher complexity systems (4 or more LRU's) exhibit many more suspected/proven wiring problems.</p>	
F-15						

TREND EVALUATION: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
F-15 (Cont)	AN/AWG-20 Armament Control	<ul style="list-style-type: none"> • 2 LRUs • BIT (constant fault-monitoring and initiateable) • Plug-in electronic SRUs utilized extensively 	<ul style="list-style-type: none"> • Poor quality connector pin extraction/insertion tools 	<ul style="list-style-type: none"> • BIT provides inadequate fault-isolation capability • Connector repair difficulties • Wiring problems (breakage at connectors) 	Positive
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • 1 LRU • No chassis • All components contained in 5 SRUs • Circuit boards used extensively in SRUs • No system-level alignments required in aircraft 	<ul style="list-style-type: none"> • No BIT features • Flat ribbon cable interconnecting SRUs and circuit boards (easily broken during radio maintenance) 	<ul style="list-style-type: none"> • No BIT meter on receiver/transmitter • BIT (manually initiateable in cockpit) 	Positive
	AN/ARN-118 TACAN Set				

TREND EVALUATION: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> Sortie data logged on debriefing forms Maintenance data logged on 349s/350s Periodic/special reports generated Constant review/analysis not required Debriefing forms create aircraft histories 	<ul style="list-style-type: none"> Camera operating hours per flight hour cannot be determined 	<ul style="list-style-type: none"> Real time analysis/reports generated manually Aircraft history not available in camera shop 	Positive	<ol style="list-style-type: none"> 1) Low complexity, high reliability systems can be maintained effectively with little or no maintenance data analysis. Higher complexity, low reliability systems cannot be maintained effectively without implementing a comprehensive maintenance data analysis program. 2) All maintenance shops tend to maintain files for analysis purposes. Most shops will normally use 349 files for real time analysis and 349 summary reports for non-real time analysis. In addition to 349 files, those shops maintaining complex systems (such as radarsets) normally file and analysis debriefing forms to obtain real-time comprehensive malfunction/maintenance data.
F-4E	AN/ASX-1 TISEO	<ul style="list-style-type: none"> Sortie data logged on debriefing forms Debriefing forms create aircraft histories Maintenance data logged on 349s/350s Periodic/special reports generated 	<ul style="list-style-type: none"> Review/analysis required 	<ul style="list-style-type: none"> Real time analysis/reports generated manually 	Questionable	

TREND EVALUATION: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
AN/ARC-109 Radio Set		<ul style="list-style-type: none"> • Sortie data logged on debriefing forms • Debriefing forms create aircraft history • Maintenance data logged on 349s/350s • Periodic/special reports generated • Constant review/analysis not required 	<ul style="list-style-type: none"> • NADAR/GPS provides automatic 349 generation (supplements debriefing activity) • Real time analysis/reports generated manually • Aircraft history not available in radio shop 	Positive	<p>3) Periodic reports (which summarize debriefing forms and 349 data) are normally provided by an Analysis Section to the maintenance shops. Periodic reports are developed utilizing Automatic Data Processing techniques. Periodic reports can be generated on a weekly basis but most are produced monthly.</p> <p>4) Special reports summarizing debriefing/349 data can also be generated by an Analysis Section. Special reports can be obtained within one or two days. Data can be arranged by aircraft tail number, malfunction, system, etc.</p> <p>5) Periodic reports serve to satisfy maintenance management requirements. Special reports, if utilized, are normally directed toward providing maintenance shops with information which can be used to improve maintenance efficiency.</p>
C-5A	MARK V TACAN Set	<ul style="list-style-type: none"> • Sortie data logged on debriefing forms • Debriefing forms create aircraft history • Maintenance data logged on 349s/350s • Periodic/special reports generated • Constant review/analysis not required • Operating time available for elapsed time indicators 	<ul style="list-style-type: none"> • NADAR/GPS provides automatic 349 generation (supplements debriefing activity) • Real time analysis accomplished manually • Aircraft history not available in navigation shop 	Positive	

TREND EVALUATION: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
	KB-18A Strike Camera System	<ul style="list-style-type: none"> ● Sortie data logged on debriefing forms ● Debriefing forms create aircraft history ● Maintenance data logged on 349s/350s ● Periodic/special reports generated ● Constant review/analysis not required 	<ul style="list-style-type: none"> ● System operating time cannot be determined 	<ul style="list-style-type: none"> ● Real time analysis accomplished manually 	<p>6) Maintenance shops, even when supported with periodic and special reports, find it essential to rely on files of forms (bulky, require constant updating, etc.) and manual analysis to provide real time data conveniently available to users on a reliable basis.</p>
F-111D	AN/APQ-130 Radar	<ul style="list-style-type: none"> ● Sortie data logged on debriefing forms ● Debriefing forms create aircraft history ● Maintenance data logged on 349s/350s ● Periodic/special reports generated ● Operating time can be determined from elapsed time indicators 	<ul style="list-style-type: none"> ● Constant review/analysis is required ● Real time analysis accomplished manually 	<p>7) Malfunction data recorded on debriefing forms normally does not provide adequate information for maintenance. A need exists for in-flight recording of malfunction data to supplement data recorded in debriefing. Experience with in-flight recording systems (such as MADAR used in C-5A) indicates the feasibility of the in-flight recording concept while bringing out the requirement for refinements if such a system is to serve as a maintenance aid.</p>	

TREND EVALUATION: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-15	AN/APG-63 Radar	<ul style="list-style-type: none"> • Sortie data logged on debriefing forms • Debriefing forms create aircraft history • Maintenance data logged in 349s/350s • Periodic/special reports generated • Operating time can be determined from elapsed time indicators 	<ul style="list-style-type: none"> Constant review/analysis is required Real time analysis accomplished manually 	Negative	8) The existing maintenance data processing procedures are adequate for support of low complexity, high reliability systems where analysis requirements are minimal. However, where data pertains to high complexity systems, the burden of processing forms, accomplishing analysis, etc. in real time has a negative impact on maintenance efficiency.	
AN/AWG-20	Armament Control	<ul style="list-style-type: none"> • Sortie data logged on debriefing forms • Debriefing forms create aircraft history • Maintenance data logged in 349s/350s • Periodic/special reports generated 	<ul style="list-style-type: none"> System operating time cannot be determined 	Negative	<ul style="list-style-type: none"> Constant review/analysis is required Real time analysis accomplished manually 	

TREND EVALUATION: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
AN/ARC-164 Radio	<ul style="list-style-type: none"> • Sortie data logged on debriefing forms • Debriefing forms create aircraft history • Maintenance data logged on 349s/350s • Periodic special reports generated • Constant review/analysis not required 	<ul style="list-style-type: none"> • System operating time cannot be determined 	<ul style="list-style-type: none"> • Aircraft history not available in radio shop • Real time analysis accomplished manually 	Positive	
AN/ARN-118 TACAN Set F-16	<ul style="list-style-type: none"> • Sortie data logged on debriefing forms • Debriefing forms create aircraft history • Maintenance data logged on 349s/350s • Periodic/special reports generated • Constant review/analysis not required • System operating time measured by elapsed time indicators 		<ul style="list-style-type: none"> • Real time analysis accomplished manually • Aircraft history not available in navigation shop 	Positive	

TREND EVALUATION: MAINTENANCE ORGANIZATION

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
KS-97A Radar Scope Camera System	F-4E	<ul style="list-style-type: none"> • Two-level maintenance organization (with no O-level) can be utilized effectively • Three-level maintenance organization can be utilized effectively • Aircrews handle film • I-level shop personnel assist O-level personnel with periodic inspections 		Positive	<p>1) Based upon cost-effectiveness studies, generally, as system complexity (represented by number of LRUs) increases, use of the three-level maintenance organization becomes more essential. Low complexity, high reliability systems can be effectively supported using a two-level maintenance organization (consisting of intermediate and depot shops). As system complexity increases, specialized maintenance functions for aircraft systems maintenance and LRU shop maintenance become necessary. Depot maintenance, which is clearly necessary for support of the majority of avionics equipment, is required because of LRU and LRU test equipment complexities and is not related directly to system complexity.</p>
AN/ASX-1 TISEO			<ul style="list-style-type: none"> • Three-level maintenance organization is essential to effective maintenance 	Questionable	

TREND EVALUATION: MAINTENANCE ORGANIZATION (Continued)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
C-5A	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> Two-level maintenance organization (with no 0-level) can be utilized effectively Three-level maintenance organization can be utilized 		Positive	2) Test equipment complexity is a key factor driving requirements for specialized maintenance organizations. Utilizing similar or identical test equipment for LRU and SRU testing increases the feasibility of simplifying maintenance organization. Take as an example AN/ARC-109 radio maintenance. Intermediate and depot maintenance shops use identical hot mock-ups to accomplish LRU/SRU repair to the component level. The intermediate maintenance shop does, in fact, have the equipment to perform all depot level maintenance. The intermediate level radio shop also accomplishes the flightline maintenance. A one-level maintenance organization could, in fact, be used to repair the AN/ARC-109 radio set.
	Mark V Tacan Set	<ul style="list-style-type: none"> Two-level maintenance organization (with no 0-level) can be utilized Three-level maintenance organization can be utilized 		Positive	Not Yet Determined Based on current information available, it is not clear if a three-level organization would be required for the Mark V Tacan Set. It is recommended that the system be evaluated to determine if a two-level organization would be sufficient.
	KB-18A Strike Camera	<ul style="list-style-type: none"> Two-level maintenance organization (no 0-level) can be utilized 		Questionable	Not Yet Determined Based on current information available, it is not clear if a two-level organization would be sufficient.

TREND EVALUATION: MAINTENANCE ORGANIZATION (Continued)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-111D	AN/APQ-130 Radar	<ul style="list-style-type: none"> Three-level maintenance organization can be utilized 	<ul style="list-style-type: none"> flightline for servicing camera film Aircraft transmitter cooling system responsibility shared between avionics and hydraulics shops 	<ul style="list-style-type: none"> Negative 	<ul style="list-style-type: none"> Three-level maintenance organization is essential for effective maintenance 	<p>3) Low complexity, non-integrated systems (communications, navigation, reconnaissance, etc.) are, in general, presently being maintained by two-level maintenance organizations.</p> <p>High complexity, integrated systems (radar, armament control, etc.) are presently being maintained by three-level maintenance organizations.</p>
F-15	AN/APG-63 Radar		<ul style="list-style-type: none"> Aircraft transmitter cooling system responsibility shared between avionics and hydraulics shops 	<ul style="list-style-type: none"> Negative 	<ul style="list-style-type: none"> Three-level maintenance organization is essential for effective maintenance 	<ul style="list-style-type: none"> Three-level maintenance organization is essential for effective maintenance

TREND EVALUATION: MAINTENANCE ORGANIZATION (Continued)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • Two-level maintenance organization (no 0-level) can be utilized • Three-level maintenance organization can be utilized 			Positive	
	AN/ARN-118 TACAN Set	<ul style="list-style-type: none"> • Two-level maintenance organization (no 0-level) can be utilized • Three-level maintenance organization can be utilized 			Positive	

TREND Evaluation: Organizational Level AGE

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
F-4E	KS-97A Radar Scope System	<ul style="list-style-type: none"> No flightline equipment Suitcase LRU test set in intermediate shop 	<ul style="list-style-type: none"> Optical alignment fixtures in intermediate level shop 	Positive	<p>1) LRU handling equipment requirements should be avoided. Maintenance personnel will handle LRUs and will avoid using special equipment if at all possible</p> <p>2) Receiver/transmitter units, optics assemblies and radar antennas are candidates for handling with equipment rather than man-handling. R/T units are presently man-handled and the special equipment is not considered essential. Antenna handling equipment has, however, proven to be an aid to maintenance and is utilized.</p> <p>Hoists are considered necessary for removal/installation of antennas when the antenna is more than approximately shoulder height. Antenna handling fixtures might be effective in minimizing antenna transportation and handling damage if a fragile antenna cannot be avoided.</p>
AN/ASX-1 TISEO		<ul style="list-style-type: none"> Reusable shipping/storage container provides protection during flight-line handling Suitcase LRU test sets SRU test sets in depot shop 	<ul style="list-style-type: none"> Same LRU test sets in intermediate and depot level shops 	Questionable	
C-5A	AN/ARC-10a Radio Set	<ul style="list-style-type: none"> No special flight-line test sets required Common radio test instruments used the flightline checks Interconnection test set (hot mock-up) used in an intermediate and depot shops 	<ul style="list-style-type: none"> Depot SRU test sets (same as LRU test sets) 	Positive	<ul style="list-style-type: none"> Interconnection test sets fabricated by using organizations

TREND Evaluation: Organizational Level ACE

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
C-5A (Cont'd)	Mark V TACAN Set	<ul style="list-style-type: none"> No special flight-line test sets required Standard flight-line TACAN test set used when required Interconnection test set (hot mock-up) for LRU tests in intermediate and depot shops SRU test sets for use in depot shop 	<ul style="list-style-type: none"> Overly complex displays/procedures for interconnection test set reported 	<ul style="list-style-type: none"> Problems with test cables and connectors on intermediate level test set reported 	<p>Reuseable shipping/storage containers have been found to be effective for use in local transportation and handling of fragile optical units</p> <p>3) Flightline test equipment utilization has been minimized or eliminated in many cases. Flightline maintenance personnel prefer not to use test equipment if at all possible even when its use is recommended.</p>
	KB-18A Strike Camera System	<ul style="list-style-type: none"> No flightline equipment required Suitcase LRU test set for intermediate level shops 		<ul style="list-style-type: none"> Eratic operation of LRU test set reported 	<p>4) Flightline test equipment has been mostly replaced by BIT. Flightline technicians are now concerned about BIT thoroughness, inability to duplicate airborne problems, etc., and recognize the need for improved BIT of flightline test equipment.</p>
F-111D					

TREND Evaluation: Organizational Level AGE

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-111D (cont'd)	AN/APQ-130 Radar	<ul style="list-style-type: none"> • No special flight-line test sets required • Hot mock-up test set in intermediate shops 	<ul style="list-style-type: none"> • Effectiveness of test stations in intermediate shops • Antenna handling equipment not provided (antenna alignments disturbed by handling) 	<ul style="list-style-type: none"> • Receiver/transmitter handling equipment required • Inconsistency of test tolerances/philosophy between BIT, intermediate and depot testing 	Negative	<p>5) Hot mock-ups, where utilized, appear to be an effective aid to maintenance. When hot mock-ups are not utilized, the intermediate level maintenance shop cannot duplicate flight-line problems and often times must test LRUs in another aircraft.</p> <p>One exception was noted. TISEO maintenance is performed satisfactorily without the use of a hot mock-up.</p> <ul style="list-style-type: none"> • Insufficient test access provided by test station • Interface cable problems on test station • Transmitter cooling oil servicing equipment in intermediate shop is excessively slow


TREND Evaluation: Organizational Level AGE

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-15	AN/APG-63 Radar	<ul style="list-style-type: none"> No special flight line test sets required Antenna hoist is an aid to removal/installation 	<ul style="list-style-type: none"> Antenna handling cradle (man-handling preferred but handling damage not reported as for AN/APQ-130 antenna) Intermediate shop test station effectiveness Transmitter coding oil servicing equipment in intermediate shop is time consuming to utilize 	<ul style="list-style-type: none"> Receiver/transmitter handling equipment required Lack of hot mock-up for intermediate level shop Inconsistency of test tolerances/philosophy between BIT, intermediate and depot tests 	Negative	<ul style="list-style-type: none"> Servicing equipment for oil cooled transmitters is considered to require excessive time to accomplish its function. Servicing the AN/APG-63 transmitter requires much less time (approximately 45 minutes) than servicing the AN/APQ-130 transmitter (7-8 hours) but further reduction of servicing times is required to minimize maintenance delays.
	AN/ANG-20 Armament Control			<ul style="list-style-type: none"> Flightline test sets required to check weapons stations (and fault-isolate armament system) Intermediate shop test station effectiveness 	Negative	<ul style="list-style-type: none"> Inconsistency of test tolerances/philosophy between BIT, intermediate and depot testing


AD-A080 495 HUGHES AIRCRAFT CO CANOGA PARK CALIF MISSILE SYSTEMS--ETC F/G 1/3
DESIGN-FOR-REPAIR CONCEPT DEFINITION VOLUME II. DETAILED ANALYS--ETC(U)
AUG 79 F A GERKIN, J L GREEN, J M KING F33615-78-C-1461
UNCLASSIFIED MSG-9285-VOL-2 AFAL-TR-79-1130-VOL-2 NL

3 OF 3
AD
A080495

12/2
1000



END
DATE
FILED
3 - 80
-
DDC



TREND Evaluation: Organizational Level AGE

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • No special flight-line test sets required • Common radio test equipment utilized when required • Interconnection test set (hot mock-up) for LRU test in intermediate and depot shops • SRU test sets in depot shop 		<ul style="list-style-type: none"> • SRU test sets in depot shop over-designed 	Positive	
	AN/ARN-118 TACAN Set	<ul style="list-style-type: none"> • No special flight-line test sets required • Common radio navigation test sets and instruments used on flightline if required • Interconnection test set (hot mock-up) used in intermediate shops 			Positive	

TREND EVALUATION: PREVENTIVE MAINTENANCE

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-111D	MARK V TACAN Set	<ul style="list-style-type: none"> None per -6 manual Maintenance personnel do not feel preventive maintenance is required 	<ul style="list-style-type: none"> MARK V TACAN, with analog design of late 60s, might operate more efficiently if tested/aligned by intermediate shop periodically 		Questionable	<p>4) Need for scheduled preventive maintenance is a function of the system design. No preventive maintenance is required or considered necessary for digital electronics. No preventive maintenance is required although there is some sentiment for preventive maintenance of analog type electronics systems.</p> <p>Electro-mechanical equipment presents the most obvious requirements for scheduled preventive maintenance, however, the details of such requirements (frequency, level of tear-down, etc.) are very controversial. Maintenance personnel would, in general, tend toward support of minimizing these requirements.</p>
	KB-18A Strike Camera System	<ul style="list-style-type: none"> 125 hour preventive maintenance does not appear essential to maintaining reliable operation 	<ul style="list-style-type: none"> Intermediate shop clean, lubricate, test, repair as required per -6 manual every 125 flying hours 		Negative	
F-15	AN/APQ-130 Radar	<ul style="list-style-type: none"> None per -6 manual None required per maintenance personnel 			Positive	
	AN/APG-63	<ul style="list-style-type: none"> None per -6 manual None required per maintenance personnel 			Positive	
	AN/AWG-20 Armament Control	<ul style="list-style-type: none"> None per -6 manual None required per maintenance personnel 			Positive	

TREND EVALUATION: PREVENTIVE MAINTENANCE

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-4E	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> • 600 hour preventive maintenance does not seem essential to maintaining reliable operation 	<ul style="list-style-type: none"> • Intermediate shop clean, lubricate, test, repair as required every 600 flying hours per -6 manual 		Questionable	<p>1) Preventive maintenance of avionics systems is being reduced in scope or eliminated entirely. Of the avionics equipment surveyed, only camera systems received scheduled preventive maintenance.</p> <p>2) Maintenance personnel, in general, prefer that preventive maintenance not be required. However, some maintenance shops perform scheduled inspection/alignments of their equipment (TISEO is an example). Shops voluntarily performing preventive maintenance maintain that system performance is improved as reflected by reduced squak rates.</p> <p>3) A greater need for scheduled preventive maintenance is perceived by intermediate level maintenance personnel than organizational level personnel. In many cases LRUs pulled from aircraft for in flight write-ups require only alignments. Some shop personnel, therefore, conclude that scheduled LRU alignments might minimize such problems.</p>
AN/ASX-1 TISEO		<ul style="list-style-type: none"> • None per -6 manual • Maintenance personnel consider none required • No aircraft removals unless required 	<ul style="list-style-type: none"> • Scheduled inspection every 90 days seems to reduce system in flight write-ups 		Questionable	
AN/ARC-109 Radio Set		<ul style="list-style-type: none"> • None per -6 manual • Maintenance personnel do not feel preventive maintenance is necessary 	<ul style="list-style-type: none"> • AN/ARC-109 radio, with analog design of late 60s, might operate more efficiently if periodically tested/aligned by intermediate shop periodically 		Questionable	
C-5A						

TREND EVALUATION: PREVENTIVE MAINTENANCE

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> • None per -6 manual • None required per flightline maintenance personnel 	<ul style="list-style-type: none"> • Intermediate level personnel feel preventive maintenance might reduce in-flight write-ups 		Questionable	
	AN/ARN-118 TACAN Set	<ul style="list-style-type: none"> • None per -6 manual • None required per maintenance personnel 	<ul style="list-style-type: none"> • Analog functions with alignments, might require periodic alignment 		Questionable	

TREND EVALUATION: TECHNICAL MANUALS

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-4E	KB-97A Radar Scope Camera System	<ul style="list-style-type: none"> ● Considered adequate by maintenance personnel 			Positive	<p>1) The quality of technical manuals, in general, appears to be good. The manuals for support of the systems surveyed were all considered adequate for their intended purposes.</p>
	AN/ASX-1 TISE0	<ul style="list-style-type: none"> ● Considered adequate by maintenance personnel 			Positive	<p>2) The technical manual problem most frequently encountered was the lack of important technical information which would be an aid to maintenance.</p>
C-5A	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> ● Considered adequate by maintenance personnel 			Positive	<p>3) The second most frequently mentioned problem with manuals was overly complex, confusing or erroneous maintenance procedures, tolerances, etc. The use of supplements, rather than change pages, was a major factor contributing to this problem.</p>
	MARK V TACAN Set	<ul style="list-style-type: none"> ● Organizational and depot level manuals considered adequate by maintenance personnel 			Questionable	<ul style="list-style-type: none"> ● Intermediate level manual test procedures contains errors and is confusing (excessive number of supplements)
	KB-18A Strike Camera System	<ul style="list-style-type: none"> ● Considered adequate by maintenance personnel 			Positive	

TREND EVALUATION: TECHNICAL MANUALS

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-111D	AN/APQ-130 Radar	• Considered adequate (except for problems noted at right) by maintenance personnel		• Insufficient technical data describing signal flow, test point values, etc.	Questionable	
F-15	AN/APG-63 Radar	• Considered adequate (except for problems noted at right) by maintenance personnel		<ul style="list-style-type: none"> • Flightline manuals provide insufficient data on BIT • Intermediate level manuals do not provide adequate technical data (no detailed LRU schematics, functional lack sufficient detail, etc.) 	Questionable	
	AN/AWG-20 Armament Control			<ul style="list-style-type: none"> • Modifications/ software changes not documented in timely fashion • Logic trees for fault-isolation of system and LRU's are difficult to understand 	Positive	

TREND EVALUATION: TECHNICAL MANUALS

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
F-16	AN/ARC-164 Radio	<ul style="list-style-type: none"> Considered adequate (exceptions noted at right) by maintenance personnel 	<ul style="list-style-type: none"> Intermediate level manuals do not clearly define level of repair authorized (SRU replacement versus circuit card replacement) 	<ul style="list-style-type: none"> Depot level manuals lack sufficient technical data for repair of some repairables 	Positive	
	AN/ARN-118 TACAN Set	<ul style="list-style-type: none"> Considered adequate (exceptions noted at right) by maintenance personnel 	<ul style="list-style-type: none"> Very limited technical data presented in intermediate level manual (not a major problem due to maintenance concept-repair by Collins) 	<ul style="list-style-type: none"> Depot level manual not available for evaluation 	Questionable	

TREND EVALUATION: TRAINING AND PERSONNEL SKILL LEVELS

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
F-4E	KS-97A Radar Scope Camera System	<ul style="list-style-type: none"> Flightline maintenance can be accomplished by 3-levels Intermediate level repair (electro-mechanical and optics) can be accomplished by 5-level personnel 5-level skilled personnel available in intermediate level shop 	<ul style="list-style-type: none"> Repair by electronic component replacement authorized for intermediate level shop (requires 7-level skills) 	<ul style="list-style-type: none"> Questionable 	<p>1) Organizational (Flightline) and intermediate maintenance shops accomplish maintenance with 3-level skilled personnel. 3-level personnel assigned to the shops are considered to be in training status and are a liability rather than a maintenance asset. 7-level personnel were normally found to be in supervisory positions.</p> <p>2) The majority of personnel assigned to flightline and intermediate shops are 5-level skilled. However, 3-levels outnumber 7-levels and the resulting average skill level available in a field shop might be less than 5-level.</p> <p>3) Many flightline and intermediate maintenance shop personnel, although having a 5-level skill rating, are not as proficient as the skill ratings would indicate due to the lack of on-the-job training. Approximately one year of OJT is considered necessary to achieve maintenance proficiency on a complex system.</p>
	AN/ASX-1 TISEO	<ul style="list-style-type: none"> Flightline maintenance can be accomplished by 5-levels Intermediate level maintenance (limited to SRU replacement) can be accomplished by 5-levels 5-level skilled personnel are assigned to flightline and intermediate level shops Intermediate shop personnel assist with inspections on the aircraft 	<ul style="list-style-type: none"> Positive 		

TRAINING AND PERSONNEL SKILL LEVELS (page 2 of 5)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
C-5A	AN/ARC-109 Radio Set	<ul style="list-style-type: none"> • Flightline maintenance can be accomplished by 3-levels • Intermediate level shop maintenance (SRU replacement) can be accomplished by 5-levels • 5-level skilled personnel are assigned 	<ul style="list-style-type: none"> • Repair by component replacement (presently authorized at intermediate level) requires 7-level skills 	<ul style="list-style-type: none"> • Questionable 	<p>4) Field maintenance shops are normally found to be under-manned. Adequate numbers of personnel are assigned and their skill level ratings will average 5-level, however, on-the-job training will be lacking. High turnover rates (approximately 40% was reported in several shops) preclude the build-up of a cadre of highly experienced personnel.</p> <p>5) Training provided technicians at the AF technical schools was reported to be excessively limited in scope. Flightline maintenance technicians reported that their training had not related to a specific aircraft. Intermediate shop personnel reported that their system-level training was slighted in favor of detailed LRU and circuit training.</p>
MARK V Tacan Set		<ul style="list-style-type: none"> • Flightline maintenance can be accomplished by 3-levels • Intermediate level maintenance (SRU replacement) can be accomplished by 5-levels • 5-level skilled personnel are assigned 		<ul style="list-style-type: none"> • Positive 	<p>6) LRU testing and SRU replacements can be easily accomplished by the 5-level skilled personnel normally available in the intermediate shops. Electronic component fault-isolation and replacement requires electronic</p> <p>(continued next page)</p>
KB-18A Strike Camera System		<ul style="list-style-type: none"> • Flightline maintenance can be accomplished by 5-levels • Intermediate level shop maintenance (electro-mechanical and optical) can be accomplished by 5-levels 		<ul style="list-style-type: none"> • Questionable 	

TRAINING AND PERSONNEL SKILL LEVELS (page 3 of 5)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
		<ul style="list-style-type: none"> • 5-level skills are assigned to the intermediate shop which also performs flightline maintenance 	Questionable		<p>repair skills (5 to 7-level) that are not consistently available in all intermediate shops.</p> <p>7) The depot level maintenance shops were found to be employing civilian technicians. Due to their extensive electronics repair experience, training provided, low turn-over rate, etc., these technicians would be considered to have 7-level electronic repair skills</p>
AN/APQ-130 Radar		<ul style="list-style-type: none"> Flightline maintenance requires 5 to 7-level skills Intermediate shop maintenance requires 5 to 7-level skills Average skills available in the flightline and intermediate shops equals 5-level 	<ul style="list-style-type: none"> Extensive on-the-job training as required before maintenance proficiency is developed 	<ul style="list-style-type: none"> • Questionable 	
AN/APG-63 Radar				<ul style="list-style-type: none"> Extensive on-the-job training is required before maintenance proficiency is developed 	
F-15				<ul style="list-style-type: none"> Extensive on-the-job training is required before maintenance proficiency is developed Skills available in flightline and intermediate level shops equal 5-level 	

TRAINING AND PERSONNEL SKILL LEVELS (page 4 of 5)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Negative		
AN/AWG-20 Armament Control		<ul style="list-style-type: none"> • Flightline maintenance can be accomplished by 5-level skilled personnel • Flightline maintenance personnel have 5-level skills 	<ul style="list-style-type: none"> • Intermediate shop maintenance requires 5 to 7-level skilled personnel • Intermediate shop skill level averages 5-level 	• Questionable	
F-16 AN/ARC-164 Radio		<ul style="list-style-type: none"> • Flightline maintenance can be accomplished by 3-levels • Intermediate level maintenance (limited to SRU replacement) can be accomplished by 5-levels • 5-level skilled personnel are available in the flightline and intermediate shops 		• Positive	
AN/ARN-118 Tacan Set			<ul style="list-style-type: none"> • Flightline maintenance can be accomplished by 3-levels • Intermediate level maintenance (limited to functional tests) can be accomplished by 3 levels 	(continued next page)	

TRAINING AND PERSONNEL SKILL LEVELS (page 5 of 5)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
		<ul style="list-style-type: none">• 5-level skilled personnel are assigned to the intermediate shop which also performs flightline maintenance				

TREND EVALUATION: TROUBLESHOOTING METHODS

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
KS-97A Radar Scope Camera System		<ul style="list-style-type: none"> System pulled from aircraft for shop check 	<ul style="list-style-type: none"> Shop uses manual procedures, circuit analysis, component substitution 	<ul style="list-style-type: none"> No plug-in SRUs to aid fault-isolation 	Positive	<p>1) Substitution is the most popular system troubleshooting technique used on the flightline</p>
F-4E AN/ASX-1 TISEO		<ul style="list-style-type: none"> BIT is performed BIT failure is analyzed SRUs substitution in conjunction with manual procedures used in shop for LRU fault-isolation 	<ul style="list-style-type: none"> Interface test set is used on the flightline as a last resort One LRU at a time is pulled for shop check 	<ul style="list-style-type: none"> BIT failure analysis requires test set Poor accessibility for connection of interface test set to system 	Questionable	<p>2) The second most popular system troubleshooting technique used by flightline personnel is to pull suspected LRUs from the aircraft for testing in the intermediate level shop. This technique is resorted to for those situations where spare units are not available for substitution in the aircraft.</p>
AN/ARC-109 Radio Set		<ul style="list-style-type: none"> System check using BIT meter Substitution in aircraft using redundant LRU SRU substitution in conjunction with manual procedures in shop 			Positive	<p>3) System BIT capability is considered to be a definite aid for system troubleshooting. A BIT capability intended for operational/functional checks allows a quick system check, which in conjunction substitution, is effective for fault-isolation. Automatic BIT diagnostics has not proven to be an effective aid for troubleshooting because of low confidence levels associated with fault-indications.</p>
C-5A						

TROUBLESHOOTING METHODS (page 2 of 5)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
MARK V Tacan Set	<ul style="list-style-type: none"> • System is first checked using BIT • LRU substitution using redundant aircraft LRUs • SRU substitution in conjunction with manual procedures used in shop for LRU fault-isolation 	<ul style="list-style-type: none"> • Procedures in intermediate manual are complex and difficult to use by other than skilled technicians 	<ul style="list-style-type: none"> • Control unit has no plug-in SRUs for substitution • Control unit troubleshoot at depot using manual procedures, circuit analysis, etc. 	Positive	<p>4) Shop-replaceable-units (plug-in modules), when provided in LRUs, are effective aids for troubleshooting. Fault-isolation by substitution of SRUs is a preferred shop technique which allows fault-isolation by lower skilled personnel. When SRUs are not included in the LRU design, technicians must accomplish fault-isolation by circuit analysis, deductive logic, and component replacement.</p>
KB-18A Strike Camera System	<ul style="list-style-type: none"> • System check utilizing BIT • LRU substitution utilized 50% of the time • LRUs pulled for shop check • SRUs substitution in conjunction with manual procedures, used in shop for LRU fault-isolation 	<ul style="list-style-type: none"> • Shop uses manual procedures, circuit analysis, etc. to troubleshoot camera unit 	<ul style="list-style-type: none"> • No plug-in SRUs in camera unit 	Positive	<p>5) Automatic fault-diagnostics on intermediate and depot level test stations has not proven to be an effective aid for troubleshooting LRUs. As with system-level automatic diagnostics, the low confidence levels associated with LRU automatic fault diagnostics have caused technicians to rely heavily on functional tests and substitution techniques.</p>
P-111D	AN/APQ-130 Radar	<ul style="list-style-type: none"> • System check using BIT first • BIT fault-diagnostics secondary 	<ul style="list-style-type: none"> • Suspected LRUs pulled for shop check if no units available for substitution (low confidence diagnostics) 	Questionable	<ul style="list-style-type: none"> • BIT fault-diagnostics is ineffective in identifying defective LRU

TROUBLESHOOTING METHODS (page 3 of 5)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
		<ul style="list-style-type: none"> • LRU substitution in aircraft when spares are available • SRU substitution in conjunction with analysis, manual procedures, etc. utilized in shop for LRU fault-isolation 		<ul style="list-style-type: none"> • Significant amount of logical analysis is required to supplement automatic diagnostics on intermediate test stations • Hot mock-up required to resolve problems of inconsistent test results in intermediate shop 		
AN/APG-63 Radar	F-15	<ul style="list-style-type: none"> • BIT fault-diagnosis provides 70-80% confidence level • BIT fault-diagnosis secondly • LRU substitution in aircraft if spares are available • Suspected LRUs pulled for shop check (70-80% confidence level using BIT diagnostics) • SRU substitution in conjunction with analysis, diagnostics, etc. utilized in shops for LRU fault-isolation 		<ul style="list-style-type: none"> • Hot mock-up required to resolve problems of inconsistent test results in intermediate shop • Automatic fault-diagnostics for ATE in the intermediate level is not fully operational 		

TROUBLESHOOTING METHODS (page 4 of 5)

Weapon System	Avionics Subsystem	Analysis Summary			Overall Assessment	Trend Analysis
		Positive	Questionable	Negative		
AN/AWG-20	Arment Control	<ul style="list-style-type: none"> • System checked using BIT • Substitution of LRU attempted in conjunction with BIT to fault-isolate to a spare is available • LRU pulled for shop check if no spare is available • SRU substitution in conjunction with automatic diagnostics, analysis, etc. used in shop for LRU fault-isolation 	<ul style="list-style-type: none"> • Test equipment (AWM-72) is required in conjunction with BIT to fault-isolate to an LRU 	<ul style="list-style-type: none"> • AWM-72 utilization requires excessive amount of time • Arment control panel malfunctions difficult to troubleshoot • Majority of Computer-Programmer unit problems beyond capability of intermediate level shop fault-isolation/repair capability • Automatic fault-diagnostics for ATE in the intermediate shop is not fully operational 	Questionable	
AN/ARC-164			<ul style="list-style-type: none"> • LRU substitution following system operational check • SRU substitution in conjunction with manual diagnostics, analysis, etc. in the intermediate shop for LRU fault-isolation 	Positive		

TROUBLESHOOTING METHODS (page 5 of 5)

Weapon System	Avionics Subsystem	Analysis Summary		Overall Assessment	Trend Analysis
		Positive	Questionable		
AN/ARN-118 Tacan Set	<ul style="list-style-type: none"> • BIT is performed initially • LRU substitution is attempted if spare LRUs are available • Suspected LRU or complete system is pulled for shop check if no spares are available for substitution • Collins accomplishes all LRU troubleshooting and repair 			Positive	

SECTION VI
MAINTENANCE ITEM AREA TRENDS

TREND SUMMARY: ACCESSIBILITY

Locations	Mounting Concepts	Access Methods	Assessment	Advantages	Disadvantages
Cockpit	Console/instrument panel	Thru cockpit	Satisfactory	<ul style="list-style-type: none"> • Direct access • Minimum access time (excluding delays caused by other shops) • Second lowest LRU remove/install time 	<ul style="list-style-type: none"> • Labor intensive area • Single-man/single-shop area (in fighters) • Poor working position • Delays caused by other shops
Electronics Compartment	Hard-mounted/ single LRU rack	Access panel	Least preferred		<ul style="list-style-type: none"> • Excessive number of torqued fasteners on panels • Some dependency on other shops for support (opening panels, removing equipment, operating support equipment, etc.) • Limited working area • Highest LRU remove/install time
Electronics Bay	Multi-LRU rack	Access door	Preferred	<ul style="list-style-type: none"> • Quick-release door latches • Stand-up working position • Quick-release LRU fasteners • Fewest delays caused by other shops • Lowest LRU remove/install time • Large unobstructed work area 	

TREND SUMMARY: ACCESSIBILITY (continued)

Locations	Mounting Concepts	Access Methods	Assessment	Advantages	Dissadvantages
Radome	Hard-mounted/ slide-out rack	Swing-away radome	Satisfactory	<ul style="list-style-type: none"> ● Large work area ● Stand-up working position ● Few maintenance delays caused by other shops 	<ul style="list-style-type: none"> ● Excessive height on some aircraft ● Fragile/hazardous equipment exposed in work area ● Indirect access to radome fasteners on some aircraft ● Lack of quick release fasteners

TREND SUMMARY: AGE OF SYSTEM AND TECHNOLOGY

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Solid-state components	Discrete	Satisfactory	<ul style="list-style-type: none"> Improving reliability Reducing size, weight Reducing cooling requirements Reducing cost per function 	<ul style="list-style-type: none"> Increasing provisioning problems Increasing requirements for special techniques (installation/removal, test, etc.)
	Small-scale integration	Improvement		
	Medium-scale integration (micro-electronics)	Preferred		
	Signal Processing Technique	Analog	<ul style="list-style-type: none"> Lower complexity 	<ul style="list-style-type: none"> Initial and periodic alignments Evaluation of performance
			<ul style="list-style-type: none"> Lack of alignments Simplified evaluation of performance 	<ul style="list-style-type: none"> Higher complexity
		Digital	<ul style="list-style-type: none"> Less complex than digital Simplified changes 	<ul style="list-style-type: none"> Modifications Software configuration management Complexity
		Hardwired logic Programmable (using software) logic	<ul style="list-style-type: none"> Satisfactory 	<ul style="list-style-type: none"> Maintenance required Integration level is highest
			<ul style="list-style-type: none"> Preferred 	<ul style="list-style-type: none"> Integration (design, operation and maintenance)
	Liquid cooling	Least preferred	<ul style="list-style-type: none"> None (from maintenance viewpoint), 	<ul style="list-style-type: none"> System complexity Maintenance required Integration level is highest
Electronics Cooling	Forced air cooling	Satisfactory	<ul style="list-style-type: none"> Reduced complexity (versus liquid) Reduced maintenance (versus liquid) 	
	Ambient, non-forced air cooling	Preferred	<ul style="list-style-type: none"> Reduced noise Less support equipment Reduced integration 	

TREND SUMMARY: AGE OF SYSTEM AND TECHNOLOGY (continued)

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Switches	Rotary	Unsatisfactory		<ul style="list-style-type: none"> ● Lost, loose knobs (or tools) in cockpit ● High density/complexity of wiring ● Higher failure rate than electronic components
	Thumbwheel (variation on rotary) Pushbutton, toggle, etc.	Satisfactory	<ul style="list-style-type: none"> ● Eliminates loose knobs and tools in cockpit ● Eliminates loose knobs/tools in cockpit ● Eliminates dense/complex wiring in LRU 	
Tuners	Electro-mechanical servos Electronic	Unsatisfactory	<ul style="list-style-type: none"> ● lower complexity 	<ul style="list-style-type: none"> ● Low reliability ● Rotary switch problems
	Discrete-wire bundles and quick-release connectors Terminal-to-terminal inter-rack wiring and rack connectors	Preferred	<ul style="list-style-type: none"> ● High reliability ● Eliminates rotary switches 	
IRU Interconnections		Satisfactory	<ul style="list-style-type: none"> ● Positive connector action ● Repairability 	<ul style="list-style-type: none"> ● Pin replacement problems
		Unsatisfactory		
SRA Interconnections	Pin-to-pin wiring (soldered connections) Wire-wrap assemblies	Satisfactory	<ul style="list-style-type: none"> ● Simple repair ● No provisioning problems 	
		Satisfactory		<ul style="list-style-type: none"> ● Difficulty of repair

TREND SUMMARY: DEBRIEFING

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Malfunction Symptom Complexity	<ul style="list-style-type: none"> • Simple • Complex (integrated with other subsystems, unique or special modes, extensive BIT, etc.) 	<ul style="list-style-type: none"> Positive Negative 	<ul style="list-style-type: none"> • Easily described by aircrew • Easily entered in forms by aircrew and debriefers • Easily understood by maintenance • Malfunctioning system (and responsible shop) is obvious to debriefers • More accurate coding of write-ups 	<ul style="list-style-type: none"> • Difficulty of communications • Technical advice required in debriefing • Maintenance experience required in debriefing • Malfunctioning subsystem is not obvious
Status (operational or non-operational)	<ul style="list-style-type: none"> • Known (determined by aircrew) • Unknown (example: camera status is unknown until film assessment is accomplished) 	<ul style="list-style-type: none"> Positive Negative 	<ul style="list-style-type: none"> • Problems associated with delayed write-ups are avoided 	<ul style="list-style-type: none"> • Delayed write-ups and associated problems: <ol style="list-style-type: none"> 1. Failure to enter write-up in forms (both aircraft and debriefing) 2. Failure to notify maintenance control of problem 3. Failure to notify responsible shop of problem

TREND SUMMARY: DEPOT SUPPORT

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Depot Level Repair	<ul style="list-style-type: none"> • Only SRAs beyond I-level capability • Most SRUs and some LRUs • All LRUs and SRUs 	Satisfactory Satisfactory Preferred	<ul style="list-style-type: none"> • Heavy demand is placed on the assets normally available in an I-level shop resulting in ineffective maintenance • I-level shops can normally be expected to be able to provide the assets required to accomplish LRU repair • I-level shop requires only limited skills, manpower and equipment (to provide fault verification capability). Emphasis can be shifted to maintaining aircraft rather than repair of repairables • Potential for higher quality LRU maintenance with lower life cycle costs 	<ul style="list-style-type: none"> • I-level shops can not provide adequately skilled personnel to accomplish repairs of highly complex electronics • I-Level shop must be extensively equipped in terms of skills, equipment, spare parts, etc. • Total dependence of operational units on supply system
Test Capability at Depot	<ul style="list-style-type: none"> • Same as I-level (implies same equipment) • Same as I-level plus more extensive capability • Extended test capability only 	Satisfactory Preferred Satisfactory	<ul style="list-style-type: none"> • Investment in equipment related costs can be minimized • Continuity of test tolerances, procedures, etc. is assured • I-level malfunction can be duplicated at depot • Test-tolerance traceability • Improved fault-isolation capability 	<ul style="list-style-type: none"> • Items repaired at depot will be rejected at I-level frequently • Equipment associated investment is highest • Limited test tolerance traceability • No duplication of I-level malfunction

TREND SUMMARY: PRE-, IN-, POST-FLIGHT INSPECTIONS

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Maintenance Inspection Requirements	Required	Unsatisfactory		<ul style="list-style-type: none"> • Requires commitment of limited avionics maintenance resources which could be better utilized elsewhere • Increases ground operating time on systems and support equipment
	Not required	Preferred	<ul style="list-style-type: none"> • Frees maintenance resources for more important uses • Reduces system ground operating times 	<ul style="list-style-type: none"> • Qualitative checks only • Heavy aircrew workload (operating switches, observing displays, etc.) • Many unchecked functions, modes, etc.
Operational Checks (by aircrew)	Without BIT	Unsatisfactory		<ul style="list-style-type: none"> • Normally not appropriate for use in flight • Operation at the discretion of the aircrew • Aircrew workload might be increased
	Including Initiateable BIT	Satisfactory	<ul style="list-style-type: none"> • Test thoroughness is better than without BIT • Quantitative checks are provided • Additional failure data can be provided maintenance by aircrew 	

TREND SUMMARY: PRE-, IN-, POST-FLIGHT INSPECTIONS (Continued)

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Operational Checks (by aircrew) (Continued)	Including Automatic BIT (nonconstant) Including Automatic BIT (constant fault-monitoring)	Satisfactory	<ul style="list-style-type: none"> • Minimum impact on aircrew workload • Appropriate for in-flight use • Quantitative checks, improved test thoroughness, and additional failure data for maintenance 	<ul style="list-style-type: none"> • Flight phase of failure cannot be identified for maintenance

TREND SUMMARY: LEVEL OF BASE REPAIR

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Authorized Base Repair	LRU fault-verification and replacement (no repair authorized)	Satisfactory	<ul style="list-style-type: none"> Higher quality LRU maintenance is possible at the depot (due to higher average skill level, more specialization, etc.). Higher quality maintenance can improve LRU reliability at the system-level. Reduced manpower requirements at the intermediate level where problems of insufficient manpower, high turnover, etc. are a major problem. 	<ul style="list-style-type: none"> Very great dependency on depot and supply system to sustain unit operations. Some maintenance personnel assigned to intermediate level feel they are being deprived of the right to perform maintenance within their capabilities. Equipment at intermediate level tends to be under-utilized.
LRU repair by SRU replacement		Satisfactory	<ul style="list-style-type: none"> Moderate demands on supply system and depot to support unit operations. Intermediate level workload is such that most personnel will not complain about under-utilization of their skills. 	<ul style="list-style-type: none"> Complexity of some LRUs being repaired at intermediate level is such that skill level requirements, test equipment requirements, etc. are excessive. Test equipment at intermediate can be more efficiently utilized since similar equipment is required to provide either fault-verification test only or fault-verification plus SRU replacement.
LRU/SRU repair by electronic component replacement		Satisfactory		<ul style="list-style-type: none"> Results in least dependency on supply system and depot Manpower, skills, equipment, etc. required at intermediate level are excessive. Even when this repair is authorized, depot still receives large number of units not repaired in field shops.

TREND SUMMARY : LEVEL OF BASE REPAIR

Factors	Variations	Overall Assessment	Advantages	Disadvantages
System-Level Alignments	Very few (or none) required	Preferred	<ul style="list-style-type: none"> • Minimizes on-the-aircraft maintenance time thereby improving aircraft availability. • Minimizes flightline test equipment requirements • Minimizes system ground operating time. • Minimizes system periodic inspection requirements • Improves probability that malfunctions can be identified by quantitative rather than qualitative means. 	<ul style="list-style-type: none"> • On-the-aircraft maintenance time will be significant. • Flightline equipment and manpower requirements will be considerable. • Periodic inspections might be required. • Identification of defective LRUs will be more difficult or at the least, delayed (alignments must be attempted prior to replacing LRU).
Scheduled Maintenance	None required	Preferred	<ul style="list-style-type: none"> • Minimizes system ground operating time. • Scarce maintenance resources are freed for other uses. • System performance might be enhanced in some cases. 	<ul style="list-style-type: none"> • System ground operating time can be excessive. • Scarce maintenance resources are tied down.
	Required	Satisfactory		

TREND SUMMARY: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Factors	Variations	Overall Assessment	Advantages	Dissadvantages
System Packaging	One to three LRUs Four or more LRUs	Preferred Satisfactory	<ul style="list-style-type: none"> Simplifies system repair by minimizing complexity of fault-isolation task Reduced LRU complexity contributes to less difficult unit repair in the intermediate/depot shop 	<ul style="list-style-type: none"> Reducing the number of LRUs increases their complexity which makes LRU repair more difficult System repair is more difficult as a result of increased fault-isolation difficulty
Racked LRUs (with inter-track wiring and plug-in LRUs)	Unsatisfactory		<ul style="list-style-type: none"> Minimized remove/install time Less likelihood of damaging rack wiring than interconnection cables when removing/installing LRUs 	<ul style="list-style-type: none"> LRU/rack connector interface problems Added complexity for troubleshooting Rack fault-isolation by substitution Rack removal/installation is difficult LRU removal/installation creates more stresses on electrical cables than rack wiring, and increases probability of wire breakage
Racked LRUs (with LRU interconnection cables)	Preferred		<ul style="list-style-type: none"> No LRU seating problems Rack maintenance limited to mechanical repairs Rack removal/installation is simplified Interconnection cables can be replaced/repaired without rack removal 	
System-level Alignments	Required	Unsatisfactory		<ul style="list-style-type: none"> Requires flightline test equipment or BIT equipment Increases system ground operating time Probability of misalignment Increased justification for scheduled maintenance

TREND SUMMARY: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Factors	Variations	Overall Assessment	Advantages	Disadvantages
System-level Alignments (Cont)	Not required	Preferred	<ul style="list-style-type: none"> • Eliminates flightline equipment requirements • Contributions to reduced ground operating time • Probability of misalignment is eliminated • Reduced requirements for scheduled maintenance • Malfunction (versus misalignment) recognition time is minimized 	<ul style="list-style-type: none"> • Fault-isolation by substitution is practical exclusively
Redundant Systems/Functions	Provided (example: C-5A COMM/NAV equipment)	Preferred	<ul style="list-style-type: none"> • Output/performance cross-checking provides positive indication of malfunction • Interchanging of LRUs/ SRUs allows rapid fault-isolation • Reduced emphasis on repair of malfunctions discovered during preflight checks 	<ul style="list-style-type: none"> • Malfunctions are less obvious and fault-isolation is more difficult • Mission essential equipment found defective during pre-flight must be fixed to avoid ground abort

TREND SUMMARY: MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Factors	Variations	Overall Assessment	Advantages	Disadvantages
BIT Capability	Not Provided	Unsatisfactory	<ul style="list-style-type: none"> ● Reduced system complexity ● Higher quality tests using external test equipment ● Similar aircrew operational checks and maintenance ground checks improves communications 	<ul style="list-style-type: none"> ● Test equipment requirements are greater ● Qualitative checks are used almost exclusively ● Excessively complex/time consuming system checks
Operational Status Checks (go/no-go test)		Satisfactory	<ul style="list-style-type: none"> ● Test equipment requirements minimized/eliminated ● Minimized complexity/time for system checks ● Quantitative checks are performed ● Good aid for troubleshooting by substitution 	<ul style="list-style-type: none"> ● System complexity becomes greater ● Maintenance BIT procedures can be extensive ● BIT confidence levels necessitate back-up operational checks by other means
Operational and Fault-diagnostics Checks		Satisfactory	<ul style="list-style-type: none"> ● Potential for improved maintenance efficiency by reducing maintenance repair time on complex systems ● Reduced O-level dependence on I-level 	<ul style="list-style-type: none"> ● Complexity (system, procedures, etc.) ● Less than satisfactory confidence levels ● Not required for low complexity systems
Operational Checks and Fault-indicators (Flags on LRUs)		Preferred	<ul style="list-style-type: none"> ● Good maintenance aid in quick-fix environment ● Minimized system ground operating time ● Maintenance procedures are less complex than for other forms of diagnostics 	<ul style="list-style-type: none"> ● Increased LRU complexity

TREND SUMMARY : MAINTAINABILITY CHARACTERISTICS OF EQUIPMENT DESIGN

Factors	Variations	Overall Assessment	Advantages	Dissadvantages
BIT Capability (Cont)	Operational Checks and Fault-Indicators (Flags on LRU's) (Cont)	Preferred (Cont)	<ul style="list-style-type: none"> Very high confidence level for isolation of BIT failure to the LRU level Reduced BIT complexity at system level 	<ul style="list-style-type: none"> Fault-isolation is difficult since substitution, an often used troubleshooting aid, is impracticable
LRU Configuration	Plug-in SRUs not utilized	Unsatisfactory	<ul style="list-style-type: none"> SRU connector problems are avoided 	<ul style="list-style-type: none"> Fault-isolation by substitution utilized almost exclusively
Plug-in SRUs		Preferred	<ul style="list-style-type: none"> Simplified fault-isolation and repair of LRUs 	<ul style="list-style-type: none"> Increased dependency on substitution techniques More complex test equipment hook-up for troubleshooting of LRU
LRU Test Connector		Satisfactory	<ul style="list-style-type: none"> Test connector problems avoided Less complex test sets 	
No LRU Test Connector		Satisfactory	<ul style="list-style-type: none"> Simplified fault-isolation to SRU level 	<ul style="list-style-type: none"> Test set complexity Test connector/cable problems
Chassis Utilized (components, inter-connecting wiring, connectors, etc.)		Satisfactory		<ul style="list-style-type: none"> Difficult to troubleshoot Cannot be replaced as an SRU
No Chassis (SRUs interconnected by flat ribbon cables, etc.)		Preferred		<ul style="list-style-type: none"> Simplified fault-isolation by substitution of cables

TREND SUMMARY: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Maintenance Data Collection/Documentation	Debriefing Forms (Comprehensive: defines utilization and status)	Preferred	<ul style="list-style-type: none"> More comprehensive aircraft/system history can be generated 	<ul style="list-style-type: none"> Complexity of debriefing forms Debriefing time required Utilization data is not essential to effective maintenance
	Debriefing Forms (Non-comprehensive: defines status only)	Satisfactory	<ul style="list-style-type: none"> Low complexity debriefing forms Minimum debriefing time Essential maintenance data (write-ups) are recorded 	<ul style="list-style-type: none"> System utilization can not be determined resulting in incomplete system history
Inflight Malfunction Recording		Preferred	<ul style="list-style-type: none"> More comprehensive utilization/status/malfunction data for use by maintenance Potential for automated debriefing 	<ul style="list-style-type: none"> Difficulty of real time readout, display, and analysis System complexity
No Inflight Malfunction Recording		Satisfactory	<ul style="list-style-type: none"> Minimum system complexity Non-essential data is avoided 	<ul style="list-style-type: none"> Limited data available from aircrew No automated debriefing possible
Elapsed Time Indicators		Preferred		<ul style="list-style-type: none"> Reliability as a function of operating time rather than flight hours, which is important data for maintenance/support planners, contractors, etc. can be collected Increased system complexity Non-essential data for field/depot maintenance organizations makes collection a problem

TREND SUMMARY: MAINTENANCE DATA COLLECTION, DOCUMENTATION AND FEEDBACK SYSTEM

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Maintenance Data Collection/ Documentation (Cont)	No Elapsed Time Indicators	Unsatisfactory	<ul style="list-style-type: none"> • Minimum system complexity • Non-essential data collection is avoided 	<ul style="list-style-type: none"> • Contractors, maintenance/ support planners lack important reliability data
Maintenance Analysis/Reports	Automatic Data Processing	Preferred (recurring reports only)	<ul style="list-style-type: none"> • Periodic reports summarizing maintenance data • Trend analysis (problem systems, LRUs, etc.) is accomplished 	<ul style="list-style-type: none"> • Real time data is not available • Data and analysis does not consider unique problems • Error correction, review of reports, etc. consumes excessive manhours
	Manual Analysis of Forms/Records	Satisfactory	<ul style="list-style-type: none"> • Real time information tailored to specific problems • Unnecessary periodic analysis can be avoided to minimize manhour consumption 	<ul style="list-style-type: none"> • Not suited to satisfying recurring report requirements
	Constant Analysis of Malfunction/Maintenance Data Necessary	Unsatisfactory	<ul style="list-style-type: none"> • Improved maintenance efficiency • Aircraft histories (form files, log books, etc.) are maintained in responsible shops 	<ul style="list-style-type: none"> • Aircraft history required in or near shop requiring information • Real time availability of data is essential
	Constant Analysis Not Required	Preferred	<ul style="list-style-type: none"> • No real time need for information • Data retrieval in shop is not essential 	

TREND SUMMARY: MAINTENANCE ORGANIZATION

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Maintenance Levels	2-Level (intermediate and depot)	Satisfactory	<ul style="list-style-type: none"> Total manpower requirements might be less than for 3-level organization Communications problems between organizational and intermediate maintenance are avoided For non-integrated low complexity systems, maintenance efficiency benefits (by using same personnel to repair system and LRUs) LRUs can be repaired on base 	<ul style="list-style-type: none"> Minimal supervision of personnel out of shop on flightline Insufficient transportation for shop personnel Insufficient aircraft systems training/experience Inability to support complex system in aircraft Lack of in-depth expertise (no LRU maintenance training/experience) on base Flightline orientated personnel required to operate/maintain some shop equipment (hot-mockups as a minimum) to provide fault-verification capability LRU repair cannot be accomplished on base (must be done at depot shop)
	2-Level (organizational and depot)	Satisfactory	<ul style="list-style-type: none"> Total manpower requirements might be less than for 3-level organization Communications problems between organizational and intermediate maintenance are avoided Maintenance efficiency benefits (by using same personnel (to fix system and test LRUs) 	

TREND SUMMARY: MAINTENANCE ORGANIZATION

Factors	Variations	Overall Assessment	Advantages	Dissadvantages
Maintenance Levels (con't)	2-Level (organizational and intermediate)	Satisfactory	<ul style="list-style-type: none"> • Maximizes self-sufficiency of military organizations • For low complexity LRUs which can be repaired by 5-level skilled personnel, maximum utilization of resources available in intermediate shops is obtained 	<ul style="list-style-type: none"> • Skill requirements (7-level) for fault-isolation/repair of complex LRUs cannot be satisfied by the military organization due to problems of training, manning, etc. • Complex, expensive test equipment cannot be cost-effectively located at each base • Benefits of specialization, production line techniques, etc. as used at depot, cannot be realized
	3-Level (organizational, intermediate, and depot)	Satisfactory	<ul style="list-style-type: none"> • Benefits of technician specialization in aircraft avionics systems maintenance or LRU maintenance for support of highly complex, integrated avionics systems 	<ul style="list-style-type: none"> • Maximum manpower requirements • Maximum communications problems • Maintenance problems due to overspecialization at organizational, intermediate levels

TREND SUMMARY: ORGANIZATIONAL LEVEL AGE

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Special Handling Equipment	Required	Unsatisfactory	<ul style="list-style-type: none"> Protects personnel from personal injury Reduces probability of LRU damage during handling 	<ul style="list-style-type: none"> Additional training requirements Maintenance delays Increased dependence on powered support equipment provided by other shops Maintenance personnel prefer man-handling Weight of LRUs must be limited Some handling damage
	Not Required	Preferred	<ul style="list-style-type: none"> Minimizes training requirements Minimizes maintenance delays 	<ul style="list-style-type: none"> Maintenance delays (finding, transporting, hook-up, checkout of equipment) Test access Non-availability for system operational checks by aircrews
Flightline Test Equipment	Required	Satisfactory	<ul style="list-style-type: none"> Reduced system complexity (assuming no BIT required) Potential for improved test thoroughness, confidence, etc. as compared to operational tests and BIT 	<ul style="list-style-type: none"> Potential for reduced confidence test thoroughness Minimized test access Problems Maintenance/aircrews can perform similar BIT/operational checks
	Not Required (BIT/operational checks only)	Preferred	<ul style="list-style-type: none"> Minimized maintenance delays 	<ul style="list-style-type: none"> Less test equipment is required (as compared to hot mock-up plus LRU test sets situation) Problems of test tolerance/philosophy continuity between system BIT and LRU test sets
Hot Mock-up	Not Utilized (Non-integrated LRU test sets employed exclusively)			

TREND SUMMARY: ORGANIZATIONAL LEVEL AGE

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Hot Mock-up (Cont.)			<ul style="list-style-type: none"> ● In ability to duplicate system malfunctions in shop ● Training problem: shop personnel develops no experience at the system level 	<ul style="list-style-type: none"> ● Test thoroughness questionable ● Test access problems ● Fault-isolation efficiency
	Utilized (in place of LRU test sets)		<ul style="list-style-type: none"> ● Minimized test equipment requirements ● Minimized test tolerance/philosophy continuity problems ● Shop can duplicate flight-line problems which aids maintenance ● Shop personnel develop system-level experience and can be used on flight-line if required 	<ul style="list-style-type: none"> ● Excessive test equipment requirements
	Utilized (in addition to LRU test sets)			<ul style="list-style-type: none"> ● Minimized LRU test thoroughness, fault-isolation efficiency, etc. (by use of LRU test sets) ● Minimized test tolerance/philosophy differences between flightline and shop tests (by use of hot mock-up)

TREND SUMMARY: PREVENTIVE MAINTENANCE

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Signal Processing Techniques	Analog Digital	Satisfactory Preferred	<ul style="list-style-type: none"> Alignments are eliminated and any possible requirements for preventive maintenance are avoided 	<ul style="list-style-type: none"> Periodic alignment to correct for ageing components might be required
Periodic Inspection (repair/align as required)	Required Unsatisfactory		<ul style="list-style-type: none"> Operating performance of system might be improved Maintenance management (especially, the chief-of-maintenance) considers periodic inspections essential to assure operations that maximum maintenance support is being provided to improve/maintain aircraft availability 	<ul style="list-style-type: none"> Excessive system ground operating time and induced failures Maintenance assets (hangar space, manpower, test equipment, etc.) required for supporting inspections, might be more productive if utilized elsewhere Aircraft in inspection status are not available for use by operations
	Not Required	Preferred		<ul style="list-style-type: none"> System ground operating time and induced failures minimized Maintenance assets can be devoted to corrective maintenance Aircraft downtime for inspections is minimized

TREND SUMMARY: TECHNICAL MANUALS

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Information Provided	Functional Level	Satisfactory	<ul style="list-style-type: none"> • Simplified manuals preferred by less experienced technicians • Less voluminous manuals possible for flightline use 	<ul style="list-style-type: none"> • Highly skilled technicians (who deal with more complex malfunctions) are provided insufficient data
	Detailed	Preferred	<ul style="list-style-type: none"> • Extensive data is provided to allow skilled technicians to accomplish repairs 	<ul style="list-style-type: none"> • Less experienced technicians are overwhelmed by the extensive/complex data provided • Voluminous manuals are required
	Supplements	Unsatisfactory	<ul style="list-style-type: none"> • Available in a timely fashion normally 	<ul style="list-style-type: none"> • Extremely confusing when extensive supplements are required
Changes	Change Pages	Preferred	<ul style="list-style-type: none"> • Confusion associated with procedural changes are minimized 	<ul style="list-style-type: none"> • Change pages for manuals are not available in the field concurrently with hardware changes but lag considerably

TREND SUMMARY: TRAINING AND PERSONNEL SKILL LEVELS

Factors	Variations	Overall Assessment	Advantages	Disadvantages
System Complexity	Low (less than 4 LRUs)	Preferred	<ul style="list-style-type: none"> Flightline personnel having 5-level skill rating and some on-the-job training can perform flightline maintenance satisfactorily 	<ul style="list-style-type: none"> Flightline personnel require extensive on-the-job training and 5 to 7-level skill rating before becoming proficient
Level of Base Repair Authorized	High (4 or more LRUs)	Satisfactory	<ul style="list-style-type: none"> Intermediate shop personnel having 3 to 5-level skills and some on-the-job training can test LRUs 	<ul style="list-style-type: none"> 5-level skills available in the intermediate shop are not utilized to their fullest
	LRU fault verification only (LRU repair at depot)	Satisfactory	<ul style="list-style-type: none"> Intermediate shop personnel having 5-level skills and some on-the-job training can successfully accomplish required maintenance 5-level skills normally found in intermediate shops will be fully utilized 	<ul style="list-style-type: none"> Intermediate shop personnel require extensive on-the-job training and 5 to 7-level skill rating before becoming proficient
	LRU repair limited to SRU replacement (SRU repair at depot)	Preferred	<ul style="list-style-type: none"> Intermediate shop personnel having 5-level skills and some on-the-job training can successfully accomplish required maintenance 5-level skills normally found in intermediate shops will be fully utilized 	<ul style="list-style-type: none"> Intermediate shop personnel require extensive on-the-job training and 5 to 7-level skill rating before becoming proficient
	LRU repair (including SRU repair by component replacement)	Satisfactory		

TREND SUMMARY: TROUBLESHOOTING METHODS

Factors	Variations	Overall Assessment	Advantages	Disadvantages
System Built-In-Test Capability	Operational Test (no automatic diagnostics)		<ul style="list-style-type: none"> • Indicates presence of faults to aid fault-isolation by substitution 	<ul style="list-style-type: none"> • For complex systems, technician must determine which LRUs to replace by analysis • More complex BIT procedures • Low confidence level in BIT diagnostics
	Operational Test, plus fault-diagnostics		<ul style="list-style-type: none"> • Indicates presence of faults to aid fault-isolation by substitution • Automatically diagnoses which LRU is at fault and informs technician 	<ul style="list-style-type: none"> • Indicates presence of faults to aid fault-isolation by substitution • Automatically diagnoses which LRU is at fault and informs technician • BIT procedures might be less complex • Fault-diagnostics is possible after sortie without turning on system
	Operational Test plus fault-diagnostics and fault-indicators (flags)		<ul style="list-style-type: none"> • Minimized connector problems 	<ul style="list-style-type: none"> • Fault-isolation by substitution is made very difficult and time consuming • Test access is not satisfactory
	Not Utilized			
	Shop-Replaceable-Units			

TREND SUMMARY: TROUBLESHOOTING METHODS (continued)

Factors	Variations	Overall Assessment	Advantages	Disadvantages
Shop-Replaceable- Units (continued)	Utilized		<ul style="list-style-type: none"> • Fault-isolation by substitution can be accomplished and the unit repaired using much lower skilled personnel • Good test access by the use of extender boards, etc. • SRUs can be pulled for tests on SRU testers to accomplish fault-isolation 	

SECTION VII
DESIGN FEATURES AND TECHNIQUES DEFINITION

COMMUNICATION SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Accessibility:</u> <ul style="list-style-type: none"> o Location of antenna switching relays o Control of access to preset frequency programmers o Location of overload protection fuses/circuit breakers 	<ul style="list-style-type: none"> o Smaller receiver/transmitter units possibly combined with control unit and located in cockpit o Switching relay included in TACAN R/T units o Both uncontrolled and limited access concepts are used on various equipments o Fuses are presently located on front and back of units, in equipment racks, and on panels 	<ul style="list-style-type: none"> o <u>Physical Partitioning Optimization</u> - to consider locating antenna switching network in R/T o <u>Functional Layout Optimization</u> - to locate relays in aircraft for better accessibility o <u>Functional Layout Optimization</u> - to allow access by operations/maintenance or limit access to maintenance o <u>Functional Layout Optimization</u> - to asses fuses versus circuit breakers and various locations on LRUs o <u>Physical Partitioning Optimization</u> - to consider panel, rack, and LRU locations for overload protection o <u>Mechanical Interface Optimization</u> - to determine advantages of replacing rotary switches with more repairable switches o <u>Integrated Electronics Applications</u> - to accomplish all tuning with solid state electronic components
<u>Repairability:</u> <ul style="list-style-type: none"> o Multiwafer rotary switches o Electro-mechanical servo tuners 	<ul style="list-style-type: none"> o Rotary switches are still being used for many control functions o Thumbwheel switches, push button switches, etc. offer advantages o Eliminated by combining R/T unit and control unit in cockpit o Eliminated by digital frequency synthesis 	

COMMUNICATION SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 2 of 3)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Controls/Displays:</u>		
o Control knob attachment	<ul style="list-style-type: none"> o Thumbwheel switches, push button switches, etc. preclude problems with loose hardware in cockpit o Control knobs with set screws (which invariably cause maintenance problems) are used in some applications 	<ul style="list-style-type: none"> o <u>Mechanical Interface Optimization</u> - to avoid loose hardware or contain it within the LRU
<u>Testability:</u>		
	<ul style="list-style-type: none"> o Operational checks are qualitative (no BIT features are provided for quantitative checks from the cockpit) o Radio sets are normally not equipped with fault-monitoring BIT features for use by aircrews o Receiver/transmitters are normally equipped with BIT meters except when the R/T unit is located in the cockpit o Flightline test equipment is required for fault-verification and fault-isolation (applies to those systems with no BIT meter on the receiver/transmitter) 	<ul style="list-style-type: none"> o <u>Continuous Fault-Monitoring</u> - for minimizing need for scheduled maintenance inspections to check radio alignments o <u>BIT Versus External Test Equipment</u> - to consider advantages of eliminating flightline radio test equipment o <u>Test Commonality/Optimization</u> - to consider advantages of using BIT features as part of LRU shop testing concept
<u>Preventive Maintenance:</u>		
	<ul style="list-style-type: none"> o Analog signal processing with alignments required for optimum performance 	<ul style="list-style-type: none"> o <u>Continuous Fault-Monitoring</u> - for alerting aircrews/maintenance that out-of-tolerance conditions exist o <u>Integrate Electronics</u> - digital signal processing techniques to eliminate alignments

COMMUNICATION SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 3 of 3)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Interfaces:</u> <ul style="list-style-type: none"> ○ Flat cable assemblies (inter-connecting SRUs, circuit boards, etc.) are easily broken during radio repair 	<ul style="list-style-type: none"> ○ Receiver/transmitter unit with no chassis (SRUs attached to each other and interconnected by cable assemblies) exhibits many improved maintenance characteristics 	<ul style="list-style-type: none"> ○ <u>Connecting Device Optimization</u> - to minimize susceptibility to breakage while maintaining the positive features ○ <u>Functional Partitioning Optimization</u> - to consider advantages of chassis elimination

NAVIGATION SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Accessibility:</u> <ul style="list-style-type: none"> o Excessive number of fasteners on access panels/doors <u>Repairability:</u> <ul style="list-style-type: none"> o Multi-wafer rotary switches o Cooling air plenums, heat sinks, etc. increase complexity of chassis repair o Non-modularity of control units 	<p><u>Accessibility:</u></p> <ul style="list-style-type: none"> o Access doors (with latches) provide good accessibility o Access panels (with numerous torqued fasteners) provide less than optimum accessibility <p><u>Repairability:</u></p> <ul style="list-style-type: none"> o Rotary switches are still used for many control functions o Thumbwheel switches, pushbutton switches, etc. eliminate some rotary switch problems o TACAN receiver/transmitters generally require forced air electronic cooling o Decreasing power consumption and heat dissipation associated with LSI technology is reducing cooling requirements o Plug-in subassemblies used extensively to simplify repair o Thumbwheel switches offer the advantage of modularity (over rotary switches) if used in the switching function <p><u>Integrated Electronics Applications</u> - to miniaturize R/T unit and eliminate cooling requirement, thereby providing installation in more accessible compartments</p> <p><u>Functional Layout Optimization</u> - to identify optimum TACAN locations for accessibility</p> <p><u>Mechanical Interface Optimization</u> - to determine advantages of replacing rotary switches with more repairable switches</p> <p><u>Physical Partitioning Optimization</u> - to consider chassis elimination and use of flat wiring assemblies for SRU interconnection</p> <p><u>Mechanical Interface Optimization</u> - to identify improved switching technology for replacing rotary switches with modular switching</p> <p><u>Integrated Electronics Applications</u> - to provide solid state displays, pushbutton panels, etc.</p>	

NAVIGATION SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 2 of 3)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Control Displays:</u>		
<ul style="list-style-type: none"> o TACAN antenna selector switch location 	<ul style="list-style-type: none"> o Antenna selector switches either on TACAN control panel or some other panel 	<ul style="list-style-type: none"> o Functional Layout Optimization - to consider the advantages of TACAN antenna selector switch location on the TACAN control unit
<u>Testability:</u>		
<ul style="list-style-type: none"> o Throughness of subsystem/system BIT of TACAN interfaces 	<ul style="list-style-type: none"> o TACAN BIT verifies subsystem operation but does not verify interface with other subsystems such as inertial navigation 	<ul style="list-style-type: none"> o Federated BIT/System BIT - for providing more comprehensive navigation subsystem checks o BIT - changes to test concept to provide better verification of TACAN outputs
<ul style="list-style-type: none"> o Lack of TACAN BIT failure analysis features 	<ul style="list-style-type: none"> o TACAN systems are not equipped with BIT meters for checking antenna matching, etc. o TACAN systems are not equipped with BIT meters for checking antenna matching, etc. o Some TACAN systems have LRU failure indicators on control unit 	<ul style="list-style-type: none"> o BIT versus External Test Equipment Optimization - to identify best method for fault-isolation to the antenna system o Non-Destructive Evaluation - to consider new methods for checking SWR power out and receiver sensitivity
<u>Preventive Maintenance:</u>		
<ul style="list-style-type: none"> o Alignments required to maintain optimum performance 	<ul style="list-style-type: none"> o Scheduled inspections of TACAN are not required by -6 manual 	<ul style="list-style-type: none"> o Integrated Electronics Applications - to define how adjustable circuitry can be replaced by digital signal processing

NAVIGATION SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 3 of 3)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<p><u>Interfacing:</u></p> <ul style="list-style-type: none"> o Use of inter-rack wiring <ul style="list-style-type: none"> o TACAN shock-mount racks include power switching relays, fuses, and interface wiring with connectors o TACAN racks are used to adapt TACAN units to different aircraft installations o Receiver/transmitter test connectors do not stand up well to intermediate shop usage <ul style="list-style-type: none"> o Test connectors are provided for use with intermediate/depot level test equipment o No access is allowed through these connectors when the RIW concept is utilized o Connectors with high pin density and small pin diameter are used. 	<p><u>Reliable Trends In State-of-the-Art Equipment</u></p> <ul style="list-style-type: none"> o TACAN shock-mount racks include power switching relays, fuses, and interface wiring with connectors o TACAN racks are used to adapt TACAN units to different aircraft installations 	<ul style="list-style-type: none"> o <u>Physical Partitioning Optimization</u> - with emphasis on eliminating relays, fuses, etc. in racks o <u>Electrical Interface Optimization</u> - to consider advantages of replacing rack wiring with direct interunit cables o <u>Test Commonality Optimization</u> - to consider BIT techniques to eliminate test access requirements o <u>Connecting Device Optimization</u> - with emphasis on adequate connector ruggedness

RECONNAISSANCE SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Accessibility:</u> <ul style="list-style-type: none"> • Radar scope camera mounting/installation concept which requires camera removal for scope maintenance. 	<ul style="list-style-type: none"> • Radar scope cameras mounted directly on front of scopes (removal is required for scope maintenance). • Remote film recorders using slaved CRTs. • Magnetic tape recording of video. • Camera location (or design) such that installation/removal of film pack can only be accomplished by maintenance personnel. • Camera control unit located (in avionics bay) remotely from cockpit controls and camera. 	<ul style="list-style-type: none"> • Fiber Optics Application - to allow remote location of camera. • <u>Integrated Electronics Application</u> - for video signal processing into magnetic tape recording format and application of remote recorder. • Fiber Optics Applications - to allow camera location in cockpit. • <u>Integrated Electronics Application</u> - for video signal processing and magnetic tape recording. • <u>Integrate Electronics Application</u> - to miniaturize camera electronics leading to simplified system consisting of camera and cockpit control unit. • <u>Physical Partitioning Optimization</u> - to define number of LRUs required. • <u>Functional Layout Optimization</u> - to identify optimum camera LRU locations in aircraft. • <u>Functional Layout Optimization</u> - to provide good accessibility for test, removal and installation.

Reconnaissance Subsystem: Design Features And Techniques Definition (Page 2 of 3)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
Repairability:	<ul style="list-style-type: none"> ● Lack of modularity in control units. ● Lack of modularity in camera. 	<ul style="list-style-type: none"> ● <u>Physical Partitioning Optimization</u> <ul style="list-style-type: none"> - to define optimum amount of electronics in control unit versus camera unit and to partition electronics into SRUs. ● <u>Physical Partitioning Optimization</u> <ul style="list-style-type: none"> - to group camera electronics on plug-in circuit boards.
Testability:	<ul style="list-style-type: none"> ● Camera test panel not co-located with camera. ● Aircrew checks of camera using BIT requires a second person for usual checks. 	<ul style="list-style-type: none"> ● Functional Layout Optimization - to identify optimum location of camera BIT controls. ● BIT Applications - to provide more comprehensive test of camera operation and display of same in cockpit. ● BIT Application - to provide improved means for verifying film advancement and film remaining.
Preventive Maintenance:		<ul style="list-style-type: none"> ● Reliability Centered Maintenance ● Concept Application - to eliminate scheduled maintenance.
	<ul style="list-style-type: none"> ● Gear/bearing materials and lubricants which minimize or eliminate need for periodic lubrication. ● Camera electro-mechanical mechanisms which require lubrication, cleaning, alignment, etc., on a periodic basis. 	

Reconnaissance Subsystem: Design Features And Techniques Definition (Sheet 3 of 3)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<p><u>Electrical Interfaces:</u></p> <ul style="list-style-type: none"> • Electrical cables/connectors hidden from view. 	<ul style="list-style-type: none"> • Extended inspection intervals to coincide with major aircraft inspections. 	<ul style="list-style-type: none"> • <u>Integrated Electronics Applications</u> – to process video electronically and eliminate electro-mechanical functions. • <u>Electrical Interface Optimization</u> – to optimize location of connectors • <u>Fiber Optics Application</u> – to allow remote location of camera with improved connector accessibility.

WEAPONS DELIVERY EQUIPMENT: DESIGN FEATURES AND TECHNIQUES DEFINITION

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Accessibility:</u> • Inadequate service loop in cables limits accessibility to connectors on back of LRU	<u>Repairability:</u> • Pins in connectors difficult to remove/replace	<ul style="list-style-type: none"> • <u>Electrical Interface Optimization</u> - with emphasis on optimum cable length • <u>Electrical Interface Optimization</u> - with case of pin replacement as one criterion. • <u>Fiber Optics/Multiplexing Applications</u> <ul style="list-style-type: none"> - to reduce density of connections in connectors, thereby allowing use of more rugged and repairable contacts. • <u>BIT Versus External Test Equipment Optimization</u> - to identify BIT techniques for stray voltage testing. • <u>Non-Destructive Evaluation Techniques Application</u> - for built-in stray voltage tests. • <u>Federated BIT/System BIT Optimization</u> - to identify improved BIT concept and reduce need for flight-line test equipment.
	<u>Testability:</u> • Stray voltage checks with test set are required prior to loading weapons. • BIT is not normally adequate for fault-isolation to the defective LRU (test set is necessary).	<ul style="list-style-type: none"> • Common problem associated with connectors in avionics systems. Pin extraction/insertion tool design/quality is a related factor. • All weapons launch stations are given a stray voltage test as part of weapons loading. In addition, stations are functionally checked on a scheduled basis or following maintenance. • Fault-isolation between weapon launcher and weapon control system requires external test equipment.

Weapons Delivery Equipment: Design Features and Techniques Definition (Page 2 of 2)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
	<ul style="list-style-type: none"> • BIT circuitry fails more frequently than primary functions. • LRUs are difficult to fault-isolate to the SRU level. 	<ul style="list-style-type: none"> • <u>BIT-Software Versus Hardware Optimization</u> - to define improved BIT techniques. • <u>BIT Versus External Test Equipment Optimization</u> - to define areas where BIT can provide improvements over external test equipment capability. • <u>Microprocessor application</u> - for higher reliability. • <u>BIT-Software Versus Hardware Optimization</u> - to minimize reliance on BIT hardware. • <u>Test Commonality/Optimization</u> - to define techniques for using LRU BIT features to aid in LRU fault-isolation.
	<u>Mechanical Interfaces:</u> <ul style="list-style-type: none"> • Soft metal mounting screws with easily stripped torque slots used in cockpit. 	<ul style="list-style-type: none"> • Quarter-turn quick-release fasteners are normally utilized for mounting LRUs in cockpit consoles or panels. • <u>Mechanical Interface Optimization</u> - improving cockpit mounting techniques.
	<u>Electrical Interfaces:</u> <ul style="list-style-type: none"> • Problem with wires pulling and breaking at quick-disconnect connectors. 	<ul style="list-style-type: none"> • Common avionics equipment problem associated with insufficient cable lengths or improper connector backshell/collar selection. • <u>Electrical Interface Optimization</u> - with minimizing stress on pins and wires as a major consideration. • <u>Fiber Optics/Multiplexing Application</u> to reduce size of wire bundles.

WEAPONS CONTROL SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Accessibility:</u> <ul style="list-style-type: none"> • Excessive number of fasteners on doors/panels • Fuses located in convenient locations • Undersize access panels/doors • Internal access (such as through avionics compartment) rather than external access to radome fasteners • Location of system interface connectors, couplings, fittings, etc., on equipment racks 	<u>Related Trends In State-of-the-Art Equipment</u> <ul style="list-style-type: none"> • Access doors equipped with minimum number of latches providing good accessibility • Panels and access doors equipped with torqued fasteners increase access time • Fuses are presently located on front and back of units, in equipment racks, and on panels • Both internal and external fasteners for swing-away radomes are being utilized • Many equipment racks have connectors, fittings, etc., located for poor accessibility <u>Potentially Applicable Design-For-Repair Concepts</u> <ul style="list-style-type: none"> • <u>Functional Layout Optimization</u> - to identify optimum locations for electronics • <u>Mechanical Interface Optimization</u> - to identify optimum fastener concepts for minimizing number required. • <u>Functional Layout Optimization</u> - to identify best locations for fuses and circuit breakers • <u>Integrated Electronics Application</u> - to miniaturize LRUs to allow flexibility in location • <u>Functional Layout Optimization</u> - to place units for avoidance of accessibility problems • <u>Mechanical Interface Optimization</u> - to identify optimum radome fasteners • <u>Connecting Device Optimization</u> - to eliminate rack internal wiring, connectors, etc. • <u>Functional Layout Optimization</u> - to identify locations for connectors, fittings, etc., for maximum accessibility 	

WEAPONS CONTROL SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (Page 2 of 6)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Repairability:</u> <ul style="list-style-type: none"> • Excessive system complexity (as measured by number of LRUs) • SRUs which require marriage alignments after installation in LRU • LRU liquid cooling system design such that cooling oil must be drained/oil must be drained/refilled for most LRU repairs • Difficult connector contact removal/insertion • LRU fasteners (for mounting unit in rack) which cannot be replaced using common hand tools • Pressurized LRUs which can be hazardous if maintenance instructions are not followed precisely 	<ul style="list-style-type: none"> • Size, weight and volume required for electronic functions is being greatly reduced by use of integrated electronics • Digital signal processing is being utilized in increasing numbers of applications • Liquid cooling systems are used extensively for cooling of high-power transmitter components • Common problem found with many connectors having snap in contacts. Insertion/removal tool quality and design seems to be directly associated with this problem • Avionics shop replaceable fasteners are available and are used in some applications • Pressurized LRUs are being utilized less frequently 	<ul style="list-style-type: none"> • <u>Integrated Electronics Application</u> - to allow packaging of subsystem in minimum number of LRUs • <u>Physical Partitioning Optimization</u> - to define optimum number of LRUs • <u>Integrated Electronics Application</u> - to allow use of digital signal processing techniques • <u>Integrated Electronics Application</u> - to reduce or eliminate cooling requirements • <u>Connecting Device Optimization</u> - to miniaturize contact replacement problems • <u>Fiberoptics/Multiplexing Applications</u> - to reduce contact density, etc. • <u>Mechanical Interface Optimization</u> - to identify repairable fasteners for use on LRUs • <u>Physical Partitioning Optimization</u> - to minimize need to go inside of pressurized areas

WEAPONS CONTROL SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (Page 3 of 6)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<ul style="list-style-type: none"> • LRU liquid cooling system servicing (following LRU repair) which is excessively time consuming 	<ul style="list-style-type: none"> • Liquid cooling systems are used extensively for cooling of high-power transmitter components 	<ul style="list-style-type: none"> • <u>Integrated Electronics Application</u> - to reduce/eliminate cooling requirements • <u>Physical Partitioning Optimization</u> - to minimize need to go into oil-filled areas of units

Testability:

- Insufficient BIT capability for verification/fault-isolation of common radar malfunctions (false targets, range/angle tracking problems, etc.)
- Inadequate BIT fault-diagnostic capability for identification of defective LRU
- BIT circuitry which provides inconsistent test results and insufficient data for analysis of intermittent failures
- Flightline test equipment requirements are avoided

- Common problem frequently associated with BIT features
- Common problem associated with BIT diagnostics, however, individual LRU fault-indicators reduces problem somewhat
- Common problem associated with complex avionics systems
- Flightline test equipment requirements are avoided

- BIT Versus External Test Equipment Optimization - to define requirements for external test
- BIT Software Versus Hardware Optimization - to define improved BIT methods
- Federated BIT/System BIT Optimization - to define improved BIT methods
- Federated BIT/System BIT Optimization - to trade-off concepts for best fault-isolation capability
- Federated BIT/System BIT Optimization - to define optimum amount of LRU BIT
- Microprocessor Applications - to provide improved LRU BIT
- BIT Versus External Test Equipment Optimization - to identify optimum methods for avoiding flightline test equipment

WEAPONS CONTROL SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (Page 4 of 6)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<ul style="list-style-type: none"> • LRU fault-indicators (or system automatic fault-diagnostics) which provide 60-70% confidence level • Differences between aircraft and ground power systems which require operation of aircraft engine to duplicate airborne malfunction • System/LRU BIT failures cannot be duplicated on the shop test equipment • Flightline test equipment is required for analysis of BIT failures • BIT controls/displays located only in cockpit • Use of fuses (rather than circuit breakers) for overload protection 	<ul style="list-style-type: none"> • BIT circuitry (for driving fault-indicators) cannot provide 100% confidence levels. Levels of 80-⁷ confidence are being achieved in some applications • Improved aircraft power system designs have almost eliminated this problem • Common problem associated with the lack of hot-mockup for use in the shop • Flightline test equipment, especially for BIT failure analysis, is not required for support • BIT controls/indicators are frequently found in the cockpit or on an LRU in the avionics bay • Fuses and circuit breakers are being utilized 	<ul style="list-style-type: none"> • <u>BIT Software Versus Hardware Optimization</u> - to define improved BIT techniques • <u>Microprocessor Application</u> - to improve BIT capability • <u>Integrated Electronics Applications</u> - distributed power subsystems such that LRUs operate on basic aircraft power rather than unique generated power forms • Test <u>Commonality Optimization</u> - to explore possibilities of utilizing BIT capabilities in shop • <u>BIT Versus External Test Equipment Optimization</u> - to consider feasibility of eliminating flightline equipment • Functional <u>Layout Optimization</u> - to identify most effective locations for BIT controls/displays • <u>Integrated Electronics Application</u> - to provide built-in overload protection

WEAPONS CONTROL SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (Page 5 of 6)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Handling:</u> <ul style="list-style-type: none"> Excessive weight of LRU's (especially, receiver/transmitters) which makes necessitates support equipment for handling LRU alignments (such as antenna electrical bore-sight) which are sensitive to the shock/vibration as encountered during maintenance handling 	<ul style="list-style-type: none"> Common problem with fielded radar sets New antenna designs have eliminated this problem 	<ul style="list-style-type: none"> <u>Integrated Electronics Application</u> - to reduce volume and weight of electronics <u>Physical Partitioning Optimization</u> - to result in LRUs that can be easily manhandled by two men <u>Mechanical Interfaces Optimization</u> - to ensure protection for fragile components
<u>Electrical Interfaces:</u> <ul style="list-style-type: none"> Electronic equipment racks with internal rack wiring for interconnecting LRUs Wiring problems associated with poor aging characteristics 	<ul style="list-style-type: none"> Both internal rack wiring and direct LRU interconnection with harnesses are found in fielded equipment 	<ul style="list-style-type: none"> <u>Connecting Devices Optimization</u> - to eliminate rack internal wiring, connectors, etc. <u>Fiberoptics/Multiplexing Applications</u> <ul style="list-style-type: none"> - to minimize interconnections, reduce number of connectors, etc. <u>Fiberoptics/Multiplexing Applications</u> <ul style="list-style-type: none"> - to utilize new type of conductor, reduce wire bundle sizes, etc. Non-potted connectors simplify repair <ul style="list-style-type: none"> Wiring being used in new systems could have the same problem after ten years of environmental exposure

WEAPONS CONTROL SUBSYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (Page 6 of 6)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<ul style="list-style-type: none"> • Use of flat ribbon cable (for interconnecting LRUs/ SRUs) which is prone to breakage at the connectors <p><u>Preventive Maintenance:</u></p> <ul style="list-style-type: none"> • Waveguide dehumidification which requires frequent servicing to avoid moisture accumulation in waveguides • LRUs which require alignment for optimum performance due to the use of analog signal processing 	<ul style="list-style-type: none"> • Common problem with flat ribbon cables and connectors presently being used on fielded equipment 	<ul style="list-style-type: none"> • <u>Connecting Devices Optimization</u> - to identify improved connector, cable designs for use in avionics • <u>Reliability Centered Maintenance Concept Application</u> - to ensure proper preventive maintenance is established for mechanical items and desiccants • <u>Integrated Electronics Application</u> - for digital signal processing and elimination of analog functions

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<p><u>Debriefing:</u></p> <ul style="list-style-type: none"> o System status cannot be determined during debriefing of aircrew (example: camera systems status unknown until film processed) o System maintenance experience essential for debriefers o Extensive data concerning malfunctions is essential for effective maintenance but is not normally entered on the debriefing forms o Shop representatives (acting as technical advisors) are required in debriefing o Correct assignment of work unit codes is difficult due to the integrated nature of the avionics subsystems that might cause problem 	<ul style="list-style-type: none"> o Common problem with camera systems associated with recording systems. Magnetic tape recording systems avoid this problem o Common problem associated with systems which are functionally complex o Common problem associated with systems which are functionally complex o Common problem associated with systems which are functionally complex o Common problem associated with integrated avionics which is maintained by more than one shop 	<ul style="list-style-type: none"> o <u>Integrated Electronics Applications</u> - For replacement of film recording systems with video tape systems o <u>Built-In-Test Optimization</u> - to ensure status of system is provided to aircrew o Design-for-repair concepts not applicable o Design-for-repair concepts not applicable o <u>Federated BIT Versus System BIT Optimization</u> - to provide positive indications as to defective subsystem/LRU

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 2 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Depot Support:</u> <ul style="list-style-type: none"> o Inadequate spares in supply system o Intermediate level shop must test and align items received from depot prior to issue for installation in aircraft o High percent rate by intermediate level shop for items repaired in depot shop 	<u>Related Trends In State-of-the-Art Equipment</u> <ul style="list-style-type: none"> o Digital signal processing is eliminating most requirements for alignments o Common problem associated with items tested on test stations rather than hot mock-ups 	<u>Potentially Applicable Design-For-Repair Concepts</u> <ul style="list-style-type: none"> o <u>Standard Electronic Modules</u> - to provide both improved reliability and more readily available modules for LRU repairs o <u>Standardization of Electronic Parts</u> - to provide readily available parts in order to reduce awaiting-parts times o <u>Integrated Electronics Applications</u> - to provide digital signal processing in other than analog signal processing o <u>Test Commonality Optimization</u> - to ensure appropriate traceability of test tolerances, test procedures, etc. o <u>Built-In-Test Optimization</u> - to provide system test capabilities under all conditions without support equipment

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 3 of 10)

Areas Identified as Needing Maintenance Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Pre-, In-, Post-Flight Inspections:</u> (cont)	<ul style="list-style-type: none"> o Maintenance personnel are required to assist aircrews with operational checks o System operational checks are required following servicing <p><u>Level of Base Repair:</u></p> <ul style="list-style-type: none"> o Repair at the component level is allowed in the intermediate level o LRU's that are beyond intermediate level repair capability and must be sent to the depot for repair o LRU chassis beyond repair capability at intermediate shop and must be repaired at depot (entails shipping complete LRU to depot) 	<ul style="list-style-type: none"> o <u>Built-In-Test Optimization</u> - to provide indications of proper operation of all critical system functions to the aircrew in the cockpit o Common requirement associated with camera system film loading <p><u>Physical Partitioning Optimization - to Investigate application of SRU concept for repair of LRU's</u></p> <ul style="list-style-type: none"> o Most LRUs incorporate SRUs which are replaced at intermediate level and repaired in a depot shop o SRU concept is used extensively o Chassis is eliminated in some LRUs and SRUs directly interconnected by flat ribbon cables <p><u>Physical Partitioning Optimization - to Investigate LRU configurations composed entirely of SRUs</u></p>

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 4 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Maintenance Data Collection, Documentation and Feedback System:</u> <ul style="list-style-type: none"> o Aircraft history not reviewed by maintenance personnel prior to accomplishing maintenance o Logs generated manually to provide historical data on malfunction, reports, corrective action, etc. o Analysis of historical data accomplished manually by maintenance personnel working problem 	<u>Maintenance Organization:</u> <ul style="list-style-type: none"> o Three-level maintenance organization is essential to effective maintenance 	<ul style="list-style-type: none"> o Design-for-repair concepts not applicable o Design-for-repair concepts not applicable o Design-for-repair concepts not applicable o Integrated Electronics Applications - to miniaturize electronics for packaging in fewer LRUs o Physical Partitioning Optimization - to evaluate advantages associated with minimizing the number of LRUs o Design-for-repair concepts not applicable o Applies primarily to recording systems which presently require replacement of film, tape, etc. between missions

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 5 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Maintenance Organization:</u> (cont) <ul style="list-style-type: none"> o Servicing/maintenance tasks are the responsibility of more than one shop 	<u>Organizational Level Age:</u> <ul style="list-style-type: none"> o Common problem associated with radar oil cooling systems 	<ul style="list-style-type: none"> o <u>Integrated Electronics Application</u> - to eliminate oil cooling requirements
<ul style="list-style-type: none"> o LRU handling equipment required due to LRU weight or susceptibility to handling damage o System level malfunctions cannot be duplicated in the shop due to the lack of hot mock-up o Inconsistencies between test tolerances/philosophies for BIT, intermediate shop equipment, and depot equipment o Cooling oil servicing equipment which is time consuming to utilize o Flightline test sets required for system checks 	<ul style="list-style-type: none"> o Radar receiver/transmitter units presently weigh more than two men can easily handle o Common problem with equipment which is supported only by LRU test stations at the intermediate level o Common problem with equipment which is tested on general purpose ATE o Common problem with oil cooled radar servicing o Flightline support equipment requirements are being minimized 	<ul style="list-style-type: none"> o <u>Integrated Electronics Application</u> - to minimize LRU weight o <u>Physical Partitioning Optimization</u> - to separate system into LRUs which are easily handled by two-man crew without handling equipment o <u>Test Commonality Optimization</u> - to investigate advantages of utilizing BIT functions at intermediate level o <u>Test Commonality Optimization</u> - to ensure each lower maintenance level uses more open test tolerances and appropriate test concept o <u>Integrated Electronics Application</u> - to eliminate need for oil cooling and associated servicing equipment o <u>BIT Versus External Test Equipment</u> - to investigate advantages of eliminating flightline equipment requirements

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 6 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Organizational Level Age:</u> (cont) <ul style="list-style-type: none"> o Test set interface cables are high failure items o Insufficient test access provided by test sets o Insufficient test thoroughness with shop test equipment <u>Preventive Maintenance:</u> <ul style="list-style-type: none"> o Scheduled testing, lubrication and cleaning of LURs in the intermediate shop on a scheduled basis o Scheduled inspection/alignment of equipment in aircraft required to ensure satisfactory performance 	<ul style="list-style-type: none"> o Common problem associated with intermediate level equipment 	<ul style="list-style-type: none"> o <u>Connecting Devices Optimization</u> - to ensure adequate ruggedness for hold environment o <u>Connecting Devices Optimization</u> - to provide adequate access to interface signals o Design-for-repair concepts not applicable <ul style="list-style-type: none"> o Requirements associated with electro-mechanical recording systems <ul style="list-style-type: none"> o Solid-state electronics and digital signal processing is eliminating recurring alignment requirements <ul style="list-style-type: none"> o <u>Integrated Electronics Application</u> - to utilize solid-state electronics and digital signal processing to minimize need for periodic alignments o <u>Reliability Centered Maintenance Concept Application</u> - to minimize maintenance to essential tasks

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 7 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<p><u>Preventive Maintenance:</u> (cont)</p> <ul style="list-style-type: none"> o LRUs must be tested and aligned by intermediate shop prior to issue for aircraft installation <p><u>Technical Manuals:</u></p> <ul style="list-style-type: none"> o Confusing procedures in manuals as a result of complexity, errors, or excessive use of supplement pages o Insufficient technical data in flightline manual on signal flow, test point signal values, etc. o Insufficient data in flightline manuals on BIT o Insufficient technical data (such as detailed schematics) in intermediate manuals 	<ul style="list-style-type: none"> o Solid-state electronics and digital signal processing is eliminating recurring alignment requirements <p><u>Reliability Centered Maintenance Concept Application:</u> - to minimize maintenance to essential tasks</p> <ul style="list-style-type: none"> o Design-for-repair concepts not applicable o Common problem with complex systems having many interface signals o Flightline manuals presently provide very limited BIT theory of operation, etc. o Shop manuals for intermediate level use presently contain data of a functional nature. Detailed data is avoided to minimize manual complexity 	<ul style="list-style-type: none"> o Integrated Electronics Application - to utilize solid-state electronics and digital signal processing to minimize need for periodic alignments o Reliability Centered Maintenance Concept Application - to minimize maintenance to essential tasks o Design-for-repair concepts not applicable

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 8 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Technical Manuals:</u> (cont)	<ul style="list-style-type: none"> o Modifications/software changes not documented in a timely fashion in the intermediate level manuals o Overly complex fault-diagnostic logic trees in flight-line and shop manuals o Intermediate level manuals do not clearly describe level of repair intended o Depot level manuals lack sufficient data for test/repair of repairables 	<ul style="list-style-type: none"> o Common problems associated with initial fielding of general purpose ATE o Extremely simplified fault-diagnostic information is presented in flightline manuals for state-of-the-art equipment o Uncommon problem associated with combining intermediate and depot repair procedures in a single manual o Design-for-repair concepts not applicable
<u>Training and Personnel Skill Levels:</u>	<ul style="list-style-type: none"> o Electronic component replacement in intermediate level shop requires 7-level skills and only 5-level skills are available normally 	<ul style="list-style-type: none"> o LRU repair is commonly limited to SRU replacement o <u>Physical Partitionint Optimization - with extensive use of SRUs to simplify LRU repair</u>

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 9 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Training and Personnel Skill Levels:</u> (cont)	<ul style="list-style-type: none"> o Common problem associated with complex subsystems o Extensive on the job experience is required before maintenance proficiency is developed (weapons control and armament control system support) 	<ul style="list-style-type: none"> o Integrated Electronics Application - to reduce volume of electronics for packaging in fewer LRUs o Physical Partitioning Optimization - to package subsystem in fewer LRUs to reduce complexity o Integrated Electronics Application - to reduce volume of electronics for packaging in fewer LRUs o Physical Partitioning Optimization - to package subsystem in fewer LRUs to reduce complexity o Built-In-Test Applications - to simplify system test and fault-isolation o Federated BIT Versus System BIT Optimization - for positive identification of defective LRUs causing BIT failures <p><u>Troubleshooting Methods:</u></p> <ul style="list-style-type: none"> o Fault-isolation of LRU by substitution method is impractical due to the lack of SRUs o BIT failure analyzing requires use of flightline test equipment o Most LRU incorporate SRUs to simplify repair o BIT is replacing flightline test equipment o Physical Partitioning Optimization - to ensure use of SRUs o Federated BIT Versus System BIT Optimization - to investigate potential for improving fault-isolation capability

SUPPORT SYSTEM: DESIGN FEATURES AND TECHNIQUES DEFINITION (page 10 of 10)

Areas Identified as Needing Maintainability Improvement	Related Trends In State-of-the-Art Equipment	Potentially Applicable Design-For-Repair Concepts
<u>Troubleshooting Methods:</u> (cont) <ul style="list-style-type: none"> o Fault-isolation by shop testing LRUs in order of failure probability rather than use flightline test equipment o BIT fault-diagnostics is ineffective in identifying defective LRU o Flightline test equipment for system checks is time consuming to utilize o Automatic fault-diagnostic routines for ATE are inoperative or ineffective o Aircraft or shop test equipment must be used as a hot mock-up to resolve inconsistent test results between system BIT and shop test stations o Significant amount of logical analysis is required to supplement automatic diagnostics on intermediate level ATE 	<ul style="list-style-type: none"> o BIT is replacing flightline test equipment o Common problem with system oriented BIT concepts o Flightline test equipment requirements are being minimized or eliminated o Design-for-repair concepts not applicable o Common problem where LRU test stations are utilized at intermediate level rather than a hot mock-up o Test Commonality Optimization - to ensure compatibility of test concepts at various maintenance levels o Design-for-repair concepts not applicable 	

SECTION VIII
DESIGN-FOR-REPAIR
CONCEPT/MAINTENANCE
CONCEPT EVALUATION

COMMUNICATION SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION

Design-For-Repair Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas			Maintenance Levels Impacted				
		Support Equipment	Labor	Training	Technical Data Supply	2-Level Maintenance Organization Without RIW	3-Level Maintenance Organization With RIW	Without RIW	With RIW
<u>Optimized Physical Partitioning:</u>									
o Trade-off antenna switching in R/T unit versus aircraft	Minor	X	X		Organizational	Organizational	Organizational	Organizational	Organizational
o Trade-off locations for fuses/circuit breakers in aircraft versus on LRU's	Minor	X	X		Organizational	Organizational	Organizational	Organizational	Organizational
<u>Optimized Functional Layout:</u>									
o Trade-off antenna switching locations in aircraft	Minor	X			Organizational	Organizational	Organizational	Organizational	Organizational
o Trade-off aircrafts and maintenance accessibility to preset frequency programmer	Minor	X			Organizational	Organizational	Organizational	Organizational	Organizational
o Trade-off possible fuse/circuit breaker locations in aircraft and on LRU's	Minor	X	X		Organizational	Organizational	Organizational	Organizational	Organizational
o Trade-off location of all components on SRUs (eliminates chassis) versus chassis utilization	Major	X	X	X	Depot	Contractor	Intermediate, Depot	Intermediate, Contractor	Intermediate, Contractor
<u>Optimized Electrical Interfaces:</u>									
o Trade-off interconnection of SRUs by flat cable assemblies and other concepts	Minor	X			Depot	Contractor	Intermediate, Depot	Intermediate, Contractor	Intermediate, Contractor
o Trade-off new switching technology versus rotary switches	Major	X			Depot	Contractor	Intermediate, Depot	Intermediate, Contractor	Intermediate, Contractor
o Trade-off control knob fasteners	Minor	X			Organizational	No Impact	Organizational	No Impact	No Impact

COMMUNICATION SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 2 of 2)

Design-For-Repair Concepts/Maintenance Concept Applications	Magnitude of Support Requirements/ Impact	Major Impact Areas				Maintenance Levels Impacted			
		Support Equipment	Labor	Train- ing	Tech- nical Data	2-Level Maintenance Organization Without RIW	With RIW	3-Level Maintenance Organization Without RIW	With RIW
<u>Integrate Digital Applications:</u>									
o Elimination of electro-mechanical services	Major	X				Depot		Contractor	Intermediate, Contractor
o Elimination of alignments/ preventive, scheduled maintenance	Major	X				Depot		Contractor	Intermediate, Contractor
<u>Continuous Fault-Monitoring:</u>									
o Quantitative flightline testing continuously versus preventive, scheduled maintenance	Major	X	X	X				Organizational	Organizational
<u>BIT Versus External Test Equipment:</u>									
o Built-in-test equipment versus flightline radio test sets presently utilized	Major	X	X	X				Organizational	Organizational
<u>Optimized Test Commonality:</u>									
o Built-in-test equipment versus external shop test equipment	Major	X	X	X	X	Depot		Contractor	Intermediate, Contractor

NAVIGATION SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION

Design-For-Repair Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas	Maintenance Levels Impacted					
			Support Equipment	Labor	2-Level Maintenance Organization		3-Level Maintenance Organization	
					Without RIW	With RIW	Without RIW	With RIW
<u>Optimized Physical Partitioning:</u>			X	X	X	Depot	Contractor	Intermediate, Contractor
o Improved LRU repairability by optimized component partitioning between LRU chassis and SRUs	Major		X	X	X	Organizational	Organizational, Intermediate	Organizational, Intermediate
o Improved subsystem repairability by optimizing partitioning of components between rack and LRUs	Minor		X	X	X	Organizational	Organizational	Organizational
<u>Optimized Functional Layout:</u>			X			Organizational	Organizational	Organizational
o Minimized access times by optimizing subsystem layout in aircraft	Minor		X			Organizational	Organizational	Organizational
o Enhanced subsystem repairability thru consolidation of controls on the control unit in cockpit	Minor		X			Organizational	Organizational	Organizational
<u>Optimized Electrical Interfaces:</u>			X	X	X	Organizational	Organizational	Organizational, Intermediate
o Improved system repairability by optimizing use of intra rack wiring versus use of wiring harnesses for direct LRU and system interconnection	Minor		X			Organizational	Organizational	Organizational, Intermediate
<u>Optimized Mechanical Interfaces:</u>			X		X	Depot	Contractor	Intermediate, Depot
o Optimize repairability by trade-off of advanced switching concepts against multi-safer rotary switches in control units	Major		X					Contractor

NAVIGATION SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 2 of 3)

Design-for-Repair Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Labor	Train- ing	Tech- nical Data	Sup- ply	Maintenance Levels Impacted		
							2-Level Maintenance Organization Without RIW	2-Level Maintenance Organization With RIW	3-Level Maintenance Organization Without RIW
Integrated Electronics Applications:									
o Improved accessibility by mini- mizing constraints on location of LRUs thru elimination of cool- ing air requirements and mini- turization of R/T units	Minor	X				Organizational	Organizational	Organizational	Organizational
o Optimize control unit repair- ability by effective use of electronic displays, digital frequency entry, etc.	Major	X		X	X	Depot	Contractor	Intermediate, Depot	Contractor
Optimized BIT:									
o Trade-off BIT techniques for improved thoroughness to optimize navigation system repairability	Minor	X		X		Organizational	Organizational	Organizational	Organizational
Optimized BIT Versus External Test Equipment:									
o Trade-off requirements for flightline test sets versus more extensive BIT features	Major	X	X	X	X	Organizational	Organizational	Contractor	Intermediate, Depot
Optimized Test Commonality:									
o Optimize common use of LRU BIT features at organizational, intermediate and depot levels to minimize requirements for test equipment and test access	Major	X	X	X	X	Depot	Contractor	Intermediate, Contractor	Intermediate, Contractor

NAVIGATION SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 3 of 3)

Design-For-Repair Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas	Maintenance Levels Impacted					
				Labor	Training	Technical Data	Supply	2-Level Maintenance Organization Without RIW	With RIW
Optimized Federated BIT/System BIT:	Minor	X	X	X	X	X	X	Organizational	Organizational
o Optimize navigation system repairability by trading-off BIT techniques									
Optimized Connecting Devices:	Minor	X				X	X	Contractor	Intermediate, Depot
o Trade-off LRU test connection concepts to eliminate or minimize test connector problems									

RECONNAISSANCE SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION

Design-For-Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas				Maintenance Levels Impacted			
			Labor	Training	Technical Data	Supply	2-Level Maintenance Organization Without RIW	With RIW	3-Level Maintenance Organization Without RIW	With RIW
<u>Optimized Physical Partitioning:</u>										
• Improved accessibility by co-location of equipment in fewer LRUs.	Minor	X					Organizational	Organizational	Organizational	Organizational
• Improved repairability by grouping electronic components on plug-in SRUs	Major	X	X			X	Depot	Contractor	Intermediate Depot	Contractor
• Improved repairability by location of all electronics in one LRU.	Minor	X	X				Organizational	Organizational	Organizational	Organizational
<u>Optimized Functional Layout:</u>										
• Improved accessibility by optimizing location of equipment in aircraft.	Minor	X					Organizational	Organizational	Organizational	Organizational
• Improved testability by optimizing locations for BIT controls and indicators in aircraft.	Minor	X					Organizational	Organizational	Organizational	Organizational
<u>Optimized Electrical Interfaces:</u>										
• Reduced damage to cables/connectors by locating connectors in visible locations.	Minor	X					Depot	Contractor	Intermediate Depot	Contractor

Reconnaissance Subsystem: Design-For-Repair Concept/Maintenance Concept Evaluation (Page 2 of 2)

	Magnitude of Support Requirements Impact	Major Impact Areas	Maintenance Levels Impacted							
			Support Equipment	Labor	Training	Technical Data Supply	2-Level Maintenance Organization Without RIW	With RIW	3-Level Maintenance Organization Without RIW	With RIW
Design-For-Maintenance Concept Applications	Major									
Integrated Electronics Applications:										
• Electro-mechanical functions replaced with electronic video processing to eliminate preventive maintenance requirements, improve accessibility, etc.			X				Depot		Contractor	Contractor
Fiber Optics Applications:										
• Improved accessibility by use of remote camera locations.	Minor		X							
• Reduced electrical interface problems by reducing interface constraints through use of remote camera location.	Minor		X							
Reliability Centered Maintenance Concept Application:	Major						Depot		Contractor	Intermediate
• Eliminated scheduled maintenance.										

WEAPONS DELIVERY SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION

Design-For-Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas					Maintenance Levels Impacted			
		Support Equipment	Labor	Training	Technical Data Supply		2-Level Maintenance Organization Without RIW	With RIW	3-Level Maintenance Organization Without RIW	With RIW
<u>Optimized Electrical Interfaces:</u>										
• Improved accessibility with adequate service loops in cables.	Minor	X				Organizational	Organizational		Organizational	Organizational
• Improved connector repairability by use of easily replaceable contacts.	Minor	X				Organizational	Organizational Contractor		Organizational Intermediate Depot	Organizational Contractor
• Reduced connector/cable maintenance by use of appropriate connector backsheets and collars to minimize wire breakage	Minor	X				Organizational	Organizational		Organizational	Organizational
<u>Fiber Optics/Multiplexing Applications:</u>										
• Reduced connector/cable maintenance and improved maintainability through reduced conductor/contact densities.	Minor	X	X			X	Organizational		Organizational	Organizational
<u>Non-Destructive Evaluation Techniques:</u>										
• Elimination of stray-voltage testing requirements	Major	X				Organizational	Organizational		Organizational	Organizational

Weapons Delivery Subsystem: Design-For-Repair Concept/Maintenance Concept Evaluation (Page 2 of 3)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Maintenance Levels Impacted								
		Major Impact Areas	Support Equipment	Labor	Training	Technical Data	Supply	2-Level Maintenance Organization With RIW Without RIW	3-Level Maintenance Organization With RIW Without RIW	Organization With RIW
<u>Optimized BIT-Software Versus Hardware:</u>	Minor	X				X		Organizational Contractor	Organizational Intermediate Depot	Organizational Intermediate Contractor
<u>Optimized BIT Versus External Test Equipment:</u>	Major	X						Organizational	Organizational	Organizational
<u>Optimized Federated BIT/System BIT:</u>	Major	X	X					Organizational	Organizational	Organizational
<u>Microprocessor Applications:</u>	Major	X	X					Organizational	Organizational	Organizational

Design-For-Repair Concept/Maintenance Concept Evaluation (Page 3 of 3)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas	Maintenance Levels Impacted						
			Support Equipment	Support Labor	Training	Technical Data	Supply	2-Level Maintenance Organization With RIW	2-Level Maintenance Organization Without RIW
Optimized Test Commonality:	Major	X	X	X	X	X	X	Contractor	Intermediate Depot

• Improved testability by use of LRU BIT, features in the shop

WEAPONS CONTROL SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION

Design-For-Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas	Maintenance Levels Impacted			
				2-Level Maintenance Organization		3-Level Maintenance Organization	
				Without RIW	With RIW	Without RIW	With RIW
Optimized Physical Partitioning:			X	Depot	Contractor	Intermediate Depot	Contractor
	• Improved repairability by location of high failure components outside of pressurized or oil filled vessels	Major	X	X	Organizational	Organizational	Organizational
	• Improved handling by not allowing LRU weight to exceed man-handling capability	Major	X	X	Organizational	Organizational	Organizational
	• Improved repairability by minimizing number of LRUs	Major	X	X	Organizational	Organizational	Organizational
Optimized Functional Layout:							
	• Improved accessibility by optimizing LRU locations	Minor	X	Organizational	Organizational	Organizational	Organizational
	• Improved repairability by attention to location of fuses and circuit breakers	Minor	X	Organizational	Organizational	Organizational	Organizational
	• Improved accessibility and repairability by optimizing locations of rack mounted components	Minor	X	Organizational	Organizational	Organizational	Organizational
	• Improved testability by optimizing location of BIT controls and indicators	Minor	X	Organizational	Organizational	Organizational	Organizational

WEAPONS CONTROL SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (Page 2 of 6)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas				Maintenance Levels Impacted			
		Support Equipment	Labor	Training	Technical Data	Without RIW	With RIW	2-Level Maintenance Organization	3-Level Maintenance Organization
<u>Optimized Electrical Interfaces:</u>					X	X	X	Organizational	Organizational
• Improved repairability by elimination of rack wiring	Minor	X				X	X	Organizational	Organizational
• Improved repairability by considering contact replacement problems in connector selection process	Minor	X				X	X	Organizational Contractor	Organizational Contractor
• Improved repairability by identification of better flat ribbon cable connectors	Minor	X				X	X	Depot	Depot
<u>Optimized Mechanical Interfaces:</u>						X	X	Contractor	Contractor
• Improved accessibility by minimizing door/panel fasteners	Minor	X						Intermediate	Intermediate
• Improved accessibility by providing external fasteners or swing-away radomes	Minor	X						Contractor	Contractor
• Improved repairability by use of shop replaceable LRU fasteners	Minor	X						Organizational	Organizational
• Improved handling by protection of fragile components	Minor	X							

WEAPONS CONTROL SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (Page 3 of 6)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas				Maintenance Levels Impacted			
		Support Equipment	Labor	Training	Technical Data	With RIW	Without RIW	2-Level Maintenance Organization	3-Level Maintenance Organization
<u>Integrated Electronics Applications:</u>									
• Improved accessibility by use at optimum locations allowed by miniaturizing electronics (and LRUs)	Major	X				Organizational	Organizational	Organizational	Organizational
• Improved repairability by miniaturizing electronics for packaging in fewer LRUs	Major	X	X		X	Organizational	Organizational	Organizational	Organizational
• Improved repairability by elimination of requirements for liquid cooling	Major	X	X			Organizational Depot	Organizational Contractor	Organizational Contractor	Organizational Contractor
• Improved repairability by elimination of SRU marriage problems through use of digital signal processing techniques	Major	X				Depot	Contractor	Intermediate	Contractor
• Improved testability by power system designs which minimize the differences between aircraft and ground power	Minor	X				Organizational	Organizational	Organizational	Organizational
• Improved testability repairability and accessibility by elimination of fuses and circuit breakers through use of built-in overload protection circuits	Minor	X				Organizational	Organizational	Organizational	Organizational

WEAPONS CONTROL SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (Page 4 of 6)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas	Maintenance Levels Impacted			
				2-Level Maintenance Without RIW	With RIW	3-Level Maintenance Without RIW	With RIW
• Improved handling by allowing reduced LRU weights	Major	X	Training	Technical Data	Supply	Organizational	Organizational
• Minimized preventive maintenance requirements by replacing analog with digital signal processing	Major	X	Labor			Organizational	Organizational
<u>Fiber optics/Multiplexing Applications:</u>						Organizational	Organizational
• Improved repairability by reducing the number of conductors, connector contact densities, and the number of connectors	Major	X				Organizational	Organizational
<u>Optimized BIT Versus External Test Equipment:</u>						Organizational	Organizational
• Improved testability by use of external test equipment where BIT cannot perform adequate tests	Major	X	X	X		Organizational	Organizational
• Improved testability by elimination of flightline test equipment where possible	Major	X	X	X		Organizational	Organizational

WEAPONS CONTROL SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (Page 5 of 6)

Design-For-Concepts/Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas					Maintenance Levels Impacted			
		Support Equipment	Labor	Training	Technical Data	Technical Supply	2-Level Maintenance Organization Without RIW	With RIW	3-Level Maintenance Organization Without RIW	With RIW
<u>Optimized BIT Software Versus Hardware:</u>	Major	X					Organizational	Organizational	Organizational	Organizational
• Improved testability by optimizing use of software rather than hardware										
<u>Optimized Federated BIT Versus System BIT:</u>	Major	X					Organizational	Organizational	Organizational	Organizational
• Improved testability by providing better verification of inflight problems	Major	X					Organizational	Organizational	Organizational	Organizational
• Improved testability by use of LRU fault-indicators	Major	X					Organizational	Organizational	Organizational	Organizational
• Improved testability by providing higher consistency of failure data	Major	X	X				Organizational	Organizational	Organizational	Organizational
<u>Microprocessor Applications:</u>	Major	X	X	X	X		Organizational Depot	Organizational Contractor	Organizational Intermediate	Organizational Contractor
• Improved testability by using microprocessor controlled BIT within LRUs										
<u>Optimized Test Commonality:</u>	Major	X	X				Depot	Contractor	Intermediate	Contractor
• Improved testability by use of LRU BIT compatibility for the shop test										

WEAPONS CONTROL SUBSYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (Page 6 of 6)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas	Maintenance Levels Impacted							
				Labor	Training	Technical Data	Supply	Without RIW	With RIW	Without RIW	With RIW
<u>Reliability Centered Maintenance Concept Application:</u>	Minor	X									
• Improved preventive maintenance of mechanical components and desiccants											

SUPPORT SYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas				Maintenance Levels Impacted			
		Support Equipment	Labor	Training	Technical Data Supply	2-Level Maintenance Organization Without RIW	2-Level Maintenance Organization With RIW	3-Level Maintenance Organization Without RIW	3-Level Maintenance Organization With RIW
Optimized Physical Partitioning:									
o Packaging of LRU electronics in SRUs for simplified repair at intermediate level	Major	X	X		X	Depot	Contractor	Intermediate	Contractor
o Elimination of LRU chassis and direct interconnection of SRUs with harnesses	Major		X		X	Depot	Contractor	Intermediate	Contractor
o Packaging of LRUs such that weight does not exceed two-man handling capability	Major	X	X			Organizational	Organizational	Organizational	Organizational
Integrated Electronics Applications:									
o Elimination of film recording medium by use of magnetic tape recorders for improved debriefing	Minor		X			Organizational	Organizational	Organizational	Organizational
o Elimination of intermediate level alignment requirements following depot repair by use of digital signal processing in place of analog functions	Minor		X			No Impact	No Impact	Intermediate	No Impact
o Reduced requirement for three-level maintenance organization through improved reliability and reduced system complexity (reduced number of LRUs)	Major	X	X		X	Organizational	Organizational	Organizational	Organizational

SUPPORT SYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 2 of 5)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas	Maintenance Levels Impacted					
			Support Equipment	Labor	Training	Technical Data	2-Level Maintenance Organization	
							Without RIW	With RIW
<u>Integrated Electronics Applications:</u> (cont)								
o Reduced/eliminated servicing problems by elimination of oil cooling requirements	Major	X	X				Organizational	Organizational, Intermediate
o Elimination of LRU handling equipment by reducing volume/weight of electronics	Major	X	X				Organizational	Organizational
o Minimized need for scheduled inspection/alignment of LRUs by elimination of analog circuitry	Minor		X				Organizational	Organizational, Intermediate
o Reduced skill level requirements by elimination of system complexity through use of fewer LRUs	Major		X	X			Organizational	Organizational
<u>Optimized Built-In-Test Applications:</u>								
o Improved debriefing by providing aircrews with improved operational checks	Minor						Organizational	Organizational
o Minimized requirements for flightline test equipment	Major		X				Organizational	Organizational

SUPPORT SYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 3 of 5)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas	Maintenance Levels Impacted						
				Labor	Training	Technical Data	Supply	2-Level Maintenance Organization Without RIW	With RIW	3-Level Maintenance Organization With RIW
<u>Optimized Built-In-Test Applications:</u> (cont)	Minor	X						Organizational	Organizational	Organizational
o Elimination of requirements for maintenance personnel to assist aircrews with system operational checks										
o Reduced training/skill requirements by provision of automatic fault-diagnostics, etc.	Minor		X X					Organizational	Organizational	Organizational
<u>Optimized Federated BIT Versus System BIT:</u>										
o Enhanced debriefing capabilities by providing LRU failure data to aircrews	Major	X						Organizational	Organizational	Organizational
o Reduced training/skill requirements by use of built-in fault monitoring and LRU fault indicators	Major	X						Organizational	Organizational	Organizational
o Improved BIT effectiveness reducing false removal rate	Major	X						Organizational	Organizational, Intermediate	

SUPPORT SYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 4 of 5)

Design-For-Maintenance Concepts/Concept Applications	Magnitude of Support Requirements Impact	Major Impact Areas	Maintenance Levels Impacted					
			Support Equipment	Labor	2-Level Maintenance Organization		3-Level Maintenance Organization	
					Without RIW	With RIW	Without RIW	With RIW
Standardized Electronics Modules/Electronic Parts:					X	Depot	Contractor	Depot
Optimized Test Commonality:	Major	Major			X	Depot	Contractor	Contractor
Reduced repair turn-around time by increasing parts availability with standardization/commonality concepts	Major	Major			X	No Impact	No Impact	Intermediate, Contractor
Reduced reject rate at intermediate level for items received from depot by using like test procedures and tighter tolerances at depot level	Major	Major	X	X	X	No Impact	No Impact	Intermediate, Depot
Reduced reject rate at organizational level for LRUs repaired at higher level by use of like test procedures (BIT, etc.) and tighter tolerances at intermediate/depot levels	Major	Major	X	X	Organizational, Depot	Organizational, Contractor	Organizational, Intermediate	Organizational, Intermediate
Connecting Device Optimization:	Minor	Minor			X	No Impact	Intermediate	Intermediate
Reduced test equipment maintenance requirements by use of more rugged test connectors						No Impact		

SUPPORT SYSTEM: DESIGN-FOR-REPAIR CONCEPT/MAINTENANCE CONCEPT EVALUATION (page 5 of 5)

Design-For-Maintenance Concept Applications	Magnitude of Support Requirements Impact	Support Equipment	Major Impact Areas	Maintenance Levels Impacted			
				2-Level Maintenance Organization		3-Level Maintenance Organization	
				Without RIW	With RIW	Without RIW	With RIW
<u>Connecting Device Optimization:</u> (cont)	Minor	X		No Impact		Intermediate	No Impact
o Improved fault-isolation capability by improved accessibility to interface signals through test connectors							No Impact
<u>Reliability Centered Maintenance Concept Application:</u>		X				Organizational	Organizational, Intermediate
o Minimized/eliminated scheduled maintenance on avionics equipment except where analysis clearly indicates positive benefits							Organizational